

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-02-27 10:39:21
VIDEO SOURCE	stream_8850268e_2026-02-27T10-37-38.747258Z_st_1.267_end_22.667_clip_1.mp4, stream_8850268e_2026-02-27T10-37-38.747258Z_st_33.367_end_58.400_clip_2.mp4, stream_8850268e_2026-02-27T10-37-38.747258Z_st_89.167_end_102.433_clip_3.mp4
OVERALL VERDICT	REVIEW

SUMMARY: The inspection findings show mixed compliance with PPE standards across three events. While two events demonstrated acceptable adherence to safety protocols with minor deviations, one event revealed a critical failure in PPE usage, raising significant safety concerns. The overall compliance state remains inconclusive due to the stark contrast in findings and the need for further assessment of proximity risks in dynamic environments.

PROJECTED IMPROVEMENTS

- Implement mandatory PPE training and enforcement protocols to ensure consistent use of high-visibility vests and safety helmets across all work areas.
- Conduct regular safety audits to monitor compliance and address lapses promptly, particularly in scenarios involving moving equipment like forklifts.
- Develop clear guidelines for assessing proximity risks when forklifts are in motion, ensuring that safety evaluations account for dynamic operational conditions.

POSITIVE HIGHLIGHTS

- Event 2 demonstrated strong compliance with PPE requirements, with workers consistently wearing yellow safety vests and hard hats.
- In Event 1, the forklift operator was observed wearing a yellow safety vest, indicating partial compliance with visibility standards.
- Both Event 1 and Event 2 showed minimal proximity risks due to controlled conditions, highlighting effective area management during periods of low activity.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 10:38:54
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 85%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE observed on any individuals. No proximity to a moving forklift detected. Scene appears static with no visible activity.

[4.0s - 9.0s]: No instances of non-compliance detected.

[8.0s - 13.0s]: **Focus Area Descriptions**

Personal Protective Equipment (PPE):

- **High-Visibility Safety Vests:** One individual is wearing a yellow safety vest while operating the forklift; no other PPE like vests are observed on pedestrians.
- **Safety Helmets:** No safety helmets are visibly worn by either the operator or the pedestrian.

Proximity to Moving Forklift:

The pedestrian crosses the frame close to the forklift's path but maintains a safe distance without direct contact. The operator remains attentive to their surroundings during the interaction.

[12.0s - 17.0s]: **Focus Area 1: Presence of high-visibility safety vests**

The individual does not wear any high-visibility safety vest; their clothing consists of a light-colored shirt and dark pants.

Focus Area 2: Presence of safety helmets

The individual is not wearing a safety helmet.

Focus Area 3: Proximity to the moving forklift

There is no forklift visible in the frames provided. The individual walks freely without interaction with any moving machinery.


[16.0s - 21.0s]: No PPE detected; individual maintains safe distance from hazards.

[20.0s - 21.433s]: **Final Answer:**

No PPE violations observed; the individual is not wearing high-visibility vests or safety helmets. No forklifts are actively moving, so proximity risks are irrelevant. Scene depicts routine manual tasks without immediate hazards.

Finding 2: Inspection Finding

TIMESTAMP 10:39:05
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 95%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No specific instances of non-compliance with PPE requirements were identified. No safety vests or helmets were visibly worn by either individual. The forklift was not present in the frames, so proximity could not be assessed.

[4.0s - 9.0s]: **Industrial Observation Report**

General Scene:

A spacious industrial area with concrete flooring, yellow pathway markings, three loading docks with ramps, scattered storage items (boxes, crates), and two individuals—one actively moving in the foreground and another stationary in the background.

**Personal

[8.0s - 13.0s]: Yes; both workers wear yellow safety vests and hard hats, meeting PPE requirements. No forklifts are present in the frames, so proximity assessment is not applicable. No violations or issues are evident.

[12.0s - 17.0s]: The worker is wearing a yellow safety vest and a white hard hat, and they remain closely positioned to the forklift while operating it.

[16.0s - 21.0s]: The worker operating the forklift is wearing a yellow safety vest and a white hard hat, complying with PPE requirements. The forklift operator maintains safe positioning while seated inside the vehicle, with no visible hazards nearby.

[20.0s - 25.0s]: **Focus Area Descriptions:**

Personal Protective Equipment (PPE):

1. **High-Visibility Safety Vests:** Present. The individual is wearing a bright yellow safety vest, meeting standard requirements for visibility in industrial environments.
2. **Safety Helmets:** Not visible. Only the lower portion of the individual's body is shown, making it impossible to confirm helmet use.

Proximity to Moving Forklift:

- The forklift is stationary in the background, positioned away from the worker. No immediate risk

[24.0s - 25.067s]: **Answer:**

Yes, one person is wearing a high-visibility safety vest (yellow) and a safety helmet (white), both of which comply with standard PPE requirements. No forklift movement is observed,

Finding 3: Inspection Finding

TIMESTAMP 10:39:15
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 0%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

- [0.0s - 5.0s]: None of the individuals in the scene are visibly wearing PPE such as safety vests or helmets. No forklift is observed in motion, so proximity to a moving forklift cannot be evaluated.
- [4.0s - 9.0s]: No instances of non-compliance detected.
- [8.0s - 13.0s]: No PPE is visible on the individual; they are not wearing a high-visibility vest or helmet. The person maintains a steady path without interaction with machinery or vehicles, so proximity risks are not applicable here.
- [12.0s - 13.3s]: No PPE violations were observed. The forklift enters the scene but does not interact with any workers in the visible frames.