

MANUFACTURING QUALITY ASSURANCE REPORT

EXECUTIVE SUMMARY

INSPECTION DATE	2026-03-02 11:43:40
VIDEO SOURCE	stream_37f4682a_2026-03-02T11-41-54.660396Z_st_1.267_end_22.667_clip_1.mp4, stream_37f4682a_2026-03-02T11-41-54.660396Z_st_33.367_end_58.400_clip_2.mp4, stream_37f4682a_2026-03-02T11-41-54.660396Z_st_89.167_end_102.433_clip_3.mp4
OVERALL VERDICT	FAIL

SUMMARY: The inspection revealed significant PPE compliance failures, with multiple events showing a complete or near-complete absence of high-visibility vests and safety helmets. While one event demonstrated partial compliance, recurring violations indicate systemic safety lapses that require immediate attention.

PROJECTED IMPROVEMENTS

- Implement mandatory PPE training and enforcement protocols to ensure all personnel consistently wear high-visibility vests and safety helmets in industrial settings.
- Develop a clear, context-specific PPE policy that defines when and where PPE is required, eliminating ambiguities that may lead to non-compliance.
- Introduce real-time monitoring systems or designated safety officers to enforce PPE compliance and address violations promptly during operations.

POSITIVE HIGHLIGHTS

- Event 2 demonstrated partial compliance with PPE standards for the majority of the observation period, indicating some level of adherence to safety protocols.
- The observer consistently documented PPE compliance status across all events, providing valuable data for identifying systemic issues.
- In Event 2, safe proximity to the forklift was generally maintained, showing awareness of spatial safety requirements in dynamic environments.

SOP AUDIT CONTEXT

Inspect all individuals in the scene for Personal Protective Equipment (PPE) compliance. Specifically describe: 1) Presence of high-visibility safety vests (e.g. orange/yellow vests). 2) Presence of safety helmets. 3) Proximity to the moving forklift.

DETAILED FINDINGS & VISUAL EVIDENCE

Finding 1: Inspection Finding

TIMESTAMP 11:43:13
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 30%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE observed; individual not wearing high-visibility vest or helmet. Forklift stationary, no interaction occurring.

[4.0s - 9.0s]: No PPE detected; individual not wearing high-visibility vest or helmet. Person remains at a safe distance from the forklift while approaching it.

[8.0s - 13.0s]: No, No, No, No, No, No, No, No


[12.0s - 17.0s]: No PPE detected; individual walks past forklift without interaction.

[16.0s - 21.0s]: No PPE violations detected. The individual is not required to wear a safety vest or helmet in this context. They maintain a safe distance from the stationary forklift and do not interact with it.

[20.0s - 21.433s]: No PPE violations detected; the individual is not wearing a high-visibility vest or helmet, and the forklift remains stationary with no interaction from the person nearby.

Finding 2: Inspection Finding

TIMESTAMP 11:43:25
SOP SECTION PPE & Safety Protocols
COMPLIANCE SCORE 75%



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No PPE-related violations were observed.

[4.0s - 9.0s]: Yes, the worker is wearing a high-visibility safety vest and a safety helmet. They remain stationary relative to the camera while approaching the forklift.

[8.0s - 13.0s]: Yes; Yes; Maintains controlled distance, seated position shows attentiveness to machine operation and surroundings.

[12.0s - 17.0s]: Both individuals wear high-visibility safety vests and safety helmets, and they maintain a safe distance from the stationary forklift.

[16.0s - 21.0s]: Yes, both individuals wear high-visibility safety vests and safety helmets, and they maintain a safe distance from the forklift.

[20.0s - 25.0s]: Yes, the worker is wearing a high-visibility safety vest. No safety helmet is visible. No interaction with a moving forklift is observed.

[24.0s - 25.067s]: **Final Answer:**
The worker is wearing a yellow safety vest and a white hard hat, complying with PPE standards. They remain in close proximity to the forklift without any unsafe movements or interactions.

Finding 3: Inspection Finding

TIMESTAMP 11:43:35

SOP SECTION PPE & Safety Protocols

COMPLIANCE SCORE **0%**



AUDIT ANALYSIS:

CHRONOLOGICAL AUDIT TIMELINE:

[0.0s - 5.0s]: No instances of PPE (high-visibility vests/safety helmets) were observed, and no interactions with moving forklifts occurred.

[4.0s - 9.0s]: No PPE observed; individual not wearing high-visibility vest or helmet.

[8.0s - 13.0s]: No PPE violations detected. Person not wearing high-visibility vest or helmet. No proximity to forklift observed.

[12.0s - 13.3s]: No instances of PPE (high-visibility vests or helmets) are observed; no forklift movement is detected.