

BUTTONS: Too bright. Need Resistors or PWM?

Sheet: / File: mht-base.kicad_sch Title: