
Figure 5A - Steady-State Contraction-Certified Operating Regions
gamma0_max_R1 = 21.091668 deg
gamma0_min_R1 = 15.322599 deg
gamma0_max_R2 = 81.415963 deg
gamma0_min_R2 = 48.626362 deg
Steady-state contraction-certified Region 1
Steady-state contraction-certified Region 2
Case 1
12 deg
Case 2
17.4576 deg
Case 3
35 deg
Case 4
65 deg
Case 5
120 deg
0
20
40
60
80
100
120
gamma0 (deg)
Locally stable, not certified
Contraction-certified
Locally unstable