


Markers: fault clearing. Solid: recovered; dashed: finite-horizon non-recovery, not proven instability.