


Markers: fault clearing. Solid: recovered; dashed: finite-horizon non-recovery, not proven instability. Dotted: fault-on; black star: equilibrium. Rectangle membership alone is not stability certification.