

# GroupTrack

## Release Notes

Version 2.4 Production — April 5, 2026 | Tag: v2.4-20260405

|               |                                                          |
|---------------|----------------------------------------------------------|
| Release Type  | Production — First Production Release                    |
| Package       | com.geeksville.mesh.google (no .debug suffix)            |
| APK Filename  | GroupTrack_v2.4_20260405.apk                             |
| Git Tag       | v2.4-20260405                                            |
| Build Stamp   | GEAR panel — GroupTrack v2.4 — Build YYYYMMDD.HHMM (UTC) |
| Prior Version | V2.4 debug builds (com.geeksville.mesh.google.debug)     |

### IMPORTANT — Action Required

|                                            |                                                                                                 |
|--------------------------------------------|-------------------------------------------------------------------------------------------------|
| Re-download offline maps                   | Package name changed from .google.debug to .google. Previously downloaded tiles will not be     |
| Radio firmware 2.7 — manually update radio | If your radio runs Meshtastic firmware 2.7.x, Apply Master Config will NOT write channel name c |
| Build stamp required on all Open GEARs     | Open GEARs panel. Note your build stamp: GroupTrack v2.4 — Build YYYYMMDD.HHMM. Inclu           |
| Submit issues to coordinator               | All issues go to the tester coordinator. Do not contact the developer directly.                 |

### Commits in This Release

|                   |                                                                                                                                                                         |
|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 4b870afef [fix]   | Tile overlay — perimeter bounding box from actual tile extents<br>SHOW DOWNLOADED draws a single rectangle from outermost downloaded tile coordinates. Accur            |
| d71f9fd3f [fix]   | Downloaded tile overlay — all tiles on disk, no viewport filter<br>Removed viewport filter from overlay calculation. All downloaded tiles included in coverage display. |
| 98d7d6616 [fix]   | RECALC LEAD — immediately locks furthest traveled node<br>RECALC LEAD instantly elects whoever has highest distance accumulator. No waiting. No gap in GF               |
| 9f2b29eb3 [fix]   | Capture screen — asset pull commands use context.packageName<br>adb pull commands on capture screen use actual runtime package name — correct for debug and pr          |
| 475aa00ec [fix]   | Downloaded tile area overlay reads from getExternalFilesDir<br>SHOW DOWNLOADED overlay now reads from external storage where tiles are actually stored.                 |
| e098d9eaf [chore] | Master config assets — SHORT_NAME removed from apply list<br>SHORT_NAME removed from deviceFields. Radio retains existing short name. Eliminates validation             |

### Known Issues in This Release

---

| ID     | Fix Target    | Issue                                                                                       |
|--------|---------------|---------------------------------------------------------------------------------------------|
| BUG-02 | V2.4.1 Apr 12 | Radio firmware 2.7 — channel name and PSK not written by Apply Master Config. Manual        |
| BUG-03 | V2.4.2 Apr 19 | Offline HYB map layer fails on first selection. Workaround: select SAT first then switch to |
| BUG-04 | V2.4.2 Apr 19 | GPX/KML export — share sheet not implemented. File written to storage but not directly s    |

## Next Release — V2.4.1 Sunday April 12

---

Radio firmware 2.7 fix — versioned binary builder dispatcher. Automatically writes correct channel configuration for both 2.6 and 2.7 firmware. Manual channel entry no longer required after V2.4.1.