

Contractor Response Checklist

SLR	Scope Item	Response	Reason
001	MDF Buildout	Included	
007	Head-End Programming	Excluded	By owner per proposal qualifications