

Validated software path: block 0x65 request registers + block 0xF1 result readback

Boardview rail labels: CPU-side 1.8 V; gauge-side 3.3 V. No physical bridge was installed.