
Tachometer output and ground
Motor input and on/off switch
Voltage source
Voltmeter
Encoder output
LOAD
12V
TecQuipment
LOW PASS
BAND PASS
HIGH PASS
GRAY
BINARY
G3
G2
G1
G0
B3
B2
B1
0-5V
0-500Hz
4-20mA
Hz