# Control computarizado - Asignaciónde polos (RST posicional)


Kjartan Halvorsen

July 13, 2020

# Objetivo

► Entender diseño de un controlador por asignación de polos

# Controlador de dos grados de libertad



#### Procedimiento

Dado modelo del proceso  $H(z) = \frac{B(z)}{A(z)}$ , y specificaciones de polos deseados del sistema en lazo cerrado  $A_{cl}(z) = (z - \alpha_1)(z - \alpha_2) \cdots (z - \alpha_{n_c})$ 

1. Determina la ecuación diofántica

$$A(z)R(z)z^d + B(z)S(z) = A_{cl}(z)$$

2. Determina polinomios R(z) y S(z) donde  $n_R \ge n_S$  que satisfican

$$A(z)R(z)z^d + B(z)S(z) = A_{cl}(z)$$

3. Factoriza el polinomio caracteristico del lazo cerrado  $A_{cl}(z) = A_c(z)A_o(z)$ , donde  $n_{A_o} \le n_R$ . Eliga

$$T(z)=t_0A_o(z),$$

donde 
$$t_0 = \frac{A_c(1)}{B(1)}$$
.

Nos da el ley de control

$$R(q)u(k) = T(q)u_c(k) - S(q)y(k).$$

#### Determining the order of the controller

With Diophantine equation

$$A(z)R(z)z^d + B(z)S(z) = A_{cl}(z) \qquad (*)$$

and feedback controller

$$F_b(z) = \frac{S(z)}{R(z)} = \frac{s_0 z^n + s_1 z^{n-1} + \dots + s_n}{z^n + r_1 z^{n-1} + \dots + r_n}$$

How should we choose the order of the controller? Note:

- ▶ the controller has  $n + n + 1 = 2 \deg R + 1$  unknown parameters
- ▶ the LHS of (\*) has degree deg  $(A(z)R(z)z^d + B(z)S(z)) = \deg A + \deg R + d$
- ▶ The diophantine gives as many (nontrivial) equations as the degree of the polynomials on each side when we set the coefficients equal.
  - $\Rightarrow$  Choose deg R so that  $2 \deg R + 1 = \deg A + \deg R + d$



With the plant model

$$H(z) = \frac{B(z)}{A(z)} = \frac{b}{z+a}$$

and d = 0 (no delay), what is the appropriate degree of the controller

$$F_b(z) = \frac{S(z)}{R(z)} = \frac{s_0 z^n + s_1 z^{n-1} + \dots + s_n}{z^n + r_1 z^{n-1} + \dots + r_n}$$

$$A(z)R(z) + B(z)S(z) = A_c(z)A_o(z)?$$

1. 
$$n = 0$$
 2.  $n = 1$ 

3. 
$$n = 2$$
 4.  $n = 3$ 

With the plant model

$$H(z) = \frac{B(z)}{A(z)} = \frac{b}{z+a}$$

and d = 0 (no delay), what is the appropriate degree of the controller

$$F_b(z) = \frac{S(z)}{R(z)} = \frac{s_0 z^n + s_1 z^{n-1} + \dots + s_n}{z^n + r_1 z^{n-1} + \dots + r_n}$$

$$A(z)R(z) + B(z)S(z) = A_c(z)A_o(z)$$
?  
1.  $n = 0$  2.  
3. 4.

With the plant model

$$H(z) = \frac{B(z)}{A(z)} = \frac{b_0 z + b_1}{z^2 + a_1 z + a_2}$$

and d = 2, what is the appropriate degree of the controller

$$F_b(z) = \frac{S(z)}{R(z)} = \frac{s_0 z^n + s_1 z^{n-1} + \dots + s_n}{z^n + r_1 z^{n-1} + \dots + r_n}$$

$$A(z)R(z)z^2 + B(z)S(z) = A_c(z)A_o(z)?$$

1. 
$$n = 1$$
 2.  $n = 2$ 

3. 
$$n = 3$$
 4.  $n = 4$ 

With the plant model

$$H(z) = \frac{B(z)}{A(z)} = \frac{b_0 z + b_1}{z^2 + a_1 z + a_2}$$

and d = 2, what is the appropriate degree of the controller

$$F_b(z) = \frac{S(z)}{R(z)} = \frac{s_0 z^n + s_1 z^{n-1} + \dots + s_n}{z^n + r_1 z^{n-1} + \dots + r_n}$$

$$A(z)R(z)z^{2} + B(z)S(z) = A_{c}(z)A_{o}(z)$$
?

1. 2.
3.  $n = 3$  4.

With the plant model

$$H(z) = \frac{B(z)}{A(z)} = \frac{b_0 z + b_1}{z^2 + a_1 z + a_2}$$

and d=2 the appropriate degree of the controller is 3

$$F_b(z) = \frac{S(z)}{R(z)} = \frac{s_0 z^3 + s_1 z^2 + s_2 z + s_3}{z^3 + r_1 z^2 + r_2 z + r_3}.$$

What are the possible choices of the degree of the observer polynomial  $A_o(z)$  in

$$A(z)R(z)z^2 + B(z)S(z) = A_c(z)A_o(z)?$$

- 1. less than 2 2. less than 3
- 3. higher than 2 4. less than or equal to 3

With the plant model

$$H(z) = \frac{B(z)}{A(z)} = \frac{b_0 z + b_1}{z^2 + a_1 z + a_2}$$

and d=2 the appropriate degree of the controller is 3

$$F_b(z) = rac{S(z)}{R(z)} = rac{s_0 z^3 + s_1 z^2 + s_2 z + s_3}{z^3 + r_1 z^2 + r_2 z + r_3}.$$

What are the possible choices of the degree of the observer polynomial  $A_o(z)$  in

$$A(z)R(z)z^2 + B(z)S(z) = A_c(z)A_o(z)?$$

- 4. less than or equal to 3

# Where to place the closed-loop poles?

