

BCM Door Functionality Validation Report

Test Execution Summary

Total Test Cases : 14

Passed Test Cases : 9

Failed Test Cases : 3


Not Executes Test Cases: 2

Pass Percentage : 64.29%

Fail Percentage : 21.43%

Not_Executes_test_cases: 14.29%

Pass / Fail Pie Chart



Detailed Test Results

TC_ID	Description	Engine Status	Speed	Expected	Actual	Status	Remarks
TC01	Verify that all vehicle	OFF	0	Door Locked	Door Unlocked	Fail	Driver Door

	doors are locked successfully when the Lock button on the key fob is pressed						Open, Rear Left Door Open, Boot Door Open, Lock Failed
TC02	Verify that all vehicle doors are unlocked successfully when the Unlock button on the key fob is pressed	OFF	0	Door Unlocked	Door Unlocked	Pass	Driver Door Open, Unlock Successful
TC03	Verify that door unlock operation is allowed using the central unlocking switch when vehicle speed is below 10 km/h	ON	30	Door Locked	Door Locked	Pass	Vehicle Speed Above Limit
TC04	Verify that door unlock operation is blocked using the central unlocking switch when vehicle speed exceeds 10 km/h	ON	9	Door Unlocked	Door Unlocked	Pass	Unlock Allowed
TC05	Verify that central unlock request is	ON	60	Door Locked	Door Locked	Pass	Driver Door Open, Rear Left Door

	allowed or not at the vehicle speed of 60 km/h						Open, Vehicle Speed Above Limit
TC06	Verify that automatic door locking is activated when vehicle speed exceeds 20 km/h	ON	15	Door Locked	Door Unlocked	Fail	Speed Below Auto Lock Threshold
TC06	Verify that automatic door locking is activated when vehicle speed exceeds 20 km/h	ON	25	Door Locked	Not Executed	Not Executed	One or more mandatory fields are blank.
TC07	Verify that key fob lock request is rejected when the driver door is open	ON	15	Door Unlocked	Door Unlocked	Pass	Driver Door Open, Lock Failed
TC08	Verify that all vehicle doors are locked successfully using the central locking switch	OFF	0	Door Locked	Door Unlocked	Fail	Driver Door Open, Central Lock Failed
TC09	Verify that all vehicle doors are unlocked successfully using the central unlocking	OFF	0	Door Unlocked	Door Unlocked	Pass	Rear Right Door Open, Unlock Allowed

	switch						
TC10	Verify that lock request through the key fob is rejected when the boot door is open and the vehicle is parked	OFF	0	Door Unlocked	Door Unlocked	Pass	Boot Door Open, Lock Failed
TC11	Verify lock request when some fields are missing	OFF	0	Door Locked	Not Executed	Not Executed	One or more mandatory fields are blank.
TC12	Verify that all vehicle doors are locked successfully when the Lock button on the key fob is pressed	OFF	0	Door Locked	Door Locked	Pass	Lock Successful
TC13	Verify that all vehicle doors are unlocked successfully when the Unlock button on the key fob is pressed	OFF	0	Door Unlocked	Door Unlocked	Pass	Unlock Successful

Failed Test Cases

TC01 : Driver Door Open, Rear Left Door Open, Boot Door Open, Lock Failed

TC06 : Speed Below Auto Lock Threshold

TC08 : Driver Door Open, Central Lock Failed

Conclusion

A total of 14 test cases were executed.

9 test cases passed.

3 test cases failed.

2 test cases not executed.

Pass Percentage : 64.29%