Block=UART_Receiver Sheet=1 Page=1 For =17 For <16 Adder Count Error CLK16P Status Out SER_IN CIK Cata(0) Result