
Online Examination Report

Date:	28.07.2014
Attempts:	1
Examinee:	Kibuuka, Elvis
Date of birth:	11/16/1989
Subject:	070-Operational procedures
Result:	0 %
Time used:	00:00:18 (HH:MM:SS)

Attachments

1. List of result by question
2. List of result by topic
3. Detailed question result report

Attachment 1: List of result by question

CQB Number	Internal Number	Syllabus reference	Chapter	Points	Max. Points
1	190	71. OPERATIONAL PROCEDURES		0,00	1,00
2	179	71. OPERATIONAL PROCEDURES		0,00	1,00
3	118	71.1.1.3	General	0,00	1,00
4	69	71.1.2.5	Civil Aviation Regulations	0,00	1,00
5	24	71.1.2.6	Civil Aviation Regulations	0,00	1,00
6	76	71.1.2.6	Civil Aviation Regulations	0,00	1,00
7	22	71.1.2.6	Civil Aviation Regulations	0,00	1,00
8	29	71.1.3.3	MNPS Airspace	0,00	1,00
9	82	71.1.3.3	MNPS Airspace	0,00	1,00
10	21	71.2.1	Operations Manual	0,00	1,00
11	160	71.2.1.1	Operating procedures	0,00	1,00
12	107	71.2.1.1	Operating procedures	0,00	1,00
13	138	71.2.1.1	Operating procedures	0,00	1,00
14	109	71.2.1.1	Operating procedures	0,00	1,00
15	110	71.2.1.1	Operating procedures	0,00	1,00
16	28	71.2.1.1	Operating procedures	0,00	1,00
17	3	71.2.2	Icing conditions	0,00	1,00
18	114	71.2.2.1	On ground de-/anti-icing	0,00	1,00
19	140	71.2.2.1	On ground de-/anti-icing	0,00	1,00
20	124	71.2.2.1	On ground de-/anti-icing	0,00	1,00
21	144	71.2.4.2	Influence of the flight procedure	0,00	1,00
22	117	71.2.5.3	Fire in the cabin, cockpit, cargo comp	0,00	1,00
23	141	71.2.5.6	Types of extinguishers	0,00	1,00
24	134	71.2.5.6	Types of extinguishers	0,00	1,00
25	16	71.2.5.6	Types of extinguishers	0,00	1,00
26	98	71.2.5.6	Types of extinguishers	0,00	1,00
27	131	71.2.5.6	Types of extinguishers	0,00	1,00
28	11	71.2.7	Wind shear and microburst	0,00	1,00

CQB Number	Internal Number	Syllabus reference	Chapter	Points	Max. Points
29	162	71.2.8	Wake turbulence	0,00	1,00
30	38	71.2.8.2	List of relevant parameters	0,00	1,00
31	79	71.2.9	Security (unlawful events)	0,00	1,00
32	108	71.2.9	Security (unlawful events)	0,00	1,00
33	17	71.2.9.1	ICAO Annex 17	0,00	1,00
34	58	71.2.9.4	Bomb on board	0,00	1,00
35	159	71.2.9.4	Bomb on board	0,00	1,00
36	8	71.2.12	Transport of dangerous goods	0,00	1,00
37	164	71.2.12	Transport of dangerous goods	0,00	1,00
38	142	71.2.13	Contaminated runways	0,00	1,00
39	70	71.2.13	Contaminated runways	0,00	1,00
40	154	71.2.13	Contaminated runways	0,00	1,00
Total:0%				0,00	40,00

Attachment 2: List of result by topic

Licence

Date: 28.07.2014

Examinee: Kibuuka, Elvis

Location: Uganda Civil Aviation Authority

Your Result: 0,00 from 40,00 Points (0,00 %)

Topics	Ammount of Questions	Points achieved	Maximum Points	Percent
71. OPERATIONAL PROCEDURES	40	0,00	40,00	0,00
71.1. GENERAL REQUIREMENTS	7	0,00	7,00	0,00
71.2. SPECIAL OPERATIONAL PROCEDURES	31	0,00	31,00	0,00
Total	40	0,00	40,00	0,00

1

What effect would a light crosswind of approximately 7 knots have on vortex behavior?

- ☐ The downwind vortex would tend to remain over the runway.
- ☒ The upwind vortex would tend to remain over the runway.
- ☐ The light crosswind would rapidly dissipate vortex strength.

2

What aural and visual indications should be observed over an ILS middle marker?

- ☐ Continuous dots at the rate of six per second.
- ☒ Alternate dots and dashes at the rate of two per second.
- ☐ Continuous dashes at the rate of two per second.

3

90 % of bird strikes occur :

- ☐ above 1 000 m
- ☐ between 500 and 1 000 m
- ☒ under 500 m
- ☐ between 500 and 1 500 m

4

In accordance to the EAC states' Civil aviation regulations (Aerodrome Operating Minima), for a Category III B approach, the RVR shall not be less than:

☐ 150 m

☐ 50 m

☐ 100 m

☒ 75 m

5

In accordance with civil aviation regulations, for aeroplanes intended to be operated at pressure altitude of 39000 ft, the total number of oxygen dispensing units and outlets shall exceed:

- ☐ the number of passengers.
- ☐ the number of seats.
- ☒ the number of seats by at least 10%.
- ☐ the number of passengers by at least 10%.

6

According to civil aviation regulations, an aeroplane whose maximum approved passenger seating configuration is 10 seats must be equipped with:

- ☐ one hand fire-extinguisher on the flight deck and two hand fire-extinguishers in the passenger compartment.
- ☐ two hand fire-extinguishers on the flight deck and two hand fire-extinguishers in the passenger compartment.
- ☐ three hand fire-extinguishers in the passenger compartment.
- ☒ one hand fire-extinguisher on the flight deck and one hand fire-extinguisher in the passenger compartment.

7

In accordance with civil aviation regulations, an aeroplane whose maximum approved passenger seating configuration is greater than 600 seats must be equipped with at least:

- ☐ 9 hand fire-extinguishers conveniently located in the passenger compartment.
- ☐ 6 hand fire-extinguishers conveniently located in the passenger compartment.
- ☒ 8 hand fire-extinguishers conveniently located in the passenger compartment.
- ☐ 7 hand fire-extinguishers conveniently located in the passenger compartment.

Candidate: Elvis Kibuuka
Date of birth: 1989-11-16

Subject: 070-Operational procedures
Date: 2014-07-28



8

In airspace where MNPS is applicable, the minimum vertical separation between FL 290 and FL 410 is:

- ☐ 500 ft
- ☐ 1 500 ft
- ☒ 1 000 ft
- ☐ 2000ft

9

An aircraft operating within MNPS Airspace is unable to continue flight in accordance with its air traffic control clearance, but is able to maintain its assigned level, and due to a total loss of communications capability, cannot obtain a revised clearance from ATC. The aircraft should offset from the assigned route by 15 NM and climb or descent 500 ft, if:

☐ at FL410

☐ at FL430

☐ above FL410

☒ below FL410

10

You are the captain of a commercial airplane and you notice, after take-off, a flock of birds which may present a bird strike hazard, you must:

- ☐ draft a bird strike hazard report upon arrival and within at most 48 hours.
- ☒ immediately inform the appropriate ground station.
- ☐ inform the appropriate ground station within a reasonable period of time.
- ☐ inform the other aircraft by radio.

11

During an explosive decompression at flight level 370 (FL 370), your first action will be :

- ☒ to put on the oxygen mask
- ☐ to comfort your passengers
- ☐ to warn the ATC
- ☐ to set the transponder to 7700

12

For aircraft certified , cockpit voice recorder must keep the conversations and sound alarms recorded during the last :

- ☐ 25 hours of operation.
- ☐ 48 hours of operation.
- ☐ flight.
- ☒ 30 minutes of operation.

13

On overwater flights, an operator shall not operate an aeroplane at a distance away from land, which is suitable for making an emergency landing greater than that corresponding to :

- ☒ 400 NM or 120 minutes at cruising speed.
- ☐ 200 NM or 45 minutes at cruising speed.
- ☐ 100 NM or 30 minutes at cruising speed.
- ☐ 300 NM or 90 minutes at cruising speed.

14

After a landing, with overweight and overspeed conditions, the tyres and brakes are extremely hot. The fireguards should approach the landing gear tyres:

- ☐ under no circumstances.
- ☐ from any side.
- ☐ only from left or right side.
- ☒ only from front or rear side.

15

Following an emergency landing which will need an evacuation from the aircraft?

- 1 - remain on the runway,*
- 2 - clear the runway using the first available taxiway,*
- 3 - keep one engine or the APU running in order to maintain the electrical power supply on,*
- 4 - turn off all systems.*

☐ 2,4.

☐ 1,3.

☐ 2,3.

☒ 1,4.

16

An aircraft is flying in heavy rain. To carry out a safe approach, it is necessary to :

- ☐ carry out an approach with flaps up, in order to avoid exposing too much lifting surface to the rain
- ☐ reduce the approach speed, because the runway may be very slippery on landing
- ☐ maintain the normal approach speed up to landing
- ☒ increase its approach speed, because the rain affects the lift by deteriorating the boundary layer

17

The maximum validity of a SNOWTAM is :

☐ 12 hours

☒ 24 hours

☐ 3 hours

☐ 6 hours

18

The anti-icing fluid protecting film can wear off and reduce considerably the protection time:

- ☐ when the outside temperature is close to 0 °C.
- ☐ when the airplane is into the wind.
- ☐ when the temperature of the airplane skin is close to 0 °C.
- ☒ during strong winds or as a result of the other aircraft engines jet wash.

19

An aircraft having undergone an anti-icing procedure and having exceeded the protection time of the anti-icing fluid:

- ☐ must only undergo a de-icing procedure for take-off.
- ☐ need not to undergo a new anti-icing procedure for take-off.
- ☐ must only undergo a new anti-icing procedure for take-off.
- ☒ must undergo a de-icing procedure before a new application of anti-icing fluid for take-off.

20

If after anti-icing has been completed a pre-departure inspection reveals evidence of freezing, the correct action is to :

- ☐ complete departure as soon as possible to reduce the possibility of further freezing
- ☐ complete departure provided that the recommended anti-icing holdover (protection) time for the prevailing conditons and type of fluid used has not been exceeded
- ☒ carry out a further de-icing process
- ☐ switch on all the aeroplane anti-icing and de-icing systems and leave on until clear of icing conditions when airborne

21

As regards the detection of bird strike hazard, the pilot's means of information and prevention are:

1 - ATIS.

2 - NOTAMs.

3- BIRDTAMs.

4 - Weather radar.,

☐ 1,2,3,4,5

☐ 2,5

☒ 1,2,5

☐ 1,3,4

22

To extinguish a fire in the cockpit, you use:

- 1. a water fire-extinguisher*
- 2. a powder or chemical fire-extinguisher*
- 3. a halon fire-extinguisher*
- 4. a CO2 fire-extinguisher*

☐ 1, 2, 3, 4

☐ 2, 3, 4

☒ 3, 4

☐ 1, 2

23

A fire occurs in a wheel and immediate action is required to extinguish it. The safest extinguishant to use is :

- ☐ water
- ☐ foam
- ☒ dry powder
- ☐ CO2 (carbon dioxide)

24

The fire extinguisher types which may be used on class B fires are:

*1 - H₂O,
2 - CO₂,
3 - dry-chemical,
4 - halogen*

☐ 3 - 4

☐ 2

☐ 1 - 2 - 3 - 4,

☒ 2 - 3 - 4

25

You will use a CO2 fire-extinguisher for :

- 1. a paper fire*
- 2. a plastic fire*
- 3. a hydrocarbon fire*
- 4. an electrical fire*

The combination regrouping all the correct statements is:

☐ 3,4

☐ 2,3

☒ 1,2,3,4

☐ 1,2,3

26

A CO2 fire extinguisher can be used for:

- 1. a paper fire*
- 2. a hydrocarbon fire*
- 3. a fabric fire*
- 4. an electrical fire*
- 5. a wood fire*

The combination regrouping all the correct statements

☐ 2, 3, 4

☒ 1, 2, 3, 4, 5

☐ 2, 4, 5

☐ 1, 3, 5

27

You will use a halon extinguisher for a fire of:

1 - solids (fabric, plastic, ...)

2 - liquids (alcohol, gasoline, ...)

3 - gas

4 - metals (aluminium, magnesium, ...)

The combination regrouping all the correct statements

☒ 1,2,3

☐ 1,2,3,4

☐ 1,2,4

☐ 2,3,4

28

One of the main characteristics of windshear is that it :

- ☐ can occur at any altitude and only in the horizontal plane
- ☐ occurs only at a low altitude (2000 ft) and never in the vertical plane
- ☒ can occur at any altitude in both the vertical and horizontal planes
- ☐ occurs only at a low altitude (2000 ft) and never in the horizontal plane

29

The greatest wake turbulence occurs when the generating aircraft is :

- ☐ Small, light, at maximum speed in full flaps configuration
- ☐ Small, light, at low speed in clean configuration
- ☐ Large, heavy, at maximum speed in full flaps configuration
- ☒ Large, heavy, at low speed in clean configuration

30

The greatest wake turbulence occurs when the generating aircraft is:

- ☐ Large, heavy, at maximum speed in full flaps configuration
- ☐ Small, light, at maximum speed in full flaps configuration
- ☐ Small, light, at low speed in clean configuration
- ☒ Large, heavy, at low speed in clean configuration

31

What transponder code should be used to provide recognition of an aircraft which is being subjected to unlawful interference :

☐ code 7600

☐ code 7700

☒ code 7500

☐ code 2000

32

The flight deck door should be capable of being :

- ☐ remotely locked by cabin crew operation from outside the compartment
- ☒ locked from within the compartment
- ☐ directly locked from outside the compartment
- ☐ remotely locked from either inside or outside the compartment

33

According to ICAO Annex 17, following an unlawful interference, who shall take adequate measures for the safety of passengers and crew of an aircraft, until their journey can be continued?

- ☒ The contracting State where the aircraft is located.
- ☐ The commander of the aircraft.
- ☐ The aircraft's operator.
- ☐ The responsible Civil Aviation Authority

34

In case of a serious threat based on the presence of a bomb on board a pressurized aircraft and disregarding any fuel considerations:

- ☐ you carry out an emergency descent to reach the safety altitude.
- ☐ you go down to the level corresponding to the indicated cabin altitude and keep the aircraft in a clean configuration until the final approach.
- ☐ you climb to the maximum flight level which does not need the use of pressurization.
- ☒ you descend to the flight level corresponding to the indicated cabin altitude or the safety altitude if higher and take preventive steps by putting yourself in a landing approach configuration.

35

In case of a serious threat based on the presence of a bomb on board a pressurized aircraft and disregarding any fuel considerations:

- ☐ you carry out an emergency descent to reach the safety altitude.
- ☐ you climb to the maximum flight level which does not need the use of pressurization.
- ☒ you descend to the flight level corresponding to the indicated cabin altitude or the safety altitude if higher and take preventive steps by putting yourself in a landing approach configuration.
- ☐ you go down to the level corresponding to the indicated cabin altitude and keep the airplane in a clean configuration until the final approach.

36

In the hazardous materials transportation act, the freight compliance with the regulatory arrangements is the responsibility of the :

☐ aerodrome manager.

☐ captain.

☒ sender.

☐ station manager.

37

In compliance with the civil aviation regulations in order to carry dangerous goods on board a public transport airplane, they must be accompanied with a :

- ☐ representative of the company owning the materials.
- ☐ system to warn the crew in case of a leak or of an abnormal
- ☒ transport document for dangerous goods.
- ☐ specialized handling employee.

38

For an airplane with a tyre pressure of 12 bars, there is a risk of dynamic hydroplaning as soon as the :

1- water height is equal to the depth of the tyre grooves.

2- speed is greater than 114 kt.

3- water height is equal to the half of the depth of the tyre grooves.

4- speed is greater than 83 kt.

The combination regrouping all the correct statements is :

☒ 1 and 2.

☐ 1 and 4.

☐ 3 and 4.

☐ 2 and 3.

39

A braking action of 0.25 and below reported on a SNOWTAM is :

☐ good

☐ medium

☐ unreliable

☒ poor

40

According to the civil aviation regulations a runway is considered damp when:

- ☐ it is covered with a film of water of less than 3 mm.
- ☒ its surface is not dry, and when surface moisture does not give it a shiny appearance.
- ☐ surface moisture gives it a shiny appearance.
- ☐ it is covered with a film of water of less than 1 mm.