

Online Examination Report

Date:	28.07.2014
Attempts:	1
Examinee:	Mbuya 2, Denis
Date of birth:	11/10/1986
Subject:	070-Operational procedures
Result:	0 %
Time used:	00:00:15 (HH:MM:SS)

Attachments

1. List of result by question
2. List of result by topic
3. Detailed question result report

Attachment 1: List of result by question

CQB Number	Internal Number	Syllabus reference	Chapter	Points	Max. Points
1	180	71. OPERATIONAL PROCEDURES		0,00	1,00
2	185	71. OPERATIONAL PROCEDURES		0,00	1,00
3	186	71. OPERATIONAL PROCEDURES		0,00	1,00
4	179	71. OPERATIONAL PROCEDURES		0,00	1,00
5	174	71. OPERATIONAL PROCEDURES		0,00	1,00
6	191	71. OPERATIONAL PROCEDURES		0,00	1,00
7	25	71.1.1 ICAO Annex 6		0,00	1,00
8	59	71.1.1.1 Definitions		0,00	1,00
9	173	71.1.2 Civil Aviation Regulations		0,00	1,00
10	31	71.1.2.3 Civil Aviation Regulations		0,00	1,00
11	69	71.1.2.5 Civil Aviation Regulations		0,00	1,00
12	73	71.1.2.6 Civil Aviation Regulations		0,00	1,00
13	76	71.1.2.6 Civil Aviation Regulations		0,00	1,00
14	77	71.1.3 Long-range flights		0,00	1,00
15	82	71.1.3.3 MNPS Airspace		0,00	1,00
16	40	71.1.3.3 MNPS Airspace		0,00	1,00
17	53	71.1.3.3 MNPS Airspace		0,00	1,00
18	42	71.2.1 Operations Manual		0,00	1,00
19	126	71.2.1 Operations Manual		0,00	1,00
20	34	71.2.1.1 Operating procedures		0,00	1,00
21	125	71.2.1.1 Operating procedures		0,00	1,00
22	3	71.2.2 Icing conditions		0,00	1,00
23	114	71.2.2.1 On ground de-/anti-icing		0,00	1,00
24	16	71.2.5.6 Types of extinguishers		0,00	1,00
25	131	71.2.5.6 Types of extinguishers		0,00	1,00
26	134	71.2.5.6 Types of extinguishers		0,00	1,00
27	87	71.2.5.6 Types of extinguishers		0,00	1,00
28	11	71.2.7 Wind shear and microburst		0,00	1,00

CQB Number	Internal Number	Syllabus reference	Chapter	Points	Max. Points
29	78	71.2.7.1	Effects and recognition	0,00	1,00
30	166	71.2.8	Wake turbulence	0,00	1,00
31	12	71.2.8.1	Cause	0,00	1,00
32	108	71.2.9	Security (unlawful events)	0,00	1,00
33	55	71.2.9.2	Use of SSR	0,00	1,00
34	33	71.2.11.2	Requirements	0,00	1,00
35	164	71.2.12	Transport of dangerous goods	0,00	1,00
36	165	71.2.12	Transport of dangerous goods	0,00	1,00
37	146	71.2.12	Transport of dangerous goods	0,00	1,00
38	54	71.2.12.1	ICAO Annex 18	0,00	1,00
39	18	71.2.13.1	Kinds of contamination	0,00	1,00
40	65	71.2.13.4	Procedures	0,00	1,00
Total:0%				0,00	40,00

Attachment 2: List of result by topic

Licence

Date: 28.07.2014

Examinee: Mbuya 2, Denis

Location: Uganda Civil Aviation Authority

Your Result: 0,00 from 40,00 Points (0,00 %)

Topics	Ammount of Questions	Points achieved	Maximum Points	Percent
71. OPERATIONAL PROCEDURES	40	0,00	40,00	0,00
71.1. GENERAL REQUIREMENTS	11	0,00	11,00	0,00
71.2. SPECIAL OPERATIONAL PROCEDURES	23	0,00	23,00	0,00
Total	40	0,00	40,00	0,00

1

What aural and visual indications should be observed over an ILS outer marker?

- ☐ Continuous dots at the rate of six per second.
- ☐ Alternate dots and dashes at the rate of two per second.
- ☒ Continuous dashes at the rate of two per second.

2

How does the wake turbulence vortex circulate around each wingtip?

- ☐ Inward, upward, and around each tip.
- ☒ Outward, upward, and around each tip.
- ☐ Inward, upward, and counterclockwise.

3

Which is a necessary condition for the occurrence of a low-level temperature inversion wind shear?

- ☐ A wind direction difference of at least 30 degrees C between the wind near the surface and the wind just above the inversion.
- ☒ A calm or light wind near the surface and a relatively strong wind just above the inversion.
- ☐ The temperature differential between the cold and warm layers must be at least 10 degrees C.

4

What aural and visual indications should be observed over an ILS middle marker?

- ☐ Continuous dashes at the rate of two per second.
- ☒ Alternate dots and dashes at the rate of two per second.
- ☐ Continuous dots at the rate of six per second.

5

Which incident would require that the nearest Flight Control Center field office be notified immediately?

- ☐ Ground fire resulting in fire equipment dispatch.
- ☐ Fire of the primary aircraft while in a hangar which results in damage to other property of more than \$25,000.
- ☒ In-flight fire.

6

When landing behind a large jet aircraft, at which point on the runway should you plan to land?

- ☒ **Beyond the jet's touchdown point.**
- ☐ **At least 1,000 feet beyond the jet's touchdown point.**
- ☐ **If any crosswind, land on the windward side of the runway and prior to the jet's touchdown point.**

7

The master minimum equipment list (M MEL) is established by:

- ☐ the operator of the aircraft, and accepted by the authority
- ☐ the manufacturer of the aircraft, but need not to be accepted by the authority
- ☒ the manufacturer of the aircraft, and accepted by the authority
- ☐ the operator of the aircraft, and accepted by the manufacturer

8

According to Annex 6, 'RNP type' is defined as a containment value expressed as a distance in ... (i) ... from the intended position within which flights would be for at least ... (ii) ... of the total flying time.

- ☐ (i) kilometers
(ii) 90%
- ☒ (i) nautical miles
(ii) 95%
- ☐ (i) kilometers
(ii) 95%
- ☐ (i) nautical miles
(ii) 90%

9

An airplane operated by a commercial operator flying over uninhabited terrain must carry which emergency equipment?

- ☐ Survival kit for each passenger.
- ☐ A signal mirror and colored smoke flares.
- ☒ An approved survival-type emergency locator transmitter.

10

According to Annex 6, what is the definition of an Air Operator Certificate?

- ☐ A certificate needed to carry out specified commercial international air transport operations, but not for domestic commercial flights.
- ☐ A certificate automatically authorising an operator to carry out domestic air services in any ICAO contracting State.
- ☐ A certificate the crew will present to immigration officers, stating that all passengers on board fulfil the visa requirements needed.
- ☒ A certificate authorising an operator to carry out specified commercial air transport operations.

11

In accordance to the EAC states' Civil aviation regulations (Aerodrome Operating Minima), for a Category III B approach, the RVR shall not be less than:

☒ 75 m

☐ 100 m

☐ 50 m

☐ 150 m

12

In accordance with the civil aviation regulations, a single deck aeroplane, equipped with an approved seating capacity of 61 seats and carrying passengers, must be equipped with at least:

☐ 2 megaphones if there are more than 31 passengers on board.

☐ 2 megaphones.

☒ 1 megaphone.

☐ 3 megaphones.

13

According to civil aviation regulations, an aeroplane whose maximum approved passenger seating configuration is 10 seats must be equipped with:

- ☒ one hand fire-extinguisher on the flight deck and one hand fire-extinguisher in the passenger compartment.
- ☐ three hand fire-extinguishers in the passenger compartment.
- ☐ two hand fire-extinguishers on the flight deck and two hand fire-extinguishers in the passenger compartment.
- ☐ one hand fire-extinguisher on the flight deck and two hand fire-extinguishers in the passenger compartment.

14

A jet-powered aircraft, flying above the optimum altitude will have :

- ☒ reduced range
- ☐ increased flight envelope
- ☐ increased Mach number stability
- ☐ increased manoeuvring limits

15

An aircraft operating within MNPS Airspace is unable to continue flight in accordance with its air traffic control clearance, but is able to maintain its assigned level, and due to a total loss of communications capability, cannot obtain a revised clearance from ATC. The aircraft should offset from the assigned route by 15 NM and climb or descent 500 ft, if:

☒ below FL410

☐ above FL410

☐ at FL430

☐ at FL410

16

Air traffic services may require an aircraft to report position when flying east-west, south of 70°N between 5°W and 65°W, every:

☐ 5° of longitude.

☐ 15° of longitude.

☒ 10° of longitude.

☐ 20° of longitude.

17

In Minimum Navigation Performance Specification (MNPS) airspace, the speed reference for turbo-jet aircraft is the:

☐ indicated airspeed.

☒ Mach number.

☐ true airspeed.

☐ ground speed.

18

During a flight, the chief steward informs the crew that a passenger is using a portable device suspected to disturb the aircraft electronic systems. The captain:

- ☐ authorizes its use during the whole flight phase.
- ☐ may authorize the use of this device, as an exception.
- ☐ authorizes its use except during take-off and landing phases.
- ☒ must not authorize any person to use such a device on board.

19

The Master Minimum Equipment List (MMEL) defines the equipment on which certain in-flight failures can be allowed and the conditions under which this allowance can be accepted. This MMEL is drawn up by :

- ☐ the operator from a main list drawn up by the manufacturer
- ☐ the operator and is specified in the operation manual
- ☐ the operator and approved by the certification authority
- ☒ the manufacturer and approved by the certification authority

20

Flight crew members on the flight deck shall keep their safety belt fastened:

- ☐ from take off to landing.
- ☒ only during take off and landing.
- ☐ only during take off and landing and whenever necessary by the commander in the interest of safety.
- ☐ while at their station.

21

For the flight crew members, quickly-fitted oxygen masks are compulsory on board any pressurized aircraft flying at a pressure altitude greater than :

☐ 29 000 ft

☐ 13 000 ft

☒ 25 000 ft

☐ 10 000 ft

22

The maximum validity of a SNOWTAM is :

☒ 24 hours

☐ 6 hours

☐ 3 hours

☐ 12 hours

23

The anti-icing fluid protecting film can wear off and reduce considerably the protection time:

- ☒ during strong winds or as a result of the other aircraft engines jet wash.
- ☐ when the temperature of the airplane skin is close to 0 °C.
- ☐ when the airplane is into the wind.
- ☐ when the outside temperature is close to 0 °C.

24

You will use a CO2 fire-extinguisher for :

- 1. a paper fire*
- 2. a plastic fire*
- 3. a hydrocarbon fire*
- 4. an electrical fire*

The combination regrouping all the correct statements is:

☐ 2,3

☐ 1,2,3

☐ 3,4

☒ 1,2,3,4

25

You will use a halon extinguisher for a fire of:

1 - solids (fabric, plastic, ...)

2 - liquids (alcohol, gasoline, ...)

3 - gas

4 - metals (aluminium, magnesium, ...)

The combination regrouping all the correct statements

☐ 2,3,4

☒ 1,2,3

☐ 1,2,4

☐ 1,2,3,4

26

The fire extinguisher types which may be used on class B fires are:

- 1 - H₂O,*
- 2 - CO₂,*
- 3 - dry-chemical,*
- 4 - halogen*

☐ 2

☒ 2 - 3 - 4

☐ 1 - 2 - 3 - 4,

☐ 3 - 4

27

CO2 type extinguishers are fit to fight:

1 - class A fires

2 - class B fires

3 - electrical source fires

4 - special fires: metals, gas, chemical product

Which of the following combinations contains all the correct statements:

☒ **1 - 2 - 3**

☐ **1 - 3 - 4**

☐ **2 - 3 - 4**

☐ **1 - 2 - 4**

28

One of the main characteristics of windshear is that it :

- ☐ occurs only at a low altitude (2000 ft) and never in the horizontal plane
- ☒ can occur at any altitude in both the vertical and horizontal planes
- ☐ occurs only at a low altitude (2000 ft) and never in the vertical plane
- ☐ can occur at any altitude and only in the horizontal plane

29

During a manual approach, the aeroplane is subjected to windshear with an increasing tail wind. In the absence of a pilot action, the aeroplane:

- 1- flies above the intended approach path
- 2- flies below the intended approach path
- 3- has an increasing true airspeed
- 4- has a decreasing true airspeed

The combination of correct statements is:

☐ 2, 3.

☐ 1, 4.

☐ 1, 3.

☒ 2, 4.

30

When taking-off after a widebody aircraft which has just landed, you should take-off :

- ☒ beyond the point where the aircraft's wheels have touched down.
- ☐ in front of the point where the aircraft's wheels have touched down.
- ☐ at the point where the aircraft's wheels have touched the ground and on the underwind side of the runway .
- ☐ at the point where the aircraft's wheels have touched down and on the wind side of the runway .

31

The wake turbulence caused by an aircraft is mainly the result of:

1. An aerodynamic effect (wing tip vortices).
2. The engines action (propellers rotation or engine gas exhausts).
3. The importance of the drag devices (size of the landing gear, of the flaps, etc.).

The combination regrouping all the correct statements is:

☐ 3.

☐ 1, 2 and 3.

☐ 2 and 3.

☒ 1.

32

The flight deck door should be capable of being :

- ☒ locked from within the compartment
- ☐ directly locked from outside the compartment
- ☐ remotely locked from either inside or outside the compartment
- ☐ remotely locked by cabin crew operation from outside the compartment

33

What is the transponder code to be used by the commander of an aircraft that is subject to unlawful interference?

☐ A 7700

☐ A 7600

☒ A 7500

☐ A 7800

34

According to Civil aviation authority, if a fuel jettisoning system is required, it must be capable of jettisoning enough fuel within:

☐ 60 minutes

☒ 15 minutes

☐ 45 minutes

☐ 30 minutes

35

In compliance with the civil aviation regulations in order to carry dangerous goods on board a public transport airplane, they must be accompanied with a :

- ☐ system to warn the crew in case of a leak or of an abnormal
- ☐ specialized handling employee.
- ☐ representative of the company owning the materials.
- ☒ transport document for dangerous goods.

36

Who makes sure that the air transportation of an item of dangerous goods is not prohibited?

- ☐ The operator.
- ☒ The shipper when completing the shipper's declaration for dangerous goods.
- ☐ The captain, always using the list of prohibited aircraft items.
- ☐ It is not specified.

37

The dangerous goods transport document, if required, shall be drawn up by :

- ☒ the shipper.
- ☐ the captain.
- ☐ the handling agent.
- ☐ the operator.

38

The content of the dangerous goods transport document is specified in the:

- ☐ OPS documentation.
- ☒ Technical Instructions.
- ☐ Flight Manual.
- ☐ Air Transport Permit.

39

In the civil aviation regulation, a runway is considered wet when:

1. it is covered with a quantity of water or loose or slushy snow less than or equal to the equivalent of 3 mm of water.
2. the amount of surface moisture is sufficient to modify its colour but does not give it a shiny appearance.
3. the amount of surface moisture is sufficient to make it reflective, but does not create large stagnant sheets of water.
4. it bears stagnant sheets of water.

The combination regrouping all the correct statements is:

☐ 1, 2, 3

☐ 4

☒ 1, 3

☐ 1, 2

40

For an airplane with a tyre pressure of 14 bars, there is a risk of dynamic hydroplaning as soon as the :

1- water height is equal to the depth of the tyre grooves.

2- speed is greater than 123 kt.

3- water height is equal to the half of the depth of the tyre grooves.

4- speed is greater than 95 kt. The combination regrouping all the correct statements is:

☒ 1 and 2.

☐ 3 and 4.

☐ 2 and 3.

☐ 1 and 4.