

Online Examination Report

Date:	23.07.2014
Attempts:	1
Examinee:	Menya Komyhendo, Ruth
Date of birth:	11/28/1988
Subject:	070-Operational procedures
Result:	34,99 %
Time used:	00:19:58 (HH:MM:SS)

Attachments

1. List of result by question
2. List of result by topic
3. Detailed question result report

Attachment 1: List of result by question

CQB Number	Internal Number	Syllabus reference	Chapter	Points	Max. Points
1	175	71. OPERATIONAL PROCEDURES		0,00	1,00
2	190	71. OPERATIONAL PROCEDURES		1,00	1,00
3	200	71. OPERATIONAL PROCEDURES		1,00	1,00
4	180	71. OPERATIONAL PROCEDURES		0,00	1,00
5	179	71. OPERATIONAL PROCEDURES		0,00	1,00
6	174	71. OPERATIONAL PROCEDURES		0,00	1,00
7	118	71.1.1.3 General		0,00	1,00
8	99	71.1.2 Civil Aviation Regulations		1,00	1,00
9	69	71.1.2.5 Civil Aviation Regulations		0,00	1,00
10	24	71.1.2.6 Civil Aviation Regulations		1,00	1,00
11	76	71.1.2.6 Civil Aviation Regulations		0,00	1,00
12	10	71.1.3.3 MNPS Airspace		0,00	1,00
13	82	71.1.3.3 MNPS Airspace		1,00	1,00
14	172	71.2 SPECIAL OPERATIONAL PROCEDURES		0,00	1,00
15	42	71.2.1 Operations Manual		1,00	1,00
16	100	71.2.1 Operations Manual		1,00	1,00
17	123	71.2.1.1 Operating procedures		1,00	1,00
18	138	71.2.1.1 Operating procedures		0,00	1,00
19	148	71.2.2 Icing conditions		0,00	1,00
20	3	71.2.2 Icing conditions		0,00	1,00
21	140	71.2.2.1 On ground de-/anti-icing		0,00	1,00
22	163	71.2.2.1 On ground de-/anti-icing		0,00	1,00
23	124	71.2.2.1 On ground de-/anti-icing		0,00	1,00
24	144	71.2.4.2 Influence of the flight procedure		0,00	1,00
25	119	71.2.5 Fire/smoke		0,00	1,00
26	102	71.2.5.3 Fire in the cabin, cockpit, cargo comp		0,00	1,00
27	50	71.2.5.3 Fire in the cabin, cockpit, cargo comp		1,00	1,00
28	131	71.2.5.6 Types of extinguishers		1,00	1,00

CQB Number	Internal Number	Syllabus reference	Chapter	Points	Max. Points
29	98	71.2.5.6	Types of extinguishers	1,00	1,00
30	134	71.2.5.6	Types of extinguishers	0,00	1,00
31	78	71.2.7.1	Effects and recognition	0,00	1,00
32	15	71.2.8.1	Cause	0,00	1,00
33	12	71.2.8.1	Cause	0,00	1,00
34	38	71.2.8.2	List of relevant parameters	0,00	1,00
35	159	71.2.9.4	Bomb on board	1,00	1,00
36	58	71.2.9.4	Bomb on board	1,00	1,00
37	54	71.2.12.1	ICAO Annex 18	0,00	1,00
38	142	71.2.13	Contaminated runways	1,00	1,00
39	154	71.2.13	Contaminated runways	0,00	1,00
40	65	71.2.13.4	Procedures	0,00	1,00
Total:35%				14,00	40,00

Attachment 2: List of result by topic

Licence

Date: 23.07.2014

Examinee: Menya Komyhendo, Ruth

Location: Uganda Civil Aviation Authority

Your Result: 14,00 from 40,00 Points (35,00 %)

Topics	Ammount of Questions	Points achieved	Maximum Points	Percent
71. OPERATIONAL PROCEDURES	40	14,00	40,00	35,00
71.1. GENERAL REQUIREMENTS	7	3,00	7,00	42,86
71.2. SPECIAL OPERATIONAL PROCEDURES	27	9,00	27,00	33,33
Total	40	14,00	40,00	35,00

Candidate: Ruth Menya Komyhendo
Date of birth: 1988-11-28

Subject: 070-Operational procedures
Date: 2014-07-23



1

(Refer to Figure 126.) Which altitude (box 1) is applicable to the vertical extent of the inner and outer circles (now called surface and shelf areas)?

☐ 3,000 feet above airport.

☐ 4,000 feet above airport.

☒ 3,000 feet AGL.

See Attachments:

1. atp_126.jpg

Figure 126

(Attachment
No.1)

2

What effect would a light crosswind of approximately 7 knots have on vortex behavior?

- ☒ The upwind vortex would tend to remain over the runway.
- ☐ The downwind vortex would tend to remain over the runway.
- ☐ The light crosswind would rapidly dissipate vortex strength.

3

If during a VFR practice instrument approach, Radar Approach Control assigns an altitude or heading that will cause you to enter the clouds, what action should be taken?

- ☒ **Avoid the clouds and inform ATC that altitude/heading will not permit VFR.**
- ☐ **Enter the clouds, since ATC authorization for practice approaches is considered an IFR clearance.**
- ☐ **Abandon the approach.**

4

What aural and visual indications should be observed over an ILS outer marker?

- ☐ Continuous dashes at the rate of two per second.
- ☐ Alternate dots and dashes at the rate of two per second.
- ☒ Continuous dots at the rate of six per second.

5

What aural and visual indications should be observed over an ILS middle marker?

- ☒ Continuous dashes at the rate of two per second.
- ☐ Continuous dots at the rate of six per second.
- ☐ Alternate dots and dashes at the rate of two per second.

6

Which incident would require that the nearest Flight Control Center field office be notified immediately?

☒ **Ground fire resulting in fire equipment dispatch.**

☐ **In-flight fire.**

☐ **Fire of the primary aircraft while in a hangar which results in damage to other property of more than \$25,000.**

7

90 % of bird strikes occur :

☒ **between 500 and 1 000 m**

☐ **under 500 m**

☐ **above 1 000 m**

☐ **between 500 and 1 500 m**

8

*Who checks, before flight, that the aircraft's weight is such that flight can be safely made, and that any transported cargo is properly distributed and secured?
(Annex 6, Part I)*

- ☐ The operator.
- ☐ The mechanic on board, or in his absence the co-pilot.
- ☒ The captain.
- ☐ The company's cargo technicians.

Candidate: Ruth Menya Komyhendo
Date of birth: 1988-11-28

Subject: 070-Operational procedures
Date: 2014-07-23

9

In accordance to the EAC states' Civil aviation regulations (Aerodrome Operating Minima), for a Category III B approach, the RVR shall not be less than:

☒ 100 m

☐ 150 m

☐ 75 m

☐ 50 m

10

In accordance with civil aviation regulations, for aeroplanes intended to be operated at pressure altitude of 39000 ft, the total number of oxygen dispensing units and outlets shall exceed:

☐ the number of passengers by at least 10%.

☒ the number of seats by at least 10%.

☐ the number of passengers.

☐ the number of seats.

11

According to civil aviation regulations, an aeroplane whose maximum approved passenger seating configuration is 10 seats must be equipped with:

- ☐ three hand fire-extinguishers in the passenger compartment.
- ☐ one hand fire-extinguisher on the flight deck and two hand fire-extinguishers in the passenger compartment.
- ☒ one hand fire-extinguisher on the flight deck and one hand fire-extinguisher in the passenger compartment.
- ☒ two hand fire-extinguishers on the flight deck and two hand fire-extinguishers in the passenger compartment.

12

Aircraft may operate in MNPS airspace along a number of special routes, if the aircraft is equipped with at least:

- ☐ two Inertial Navigation Systems (INS).
- ☐ three Inertial Navigation System (INS).
- ☐ one Long Range Navigation System (LNRS).
- ☒ two independent Long Range Navigation Systems (LRNS).

13

An aircraft operating within MNPS Airspace is unable to continue flight in accordance with its air traffic control clearance, but is able to maintain its assigned level, and due to a total loss of communications capability, cannot obtain a revised clearance from ATC. The aircraft should offset from the assigned route by 15 NM and climb or descent 500 ft, if:

☐ above FL410

☐ at FL410

☒ below FL410

☐ at FL430

14

An airplane operated by a supplemental air carrier flying over uninhabited terrain must carry which emergency equipment?

- ☐ Suitable pyrotechnic signaling devices.
- ☒ Survival kit for each passenger.
- ☐ Colored smoke flares and a signal mirror.

15

During a flight, the chief steward informs the crew that a passenger is using a portable device suspected to disurb the aircraft electronic systems. The captain:

- ☒ must not authorize any person to use such a device on board.
- ☐ authorizes its use during the whole flight phase.
- ☐ authorizes its use except during take-off and landing phases.
- ☐ may authorize the use of this device, as an exception.

16

Information concerning evacuation procedures can be found in the :

- ☐ journey logbook.
- ☐ operational flight plan.
- ☐ flight manual.
- ☒ operation manual.

17

The Civil Aviation Regulations establishes that, a co-pilot is not assigned to operate at the flight controls during take-off and landing unless :

- ☐ he has carried out at least three flights as pilot-in-command or as a co-pilot at the controls of the type to be used, in the preceding 90 days.
- ☐ he has carried out as pilot-in-command or as co-pilot at least three take-off and three landings in an aeroplane or an approved flight simulator of the type used, in the preceding 90 days.
- ☒ he has operated as pilot-in-command or as co-pilot at the controls during take-off and landing of the type to be used in the preceding 90 days.
- ☐ he has carried out as-pilot-in-command or as co-pilot at lest three take-off and three landings in an aeroplane or an approved flight simulator of the type used, in the preceding 30 days

18

On overwater flights, an operator shall not operate an aeroplane at a distance away from land, which is suitable for making an emergency landing greater than that corresponding to :

- ☐ 300 NM or 90 minutes at cruising speed.
- ☐ 100 NM or 30 minutes at cruising speed.
- ☐ 400 NM or 120 minutes at cruising speed.
- ☒ 200 NM or 45 minutes at cruising speed.

19

The greatest possibility of ice buildup, while flying under icing conditions, occurs on :

- ☒ The upper and lower wingsurfaces.
- ☐ Only the pitot and static probes.
- ☐ The upper and lower rudder surfaces.
- ☐ The aircraft front areas.

Candidate: Ruth Menya Komyhendo
Date of birth: 1988-11-28

Subject: 070-Operational procedures
Date: 2014-07-23

20

The maximum validity of a SNOWTAM is :

☐ 6 hours

☐ 3 hours

☒ 12 hours

☐ 24 hours

21

An aircraft having undergone an anti-icing procedure and having exceeded the protection time of the anti-icing fluid:

- ☐ must undergo a de-icing procedure before a new application of anti-icing fluid for take-off.
- ☒ must only undergo a new anti-icing procedure for take-off.
- ☐ must only undergo a de-icing procedure for take-off.
- ☐ need not to undergo a new anti-icing procedure for take-off.

22

An aircraft having undergone an anti-icing procedure must be anti-icing fluid free at the latest when :

- ☐ it is implementing its own anti-icing devices.
- ☒ it is rotating (before taking-off).
- ☒ releasing the brakes in order to take-off.
- ☐ leaving the icing zone.

23

If after anti-icing has been completed a pre-departure inspection reveals evidence of freezing, the correct action is to :

- ☐ complete departure as soon as possible to reduce the possibility of further freezing
- ☐ complete departure provided that the recommended anti-icing holdover (protection) time for the prevailing conditons and type of fluid used has not been exceeded
- ☒ switch on all the aeroplane anti-icing and de-icing systems and leave on until clear of icing conditions when airborne
- ☐ carry out a further de-icing process

24

As regards the detection of bird strike hazard, the pilot's means of information and prevention are:

1 - ATIS.

2 - NOTAMs.

3- BIRDTAMs.

4 - Weather radar.,

☐ 1,2,3,4,5

☐ 2,5

☒ 1,3,4

☐ 1,2,5

25

The "NO SMOKING" sign must be illuminated :

- ☐ when oxygen is being supplied in the cabin.
- ☒ in each cabin section if oxygen is being carried.
- ☐ during take off and landing.
- ☐ during climb and descent.

26

If smoke appears in the air conditioning, the first action to take is to :

- ☐ Begin an emergency descent.
- ☐ Determine which system is causing the smoke.
- ☐ Put on the mask and goggles.
- ☒ Cut off all air conditioning units.

27

An aircraft having undertaken an anti-icing procedure and having exceeded the holdover time of the anti-icing fluid:

- ☒ **must undertake a de-icing procedure before a new application of anti-icing fluid before take-off.**
- ☐ **does not require a new anti-icing procedure before take-off.**
- ☐ **must only undertake a de-icing procedure before take-off.**
- ☐ **must only undertake a new anti-icing procedure before take-off.**

28

You will use a halon extinguisher for a fire of:

1 - solids (fabric, plastic, ...)

2 - liquids (alcohol, gasoline, ...)

3 - gas

4 - metals (aluminium, magnesium, ...)

The combination regrouping all the correct statements

☐ 1,2,3,4

☐ 1,2,4

☒ 1,2,3

☐ 2,3,4

29

A CO2 fire extinguisher can be used for:

- 1. a paper fire*
- 2. a hydrocarbon fire*
- 3. a fabric fire*
- 4. an electrical fire*
- 5. a wood fire*

The combination regrouping all the correct statements

☐ 2, 4, 5

☐ 2, 3, 4

☐ 1, 3, 5

☒ 1, 2, 3, 4, 5

30

The fire extinguisher types which may be used on class B fires are:

- 1 - H₂O,*
- 2 - CO₂,*
- 3 - dry-chemical,*
- 4 - halogen*

☐ 2 - 3 - 4

☐ 1 - 2 - 3 - 4,

☐ 3 - 4

☒ 2

31

During a manual approach, the aeroplane is subjected to windshear with an increasing tail wind. In the absence of a pilot action, the aeroplane:

- 1- flies above the intended approach path
- 2- flies below the intended approach path
- 3- has an increasing true airspeed
- 4- has a decreasing true airspeed

The combination of correct statements is:

- ☐ 2, 4.
- ☐ 1, 3.
- ☐ 1, 4.
- ☒ 2, 3.

32

Aeroplane wake turbulence during take off starts when:

- ☐ the take off roll commences.
- ☐ out of ground effect.
- ☒ slats and flaps are extended only.
- ☐ the nose wheel lifts off the runway.

33

The wake turbulence caused by an aircraft is mainly the result of:

1. An aerodynamic effect (wing tip vortices).
2. The engines action (propellers rotation or engine gas exhausts).
3. The importance of the drag devices (size of the landing gear, of the flaps, etc.).

The combination regrouping all the correct statements is:

☐ 1.

☒ 2 and 3.

☐ 1, 2 and 3.

☐ 3.

34

The greatest wake turbulence occurs when the generating aircraft is:

- ☒ **Small, light, at low speed in clean configuration**
- ☐ **Large, heavy, at maximum speed in full flaps configuration**
- ☐ **Large, heavy, at low speed in clean configuration**
- ☐ **Small, light, at maximum speed in full flaps configuration**

35

In case of a serious threat based on the presence of a bomb on board a pressurized aircraft and disregarding any fuel considerations:

- ☐ you climb to the maximum flight level which does not need the use of pressurization.
- ☒ you descend to the flight level corresponding to the indicated cabin altitude or the safety altitude if higher and take preventive steps by putting yourself in a landing approach configuration.
- ☐ you carry out an emergency descent to reach the safety altitude.
- ☐ you go down to the level corresponding to the indicated cabin altitude and keep the airplane in a clean configuration until the final approach.

36

In case of a serious threat based on the presence of a bomb on board a pressurized aircraft and disregarding any fuel considerations:

- ☐ you climb to the maximum flight level which does not need the use of pressurization.
- ☐ you carry out an emergency descent to reach the safety altitude.
- ☒ you descend to the flight level corresponding to the indicated cabin altitude or the safety altitude if higher and take preventive steps by putting yourself in a landing approach configuration.
- ☐ you go down to the level corresponding to the indicated cabin altitude and keep the aircraft in a clean configuration until the final approach.

37

The content of the dangerous goods transport document is specified in the:

- ☐ Air Transport Permit.
- ☐ OPS documentation.
- ☒ Flight Manual.
- ☐ Technical Instructions.

38

For an airplane with a tyre pressure of 12 bars, there is a risk of dynamic hydroplaning as soon as the :

1- water height is equal to the depth of the tyre grooves.

2- speed is greater than 114 kt.

3- water height is equal to the half of the depth of the tyre grooves.

4- speed is greater than 83 kt.

The combination regrouping all the correct statements is :

☐ 1 and 4.

☐ 3 and 4.

☒ 1 and 2.

☐ 2 and 3.

39

According to the civil aviation regulations a runway is considered damp when:

- ☒ it is covered with a film of water of less than 3 mm.
- ☐ its surface is not dry, and when surface moisture does not give it a shiny appearance.
- ☐ it is covered with a film of water of less than 1 mm.
- ☐ surface moisture gives it a shiny appearance.

40

For an airplane with a tyre pressure of 14 bars, there is a risk of dynamic hydroplaning as soon as the :

1- water height is equal to the depth of the tyre grooves.

2- speed is greater than 123 kt.

3- water height is equal to the half of the depth of the tyre grooves.

4- speed is greater than 95 kt. The combination regrouping all the correct statements is:

☐ 3 and 4.

☒ 1 and 4.

☐ 1 and 2.

☐ 2 and 3.


Attachment No. 1

Questions 1

Figure 126

atp_126.jpg

Class C Airspace



Services upon establishing two-way radio communication and radar contact:

Sequencing Arrivals

IFR/VFR Standard Separation

IFR/VFR Traffic Advisories and Conflict Resolution

VFR/VFR Traffic Advisories

IFR: Instrument Flight Rules
VFR: Visual Flight Rules

Figure 126. Class C Airspace © ASA