



Formula Home

■ Plate Theory

Kinematics

Constitutive

Resultants

Equilibrium

Sign Convention

Plate Calculators

Calculator List


Material Data

Resources

Bibliography

Elastic Moduli

Classical Plate





To enforce equilibrium, consider the balance of forces and moments acting on a small section of plate. There are six (6) equilibrium equations, three for the forces and three for the moments, that need to be satisfied.

The equations of force equilibrium are

x direction:
$$\frac{\partial N_{\chi}}{\partial x} + \frac{\partial N_{y\chi}}{\partial y} + p_{\chi} = 0$$

y direction:
$$\frac{\partial N_{xy}}{\partial x} + \frac{\partial N_y}{\partial y} + p_y = 0$$

z direction:
$$\frac{\partial Q_{xz}}{\partial x} + \frac{\partial Q_{yz}}{\partial y} + p_z = 0$$

Laser Focus World

Semiconductors, medical equipment, lasers, optics and aviation and aerospace.

Offshore

International news and technology for marine/offshore operations around the world.

Wind Systems

Towers, turbines, gearboxes; processes for shaping and finishing component parts.

Chemical Engineering

The industry gateway for chemical engineering and plant operations.

where N_x , N_y , N_{xy} , N_{yx} , Q_{xz} , and Q_{yz} are force resultants; p_x , p_y , and p_z are distributed external forces applied on the plate.

The equations of moment equilibrium are

x direction:
$$-\frac{\partial M_{xy}}{\partial x} - \frac{\partial M_y}{\partial y} + Q_{yz} + m_{\chi} = 0$$

y direction:
$$\frac{\partial M_{\chi}}{\partial x} + \frac{\partial M_{y\chi}}{\partial y} - Q_{\chi Z} + m_y = 0$$

z direction:
$$N_{\rm XY}-N_{\rm YX}+m_{\rm Z}=0$$

where M_{v} , M_{v} , M_{vv} , M_{vv} , M_{vv} , and M_{vv} are moment resultants; and m_{v} , m_{v} , and m_{τ} are distributed external






신용미세먼지 내쫓자!

Ad NICE지키미

Further Simplicification



To further simplify the problem, consider a plate subjected to transverse loads. In other words, only p_z is the non-zero external force. All forces and moments in other directions are zero: $p_x = p_y = m_x = m_y = m_z = 0$

The above six equations of equilibrium become

$$\frac{\partial N_{x}}{\partial x} + \frac{\partial N_{yx}}{\partial y} = 0$$

$$\frac{\partial N_{xy}}{\partial x} + \frac{\partial N_y}{\partial y} = 0$$

$$\frac{\partial Q_{xz}}{\partial x} + \frac{\partial Q_{yz}}{\partial y} = -p_z$$

-∂M... - ∂M..







$$N_{\chi y} = N_{y\chi}$$

Due to the lack of external force components other than p_z , the shear stresses at any given point are paired as follows:

$$\sigma_{\chi y} = \sigma_{y \chi}$$

$$\sigma_{yx} = \sigma_{xy}$$

$$\sigma_{ZX} = \sigma_{XZ}$$

This yields

$$N_{\chi y} = N_{y \chi}$$

$$M_{\chi y} = M_{y\chi}$$


갤럭시Z플립3 재고정

Ad 800대 한정 / 부가서비기기반납 X / 전국당일배원

다모렛

자세히 알아보기







Membership About Us Privacy Disclaimer Contact Us Directory Advertise copyright © 1999-2022 eFunda, Inc.



