

The harbor survey began on a cold morning in March. Inspectors walked the length of each dock and noted every cracked piling, loose plank, and rusted cleat. Dock A showed the worst damage along its north side. Tide gauges were checked against the harbor records.