



8085 microprocessor

Add 16



Sub 16



Mul 16

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

A	00	00	S	0
BC	00	00	Z	1
DE	00	05	AC	0
HL	09	C6	P	1
PSW	00	00	C	0
PC	42	1F		
SP	FF	FF		
Int-Reg	00			

Flag

Load me at

1 LXI H, 2500
2 MOV E, M
3 INX H
4 MOV D, M
5
6 LXI H, 2502
7 MOV C, M
8
9 MVI A, 00
10 MVI B, 00
11
12 LOOP: ADD E
13 JNC NEXT
14 INR B
15 NEXT: DCR C
16 JNZ LOOP
17
18 STA 2504
19 MOV A, B
20 STA 2505
21 HLT

Decimal - Hex Conversion

Decimal 0 Hex 0

To Hex To Dec

I/O Ports

0 - + 00

Update Port Value

Memory

0 - + 00

Update Memory

Start 2500 OK

Address (Hex)	Address	Data
09C4	2500	5
09C5	2501	0
09C6	2502	3
09C7	2503	0
09C8	2504	15
09C9	2505	0
09CA	2506	0
09CB	2507	0
09CC	2508	0

Line No Assembler Message

0 Program assembled successfully

Simulator: Idle

Div 16

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

A	00	03	S	1
BC	00	03	Z	0
DE	04	00	AC	0
HL	00	00	P	0
PSW	00	00	C	1
PC	42	1E		
SP	FF	FF		
Int-Reg	00			

Flag

Load me at

1 LDA 2500
2 MOV B, A
3 LDA 2502
4 MOV C, A
5
6 MVI D, 00
7
8 LOOP: MOV A, B
9 CMP C
10 JC END
11 SUB C
12 MOV B, A
13 INR D
14 JMP LOOP
15
16 END: MOV A, D
17 STA 2504
18 MOV A, B
19 STA 2505
20 HLT

Decimal - Hex Conversion

Decimal 0 Hex 0

To Hex To Dec

I/O Ports

0 - + 00

Update Port Value

Memory

0 - + 00

Update Memory

Start 2500 OK

Address (Hex)	Address	Data
09C4	2500	12
09C5	2501	0
09C6	2502	3
09C7	2503	0
09C8	2504	4
09C9	2505	0
09CA	2506	0
09CB	2507	0
09CC	2508	0

Line No Assembler Message

0 Program assembled successfully

Simulator: Idle

Add 8

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

A	28	S	0
BC	19 00	Z	0
DE	00 00	AC	1
HL	00 00	P	1
PSW	00 00	C	0
PC	42 0C		
SP	FF FF		
Int-Reg	00		

Flag

Load me at

```
1 LDA 2500
2 MOV B,A
3 LDA 2501
4 ADD B
5 STA 2502
6 HLT
```

Decimal - Hex Conversion

Decimal: 0 Hex: 0

To Hex To Dec

I/O Ports

0 - + 00

Update Port Value

Memory

0 - + 00

Update Memory

Simulator: Idle

Data Stack KeyPad Memory I/O Ports

Start 2500 OK

Address (Hex)	Address	Data
09C4	2500	25
09C5	2501	15
09C6	2502	40
09C7	2503	0
09C8	2504	0
09C9	2505	0
09CA	2506	0
09CB	2507	0
09CC	2508	0

Line No Assembler Message

0 Program assembled successfully

Sub 8

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

A	0A	S	0
BC	0F 00	Z	0
DE	00 00	AC	0
HL	00 00	P	1
PSW	00 00	C	0
PC	42 0C		
SP	FF FF		
Int-Reg	00		

Flag

Load me at

```
1 LDA 2500
2 MOV B,A
3 LDA 2501
4 SUB B
5 STA 2502
6 HLT
```

Decimal - Hex Conversion

Decimal: 0 Hex: 0

To Hex To Dec

I/O Ports

0 - + 00

Update Port Value

Memory

0 - + 00

Update Memory

Simulator: Idle

Data Stack KeyPad Memory I/O Ports

Start 2500 OK

Address (Hex)	Address	Data
09C4	2500	15
09C5	2501	25
09C6	2502	10
09C7	2503	0
09C8	2504	0
09C9	2505	0
09CA	2506	0
09CB	2507	0
09CC	2508	0

Line No Assembler Message

0 Program assembled successfully

Mul 8

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

Register	Value
A	0F
BC	05 00
DE	00 00
HL	00 00
PSW	00 00
PC	42 13
SP	FF FF
Int-Reg	00

Flag

Flag	Value
S	0
Z	1
AC	0
P	1
C	0

Load me at

1 LDA 2500
2 MOV B,A
3 LDA 2501
4 MOV C,A
5 MVI A,00
6
7 LOOP: ADD B
8 DCR C
9 JNZ LOOP
10
11 STA 2502
12 HLT

Decimal - Hex Conversion

Decimal: 0 Hex: 0

To Hex To Dec

I/O Ports

0 - + 00

Update Port Value

Memory

0 - + 00

Update Memory

Start 2500 OK

Address (Hex)	Address	Data
09C4	2500	5
09C5	2501	3
09C6	2502	15
09C7	2503	0
09C8	2504	0
09C9	2505	0
09CA	2506	0
09CB	2507	0
09CC	2508	0

Line No Assembler Message

0 Program assembled successfully

Simulator: Idle

Div 8

GNUSim8085 - 8085 Microprocessor Simulator

File Reset Assembler Debug Help

Registers

Register	Value
A	00
BC	00 03
DE	04 00
HL	00 00
PSW	00 00
PC	42 1E
SP	FF FF
Int-Reg	00

Flag

Flag	Value
S	1
Z	0
AC	0
P	0
C	1

Load me at

1 LDA 2500
2 MOV B,A
3 LDA 2501
4 MOV C,A
5 MVI D,00
6
7 LOOP: MOV A,B
8 CMP C
9 JC END
10 SUB C
11 MOV B,A
12 INR D
13 JMP LOOP
14
15 END: MOV A,D
16 STA 2502
17 MOV A,B
18 STA 2503
19 HLT

Decimal - Hex Conversion

Decimal: 0 Hex: 0

To Hex To Dec

I/O Ports

0 - + 00

Update Port Value

Memory

0 - + 00

Update Memory

Start 2500 OK

Address (Hex)	Address	Data
09C4	2500	12
09C5	2501	3
09C6	2502	4
09C7	2503	0
09C8	2504	0
09C9	2505	0
09CA	2506	0
09CB	2507	0
09CC	2508	0

Line No Assembler Message

0 Program assembled successfully

Simulator: Idle