5.3 Instruction Set Summary

				Status Bits			
				V	N	Z	C
*	ADC(.B)	dst	dst + C → dst	x	x	x	x
	ADD(.B)	src,dst	src + dst → dst	x	x	x	x
	ADDC(.B)	src,dst	src + dst + C → dst	x	x	x	x
	AND(.B)	src,dst	src .and. dst → dst	0	x	x	x
	BIC(.B)	src,dst	.not.src .and. dst → dst	-	-	-	-
	BIS(.B)	src,dst	src .or. dst → dst	-	-	-	-
	BIT(.B)	src,dst	src .and. dst	0	x	x	x
*	BR	dst	Branch to	-	-	-	-
	CALL	dst	PC+2 → stack, dst → PC	-	-	-	-
*	CLR(.B)	dst	Clear destination	-	-	-	-
*	CLRC		Clear carry bit	-	-	-	0
*	CLRN		Clear negative bit	-	0	-	-
*	CLRZ		Clear zero bit	-	-	0	-
	CMP(.B)	src,dst	dst - src	x	x	x	x
*	DADC(.B)	dst	dst + C → dst (decimal)	x	x	x	x
	DADD(.B)	src,dst	src + dst + C → dst (decimal)	x	x	x	x
*	DEC(.B)	dst	dst - 1 → dst	x	x	x	x
*	DECD(.B)	dst	dst - 2 → dst	x	x	x	x
*	DINT		Disable interrupt	-	-	-	-
*	EINT		Enable interrupt	-	-	-	-
*	INC(.B)	dst	Increment destination, dst +1 → dst	x	x	x	x
*	INCD(.B)	dst	Double-Increment destination, dst+2→dst	x	x	x	x
*	INV(.B)	dst	Invert destination	x	x	x	x
	JC/JHS	Label	Jump to Label if Carry-bit is set	-	-	-	-
	JEQ/JZ	Label	Jump to Label if Zero-bit is set	-	-	-	-
	JGE	Label	Jump to Label if (N .XOR. V) = 0	-	-	-	-
	JL	Label	Jump to Label if (N .XOR. V) = 1	-	-	-	-
	JMP	Label	Jump to Label unconditionally	-	-	-	-
	JN	Label	Jump to Label if Negative-bit is set	-	-	-	-

Legend:
0 Status bit always cleared
1 Status bit always set
x Status bit cleared or set on results
- Status bit not affected
* Emulated Instructions

Table 5.3: MPS430 Family Instruction Set Summary

				Status Bits			
				V	N	Z	C
	JNC/JLO	Label	Jump to Label if Carry-bit is reset	-	-	-	-
	JNE/JNZ	Label	Jump to Label if Zero-bit is reset	-	-	-	-
	MOV(.B)	src,dst	src → dst	-	-	-	-
*	NOP		No operation	-	-	-	-
*	POP(.B)	dst	Item from stack, SP+2 → SP	-	-	-	-
	PUSH(.B)	src	SP - 2 → SP, src → @SP	-	-	-	-
	RETI		Return from interrupt TOS → SR, SP + 2 → SP TOS → PC, SP + 2 → SZP	x	x	x	x
*	RET		Return from subroutine TOS → PC, SP + 2 → SP	-	-	-	-
*	RLA(.B)	dst	Rotate left arithmetically	x	x	x	x
*	RLC(.B)	dst	Rotate left through carry	x	x	x	x
	RRA(.B)	dst	MSB → MSB ....LSB → C	0	x	x	x
	RRC(.B)	dst	C → MSB .....LSB → C	x	x	x	x
*	SBC(.B)	dst	Subtract carry from destination	x	x	x	x
*	SETC		Set carry bit	-	-	-	1
*	SETN		Set negative bit	-	1	-	-
*	SETZ		Set zero bit	-	-	1	-
	SUB(.B)	src,dst	dst + .not.src + 1 → dst	x	x	x	x
	SUBC(.B)	src,dst	dst + .not.src + C → dst	x	x	x	x
	SWPB	dst	swap bytes	-	-	-	-
	SXT	dst	Bit7 → Bit8 ..... Bit15	0	x	x	x
*	TST(.B)	dst	Test destination	x	x	x	x
	XOR(.B)	src,dst	src .xor. dst → dst	x	x	x	x

Legend:
0 The Status Bit is cleared
1 The Status Bit is set
x The Status Bit is affected
- The Status Bit is not affected
* Emulated Instructions

Table 5.3: MPS430 Family Instruction Set Summary (Concluded)

Note: Emulated Instructions

All marked instructions (*) are emulated instructions. The emulated instructions use core instructions combined with the architecture and implementation of the CPU for higher code efficiency and faster execution.