GD&T – Example Drawings


- Review

References:


- •Engineering Drawing and Design by D. Madsen, etal.
- •Geometric Dimensioning and Tolerancing, by D. Madsen.

Note: The following slides contain some errors. Review the slides use your reference material to find the errors


Example 1: Axis - Straightness




Example 1: Complete the following




Example 2: Profile of a Surface



Example 2: Complete the following




Example 3: Position, Angle, Parallel



10/8/2009 - jcs


GDT V - Examples

Example 3: Complete the following




| LMC / MMC | | Geometric Tolerance |
|-----------|------|------------------------|
| | .252 | |
| | .251 | |
| | .250 | |
| | .249 | |
| | .248 | |

Example 3: Complete the following



Example 4:



GDT V - Examples

Example 4: Complete the following




| TABLE | | | |
|-----------|----------|-----------|--|
| Column 1 | Column 2 | Column 3 | |
| LMC / MMC | Size | Geometric | |
| | | Tolerance | |
| | .25 | | |
| | .24 | | |
| | .23 | | |
| | .22 | | |




| LMC / MMC | Size | Geometric Tolerance |
|-----------|------|------------------------|
| | | |
| | | |
| | | |
| | | |
| | .313 | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

Example 5 – Find the errors



Example 6 – Find the errors



10/8/2009 - jcs

GDT V - Examples