



Fig 4: AmorE crossover — current firmware (top) vs proposed Stop-mode optimization (bottom)
Top row shows AmorE losing to direct pairing; bottom row shows where the win lives.


BN254 — BASELINE (busy-wait UART at 55 mA)
NO crossover in [1,100]




BLS12_381 — BASELINE (busy-wait UART at 55 mA)
NO crossover in [1,100]



BN254 — WITH_STOP (proposed: 0.5 μ A during ServerWait)
✓ crossover found



BLS12_381 — WITH_STOP (proposed: 0.5 μ A during ServerWait)
NO crossover in [1,100]



SYNTHETIC DATA — baseline firmware
ServerWait is busy-wait at 55 mA (no Stop mode)
See methodology document