CAR-O-LINER® Service Order Request Form (SORF)

(not to be used for Credit Returns)

Instructions:

1. Submit one Form via Email (Ticket) per Main Unit Serial Number.
2. Attach any Signed Slide Rental or Welding C-Gun Loaner forms.
3. You will receive an UPDATED FORM TO PRINT AND INCLUDE WITH THE SHIPMENT.
4. ALL SHIPMENTS must include the UPDATED FORM with SERVICE ORDER & TICKET NUMBER
5. Locate Service item # on the Service Item # Shipped for Repair lookup chart

COL Service Order Number

Ticket Number

E-Mail this completed form (and applicable Slide Rental or Welding C-Gun Loaner Form)

To: Car-O-Liner@soe.freshdesk.com

Subject: Service Order Request - Distributor - Shop - Item

All information below is required: submitted forms with missing information will be returned and cause delay.

Measuring Slide Return

☐ Empty Crate Needed for Slide Return

☑ Slide Rental Needed
(Slide Rental Form with complete address must be Included)

Welding C-Gun Loaner

☐ Welding C-Gun Loaner Needed
(Loaner Form with complete address must be Included)

Call Tag or Empty Crate ~ Required Information

☐ Ready for Call Tag for Pickup
☐ Confirm before issuing

Size:
Weight:
Item #:
Shipping Instructions:

Company Name: KLC Automotive Equipment
Attention: Jason Bain
Address: 1938 Wyott Dr. Unit D8
City, ST Zip: Cheyenne, WY 82007
Phone: 720-498-0043
E-Mail (optional): jasonb@klcautoequip.com

Distributor Information

Date Submitted: 09/10/26
Distributor: KLC Automotive Equipment
Distributor Contact: Jason Bain
Distributor Contact Phone: 720-498-0043
E-Mail: jasonb@klcautoequip.com, andym@klcautoequip.com
Collision Shop Name: Caliber 808 Parker

Ship To After Service

Company Name: KLC Automotive Equipment
Attention: Jason Bain
Address: 1938 Wyott Dr. Unit D8
City/State/Zip: Cheyenne, WY 82007
Phone #: 720-498-0043
☐ Collect Carrier:
Collect Account #:

Main Unit

Install Date is REQUIRED for Warranty Review

Main Unit Install Date: ?
Main Unit Item #: CAR46732
Main Unit Serial #: 112890
Additional Details (Weld Count):

Service Item

Required Even if the Service Item is the Main Unit

Service Item # Shipped for Repair: CAR36424
Service Item Description: Classic Slide
Service Item Serial # (if applicable): 112890
Service Item Install Date (if different):

Problem Description

There is a break in the red wire on the main cable harness. The system will not read tubes because of this break.