```
>> Untitled4
Action DEAF.csv
______
***Row Num = 1
Min = 0.908200
Max = 0.968750
Mean = 0.938599
std = 0.013063
RMS = 0.938688
_____
***Row Num = 2
Min = -0.392580
Max = -0.267090
Mean = -0.326205
std = 0.027859
RMS = 0.327366
______
***Row Num = 3
Min = 0.038574
Max = 0.153810
Mean = 0.079357
std = 0.033287
RMS = 0.085909
______
***Row Num = 4
Min = -0.896000
Max = 1.389600
Mean = 0.361405
std = 0.812836
RMS = 0.881079
***Row Num = 5
Min = 0.207520
Max = 0.726560
Mean = 0.369829
std = 0.181298
RMS = 0.410969
_____
***Row Num = 6
Min = -0.087891
Max = 0.600100
Mean = 0.169002
std = 0.166548
RMS = 0.235944
_____
***Row Num = 7
Min = -4.000000
Max = 19.000000
Mean = 0.000000
std = 3.839816
```

```
RMS = 3.795931
***Row Num = 8
Min = -13.000000
Max = 6.000000
Mean = -1.386364
std = 2.821973
RMS = 3.115212
_____
***Row Num = 9
Min = -4.000000
Max = 1.000000
Mean = -1.068182
std = 1.189053
RMS = 1.588310
_____
***Row Num = 10
Min = -3.000000
Max = 1.000000
Mean = -0.818182
std = 1.105435
RMS = 1.365151
***Row Num = 11
Min = -4.000000
Max = 2.000000
Mean = -1.113636
std = 1.466144
RMS = 1.827815
***Row Num = 12
Min = -14.000000
Max = 6.000000
Mean = -1.568182
std = 2.765214
RMS = 3.151479
______
***Row Num = 13
Min = -28.000000
Max = 12.000000
Mean = -1.363636
std = 6.153429
RMS = 6.234071
***Row Num = 14
Min = -5.000000
Max = 4.000000
Mean = -0.954545
std = 1.940445
RMS = 2.142641
```

```
_____
***Row Num = 15
Min = -32.000000
Max = 31.000000
Mean = 3.613636
std = 13.910371
RMS = 14.218266
_____
***Row Num = 16
Min = -8.000000
Max = 17.000000
Mean = 0.340909
std = 5.890249
RMS = 5.832900
***Row Num = 17
Min = -13.000000
Max = 17.000000
Mean = 0.454545
std = 4.976477
RMS = 4.940556
______
***Row Num = 18
Min = -5.000000
Max = 9.000000
Mean = -0.181818
std = 2.830669
RMS = 2.804218
_____
***Row Num = 19
Min = -9.000000
Max = 17.000000
Mean = -0.272727
std = 3.955353
RMS = 3.919647
***Row Num = 20
Min = -6.000000
Max = 19.000000
Mean = 2.363636
std = 4.993442
RMS = 5.473075
______
***Row Num = 21
Min = -19.000000
Max = 36.000000
Mean = -0.113636
std = 8.861245
RMS = 8.760708
```

```
***Row Num = 22
Min = -32.000000
Max = 73.000000
Mean = -1.522727
std = 14.708783
RMS = 14.620192
***Row Num = 23
Min = -25.438000
Max = 28.188000
Mean = 1.144898
std = 8.522337
RMS = 8.502373
______
***Row Num = 24
Min = -25.438000
Max = 28.188000
Mean = 1.144898
std = 8.522337
RMS = 8.502373
_____
***Row Num = 25
Min = -25.438000
Max = 28.188000
Mean = 1.144898
std = 8.522337
RMS = 8.502373
***Row Num = 26
Min = -50.438000
Max = 67.188000
Mean = 1.731545
std = 17.740781
RMS = 17.623293
______
***Row Num = 27
Min = -50.438000
Max = 67.188000
Mean = 1.731545
std = 17.740781
RMS = 17.623293
_____
***Row Num = 28
Min = -50.438000
Max = 67.188000
Mean = 1.731545
std = 17.740781
RMS = 17.623293
______
***Row Num = 29
```

```
Min = 2.742900
Max = 3.048900
Mean = 2.861123
std = 0.1111111
RMS = 2.863230
_____
***Row Num = 30
Min = 2.991600
Max = 3.102100
Mean = 3.044139
std = 0.045583
RMS = 3.044472
***Row Num = 31
Min = 6.898900
Max = 7.213700
Mean = 7.068959
std = 0.138508
RMS = 7.070285
_____
***Row Num = 32
Min = 6.306100
Max = 7.553700
Mean = 6.981398
std = 0.268580
RMS = 6.986445
***Row Num = 33
Min = 2.846500
Max = 6.574500
Mean = 4.122898
std = 1.655878
RMS = 4.435978
_____
***Row Num = 34
Min = 0.253250
Max = 9.967000
Mean = 6.330342
std = 3.877397
RMS = 7.400388
______
***Row Num = 35
Min = 0.896000
Max = 0.960940
Mean = 0.930974
std = 0.015814
RMS = 0.931106
***Row Num = 36
Min = -0.387700
```

```
Max = -0.308590
Mean = -0.342540
std = 0.022830
RMS = 0.343283
______
***Row Num = 37
Min = -0.005859
Max = 0.191890
Mean = 0.090476
std = 0.041730
RMS = 0.099437
_____
***Row Num = 38
Min = -0.886720
Max = 1.425800
Mean = 0.267223
std = 0.824892
RMS = 0.858132
_____
***Row Num = 39
Min = 0.193850
Max = 0.868160
Mean = 0.404874
std = 0.178663
RMS = 0.441722
______
***Row Num = 40
Min = -0.103030
Max = 0.640140
Mean = 0.203436
std = 0.187621
RMS = 0.275296
______
***Row Num = 41
Min = -4.000000
Max = 5.000000
Mean = -0.409091
std = 2.149291
RMS = 2.163751
-----
***Row Num = 42
Min = -6.000000
Max = 2.000000
Mean = -1.022727
std = 1.704831
RMS = 1.971386
_____
***Row Num = 43
Min = -3.000000
Max = 1.000000
```

```
Mean = -1.181818
std = 0.994701
RMS = 1.537412
______
***Row Num = 44
Min = -4.000000
Max = 1.000000
Mean = -0.863636
std = 1.069469
RMS = 1.365151
***Row Num = 45
Min = -3.000000
Max = 2.000000
Mean = -0.863636
std = 1.212165
RMS = 1.477098
______
***Row Num = 46
Min = -5.000000
Max = 5.000000
Mean = -0.795455
std = 1.746485
RMS = 1.900957
_____
***Row Num = 47
Min = -7.000000
Max = 22.000000
Mean = 0.159091
std = 4.280530
RMS = 4.234598
***Row Num = 48
Min = -4.000000
Max = 5.000000
Mean = -1.136364
std = 1.875062
RMS = 2.174229
______
***Row Num = 49
Min = -75.000000
Max = 42.000000
Mean = -3.659091
std = 20.359494
RMS = 20.456717
______
***Row Num = 50
Min = -33.000000
Max = 19.000000
Mean = -3.022727
```

```
std = 8.968909
RMS = 9.367497
_____
***Row Num = 51
Min = -25.000000
Max = 13.000000
Mean = -1.886364
std = 6.552883
RMS = 6.747053
_____
***Row Num = 52
Min = -9.000000
Max = 6.000000
Mean = -1.250000
std = 2.989322
RMS = 3.208653
______
***Row Num = 53
Min = -66.000000
Max = 27.000000
Mean = -1.750000
std = 11.745608
RMS = 11.742502
______
***Row Num = 54
Min = -20.000000
Max = 37.000000
Mean = 2.409091
std = 12.821345
RMS = 12.901726
***Row Num = 55
Min = -18.000000
Max = 38.000000
Mean = 0.954545
std = 10.245713
RMS = 10.173495
_____
***Row Num = 56
Min = -40.000000
Max = 24.000000
Mean = -1.750000
std = 11.235585
RMS = 11.244190
_____
***Row Num = 57
Min = -42.688000
Max = 33.250000
Mean = -0.794068
std = 12.860642
```

```
RMS = 12.738433
***Row Num = 58
Min = -42.688000
Max = 33.250000
Mean = -0.794068
std = 12.860642
RMS = 12.738433
______
***Row Num = 59
Min = -42.688000
Max = 33.250000
Mean = -0.794068
std = 12.860642
RMS = 12.738433
_____
***Row Num = 60
Min = -67.000000
Max = 60.188000
Mean = 2.005705
std = 22.161624
RMS = 21.999959
***Row Num = 61
Min = -67.000000
Max = 60.188000
Mean = 2.005705
std = 22.161624
RMS = 21.999959
***Row Num = 62
Min = -67.000000
Max = 60.188000
Mean = 2.005705
std = 22.161624
RMS = 21.999959
______
***Row Num = 63
Min = 2.686400
Max = 3.095300
Mean = 2.892775
std = 0.132682
RMS = 2.895747
***Row Num = 64
Min = 3.028600
Max = 3.128900
Mean = 3.077811
std = 0.045648
RMS = 3.078142
```

```
_____
***Row Num = 65
Min = 6.896400
Max = 7.201200
Mean = 7.038618
std = 0.114286
RMS = 7.039525
_____
***Row Num = 66
Min = 6.276300
Max = 7.467500
Mean = 6.932693
std = 0.287631
RMS = 6.938522
***Row Num = 67
Min = 2.885200
Max = 6.624600
Mean = 4.381964
std = 1.674920
RMS = 4.684357
______
***Row Num = 68
Min = 0.018220
Max = 9.984100
Mean = 5.921347
std = 4.056689
RMS = 7.151577
_____
***Row Num = 69
Min = 0.884770
Max = 0.967770
Mean = 0.934227
std = 0.013220
RMS = 0.934318
______
***Row Num = 70
Min = -0.372070
Max = -0.302250
Mean = -0.338689
std = 0.013867
RMS = 0.338967
______
***Row Num = 71
Min = 0.039551
Max = 0.146970
Mean = 0.076261
std = 0.022901
RMS = 0.079550
```

```
***Row Num = 72
Min = -0.866210
Max = 1.314900
Mean = 0.225263
std = 0.819718
RMS = 0.841077
***Row Num = 73
Min = 0.108400
Max = 0.775880
Mean = 0.427934
std = 0.182256
RMS = 0.464316
______
***Row Num = 74
Min = -0.136720
Max = 0.715330
Mean = 0.237571
std = 0.182784
RMS = 0.298481
_____
***Row Num = 75
Min = -3.000000
Max = 5.000000
Mean = -1.227273
std = 1.411969
RMS = 1.858641
***Row Num = 76
Min = -10.000000
Max = 1.000000
Mean = -1.454545
std = 1.823038
RMS = 2.315953
______
***Row Num = 77
Min = -4.000000
Max = 1.000000
Mean = -1.000000
std = 1.011561
RMS = 1.414214
_____
***Row Num = 78
Min = -3.000000
Max = 1.000000
Mean = -0.818182
std = 1.062527
RMS = 1.331438
***Row Num = 79
```

```
Min = -3.000000
Max = 2.000000
Mean = -0.840909
std = 1.218905
RMS = 1.469385
_____
***Row Num = 80
Min = -8.000000
Max = 4.000000
Mean = -1.250000
std = 1.658312
RMS = 2.061553
***Row Num = 81
Min = -12.000000
Max = 11.000000
Mean = -1.045455
std = 3.589096
RMS = 3.698894
_____
***Row Num = 82
Min = -6.000000
Max = 3.000000
Mean = -0.954545
std = 1.554507
RMS = 1.809068
***Row Num = 83
Min = -52.000000
Max = 34.000000
Mean = -3.204545
std = 14.439255
RMS = 14.629516
***Row Num = 84
Min = -62.000000
Max = 16.000000
Mean = -1.409091
std = 11.320527
RMS = 11.279507
______
***Row Num = 85
Min = -43.000000
Max = 29.000000
Mean = 0.431818
std = 9.796529
RMS = 9.694188
***Row Num = 86
Min = -21.000000
```

```
Max = 9.000000
Mean = -1.136364
std = 4.791421
RMS = 4.871065
______
***Row Num = 87
Min = -73.000000
Max = 22.000000
Mean = -1.704545
std = 12.275102
RMS = 12.253942
***Row Num = 88
Min = -47.000000
Max = 54.000000
Mean = 0.227273
std = 13.814155
RMS = 13.658164
_____
***Row Num = 89
Min = -17.000000
Max = 31.000000
Mean = -0.636364
std = 9.683577
RMS = 9.594032
_____
***Row Num = 90
Min = -46.000000
Max = 25.000000
Mean = -3.090909
std = 13.545476
RMS = 13.742767
______
***Row Num = 91
Min = -32.313000
Max = 42.875000
Mean = 0.734386
std = 12.076283
RMS = 11.960830
-----
***Row Num = 92
Min = -32.313000
Max = 42.875000
Mean = 0.734386
std = 12.076283
RMS = 11.960830
***Row Num = 93
Min = -32.313000
Max = 42.875000
```

```
Mean = 0.734386
std = 12.076283
RMS = 11.960830
______
***Row Num = 94
Min = -70.563000
Max = 44.125000
Mean = -1.681818
std = 21.855190
RMS = 21.670768
***Row Num = 95
Min = -70.563000
Max = 44.125000
Mean = -1.681818
std = 21.855190
RMS = 21.670768
______
***Row Num = 96
Min = -70.563000
Max = 44.125000
Mean = -1.681818
std = 21.855190
RMS = 21.670768
_____
***Row Num = 97
Min = 2.754200
Max = 2.960500
Mean = 2.841568
std = 0.057785
RMS = 2.842142
_____
***Row Num = 98
Min = 3.044900
Max = 3.075600
Mean = 3.062377
std = 0.009499
RMS = 3.062392
______
***Row Num = 99
Min = 7.098700
Max = 7.180000
Mean = 7.122320
std = 0.015592
RMS = 7.122337
***Row Num = 100
Min = 6.225400
Max = 7.300900
Mean = 6.814930
```

```
std = 0.232387
RMS = 6.818801
_____
***Row Num = 101
Min = 2.866600
Max = 6.537800
Mean = 4.427555
std = 1.646603
RMS = 4.717300
_____
***Row Num = 102
Min = 0.155930
Max = 9.982500
Mean = 5.936923
std = 4.057670
RMS = 7.165023
***Row Num = 103
Min = 0.893550
Max = 0.963870
Mean = 0.931740
std = 0.012808
RMS = 0.931826
______
***Row Num = 104
Min = -0.397460
Max = -0.300290
Mean = -0.344227
std = 0.017925
RMS = 0.344683
***Row Num = 105
Min = 0.057129
Max = 0.147950
Mean = 0.087991
std = 0.017179
RMS = 0.089615
***Row Num = 106
Min = -0.909670
Max = 1.236300
Mean = 0.143041
std = 0.822203
RMS = 0.825296
______
***Row Num = 107
Min = 0.096191
Max = 1.068400
Mean = 0.472125
std = 0.187956
```

```
RMS = 0.507372
***Row Num = 108
Min = -0.200680
Max = 0.793460
Mean = 0.270097
std = 0.221116
RMS = 0.347467
_____
***Row Num = 109
Min = -5.000000
Max = 1.000000
Mean = -1.227273
std = 1.327064
RMS = 1.796461
_____
***Row Num = 110
Min = -4.000000
Max = 3.000000
Mean = -0.659091
std = 1.119451
RMS = 1.288057
______
***Row Num = 111
Min = -4.000000
Max = 1.000000
Mean = -1.181818
std = 1.105435
RMS = 1.609630
***Row Num = 112
Min = -4.000000
Max = 1.000000
Mean = -0.954545
std = 1.055540
RMS = 1.414214
______
***Row Num = 113
Min = -3.000000
Max = 1.000000
Mean = -1.000000
std = 1.034296
RMS = 1.430194
***Row Num = 114
Min = -6.000000
Max = 4.000000
Mean = -0.795455
std = 1.390659
RMS = 1.588310
```

```
_____
***Row Num = 115
Min = -19.000000
Max = 32.000000
Mean = -0.272727
std = 5.985889
RMS = 5.923758
_____
***Row Num = 116
Min = -6.000000
Max = 2.000000
Mean = -1.000000
std = 1.462715
RMS = 1.758098
***Row Num = 117
Min = -42.000000
Max = 38.000000
Mean = -3.409091
std = 15.655177
RMS = 15.847283
______
***Row Num = 118
Min = -21.000000
Max = 63.000000
Mean = 0.181818
std = 12.832141
RMS = 12.686786
_____
***Row Num = 119
Min = -67.000000
Max = 22.000000
Mean = -4.863636
std = 15.570680
RMS = 16.142828
***Row Num = 120
Min = -17.000000
Max = 16.000000
Mean = -0.659091
std = 5.057544
RMS = 5.042997
______
***Row Num = 121
Min = -38.000000
Max = 72.000000
Mean = 0.386364
std = 13.171880
RMS = 13.027070
```

```
***Row Num = 122
Min = -19.000000
Max = 28.000000
Mean = 1.295455
std = 8.780474
RMS = 8.776259
***Row Num = 123
Min = -27.000000
Max = 33.000000
Mean = 1.500000
std = 11.138661
RMS = 11.113055
______
***Row Num = 124
Min = -40.000000
Max = 44.000000
Mean = 0.909091
std = 16.978534
RMS = 16.809088
_____
***Row Num = 125
Min = -22.000000
Max = 34.188000
Mean = 0.271341
std = 9.913138
RMS = 9.803597
***Row Num = 126
Min = -22.000000
Max = 34.188000
Mean = 0.271341
std = 9.913138
RMS = 9.803597
______
***Row Num = 127
Min = -22.000000
Max = 34.188000
Mean = 0.271341
std = 9.913138
RMS = 9.803597
_____
***Row Num = 128
Min = -76.938000
Max = 76.688000
Mean = 2.265659
std = 27.770052
RMS = 27.546003
***Row Num = 129
```

```
Min = -76.938000
Max = 76.688000
Mean = 2.265659
std = 27.770052
RMS = 27.546003
_____
***Row Num = 130
Min = -76.938000
Max = 76.688000
Mean = 2.265659
std = 27.770052
RMS = 27.546003
***Row Num = 131
Min = 2.812300
Max = 2.979000
Mean = 2.883107
std = 0.055000
RMS = 2.883619
_____
***Row Num = 132
Min = 3.060900
Max = 3.093200
Mean = 3.077236
std = 0.010808
RMS = 3.077255
***Row Num = 133
Min = 7.033200
Max = 7.138200
Mean = 7.085866
std = 0.023613
RMS = 7.085904
_____
***Row Num = 134
Min = 6.250900
Max = 7.256100
Mean = 6.803982
std = 0.292412
RMS = 6.810120
______
***Row Num = 135
Min = 2.882500
Max = 6.596500
Mean = 4.627745
std = 1.620807
RMS = 4.897279
***Row Num = 136
Min = 0.020836
```

```
Max = 9.928800
Mean = 5.757254
std = 4.168979
RMS = 7.080350
______
***Row Num = 137
Min = 0.897950
Max = 0.954100
Mean = 0.932274
std = 0.010462
RMS = 0.932331
_____
***Row Num = 138
Min = -0.386230
Max = -0.321780
Mean = -0.346791
std = 0.014852
RMS = 0.347102
_____
***Row Num = 139
Min = 0.059082
Max = 0.137700
Mean = 0.083507
std = 0.014943
RMS = 0.084804
______
***Row Num = 140
Min = -0.892090
Max = 1.191400
Mean = 0.083996
std = 0.813421
RMS = 0.808500
_____
***Row Num = 141
Min = 0.215330
Max = 0.936520
Mean = 0.495562
std = 0.179755
RMS = 0.526459
-----
***Row Num = 142
Min = -0.131840
Max = 0.733400
Mean = 0.298339
std = 0.221693
RMS = 0.370185
_____
***Row Num = 143
Min = -5.000000
Max = 3.000000
```

```
Mean = -0.818182
std = 1.244013
RMS = 1.477098
______
***Row Num = 144
Min = -3.000000
Max = 1.000000
Mean = -0.954545
std = 0.913835
RMS = 1.314257
***Row Num = 145
Min = -3.000000
Max = 0.000000
Mean = -1.250000
std = 0.967495
RMS = 1.573935
______
***Row Num = 146
Min = -4.000000
Max = 1.000000
Mean = -1.295455
std = 1.001848
RMS = 1.630672
_____
***Row Num = 147
Min = -3.000000
Max = 1.000000
Mean = -1.068182
std = 0.925045
RMS = 1.406155
_____
***Row Num = 148
Min = -3.000000
Max = 4.000000
Mean = -0.977273
std = 1.454562
RMS = 1.738599
______
***Row Num = 149
Min = -11.000000
Max = 29.000000
Mean = 0.068182
std = 5.707595
RMS = 5.642775
***Row Num = 150
Min = -5.000000
Max = 2.000000
Mean = -0.954545
```

```
std = 1.461992
RMS = 1.732051
_____
***Row Num = 151
Min = -46.000000
Max = 34.000000
Mean = -1.772727
std = 16.674537
RMS = 16.579012
_____
***Row Num = 152
Min = -30.000000
Max = 66.000000
Mean = -1.090909
std = 14.285817
RMS = 14.164617
***Row Num = 153
Min = -37.000000
Max = 24.000000
Mean = -3.295455
std = 10.208477
RMS = 10.616240
______
***Row Num = 154
Min = -36.000000
Max = 10.000000
Mean = -2.409091
std = 7.108194
RMS = 7.428447
***Row Num = 155
Min = -38.000000
Max = 41.000000
Mean = 1.250000
std = 11.539870
RMS = 11.476260
***Row Num = 156
Min = -13.000000
Max = 37.000000
Mean = 1.386364
std = 8.167479
RMS = 8.192291
_____
***Row Num = 157
Min = -32.000000
Max = 30.000000
Mean = -1.000000
std = 11.301369
```

```
RMS = 11.216870
***Row Num = 158
Min = -24.000000
Max = 27.000000
Mean = 0.590909
std = 10.345920
RMS = 10.244733
______
***Row Num = 159
Min = -27.500000
Max = 35.688000
Mean = -0.237170
std = 10.504009
RMS = 10.386667
_____
***Row Num = 160
Min = -27.500000
Max = 35.688000
Mean = -0.237170
std = 10.504009
RMS = 10.386667
_____
***Row Num = 161
Min = -27.500000
Max = 35.688000
Mean = -0.237170
std = 10.504009
RMS = 10.386667
***Row Num = 162
Min = -61.125000
Max = 83.750000
Mean = 5.789830
std = 26.571525
RMS = 26.898357
______
***Row Num = 163
Min = -61.125000
Max = 83.750000
Mean = 5.789830
std = 26.571525
RMS = 26.898357
***Row Num = 164
Min = -61.125000
Max = 83.750000
Mean = 5.789830
std = 26.571525
RMS = 26.898357
```

```
_____
***Row Num = 165
Min = 2.828500
Max = 2.947400
Mean = 2.862336
std = 0.031550
RMS = 2.862506
_____
***Row Num = 166
Min = 3.056100
Max = 3.096200
Mean = 3.076361
std = 0.013293
RMS = 3.076389
***Row Num = 167
Min = 7.104600
Max = 7.219100
Mean = 7.139973
std = 0.022974
RMS = 7.140009
______
***Row Num = 168
Min = 6.234800
Max = 7.288700
Mean = 6.772925
std = 0.295369
RMS = 6.779216
_____
***Row Num = 169
Min = 2.907300
Max = 6.548100
Mean = 4.736620
std = 1.585064
RMS = 4.989078
***Row Num = 170
Min = 0.170360
Max = 9.942000
Mean = 5.596829
std = 4.236121
RMS = 6.990091
_____
***Row Num = 171
Min = 0.892580
Max = 0.960940
Mean = 0.934803
std = 0.011875
RMS = 0.934877
```

```
***Row Num = 172
Min = -0.380370
Max = -0.301760
Mean = -0.339656
std = 0.018244
RMS = 0.340134
***Row Num = 173
Min = 0.066895
Max = 0.140140
Mean = 0.086437
std = 0.013280
RMS = 0.087428
______
***Row Num = 174
Min = -0.840330
Max = 1.318400
Mean = 0.402413
std = 0.806601
RMS = 0.893171
_____
***Row Num = 175
Min = 0.165530
Max = 0.698240
Mean = 0.381459
std = 0.176504
RMS = 0.419472
***Row Num = 176
Min = -0.274410
Max = 0.583010
Mean = 0.181852
std = 0.173662
RMS = 0.250086
______
***Row Num = 177
Min = -4.000000
Max = 1.000000
Mean = -1.204545
std = 1.192604
RMS = 1.685500
_____
***Row Num = 178
Min = -3.000000
Max = 2.000000
Mean = -1.022727
std = 1.248043
RMS = 1.602555
***Row Num = 179
```

```
Min = -3.000000
Max = 1.000000
Mean = -1.159091
std = 0.986966
RMS = 1.515076
_____
***Row Num = 180
Min = -3.000000
Max = 2.000000
Mean = -0.954545
std = 1.077347
RMS = 1.430194
***Row Num = 181
Min = -3.000000
Max = 2.000000
Mean = -1.022727
std = 1.045225
RMS = 1.453835
_____
***Row Num = 182
Min = -3.000000
Max = 1.000000
Mean = -1.159091
std = 1.119451
RMS = 1.602555
______
***Row Num = 183
Min = -6.000000
Max = 4.000000
Mean = -0.886364
std = 1.919495
RMS = 2.094365
***Row Num = 184
Min = -4.000000
Max = 2.000000
Mean = -1.227273
std = 1.291540
RMS = 1.770978
______
***Row Num = 185
Min = -52.000000
Max = 34.000000
Mean = -4.659091
std = 21.403046
RMS = 21.665326
***Row Num = 186
Min = -30.000000
```

```
Max = 35.000000
Mean = -0.613636
std = 11.934347
RMS = 11.813898
______
***Row Num = 187
Min = -13.000000
Max = 75.000000
Mean = 1.500000
std = 12.403113
RMS = 12.352769
***Row Num = 188
Min = -7.000000
Max = 33.000000
Mean = 0.818182
std = 6.875209
RMS = 6.845702
_____
***Row Num = 189
Min = -20.000000
Max = 74.000000
Mean = 3.250000
std = 16.788874
RMS = 16.912206
______
***Row Num = 190
Min = -31.000000
Max = 27.000000
Mean = 0.477273
std = 9.038647
RMS = 8.948083
______
***Row Num = 191
Min = -32.000000
Max = 12.000000
Mean = -1.181818
std = 8.035597
RMS = 8.031189
-----
***Row Num = 192
Min = -31.000000
Max = 47.000000
Mean = -3.045455
std = 13.278685
RMS = 13.475567
***Row Num = 193
Min = -17.750000
Max = 33.500000
```

```
Mean = 0.586648
std = 9.072743
RMS = 8.988216
______
***Row Num = 194
Min = -17.750000
Max = 33.500000
Mean = 0.586648
std = 9.072743
RMS = 8.988216
***Row Num = 195
Min = -17.750000
Max = 33.500000
Mean = 0.586648
std = 9.072743
RMS = 8.988216
______
***Row Num = 196
Min = -59.875000
Max = 34.438000
Mean = -5.245773
std = 18.109462
RMS = 18.655222
***Row Num = 197
Min = -59.875000
Max = 34.438000
Mean = -5.245773
std = 18.109462
RMS = 18.655222
***Row Num = 198
Min = -59.875000
Max = 34.438000
Mean = -5.245773
std = 18.109462
RMS = 18.655222
______
***Row Num = 199
Min = 2.836600
Max = 2.971400
Mean = 2.904995
std = 0.039090
RMS = 2.905252
***Row Num = 200
Min = 3.047900
Max = 3.094100
Mean = 3.065830
```

```
std = 0.015320
RMS = 3.065867
______
***Row Num = 201
Min = 7.106500
Max = 7.218400
Mean = 7.146675
std = 0.023924
RMS = 7.146714
_____
***Row Num = 202
Min = 6.278400
Max = 7.447900
Mean = 6.926420
std = 0.217091
RMS = 6.929744
***Row Num = 203
Min = 2.827200
Max = 6.473200
Mean = 4.050064
std = 1.577604
RMS = 4.339964
______
***Row Num = 204
Min = 0.130300
Max = 9.919700
Mean = 6.251286
std = 3.729783
RMS = 7.257665
***Row Num = 205
Min = 0.897950
Max = 0.957520
Mean = 0.931352
std = 0.009169
RMS = 0.931396
***Row Num = 206
Min = -0.373050
Max = -0.320800
Mean = -0.345959
std = 0.012371
RMS = 0.346175
_____
***Row Num = 207
Min = 0.061035
Max = 0.114260
Mean = 0.088168
std = 0.010973
```

```
RMS = 0.088833
***Row Num = 208
Min = -0.899410
Max = 1.282700
Mean = 0.038399
std = 0.818638
RMS = 0.810192
______
***Row Num = 209
Min = 0.143070
Max = 0.834470
Mean = 0.520764
std = 0.165256
RMS = 0.545787
_____
***Row Num = 210
Min = -0.060547
Max = 0.938480
Mean = 0.294811
std = 0.194705
RMS = 0.352082
_____
***Row Num = 211
Min = -4.000000
Max = 0.000000
Mean = -1.000000
std = 0.988304
RMS = 1.398051
***Row Num = 212
Min = -3.000000
Max = 2.000000
Mean = -0.681818
std = 1.073415
RMS = 1.261312
______
***Row Num = 213
Min = -2.000000
Max = 2.000000
Mean = -0.977273
std = 1.067242
RMS = 1.438117
***Row Num = 214
Min = -3.000000
Max = 1.000000
Mean = -1.022727
std = 1.130726
RMS = 1.515076
```

_____ ***Row Num = 215Min = -3.000000Max = 0.000000Mean = -1.045455std = 0.861436RMS = 1.348400_____ ***Row Num = 216Min = -3.000000Max = 1.000000Mean = -0.613636std = 0.920463RMS = 1.097518***Row Num = 217Min = -4.000000Max = 5.000000Mean = -0.704545std = 1.692384RMS = 1.815339______ ***Row Num = 218Min = -3.000000Max = 3.000000Mean = -0.863636std = 1.268416RMS = 1.522558_____ ***Row Num = 219Min = -65.000000Max = 33.000000Mean = -1.681818std = 20.379850RMS = 20.217005***Row Num = 220Min = -62.000000Max = 32.000000Mean = -2.363636std = 12.529205RMS = 12.609520______ ***Row Num = 221Min = -41.000000Max = 76.000000Mean = 1.181818std = 20.831855RMS = 20.627651

```
***Row Num = 222
Min = -14.000000
Max = 24.000000
Mean = -0.522727
std = 7.365819
RMS = 7.300374
***Row Num = 223
Min = -39.000000
Max = 18.000000
Mean = -1.772727
std = 12.218674
RMS = 12.208417
______
***Row Num = 224
Min = -52.000000
Max = 32.000000
Mean = 0.386364
std = 13.786100
RMS = 13.634015
_____
***Row Num = 225
Min = -27.000000
Max = 26.000000
Mean = -0.613636
std = 10.876080
RMS = 10.769274
***Row Num = 226
Min = -37.000000
Max = 27.000000
Mean = 1.068182
std = 12.852287
RMS = 12.750223
______
***Row Num = 227
Min = -10.188000
Max = 22.813000
Mean = 1.129284
std = 6.655222
RMS = 6.675375
_____
***Row Num = 228
Min = -10.188000
Max = 22.813000
Mean = 1.129284
std = 6.655222
RMS = 6.675375
***Row Num = 229
```

```
Min = -10.188000
Max = 22.813000
Mean = 1.129284
std = 6.655222
RMS = 6.675375
_____
***Row Num = 230
Min = -43.688000
Max = 43.938000
Mean = 0.616466
std = 19.982496
RMS = 19.763734
***Row Num = 231
Min = -43.688000
Max = 43.938000
Mean = 0.616466
std = 19.982496
RMS = 19.763734
_____
***Row Num = 232
Min = -43.688000
Max = 43.938000
Mean = 0.616466
std = 19.982496
RMS = 19.763734
______
***Row Num = 233
Min = 2.861100
Max = 2.974600
Mean = 2.907452
std = 0.035874
RMS = 2.907669
_____
***Row Num = 234
Min = 3.063600
Max = 3.091100
Mean = 3.079252
std = 0.008112
RMS = 3.079263
______
***Row Num = 235
Min = 7.159700
Max = 7.245600
Mean = 7.189130
std = 0.018333
RMS = 7.189152
***Row Num = 236
Min = 6.279000
```

```
Max = 7.069300
Mean = 6.733625
std = 0.236760
RMS = 6.737692
______
***Row Num = 237
Min = 3.000300
Max = 6.502500
Mean = 4.879580
std = 1.528183
RMS = 5.108088
***Row Num = 238
Min = 0.010064
Max = 9.994300
Mean = 5.779733
std = 4.332020
RMS = 7.193414
______
***Row Num = 239
Min = 0.869140
Max = 0.954100
Mean = 0.911864
std = 0.015671
RMS = 0.911996
______
***Row Num = 240
Min = -0.447750
Max = -0.335940
Mean = -0.388894
std = 0.029229
RMS = 0.389966
______
***Row Num = 241
Min = 0.066406
Max = 0.190430
Mean = 0.117720
std = 0.026978
RMS = 0.120703
-----
***Row Num = 242
Min = -0.926760
Max = 1.423800
Mean = 0.103792
std = 0.860458
RMS = 0.856932
_____
***Row Num = 243
Min = 0.200680
Max = 0.937010
```

```
Mean = 0.465387
std = 0.184682
RMS = 0.499918
______
***Row Num = 244
Min = -0.159180
Max = 0.724610
Mean = 0.132591
std = 0.188904
RMS = 0.229029
***Row Num = 245
Min = -4.000000
Max = 7.000000
Mean = -0.977273
std = 1.810674
RMS = 2.039385
______
***Row Num = 246
Min = -3.000000
Max = 5.000000
Mean = -0.431818
std = 1.662133
RMS = 1.698930
***Row Num = 247
Min = -5.000000
Max = 3.000000
Mean = -0.909091
std = 1.394644
RMS = 1.651446
***Row Num = 248
Min = -4.000000
Max = 1.000000
Mean = -1.204545
std = 1.024798
RMS = 1.573935
______
***Row Num = 249
Min = -3.000000
Max = 1.000000
Mean = -1.136364
std = 0.978630
RMS = 1.492405
***Row Num = 250
Min = -8.000000
Max = 5.000000
Mean = -0.840909
```

```
std = 1.803655
RMS = 1.971386
_____
***Row Num = 251
Min = -41.000000
Max = 19.000000
Mean = -0.840909
std = 7.198007
RMS = 7.165257
_____
***Row Num = 252
Min = -8.000000
Max = 3.000000
Mean = -0.681818
std = 1.926229
RMS = 2.022600
***Row Num = 253
Min = -47.000000
Max = 42.000000
Mean = -3.386364
std = 17.303335
RMS = 17.437551
______
***Row Num = 254
Min = -21.000000
Max = 44.000000
Mean = -0.227273
std = 9.557327
RMS = 9.450830
***Row Num = 255
Min = -35.000000
Max = 23.000000
Mean = -1.477273
std = 8.793466
RMS = 8.817596
***Row Num = 256
Min = -14.000000
Max = 5.000000
Mean = -1.409091
std = 3.871891
RMS = 4.078770
_____
***Row Num = 257
Min = -37.000000
Max = 43.000000
Mean = -1.318182
std = 10.351436
```

```
RMS = 10.317681
______
***Row Num = 258
Min = -71.000000
Max = 38.000000
Mean = -0.704545
std = 16.650413
RMS = 16.475188
______
***Row Num = 259
Min = -34.000000
Max = 52.000000
Mean = -0.704545
std = 12.392007
RMS = 12.270623
_____
***Row Num = 260
Min = -23.000000
Max = 49.000000
Mean = -0.931818
std = 13.737401
RMS = 13.612327
_____
***Row Num = 261
Min = -17.250000
Max = 44.125000
Mean = 2.379284
std = 11.136681
RMS = 11.263565
***Row Num = 262
Min = -17.250000
Max = 44.125000
Mean = 2.379284
std = 11.136681
RMS = 11.263565
______
***Row Num = 263
Min = -17.250000
Max = 44.125000
Mean = 2.379284
std = 11.136681
RMS = 11.263565
***Row Num = 264
Min = -97.188000
Max = 118.440000
Mean = -2.600830
std = 32.423195
RMS = 32.157978
```

```
_____
***Row Num = 265
Min = -97.188000
Max = 118.440000
Mean = -2.600830
std = 32.423195
RMS = 32.157978
_____
***Row Num = 266
Min = -97.188000
Max = 118.440000
Mean = -2.600830
std = 32.423195
RMS = 32.157978
***Row Num = 267
Min = 2.924500
Max = 3.094900
Mean = 2.975843
std = 0.042713
RMS = 2.976143
______
***Row Num = 268
Min = 3.103100
Max = 3.212700
Mean = 3.162268
std = 0.043374
RMS = 3.162559
_____
***Row Num = 269
Min = 6.855800
Max = 7.130500
Mean = 6.992207
std = 0.117812
RMS = 6.993177
***Row Num = 270
Min = 6.401900
Max = 7.657200
Mean = 7.138705
std = 0.304635
RMS = 7.145054
_____
***Row Num = 271
Min = 2.888400
Max = 6.612000
Mean = 4.671852
std = 1.720563
RMS = 4.971847
```

```
***Row Num = 272
Min = 0.013754
Max = 9.942100
Mean = 5.469072
std = 4.057456
RMS = 6.782296
***Row Num = 273
Min = 0.902830
Max = 0.948240
Mean = 0.922852
std = 0.009258
RMS = 0.922897
______
***Row Num = 274
Min = -0.440920
Max = -0.311520
Mean = -0.367277
std = 0.021447
RMS = 0.367888
_____
***Row Num = 275
Min = 0.061523
Max = 0.133790
Mean = 0.095825
std = 0.014979
RMS = 0.096962
***Row Num = 276
Min = -0.933590
Max = 1.435500
Mean = 0.022449
std = 0.815752
RMS = 0.806741
______
***Row Num = 277
Min = 0.210450
Max = 0.958500
Mean = 0.505450
std = 0.161828
RMS = 0.530163
_____
***Row Num = 278
Min = -0.316410
Max = 0.729980
Mean = 0.261808
std = 0.215454
RMS = 0.337504
***Row Num = 279
```

```
Min = -3.000000
Max = 1.000000
Mean = -0.886364
std = 1.039139
RMS = 1.356801
_____
***Row Num = 280
Min = -4.000000
Max = 1.000000
Mean = -1.272727
std = 1.042440
RMS = 1.637626
***Row Num = 281
Min = -3.000000
Max = 1.000000
Mean = -1.090909
std = 0.830191
RMS = 1.365151
_____
***Row Num = 282
Min = -3.000000
Max = 1.000000
Mean = -0.840909
std = 0.913546
RMS = 1.233988
______
***Row Num = 283
Min = -3.000000
Max = 0.000000
Mean = -1.181818
std = 0.842828
RMS = 1.445998
***Row Num = 284
Min = -2.000000
Max = 2.000000
Mean = -0.795455
std = 1.024798
RMS = 1.288057
______
***Row Num = 285
Min = -15.000000
Max = 16.000000
Mean = -0.750000
std = 3.773377
RMS = 3.804901
***Row Num = 286
Min = -7.000000
```

```
Max = 2.000000
Mean = -1.022727
std = 1.547521
RMS = 1.840207
______
***Row Num = 287
Min = -36.000000
Max = 23.000000
Mean = -3.022727
std = 15.049513
RMS = 15.181478
_____
***Row Num = 288
Min = -24.000000
Max = 15.000000
Mean = -0.022727
std = 7.394179
RMS = 7.309707
_____
***Row Num = 289
Min = -62.000000
Max = 11.000000
Mean = -2.750000
std = 10.899381
RMS = 11.120211
______
***Row Num = 290
Min = -13.000000
Max = 10.000000
Mean = -1.090909
std = 3.709311
RMS = 3.825750
______
***Row Num = 291
Min = -17.000000
Max = 18.000000
Mean = -0.318182
std = 5.281705
RMS = 5.231026
-----
***Row Num = 292
Min = -46.000000
Max = 19.000000
Mean = -1.977273
std = 10.478080
RMS = 10.545357
_____
***Row Num = 293
Min = -33.000000
Max = 13.000000
```

```
Mean = -2.204545
std = 8.737994
RMS = 8.915003
______
***Row Num = 294
Min = -18.000000
Max = 26.000000
Mean = -1.659091
std = 8.954519
RMS = 9.006311
***Row Num = 295
Min = -13.750000
Max = 27.813000
Mean = 0.826716
std = 8.224847
RMS = 8.172767
______
***Row Num = 296
Min = -13.750000
Max = 27.813000
Mean = 0.826716
std = 8.224847
RMS = 8.172767
_____
***Row Num = 297
Min = -13.750000
Max = 27.813000
Mean = 0.826716
std = 8.224847
RMS = 8.172767
_____
***Row Num = 298
Min = -81.000000
Max = 56.063000
Mean = 8.548364
std = 27.435968
RMS = 28.437639
______
***Row Num = 299
Min = -81.000000
Max = 56.063000
Mean = 8.548364
std = 27.435968
RMS = 28.437639
***Row Num = 300
Min = -81.000000
Max = 56.063000
Mean = 8.548364
```

```
std = 27.435968
RMS = 28.437639
_____
***Row Num = 301
Min = 2.881900
Max = 2.998600
Mean = 2.918482
std = 0.032369
RMS = 2.918657
_____
***Row Num = 302
Min = 3.102300
Max = 3.132800
Mean = 3.121766
std = 0.008939
RMS = 3.121778
***Row Num = 303
Min = 7.149600
Max = 7.262300
Mean = 7.209036
std = 0.034343
RMS = 7.209116
______
***Row Num = 304
Min = 6.332300
Max = 7.394400
Mean = 6.867980
std = 0.290398
RMS = 6.873977
***Row Num = 305
Min = 2.924700
Max = 6.623900
Mean = 4.924677
std = 1.585566
RMS = 5.168107
***Row Num = 306
Min = 0.044496
Max = 9.987200
Mean = 7.991350
std = 2.940907
RMS = 8.503766
_____
***Row Num = 307
Min = 0.883790
Max = 0.964360
Mean = 0.925959
std = 0.012998
```

```
RMS = 0.926048
______
***Row Num = 308
Min = -0.422850
Max = -0.301760
Mean = -0.361439
std = 0.023827
RMS = 0.362206
_____
***Row Num = 309
Min = 0.032227
Max = 0.157710
Mean = 0.094149
std = 0.021832
RMS = 0.096591
_____
***Row Num = 310
Min = -0.901370
Max = 1.302700
Mean = -0.031185
std = 0.802051
RMS = 0.793498
_____
***Row Num = 311
Min = 0.148440
Max = 0.839360
Mean = 0.488803
std = 0.178036
RMS = 0.519523
***Row Num = 312
Min = -0.184570
Max = 0.812500
Mean = 0.227783
std = 0.232527
RMS = 0.323613
______
***Row Num = 313
Min = -3.000000
Max = 3.000000
Mean = -0.704545
std = 1.339551
RMS = 1.500000
***Row Num = 314
Min = -15.000000
Max = 2.000000
Mean = -1.636364
std = 2.382991
RMS = 2.868322
```

```
_____
***Row Num = 315
Min = -4.000000
Max = 1.000000
Mean = -1.113636
std = 1.261522
RMS = 1.671961
_____
***Row Num = 316
Min = -3.000000
Max = 1.000000
Mean = -0.795455
std = 1.047245
RMS = 1.305582
***Row Num = 317
Min = -6.000000
Max = 1.000000
Mean = -1.272727
std = 1.300512
RMS = 1.809068
______
***Row Num = 318
Min = -9.000000
Max = 7.000000
Mean = -0.863636
std = 2.267987
RMS = 2.402650
_____
***Row Num = 319
Min = -27.000000
Max = 25.000000
Mean = -0.045455
std = 6.860587
RMS = 6.782330
______
***Row Num = 320
Min = -5.000000
Max = 3.000000
Mean = -0.909091
std = 1.596773
RMS = 1.821588
______
***Row Num = 321
Min = -48.000000
Max = 43.000000
Mean = -1.659091
std = 20.972788
RMS = 20.799366
```

```
***Row Num = 322
Min = -36.000000
Max = 13.000000
Mean = -3.272727
std = 9.529303
RMS = 9.972690
***Row Num = 323
Min = -65.000000
Max = 21.000000
Mean = -4.136364
std = 12.435117
RMS = 12.970246
______
***Row Num = 324
Min = -18.000000
Max = 5.000000
Mean = -1.863636
std = 4.262279
RMS = 4.607306
_____
***Row Num = 325
Min = -32.000000
Max = 61.000000
Mean = -0.977273
std = 11.932930
RMS = 11.836961
***Row Num = 326
Min = -40.000000
Max = 64.000000
Mean = -1.022727
std = 16.429538
RMS = 16.273933
______
***Row Num = 327
Min = -21.000000
Max = 28.000000
Mean = 1.136364
std = 10.038509
RMS = 9.988630
_____
***Row Num = 328
Min = -34.000000
Max = 65.000000
Mean = -0.886364
std = 14.480486
RMS = 14.342404
***Row Num = 329
```

```
Min = -18.063000
Max = 35.688000
Mean = 0.941739
std = 9.834779
RMS = 9.767881
_____
***Row Num = 330
Min = -18.063000
Max = 35.688000
Mean = 0.941739
std = 9.834779
RMS = 9.767881
***Row Num = 331
Min = -18.063000
Max = 35.688000
Mean = 0.941739
std = 9.834779
RMS = 9.767881
_____
***Row Num = 332
Min = -88.500000
Max = 79.063000
Mean = 4.545511
std = 30.361315
RMS = 30.356563
***Row Num = 333
Min = -88.500000
Max = 79.063000
Mean = 4.545511
std = 30.361315
RMS = 30.356563
_____
***Row Num = 334
Min = -88.500000
Max = 79.063000
Mean = 4.545511
std = 30.361315
RMS = 30.356563
______
***Row Num = 335
Min = 2.867800
Max = 3.027100
Mean = 2.916316
std = 0.038829
RMS = 2.916569
***Row Num = 336
Min = 3.076400
```

```
Max = 3.130100
Mean = 3.110827
std = 0.014315
RMS = 3.110859
______
***Row Num = 337
Min = 7.285200
Max = 7.439600
Mean = 7.353795
std = 0.050600
RMS = 7.353966
***Row Num = 338
Min = 6.276300
Max = 7.450900
Mean = 6.992620
std = 0.346768
RMS = 7.001018
______
***Row Num = 339
Min = 2.882700
Max = 6.604700
Mean = 4.958832
std = 1.626585
RMS = 5.213028
______
***Row Num = 340
Min = 0.023510
Max = 9.926600
Mean = 6.854541
std = 3.747649
RMS = 7.791688
______
***Row Num = 341
Min = 0.882320
Max = 0.943850
Mean = 0.929332
std = 0.010468
RMS = 0.929390
-----
***Row Num = 342
Min = -0.402340
Max = -0.312500
Mean = -0.351119
std = 0.018339
RMS = 0.351587
_____
***Row Num = 343
Min = 0.036621
Max = 0.136230
```

```
Mean = 0.091619
std = 0.019614
RMS = 0.093649
______
***Row Num = 344
Min = -0.925290
Max = 1.439500
Mean = 0.281028
std = 0.852695
RMS = 0.888561
***Row Num = 345
Min = 0.196290
Max = 0.685060
Mean = 0.410333
std = 0.159199
RMS = 0.439479
______
***Row Num = 346
Min = -0.257320
Max = 0.693850
Mean = 0.192183
std = 0.172761
RMS = 0.257104
***Row Num = 347
Min = -7.000000
Max = 4.000000
Mean = -1.204545
std = 1.759751
RMS = 2.115957
_____
***Row Num = 348
Min = -5.000000
Max = 11.000000
Mean = -0.568182
std = 2.171675
RMS = 2.220770
______
***Row Num = 349
Min = -3.000000
Max = 3.000000
Mean = -1.136364
std = 1.192826
RMS = 1.637626
***Row Num = 350
Min = -4.000000
Max = 1.000000
Mean = -1.068182
```

```
std = 1.065260
RMS = 1.500000
______
***Row Num = 351
Min = -3.000000
Max = 1.000000
Mean = -1.272727
std = 0.973214
RMS = 1.595448
_____
***Row Num = 352
Min = -7.000000
Max = 7.000000
Mean = -0.818182
std = 1.991525
RMS = 2.132007
______
***Row Num = 353
Min = -14.000000
Max = 29.000000
Mean = 0.318182
std = 6.283136
RMS = 6.219471
______
***Row Num = 354
Min = -5.000000
Max = 3.000000
Mean = -1.477273
std = 1.758549
RMS = 2.281347
***Row Num = 355
Min = -58.000000
Max = 48.000000
Mean = -3.386364
std = 20.238365
RMS = 20.291624
***Row Num = 356
Min = -68.000000
Max = 72.000000
Mean = -0.250000
std = 18.629965
RMS = 18.418740
_____
***Row Num = 357
Min = -11.000000
Max = 59.000000
Mean = 2.000000
std = 13.176794
```

```
RMS = 13.178840
***Row Num = 358
Min = -7.000000
Max = 14.000000
Mean = -0.477273
std = 3.884906
RMS = 3.870048
______
***Row Num = 359
Min = -43.000000
Max = 12.000000
Mean = -2.613636
std = 8.319816
RMS = 8.630022
_____
***Row Num = 360
Min = -24.000000
Max = 33.000000
Mean = -0.590909
std = 9.619066
RMS = 9.527472
_____
***Row Num = 361
Min = -23.000000
Max = 15.000000
Mean = -0.409091
std = 7.604522
RMS = 7.528733
***Row Num = 362
Min = -24.000000
Max = 27.000000
Mean = -1.659091
std = 9.313514
RMS = 9.355358
______
***Row Num = 363
Min = -25.938000
Max = 32.063000
Mean = 1.480136
std = 8.694837
RMS = 8.721973
***Row Num = 364
Min = -25.938000
Max = 32.063000
Mean = 1.480136
std = 8.694837
RMS = 8.721973
```

```
_____
***Row Num = 365
Min = -25.938000
Max = 32.063000
Mean = 1.480136
std = 8.694837
RMS = 8.721973
_____
***Row Num = 366
Min = -81.375000
Max = 99.750000
Mean = -0.970159
std = 30.326754
RMS = 29.995844
***Row Num = 367
Min = -81.375000
Max = 99.750000
Mean = -0.970159
std = 30.326754
RMS = 29.995844
______
***Row Num = 368
Min = -81.375000
Max = 99.750000
Mean = -0.970159
std = 30.326754
RMS = 29.995844
_____
***Row Num = 369
Min = 2.864800
Max = 2.995700
Mean = 2.912273
std = 0.029810
RMS = 2.912422
***Row Num = 370
Min = 3.079100
Max = 3.104700
Mean = 3.090880
std = 0.007702
RMS = 3.090889
______
***Row Num = 371
Min = 7.525100
Max = 7.621500
Mean = 7.573536
std = 0.035038
RMS = 7.573616
```

```
***Row Num = 372
Min = 6.257400
Max = 7.447000
Mean = 6.929000
std = 0.214539
RMS = 6.932245
***Row Num = 373
Min = 2.887000
Max = 6.586200
Mean = 4.339000
std = 1.667629
RMS = 4.641627
______
***Row Num = 374
Min = 0.021973
Max = 9.990400
Mean = 7.917398
std = 2.626550
RMS = 8.332296
_____
***Row Num = 375
Min = 0.899410
Max = 0.963870
Mean = 0.928423
std = 0.010655
RMS = 0.928482
***Row Num = 376
Min = -0.419430
Max = -0.313480
Mean = -0.352339
std = 0.018747
RMS = 0.352826
______
***Row Num = 377
Min = 0.064453
Max = 0.132810
Mean = 0.088768
std = 0.012687
RMS = 0.089649
_____
***Row Num = 378
Min = -0.943360
Max = 1.311500
Mean = 0.233465
std = 0.829905
RMS = 0.852992
***Row Num = 379
```

```
Min = 0.150880
Max = 1.005900
Mean = 0.428168
std = 0.184989
RMS = 0.465587
_____
***Row Num = 380
Min = -0.083008
Max = 0.615230
Mean = 0.205189
std = 0.167727
RMS = 0.263809
***Row Num = 381
Min = -4.000000
Max = 1.000000
Mean = -1.090909
std = 1.095831
RMS = 1.537412
_____
***Row Num = 382
Min = -3.000000
Max = 1.000000
Mean = -1.022727
std = 0.976197
RMS = 1.406155
______
***Row Num = 383
Min = -3.000000
Max = 1.000000
Mean = -1.159091
std = 1.140036
RMS = 1.616674
***Row Num = 384
Min = -3.000000
Max = 1.000000
Mean = -1.045455
std = 1.010516
RMS = 1.445998
______
***Row Num = 385
Min = -3.000000
Max = 2.000000
Mean = -1.045455
std = 1.077347
RMS = 1.492405
***Row Num = 386
Min = -3.000000
```

```
Max = 1.000000
Mean = -1.272727
std = 0.973214
RMS = 1.595448
______
***Row Num = 387
Min = -4.000000
Max = 4.000000
Mean = -0.545455
std = 1.717956
RMS = 1.783765
***Row Num = 388
Min = -6.000000
Max = 2.000000
Mean = -1.136364
std = 1.503344
RMS = 1.870829
_____
***Row Num = 389
Min = -36.000000
Max = 21.000000
Mean = -1.750000
std = 12.992171
RMS = 12.962358
_____
***Row Num = 390
Min = -19.000000
Max = 38.000000
Mean = -0.386364
std = 9.158084
RMS = 9.061657
______
***Row Num = 391
Min = -18.000000
Max = 29.000000
Mean = 0.250000
std = 7.411885
RMS = 7.331439
-----
***Row Num = 392
Min = -11.000000
Max = 11.000000
Mean = -0.386364
std = 3.571306
RMS = 3.551568
_____
***Row Num = 393
Min = -9.000000
Max = 95.000000
```

```
Mean = 2.909091
std = 15.139381
RMS = 15.246460
______
***Row Num = 394
Min = -29.000000
Max = 13.000000
Mean = -2.204545
std = 8.345949
RMS = 8.540013
***Row Num = 395
Min = -32.000000
Max = 30.000000
Mean = -1.568182
std = 10.323596
RMS = 10.325388
______
***Row Num = 396
Min = -36.000000
Max = 22.000000
Mean = -2.204545
std = 10.413720
RMS = 10.528101
***Row Num = 397
Min = -14.500000
Max = 30.250000
Mean = 0.982955
std = 7.632512
RMS = 7.609038
***Row Num = 398
Min = -14.500000
Max = 30.250000
Mean = 0.982955
std = 7.632512
RMS = 7.609038
______
***Row Num = 399
Min = -14.500000
Max = 30.250000
Mean = 0.982955
std = 7.632512
RMS = 7.609038
***Row Num = 400
Min = -87.250000
Max = 125.560000
Mean = -0.630705
```

```
std = 30.554122
RMS = 30.211504
_____
***Row Num = 401
Min = -87.250000
Max = 125.560000
Mean = -0.630705
std = 30.554122
RMS = 30.211504
_____
***Row Num = 402
Min = -87.250000
Max = 125.560000
Mean = -0.630705
std = 30.554122
RMS = 30.211504
***Row Num = 403
Min = 2.852300
Max = 2.968800
Mean = 2.904843
std = 0.030316
RMS = 2.904998
______
***Row Num = 404
Min = 3.081600
Max = 3.110800
Mean = 3.095514
std = 0.009057
RMS = 3.095527
***Row Num = 405
Min = 7.634600
Max = 7.704900
Mean = 7.660509
std = 0.015234
RMS = 7.660524
***Row Num = 406
Min = 6.174200
Max = 7.329000
Mean = 6.892752
std = 0.244978
RMS = 6.897005
_____
***Row Num = 407
Min = 2.882300
Max = 6.653600
Mean = 4.467439
std = 1.693670
```

```
RMS = 4.770884
***Row Num = 408
Min = 0.012070
Max = 9.964700
Mean = 7.576592
std = 3.057691
RMS = 8.157312
______
***Row Num = 409
Min = 0.901860
Max = 0.970210
Mean = 0.927645
std = 0.013428
RMS = 0.927740
_____
***Row Num = 410
Min = -0.440920
Max = -0.280760
Mean = -0.354703
std = 0.029298
RMS = 0.355884
_____
***Row Num = 411
Min = 0.041992
Max = 0.138180
Mean = 0.089922
std = 0.018070
RMS = 0.091679
***Row Num = 412
Min = -0.980470
Max = 1.538100
Mean = 0.305420
std = 0.812304
RMS = 0.859141
______
***Row Num = 413
Min = 0.140630
Max = 0.749510
Mean = 0.439720
std = 0.181895
RMS = 0.475066
***Row Num = 414
Min = -0.581050
Max = 0.910160
Mean = 0.239369
std = 0.238416
RMS = 0.335929
```

```
_____
***Row Num = 415
Min = -4.000000
Max = 4.000000
Mean = -0.954545
std = 1.238051
RMS = 1.552125
______
***Row Num = 416
Min = -3.000000
Max = 7.000000
Mean = -0.750000
std = 1.713490
RMS = 1.852517
***Row Num = 417
Min = -3.000000
Max = 1.000000
Mean = -1.318182
std = 0.934425
RMS = 1.609630
______
***Row Num = 418
Min = -4.000000
Max = 1.000000
Mean = -1.000000
std = 1.120631
RMS = 1.492405
_____
***Row Num = 419
Min = -4.000000
Max = 1.000000
Mean = -1.250000
std = 1.163895
RMS = 1.698930
***Row Num = 420
Min = -9.000000
Max = 5.000000
Mean = -1.113636
std = 1.907341
RMS = 2.189853
______
***Row Num = 421
Min = -20.000000
Max = 20.000000
Mean = -0.818182
std = 5.217469
RMS = 5.222330
```

```
***Row Num = 422
Min = -4.000000
Max = 3.000000
Mean = -1.000000
std = 1.509659
RMS = 1.796461
***Row Num = 423
Min = -39.000000
Max = 22.000000
Mean = 1.931818
std = 11.883930
RMS = 11.905881
______
***Row Num = 424
Min = -14.000000
Max = 34.000000
Mean = 1.000000
std = 8.918233
RMS = 8.872839
_____
***Row Num = 425
Min = -40.000000
Max = 19.000000
Mean = -2.545455
std = 9.867623
RMS = 10.081486
***Row Num = 426
Min = -14.000000
Max = 12.000000
Mean = -1.295455
std = 4.359323
RMS = 4.500000
______
***Row Num = 427
Min = -61.000000
Max = 25.000000
Mean = -1.022727
std = 11.626931
RMS = 11.539458
_____
***Row Num = 428
Min = -16.000000
Max = 20.000000
Mean = -0.704545
std = 7.617543
RMS = 7.563369
***Row Num = 429
```

```
Min = -28.000000
Max = 31.000000
Mean = -2.454545
std = 9.893513
RMS = 10.083740
_____
***Row Num = 430
Min = -14.000000
Max = 25.000000
Mean = -0.545455
std = 8.050580
RMS = 7.977240
***Row Num = 431
Min = -22.563000
Max = 32.563000
Mean = 0.686068
std = 9.837864
RMS = 9.749596
_____
***Row Num = 432
Min = -22.563000
Max = 32.563000
Mean = 0.686068
std = 9.837864
RMS = 9.749596
______
***Row Num = 433
Min = -22.563000
Max = 32.563000
Mean = 0.686068
std = 9.837864
RMS = 9.749596
_____
***Row Num = 434
Min = -84.875000
Max = 58.063000
Mean = 5.349489
std = 31.191994
RMS = 31.296090
______
***Row Num = 435
Min = -84.875000
Max = 58.063000
Mean = 5.349489
std = 31.191994
RMS = 31.296090
***Row Num = 436
Min = -84.875000
```

```
Max = 58.063000
Mean = 5.349489
std = 31.191994
RMS = 31.296090
_____
***Row Num = 437
Min = 2.848600
Max = 2.970400
Mean = 2.903066
std = 0.032379
RMS = 2.903242
***Row Num = 438
Min = 3.086000
Max = 3.118300
Mean = 3.099414
std = 0.008602
RMS = 3.099425
_____
***Row Num = 439
Min = 7.725300
Max = 7.799300
Mean = 7.759693
std = 0.017175
RMS = 7.759712
______
***Row Num = 440
Min = 6.267600
Max = 7.296400
Mean = 6.836982
std = 0.257515
RMS = 6.841720
______
***Row Num = 441
Min = 2.839300
Max = 6.627700
Mean = 4.341161
std = 1.604065
RMS = 4.621713
-----
***Row Num = 442
Min = 0.012512
Max = 9.977200
Mean = 8.070872
std = 2.310127
RMS = 8.387751
_____
***Row Num = 443
Min = 0.895020
Max = 0.962890
```

```
Mean = 0.926569
std = 0.012210
RMS = 0.926648
______
***Row Num = 444
Min = -0.443360
Max = -0.286620
Mean = -0.357744
std = 0.029235
RMS = 0.358909
***Row Num = 445
Min = 0.050293
Max = 0.145020
Mean = 0.087647
std = 0.018186
RMS = 0.089471
______
***Row Num = 446
Min = -0.952150
Max = 1.599600
Mean = 0.232832
std = 0.860214
RMS = 0.881681
_____
***Row Num = 447
Min = 0.229490
Max = 0.684080
Mean = 0.405606
std = 0.156665
RMS = 0.434169
***Row Num = 448
Min = -0.315920
Max = 0.641110
Mean = 0.193582
std = 0.169736
RMS = 0.256183
______
***Row Num = 449
Min = -5.000000
Max = 2.000000
Mean = -0.931818
std = 1.469025
RMS = 1.725478
***Row Num = 450
Min = -7.000000
Max = 2.000000
Mean = -1.545455
```

```
std = 1.634718
RMS = 2.236068
_____
***Row Num = 451
Min = -3.000000
Max = 1.000000
Mean = -1.090909
std = 0.801690
RMS = 1.348400
_____
***Row Num = 452
Min = -3.000000
Max = 1.000000
Mean = -0.977273
std = 0.952076
RMS = 1.356801
***Row Num = 453
Min = -3.000000
Max = 0.000000
Mean = -1.022727
std = 0.820908
RMS = 1.305582
______
***Row Num = 454
Min = -3.000000
Max = 3.000000
Mean = -0.636364
std = 1.331041
RMS = 1.461630
***Row Num = 455
Min = -10.000000
Max = 6.000000
Mean = -0.181818
std = 2.661288
RMS = 2.637147
***Row Num = 456
Min = -4.000000
Max = 4.000000
Mean = -0.909091
std = 1.611271
RMS = 1.834022
_____
***Row Num = 457
Min = -39.000000
Max = 41.000000
Mean = -0.477273
std = 16.543795
```

```
RMS = 16.361679
______
***Row Num = 458
Min = -13.000000
Max = 19.000000
Mean = 0.340909
std = 6.826566
RMS = 6.757151
______
***Row Num = 459
Min = -23.000000
Max = 20.000000
Mean = -0.454545
std = 6.184958
RMS = 6.131143
_____
***Row Num = 460
Min = -16.000000
Max = 5.000000
Mean = -1.750000
std = 3.538000
RMS = 3.910940
______
***Row Num = 461
Min = -45.000000
Max = 14.000000
Mean = -1.272727
std = 10.171469
RMS = 10.135446
***Row Num = 462
Min = -72.000000
Max = 29.000000
Mean = -1.409091
std = 14.921996
RMS = 14.818600
______
***Row Num = 463
Min = -41.000000
Max = 25.000000
Mean = -1.931818
std = 11.552504
RMS = 11.582707
***Row Num = 464
Min = -61.000000
Max = 33.000000
Mean = -1.340909
std = 17.565748
RMS = 17.416685
```

```
_____
***Row Num = 465
Min = -26.625000
Max = 30.125000
Mean = 0.257114
std = 9.050884
RMS = 8.951136
_____
***Row Num = 466
Min = -26.625000
Max = 30.125000
Mean = 0.257114
std = 9.050884
RMS = 8.951136
***Row Num = 467
Min = -26.625000
Max = 30.125000
Mean = 0.257114
std = 9.050884
RMS = 8.951136
______
***Row Num = 468
Min = -91.750000
Max = 90.000000
Mean = 0.490091
std = 27.561988
RMS = 27.251391
_____
***Row Num = 469
Min = -91.750000
Max = 90.000000
Mean = 0.490091
std = 27.561988
RMS = 27.251391
______
***Row Num = 470
Min = -91.750000
Max = 90.000000
Mean = 0.490091
std = 27.561988
RMS = 27.251391
______
***Row Num = 471
Min = 2.845600
Max = 2.974500
Mean = 2.894618
std = 0.033452
RMS = 2.894807
```

```
***Row Num = 472
Min = 3.083600
Max = 3.119500
Mean = 3.100439
std = 0.011703
RMS = 3.100460
***Row Num = 473
Min = 7.795100
Max = 7.878300
Mean = 7.830043
std = 0.015673
RMS = 7.830059
______
***Row Num = 474
Min = 6.292100
Max = 7.371000
Mean = 6.915920
std = 0.245721
RMS = 6.920185
_____
***Row Num = 475
Min = 2.862200
Max = 6.655200
Mean = 4.480689
std = 1.691352
RMS = 4.782492
***Row Num = 476
Min = 0.003742
Max = 9.789800
Mean = 7.637011
std = 2.845109
RMS = 8.138465
______
***Row Num = 477
Min = 0.890630
Max = 0.959960
Mean = 0.931074
std = 0.012285
RMS = 0.931154
_____
***Row Num = 478
Min = -0.434080
Max = -0.306640
Mean = -0.348500
std = 0.021981
RMS = 0.349177
***Row Num = 479
```

```
Min = 0.039551
Max = 0.119630
Mean = 0.079224
std = 0.015753
RMS = 0.080740
_____
***Row Num = 480
Min = -0.945310
Max = 1.088400
Mean = 0.369718
std = 0.819813
RMS = 0.890792
***Row Num = 481
Min = 0.193360
Max = 0.874510
Mean = 0.368608
std = 0.169184
RMS = 0.404777
_____
***Row Num = 482
Min = -0.088379
Max = 0.640630
Mean = 0.138727
std = 0.174574
RMS = 0.221424
______
***Row Num = 483
Min = -8.000000
Max = 2.000000
Mean = -1.159091
std = 1.569227
RMS = 1.936492
***Row Num = 484
Min = -6.000000
Max = 4.000000
Mean = -1.159091
std = 1.524119
RMS = 1.900957
______
***Row Num = 485
Min = -4.000000
Max = 1.000000
Mean = -1.250000
std = 1.081020
RMS = 1.644550
***Row Num = 486
Min = -4.000000
```

```
Max = 1.000000
Mean = -1.204545
std = 1.069222
RMS = 1.602555
______
***Row Num = 487
Min = -3.000000
Max = 1.000000
Mean = -1.090909
std = 1.197248
RMS = 1.609630
***Row Num = 488
Min = -3.000000
Max = 1.000000
Mean = -1.000000
std = 0.940064
RMS = 1.365151
_____
***Row Num = 489
Min = -11.000000
Max = 8.000000
Mean = -0.772727
std = 3.333157
RMS = 3.384456
_____
***Row Num = 490
Min = -7.000000
Max = 1.000000
Mean = -1.227273
std = 1.582809
RMS = 1.988604
______
***Row Num = 491
Min = -47.000000
Max = 30.000000
Mean = -2.181818
std = 15.714418
RMS = 15.687285
-----
***Row Num = 492
Min = -26.000000
Max = 69.000000
Mean = -0.545455
std = 13.182890
RMS = 13.043633
***Row Num = 493
Min = -40.000000
Max = 50.000000
```

```
Mean = -1.272727
std = 11.125842
RMS = 11.072078
______
***Row Num = 494
Min = -10.000000
Max = 9.000000
Mean = -1.000000
std = 3.569900
RMS = 3.668044
***Row Num = 495
Min = -41.000000
Max = 64.000000
Mean = -1.159091
std = 14.438230
RMS = 14.320202
______
***Row Num = 496
Min = -17.000000
Max = 18.000000
Mean = -0.250000
std = 6.520540
RMS = 6.450863
_____
***Row Num = 497
Min = -45.000000
Max = 18.000000
Mean = -1.522727
std = 9.367158
RMS = 9.384465
***Row Num = 498
Min = -32.000000
Max = 41.000000
Mean = 0.590909
std = 11.396283
RMS = 11.281521
______
***Row Num = 499
Min = -24.750000
Max = 31.000000
Mean = 0.340932
std = 9.113382
RMS = 9.015674
***Row Num = 500
Min = -24.750000
Max = 31.000000
Mean = 0.340932
```

```
std = 9.113382
RMS = 9.015674
______
***Row Num = 501
Min = -24.750000
Max = 31.000000
Mean = 0.340932
std = 9.113382
RMS = 9.015674
_____
***Row Num = 502
Min = -84.125000
Max = 69.313000
Mean = -2.473011
std = 25.996583
RMS = 25.818181
______
***Row Num = 503
Min = -84.125000
Max = 69.313000
Mean = -2.473011
std = 25.996583
RMS = 25.818181
______
***Row Num = 504
Min = -84.125000
Max = 69.313000
Mean = -2.473011
std = 25.996583
RMS = 25.818181
***Row Num = 505
Min = 2.820800
Max = 2.955700
Mean = 2.867018
std = 0.032888
RMS = 2.867203
***Row Num = 506
Min = 3.061500
Max = 3.108900
Mean = 3.082448
std = 0.015382
RMS = 3.082485
_____
***Row Num = 507
Min = 7.818700
Max = 7.902800
Mean = 7.862525
std = 0.024486
```

```
RMS = 7.862562
______
***Row Num = 508
Min = 6.234700
Max = 7.538000
Mean = 7.084011
std = 0.322270
RMS = 7.091172
_____
***Row Num = 509
Min = 2.854400
Max = 6.697700
Mean = 4.128659
std = 1.683022
RMS = 4.451293
_____
***Row Num = 510
Min = 0.062270
Max = 9.995700
Mean = 7.587505
std = 2.528537
RMS = 7.988643
_____
***Row Num = 511
Min = 0.913570
Max = 0.947270
Mean = 0.927945
std = 0.007606
RMS = 0.927976
***Row Num = 512
Min = -0.389160
Max = -0.316890
Mean = -0.356680
std = 0.014502
RMS = 0.356968
______
***Row Num = 513
Min = 0.049805
Max = 0.128420
Mean = 0.085138
std = 0.017429
RMS = 0.086864
***Row Num = 514
Min = -0.890630
Max = 1.255400
Mean = -0.065231
std = 0.803049
RMS = 0.796547
```

```
_____
***Row Num = 515
Min = 0.214840
Max = 0.785640
Mean = 0.499256
std = 0.156041
RMS = 0.522544
_____
***Row Num = 516
Min = -0.187010
Max = 0.716310
Mean = 0.257635
std = 0.205586
RMS = 0.328148
***Row Num = 517
Min = -3.000000
Max = 1.000000
Mean = -0.795455
std = 0.851252
RMS = 1.157976
______
***Row Num = 518
Min = -3.000000
Max = 1.000000
Mean = -1.250000
std = 0.892475
RMS = 1.530003
_____
***Row Num = 519
Min = -3.000000
Max = 2.000000
Mean = -1.022727
std = 0.927328
RMS = 1.373450
***Row Num = 520
Min = -2.000000
Max = 1.000000
Mean = -0.909091
std = 0.830191
RMS = 1.224745
______
***Row Num = 521
Min = -3.000000
Max = 0.000000
Mean = -1.295455
std = 0.978360
RMS = 1.616674
```

```
***Row Num = 522
Min = -4.000000
Max = 1.000000
Mean = -0.977273
std = 1.151109
RMS = 1.500000
***Row Num = 523
Min = -4.000000
Max = 2.000000
Mean = -0.795455
std = 1.503168
RMS = 1.685500
______
***Row Num = 524
Min = -5.000000
Max = 3.000000
Mean = -0.795455
std = 1.563829
RMS = 1.738599
_____
***Row Num = 525
Min = -55.000000
Max = 37.000000
Mean = 2.477273
std = 18.139625
RMS = 18.102612
***Row Num = 526
Min = -25.000000
Max = 28.000000
Mean = 1.136364
std = 10.689249
RMS = 10.628008
______
***Row Num = 527
Min = -41.000000
Max = 19.000000
Mean = 0.159091
std = 9.233264
RMS = 9.129124
_____
***Row Num = 528
Min = -13.000000
Max = 13.000000
Mean = 0.431818
std = 5.280053
RMS = 5.237539
***Row Num = 529
```

```
Min = -36.000000
Max = 81.000000
Mean = 1.477273
std = 15.148089
RMS = 15.047652
_____
***Row Num = 530
Min = -22.000000
Max = 20.000000
Mean = -2.113636
std = 7.815357
RMS = 8.009937
***Row Num = 531
Min = -30.000000
Max = 35.000000
Mean = -2.818182
std = 11.381897
RMS = 11.599373
_____
***Row Num = 532
Min = -29.000000
Max = 36.000000
Mean = -0.136364
std = 14.218545
RMS = 14.056703
***Row Num = 533
Min = -12.188000
Max = 23.125000
Mean = 0.642045
std = 7.307209
RMS = 7.252172
***Row Num = 534
Min = -12.188000
Max = 23.125000
Mean = 0.642045
std = 7.307209
RMS = 7.252172
______
***Row Num = 535
Min = -12.188000
Max = 23.125000
Mean = 0.642045
std = 7.307209
RMS = 7.252172
***Row Num = 536
Min = -38.750000
```

```
Max = 67.750000
Mean = 6.183273
std = 19.567338
RMS = 20.307923
______
***Row Num = 537
Min = -38.750000
Max = 67.750000
Mean = 6.183273
std = 19.567338
RMS = 20.307923
***Row Num = 538
Min = -38.750000
Max = 67.750000
Mean = 6.183273
std = 19.567338
RMS = 20.307923
______
***Row Num = 539
Min = 2.831300
Max = 2.965700
Mean = 2.878914
std = 0.039549
RMS = 2.879179
______
***Row Num = 540
Min = 3.078500
Max = 3.106500
Mean = 3.097432
std = 0.005877
RMS = 3.097437
______
***Row Num = 541
Min = 7.830300
Max = 7.905100
Mean = 7.860091
std = 0.016118
RMS = 7.860107
-----
***Row Num = 542
Min = 6.321500
Max = 7.404000
Mean = 6.897852
std = 0.266065
RMS = 6.902865
_____
***Row Num = 543
Min = 2.887600
Max = 6.593000
```

```
Mean = 5.055970
std = 1.589059
RMS = 5.294389
______
***Row Num = 544
Min = 7.435300
Max = 9.824700
Mean = 8.873784
std = 0.883650
RMS = 8.916677
***Row Num = 545
Min = 0.902340
Max = 0.963380
Mean = 0.928145
std = 0.009578
RMS = 0.928193
______
***Row Num = 546
Min = -0.398930
Max = -0.324710
Mean = -0.358653
std = 0.015780
RMS = 0.358992
_____
***Row Num = 547
Min = 0.059082
Max = 0.131840
Mean = 0.080300
std = 0.012064
RMS = 0.081181
_____
***Row Num = 548
Min = -0.909670
Max = 1.403800
Mean = -0.332409
std = 0.741015
RMS = 0.804437
______
***Row Num = 549
Min = 0.249020
Max = 0.891600
Mean = 0.542458
std = 0.118806
RMS = 0.555026
***Row Num = 550
Min = -0.062988
Max = 0.769530
Mean = 0.286299
```

```
std = 0.204591
RMS = 0.350533
_____
***Row Num = 551
Min = -5.000000
Max = 1.000000
Mean = -0.977273
std = 1.088815
RMS = 1.453835
_____
***Row Num = 552
Min = -4.000000
Max = 1.000000
Mean = -1.181818
std = 0.994701
RMS = 1.537412
***Row Num = 553
Min = -3.000000
Max = 2.000000
Mean = -0.909091
std = 1.137484
RMS = 1.445998
______
***Row Num = 554
Min = -3.000000
Max = 1.000000
Mean = -1.045455
std = 0.987234
RMS = 1.430194
***Row Num = 555
Min = -4.000000
Max = 2.000000
Mean = -1.340909
std = 1.218905
RMS = 1.802776
***Row Num = 556
Min = -6.000000
Max = 6.000000
Mean = -1.272727
std = 1.834598
RMS = 2.215647
_____
***Row Num = 557
Min = -12.000000
Max = 17.000000
Mean = -1.022727
std = 3.726016
```

```
RMS = 3.822779
______
***Row Num = 558
Min = -6.000000
Max = 3.000000
Mean = -0.818182
std = 1.991525
RMS = 2.132007
_____
***Row Num = 559
Min = -77.000000
Max = 42.000000
Mean = -0.409091
std = 20.782728
RMS = 20.549276
_____
***Row Num = 560
Min = -23.000000
Max = 17.000000
Mean = -0.931818
std = 9.163623
RMS = 9.106691
_____
***Row Num = 561
Min = -90.000000
Max = 87.000000
Mean = 0.409091
std = 27.372808
RMS = 27.063058
***Row Num = 562
Min = -24.000000
Max = 14.000000
Mean = -0.772727
std = 6.678197
RMS = 6.646941
______
***Row Num = 563
Min = -34.000000
Max = 15.000000
Mean = -4.136364
std = 9.056903
RMS = 9.862694
***Row Num = 564
Min = -29.000000
Max = 37.000000
Mean = 0.681818
std = 11.506869
RMS = 11.395773
```

```
_____
***Row Num = 565
Min = -25.000000
Max = 21.000000
Mean = 2.363636
std = 9.659532
RMS = 9.837313
_____
***Row Num = 566
Min = -53.000000
Max = 67.000000
Mean = -1.409091
std = 20.131334
RMS = 19.951077
***Row Num = 567
Min = -14.875000
Max = 24.313000
Mean = -0.455966
std = 7.780962
RMS = 7.705536
______
***Row Num = 568
Min = -14.875000
Max = 24.313000
Mean = -0.455966
std = 7.780962
RMS = 7.705536
_____
***Row Num = 569
Min = -14.875000
Max = 24.313000
Mean = -0.455966
std = 7.780962
RMS = 7.705536
______
***Row Num = 570
Min = -90.438000
Max = 82.188000
Mean = 5.458830
std = 31.380135
RMS = 31.498124
______
***Row Num = 571
Min = -90.438000
Max = 82.188000
Mean = 5.458830
std = 31.380135
RMS = 31.498124
```

```
***Row Num = 572
Min = -90.438000
Max = 82.188000
Mean = 5.458830
std = 31.380135
RMS = 31.498124
***Row Num = 573
Min = 2.836400
Max = 2.950800
Mean = 2.862316
std = 0.028805
RMS = 2.862458
______
***Row Num = 574
Min = 3.084200
Max = 3.109300
Mean = 3.099386
std = 0.006470
RMS = 3.099393
_____
***Row Num = 575
Min = 7.831300
Max = 7.908700
Mean = 7.863730
std = 0.013350
RMS = 7.863741
***Row Num = 576
Min = 6.255800
Max = 7.534700
Mean = 6.853511
std = 0.331349
RMS = 6.861335
______
***Row Num = 577
Min = 2.850100
Max = 6.622000
Mean = 5.622680
std = 1.355315
RMS = 5.780109
_____
***Row Num = 578
Min = 7.320400
Max = 9.745800
Mean = 9.121636
std = 0.734766
RMS = 9.150511
***Row Num = 579
```

```
Min = 0.901370
Max = 0.962890
Mean = 0.928866
std = 0.008846
RMS = 0.928907
_____
***Row Num = 580
Min = -0.386230
Max = -0.310550
Mean = -0.355935
std = 0.015263
RMS = 0.356254
______
***Row Num = 581
Min = 0.055176
Max = 0.120610
Mean = 0.078181
std = 0.014305
RMS = 0.079449
_____
***Row Num = 582
Min = -0.884280
Max = 1.321300
Mean = 0.112516
std = 0.826618
RMS = 0.824881
***Row Num = 583
Min = 0.209470
Max = 0.688480
Mean = 0.467308
std = 0.164963
RMS = 0.494945
_____
***Row Num = 584
Min = -0.288570
Max = 0.761720
Mean = 0.265192
std = 0.208438
RMS = 0.335837
______
***Row Num = 585
Min = -3.000000
Max = 2.000000
Mean = -0.704545
std = 1.024798
RMS = 1.233988
***Row Num = 586
Min = -3.000000
```

```
Max = 1.000000
Mean = -0.931818
std = 0.873318
RMS = 1.270290
______
***Row Num = 587
Min = -6.000000
Max = 2.000000
Mean = -1.068182
std = 1.283124
RMS = 1.658312
***Row Num = 588
Min = -3.000000
Max = 1.000000
Mean = -0.954545
std = 0.938939
RMS = 1.331438
_____
***Row Num = 589
Min = -3.000000
Max = 2.000000
Mean = -1.000000
std = 1.161395
RMS = 1.522558
_____
***Row Num = 590
Min = -5.000000
Max = 2.000000
Mean = -1.000000
std = 1.311842
RMS = 1.637626
______
***Row Num = 591
Min = -4.000000
Max = 3.000000
Mean = -0.750000
std = 1.571919
RMS = 1.725478
______
***Row Num = 592
Min = -4.000000
Max = 3.000000
Mean = -0.863636
std = 1.440137
RMS = 1.665151
***Row Num = 593
Min = -38.000000
Max = 40.000000
```

```
Mean = -0.500000
std = 17.337283
RMS = 17.146428
______
***Row Num = 594
Min = -18.000000
Max = 25.000000
Mean = -1.659091
std = 9.838092
RMS = 9.866150
***Row Num = 595
Min = -36.000000
Max = 39.000000
Mean = -0.454545
std = 11.923115
RMS = 11.795608
______
***Row Num = 596
Min = -11.000000
Max = 28.000000
Mean = 0.250000
std = 5.926390
RMS = 5.863989
***Row Num = 597
Min = -25.000000
Max = 32.000000
Mean = -1.113636
std = 9.580057
RMS = 9.535818
***Row Num = 598
Min = -25.000000
Max = 29.000000
Mean = -0.136364
std = 8.814868
RMS = 8.715191
______
***Row Num = 599
Min = -27.000000
Max = 33.000000
Mean = -1.909091
std = 11.387096
RMS = 11.417690
***Row Num = 600
Min = -20.000000
Max = 47.000000
Mean = -0.909091
```

```
std = 12.426188
RMS = 12.317762
_____
***Row Num = 601
Min = -12.813000
Max = 33.188000
Mean = 0.313943
std = 8.746827
RMS = 8.652558
_____
***Row Num = 602
Min = -12.813000
Max = 33.188000
Mean = 0.313943
std = 8.746827
RMS = 8.652558
______
***Row Num = 603
Min = -12.813000
Max = 33.188000
Mean = 0.313943
std = 8.746827
RMS = 8.652558
______
***Row Num = 604
Min = -66.125000
Max = 42.813000
Mean = 0.850864
std = 23.289762
RMS = 23.039301
***Row Num = 605
Min = -66.125000
Max = 42.813000
Mean = 0.850864
std = 23.289762
RMS = 23.039301
***Row Num = 606
Min = -66.125000
Max = 42.813000
Mean = 0.850864
std = 23.289762
RMS = 23.039301
_____
***Row Num = 607
Min = 2.806400
Max = 2.922000
Mean = 2.850173
std = 0.032053
```

```
RMS = 2.850349
***Row Num = 608
Min = 3.080400
Max = 3.107500
Mean = 3.094720
std = 0.008669
RMS = 3.094732
_____
***Row Num = 609
Min = 7.859200
Max = 7.933600
Mean = 7.884627
std = 0.015330
RMS = 7.884642
_____
***Row Num = 610
Min = 6.249600
Max = 7.564800
Mean = 6.818882
std = 0.294538
RMS = 6.825096
_____
***Row Num = 611
Min = 2.851100
Max = 6.542200
Mean = 4.699632
std = 1.614554
RMS = 4.963273
***Row Num = 612
Min = 7.078000
Max = 9.580000
Mean = 8.562759
std = 0.846527
RMS = 8.603555
______
***Row Num = 613
Min = 0.903810
Max = 0.981930
Mean = 0.929134
std = 0.011382
RMS = 0.929202
***Row Num = 614
Min = -0.397950
Max = -0.300290
Mean = -0.354914
std = 0.019035
RMS = 0.355413
```

```
_____
***Row Num = 615
Min = 0.050293
Max = 0.135250
Mean = 0.078658
std = 0.017720
RMS = 0.080585
_____
***Row Num = 616
Min = -0.902830
Max = 1.404300
Mean = 0.138128
std = 0.850818
RMS = 0.852361
***Row Num = 617
Min = 0.203130
Max = 0.775880
Mean = 0.475697
std = 0.166775
RMS = 0.503458
______
***Row Num = 618
Min = -0.253420
Max = 0.766110
Mean = 0.252098
std = 0.219583
RMS = 0.332678
_____
***Row Num = 619
Min = -3.000000
Max = 5.000000
Mean = -0.727273
std = 1.387044
RMS = 1.552125
***Row Num = 620
Min = -6.000000
Max = 1.000000
Mean = -0.863636
std = 1.268416
RMS = 1.522558
______
***Row Num = 621
Min = -4.000000
Max = 2.000000
Mean = -1.272727
std = 1.300512
RMS = 1.809068
```

```
***Row Num = 622
Min = -4.000000
Max = 2.000000
Mean = -1.000000
std = 1.200775
RMS = 1.552125
***Row Num = 623
Min = -3.000000
Max = 0.000000
Mean = -1.022727
std = 0.792072
RMS = 1.288057
______
***Row Num = 624
Min = -3.000000
Max = 2.000000
Mean = -0.795455
std = 1.132594
RMS = 1.373450
_____
***Row Num = 625
Min = -8.000000
Max = 3.000000
Mean = -0.431818
std = 2.004619
RMS = 2.028210
***Row Num = 626
Min = -3.000000
Max = 2.000000
Mean = -0.886364
std = 1.204949
RMS = 1.484771
______
***Row Num = 627
Min = -55.000000
Max = 31.000000
Mean = -2.863636
std = 21.864903
RMS = 21.803878
_____
***Row Num = 628
Min = -33.000000
Max = 25.000000
Mean = -1.681818
std = 9.795046
RMS = 9.828067
***Row Num = 629
```

```
Min = -63.000000
Max = 68.000000
Mean = -1.295455
std = 18.188393
RMS = 18.027126
_____
***Row Num = 630
Min = -14.000000
Max = 35.000000
Mean = 1.704545
std = 9.128487
RMS = 9.183731
***Row Num = 631
Min = -34.000000
Max = 98.000000
Mean = 3.568182
std = 22.577410
RMS = 22.602795
_____
***Row Num = 632
Min = -37.000000
Max = 44.000000
Mean = 0.295455
std = 13.460674
RMS = 13.310112
***Row Num = 633
Min = -27.000000
Max = 36.000000
Mean = 2.568182
std = 13.312693
RMS = 13.408783
***Row Num = 634
Min = -40.000000
Max = 18.000000
Mean = -5.613636
std = 15.008859
RMS = 15.863767
______
***Row Num = 635
Min = -14.688000
Max = 28.375000
Mean = 0.355091
std = 8.277661
RMS = 8.190756
***Row Num = 636
Min = -14.688000
```

```
Max = 28.375000
Mean = 0.355091
std = 8.277661
RMS = 8.190756
______
***Row Num = 637
Min = -14.688000
Max = 28.375000
Mean = 0.355091
std = 8.277661
RMS = 8.190756
_____
***Row Num = 638
Min = -85.438000
Max = 71.875000
Mean = 3.275625
std = 29.467219
RMS = 29.314028
_____
***Row Num = 639
Min = -85.438000
Max = 71.875000
Mean = 3.275625
std = 29.467219
RMS = 29.314028
______
***Row Num = 640
Min = -85.438000
Max = 71.875000
Mean = 3.275625
std = 29.467219
RMS = 29.314028
_____
***Row Num = 641
Min = 2.823300
Max = 2.936000
Mean = 2.864909
std = 0.032180
RMS = 2.865086
-----
***Row Num = 642
Min = 3.080000
Max = 3.105700
Mean = 3.091389
std = 0.006972
RMS = 3.091396
-----
***Row Num = 643
Min = 7.856300
Max = 7.914700
```

```
Mean = 7.883473
std = 0.014562
RMS = 7.883486
______
***Row Num = 644
Min = 6.329200
Max = 7.358700
Mean = 6.895909
std = 0.297995
RMS = 6.902199
***Row Num = 645
Min = 2.895300
Max = 6.607400
Mean = 4.712711
std = 1.632186
RMS = 4.981278
______
***Row Num = 646
Min = 7.257800
Max = 9.612700
Mean = 8.526600
std = 0.847217
RMS = 8.567635
_____
***Row Num = 647
Min = 0.912600
Max = 0.959470
Mean = 0.931719
std = 0.008538
RMS = 0.931757
______
***Row Num = 648
Min = -0.408690
Max = -0.290530
Mean = -0.351052
std = 0.020432
RMS = 0.351632
______
***Row Num = 649
Min = 0.012695
Max = 0.151860
Mean = 0.081110
std = 0.021321
RMS = 0.083804
***Row Num = 650
Min = -0.912110
Max = 1.830100
Mean = 0.173618
```

```
std = 0.865302
RMS = 0.872854
_____
***Row Num = 651
Min = 0.106450
Max = 0.758300
Mean = 0.412488
std = 0.177795
RMS = 0.448373
_____
***Row Num = 652
Min = -0.316890
Max = 0.688480
Mean = 0.187367
std = 0.208718
RMS = 0.278711
______
***Row Num = 653
Min = -7.000000
Max = 2.000000
Mean = -1.113636
std = 1.543417
RMS = 1.888963
______
***Row Num = 654
Min = -5.000000
Max = 2.000000
Mean = -0.886364
std = 1.384565
RMS = 1.630672
***Row Num = 655
Min = -4.000000
Max = 2.000000
Mean = -1.454545
std = 1.109254
RMS = 1.821588
***Row Num = 656
Min = -3.000000
Max = 1.000000
Mean = -1.113636
std = 0.920463
RMS = 1.438117
______
***Row Num = 657
Min = -3.000000
Max = 0.000000
Mean = -1.204545
std = 0.929605
```

```
RMS = 1.515076
***Row Num = 658
Min = -3.000000
Max = 2.000000
Mean = -0.954545
std = 1.077347
RMS = 1.430194
______
***Row Num = 659
Min = -6.000000
Max = 4.000000
Mean = -0.750000
std = 2.136341
RMS = 2.241144
_____
***Row Num = 660
Min = -5.000000
Max = 4.000000
Mean = -1.204545
std = 1.772917
RMS = 2.126670
_____
***Row Num = 661
Min = -79.000000
Max = 56.000000
Mean = 0.704545
std = 27.277710
RMS = 26.975157
***Row Num = 662
Min = -53.000000
Max = 18.000000
Mean = -0.681818
std = 11.874876
RMS = 11.758942
______
***Row Num = 663
Min = -54.000000
Max = 19.000000
Mean = -3.090909
std = 10.443242
RMS = 10.776658
***Row Num = 664
Min = -14.000000
Max = 18.000000
Mean = -0.568182
std = 6.285449
RMS = 6.239537
```

```
_____
***Row Num = 665
Min = -22.000000
Max = 21.000000
Mean = -0.590909
std = 9.850790
RMS = 9.756117
_____
***Row Num = 666
Min = -43.000000
Max = 36.000000
Mean = -0.590909
std = 15.687824
RMS = 15.519782
***Row Num = 667
Min = -24.000000
Max = 19.000000
Mean = 0.363636
std = 8.768577
RMS = 8.675986
______
***Row Num = 668
Min = -21.000000
Max = 33.000000
Mean = 1.295455
std = 10.544655
RMS = 10.504328
_____
***Row Num = 669
Min = -18.750000
Max = 28.813000
Mean = 0.769898
std = 8.451090
RMS = 8.389903
***Row Num = 670
Min = -18.750000
Max = 28.813000
Mean = 0.769898
std = 8.451090
RMS = 8.389903
______
***Row Num = 671
Min = -18.750000
Max = 28.813000
Mean = 0.769898
std = 8.451090
RMS = 8.389903
```

```
***Row Num = 672
Min = -46.938000
Max = 51.875000
Mean = 3.355136
std = 17.045012
RMS = 17.180989
***Row Num = 673
Min = -46.938000
Max = 51.875000
Mean = 3.355136
std = 17.045012
RMS = 17.180989
______
***Row Num = 674
Min = -46.938000
Max = 51.875000
Mean = 3.355136
std = 17.045012
RMS = 17.180989
_____
***Row Num = 675
Min = 2.837700
Max = 2.963400
Mean = 2.867102
std = 0.027918
RMS = 2.867235
***Row Num = 676
Min = 3.076700
Max = 3.101500
Mean = 3.087245
std = 0.007152
RMS = 3.087254
______
***Row Num = 677
Min = 7.860500
Max = 7.942300
Mean = 7.898200
std = 0.018346
RMS = 7.898221
_____
***Row Num = 678
Min = 6.269600
Max = 7.348700
Mean = 7.022573
std = 0.283437
RMS = 7.028160
***Row Num = 679
```

```
Min = 2.878100
Max = 6.630500
```

Mean = 4.557980

std = 1.736792 RMS = 4.870633

***Row Num = 680

Min = 7.384900

Max = 9.629500

Mean = 8.387380

std = 0.917613

RMS = 8.436291

>>