```
>> Untitled4
Action AND.csv
______
***Row Num = 1
Min = 0.636720
Max = 1.341800
Mean = 0.941661
std = 0.091034
RMS = 0.945952
_____
***Row Num = 2
Min = -0.639160
Max = -0.248050
Mean = -0.321256
std = 0.084510
RMS = 0.331941
______
***Row Num = 3
Min = -0.428220
Max = 0.313960
Mean = 0.004195
std = 0.129283
RMS = 0.127874
______
***Row Num = 4
Min = -1.511700
Max = 2.179200
Mean = 0.700530
std = 0.668414
RMS = 0.962998
***Row Num = 5
Min = -0.059570
Max = 1.085000
Mean = 0.343363
std = 0.305356
RMS = 0.457189
_____
***Row Num = 6
Min = -1.450200
Max = 1.233400
Mean = 0.068626
std = 0.343099
RMS = 0.346051
_____
***Row Num = 7
Min = -32.000000
Max = 11.000000
Mean = -1.613636
std = 7.412171
```

```
RMS = 7.503030
***Row Num = 8
Min = -37.000000
Max = 14.000000
Mean = -1.159091
std = 7.541955
RMS = 7.545318
______
***Row Num = 9
Min = -13.000000
Max = 11.000000
Mean = -1.022727
std = 4.043304
RMS = 4.125861
_____
***Row Num = 10
Min = -8.000000
Max = 3.000000
Mean = -0.909091
std = 2.228966
RMS = 2.383656
***Row Num = 11
Min = -9.000000
Max = 6.000000
Mean = -0.977273
std = 2.645651
RMS = 2.792034
***Row Num = 12
Min = -13.000000
Max = 6.000000
Mean = -0.636364
std = 3.918299
RMS = 3.925441
______
***Row Num = 13
Min = -48.000000
Max = 34.000000
Mean = -0.136364
std = 13.374031
RMS = 13.221883
***Row Num = 14
Min = -15.000000
Max = 14.000000
Mean = -0.136364
std = 5.156125
RMS = 5.099020
```

\_\_\_\_\_ \*\*\*Row Num = 15Min = -87.000000Max = 111.000000Mean = 5.090909std = 33.802998RMS = 33.802232\_\_\_\_\_ \*\*\*Row Num = 16Min = -51.000000Max = 79.000000Mean = 0.250000std = 18.411479RMS = 18.202772\*\*\*Row Num = 17Min = -18.000000Max = 84.000000Mean = 2.272727std = 15.327986RMS = 15.322295\_\_\_\_\_\_ \*\*\*Row Num = 18Min = -70.000000Max = 127.000000Mean = 7.227273std = 31.559367RMS = 32.024848\_\_\_\_\_ \*\*\*Row Num = 19Min = -128.000000Max = 127.000000Mean = 2.750000std = 43.791326RMS = 43.378095\_\_\_\_\_\_ \*\*\*Row Num = 20Min = -52.000000Max = 114.000000Mean = 3.454545std = 32.669917RMS = 32.480764\_\_\_\_\_ \*\*\*Row Num = 21Min = -67.000000Max = 44.000000Mean = -0.272727std = 18.239191RMS = 18.032798

```
***Row Num = 22
Min = -36.000000
Max = 93.000000
Mean = 2.750000
std = 19.049660
RMS = 19.031672
***Row Num = 23
Min = -61.375000
Max = 63.438000
Mean = 1.008568
std = 19.890740
RMS = 19.689258
______
***Row Num = 24
Min = -61.375000
Max = 63.438000
Mean = 1.008568
std = 19.890740
RMS = 19.689258
_____
***Row Num = 25
Min = -61.375000
Max = 63.438000
Mean = 1.008568
std = 19.890740
RMS = 19.689258
***Row Num = 26
Min = -120.940000
Max = 74.500000
Mean = -7.653420
std = 35.634471
RMS = 36.049008
______
***Row Num = 27
Min = -120.940000
Max = 74.500000
Mean = -7.653420
std = 35.634471
RMS = 36.049008
_____
***Row Num = 28
Min = -120.940000
Max = 74.500000
Mean = -7.653420
std = 35.634471
RMS = 36.049008
***Row Num = 29
```

```
Min = 2.192700
Max = 2.999800
Mean = 2.468632
std = 0.289106
RMS = 2.485121
_____
***Row Num = 30
Min = 2.947400
Max = 3.275700
Mean = 3.043636
std = 0.121174
RMS = 3.045993
***Row Num = 31
Min = 0.511430
Max = 1.542500
Mean = 1.169664
std = 0.345343
RMS = 1.218469
_____
***Row Num = 32
Min = 6.695800
Max = 7.820900
Mean = 7.362843
std = 0.240767
RMS = 7.366689
***Row Num = 33
Min = 2.862200
Max = 5.539500
Mean = 3.457711
std = 1.017762
RMS = 3.601120
***Row Num = 34
Min = 0.001066
Max = 3.051500
Mean = 0.826829
std = 0.854645
RMS = 1.182143
______
***Row Num = 35
Min = 0.896000
Max = 1.011200
Mean = 0.941716
std = 0.025682
RMS = 0.942058
***Row Num = 36
Min = -0.457030
```

```
Max = -0.183110
Mean = -0.335361
std = 0.044508
RMS = 0.338235
______
***Row Num = 37
Min = -0.116700
Max = 0.121090
Mean = 0.025823
std = 0.046452
RMS = 0.052684
_____
***Row Num = 38
Min = -1.103000
Max = 1.804700
Mean = 0.207810
std = 0.725606
RMS = 0.746809
_____
***Row Num = 39
Min = 0.185060
Max = 1.011700
Mean = 0.618753
std = 0.286660
RMS = 0.680560
______
***Row Num = 40
Min = -0.482910
Max = 1.144500
Mean = 0.341197
std = 0.336021
RMS = 0.476193
_____
***Row Num = 41
Min = -9.000000
Max = 5.000000
Mean = -1.500000
std = 2.889435
RMS = 3.226312
-----
***Row Num = 42
Min = -8.000000
Max = 14.000000
Mean = 0.000000
std = 4.324081
RMS = 4.274661
***Row Num = 43
Min = -6.000000
Max = 5.000000
```

```
Mean = -0.795455
std = 1.995105
RMS = 2.126670
______
***Row Num = 44
Min = -5.000000
Max = 2.000000
Mean = -1.204545
std = 1.503168
RMS = 1.912875
***Row Num = 45
Min = -6.000000
Max = 3.000000
Mean = -1.022727
std = 1.771724
RMS = 2.028210
______
***Row Num = 46
Min = -7.000000
Max = 5.000000
Mean = -0.545455
std = 2.073695
RMS = 2.121320
_____
***Row Num = 47
Min = -17.000000
Max = 26.000000
Mean = 0.750000
std = 6.549010
RMS = 6.517459
***Row Num = 48
Min = -9.000000
Max = 4.000000
Mean = -0.772727
std = 3.025962
RMS = 3.089572
______
***Row Num = 49
Min = -127.000000
Max = 115.000000
Mean = 3.681818
std = 38.742905
RMS = 38.476675
______
***Row Num = 50
Min = -79.000000
Max = 52.000000
Mean = -3.318182
```

```
std = 24.066548
RMS = 24.021770
_____
***Row Num = 51
Min = -43.000000
Max = 21.000000
Mean = -1.590909
std = 11.734105
RMS = 11.708583
_____
***Row Num = 52
Min = -90.000000
Max = 54.000000
Mean = 1.477273
std = 22.393405
RMS = 22.186708
______
***Row Num = 53
Min = -108.000000
Max = 127.000000
Mean = -5.590909
std = 52.514148
RMS = 52.214157
______
***Row Num = 54
Min = -81.000000
Max = 107.000000
Mean = 4.227273
std = 32.406476
RMS = 32.313802
***Row Num = 55
Min = -23.000000
Max = 23.000000
Mean = -1.454545
std = 10.137323
RMS = 10.126473
_____
***Row Num = 56
Min = -68.000000
Max = 62.000000
Mean = -2.659091
std = 22.567669
RMS = 22.467654
_____
***Row Num = 57
Min = -56.438000
Max = 46.125000
Mean = -2.656284
std = 21.072744
```

```
RMS = 21.000574
______
***Row Num = 58
Min = -56.438000
Max = 46.125000
Mean = -2.656284
std = 21.072744
RMS = 21.000574
_____
***Row Num = 59
Min = -56.438000
Max = 46.125000
Mean = -2.656284
std = 21.072744
RMS = 21.000574
_____
***Row Num = 60
Min = -64.688000
Max = 105.130000
Mean = 3.350989
std = 32.221837
RMS = 32.029352
_____
***Row Num = 61
Min = -64.688000
Max = 105.130000
Mean = 3.350989
std = 32.221837
RMS = 32.029352
***Row Num = 62
Min = -64.688000
Max = 105.130000
Mean = 3.350989
std = 32.221837
RMS = 32.029352
______
***Row Num = 63
Min = 2.461900
Max = 2.781800
Mean = 2.623105
std = 0.089693
RMS = 2.624603
***Row Num = 64
Min = 3.013300
Max = 3.061600
Mean = 3.040855
std = 0.013712
RMS = 3.040885
```

```
_____
***Row Num = 65
Min = 0.956330
Max = 1.214100
Mean = 1.100581
std = 0.081119
RMS = 1.103499
_____
***Row Num = 66
Min = 6.570000
Max = 7.708600
Mean = 7.040902
std = 0.325600
RMS = 7.048256
***Row Num = 67
Min = 2.903400
Max = 5.840000
Mean = 4.437695
std = 1.189225
RMS = 4.590779
______
***Row Num = 68
Min = 0.063699
Max = 9.789100
Mean = 1.675418
std = 2.025699
RMS = 2.610981
_____
***Row Num = 69
Min = 0.868650
Max = 1.011700
Mean = 0.932905
std = 0.024387
RMS = 0.933216
______
***Row Num = 70
Min = -0.502440
Max = -0.249020
Mean = -0.346247
std = 0.041817
RMS = 0.348706
_____
***Row Num = 71
Min = -0.068848
Max = 0.162110
Mean = 0.050326
std = 0.059310
RMS = 0.077269
```

```
***Row Num = 72
Min = -1.579100
Max = 1.888200
Mean = 0.167791
std = 0.756194
RMS = 0.766151
***Row Num = 73
Min = 0.030273
Max = 0.957520
Mean = 0.547297
std = 0.263934
RMS = 0.606310
______
***Row Num = 74
Min = -0.873540
Max = 1.274900
Mean = 0.399336
std = 0.371631
RMS = 0.542623
______
***Row Num = 75
Min = -6.000000
Max = 7.000000
Mean = -1.659091
std = 2.551271
RMS = 3.018880
***Row Num = 76
Min = -7.000000
Max = 6.000000
Mean = -1.250000
std = 2.383324
RMS = 2.667140
______
***Row Num = 77
Min = -7.000000
Max = 6.000000
Mean = -1.227273
std = 2.301300
RMS = 2.584921
_____
***Row Num = 78
Min = -6.000000
Max = 1.000000
Mean = -1.340909
std = 1.237837
RMS = 1.815339
***Row Num = 79
```

```
Min = -3.000000
Max = 1.000000
Mean = -0.954545
std = 1.077347
RMS = 1.430194
_____
***Row Num = 80
Min = -4.000000
Max = 4.000000
Mean = -1.068182
std = 1.515773
RMS = 1.840207
***Row Num = 81
Min = -7.000000
Max = 7.000000
Mean = -0.454545
std = 3.288136
RMS = 3.282183
_____
***Row Num = 82
Min = -7.000000
Max = 4.000000
Mean = -0.909091
std = 2.300841
RMS = 2.449490
***Row Num = 83
Min = -94.000000
Max = 92.000000
Mean = 1.090909
std = 37.202662
RMS = 36.793651
***Row Num = 84
Min = -85.000000
Max = 66.000000
Mean = -1.727273
std = 29.722252
RMS = 29.433284
______
***Row Num = 85
Min = -31.000000
Max = 78.000000
Mean = 3.477273
std = 21.129158
RMS = 21.175136
***Row Num = 86
Min = -113.000000
```

```
Max = 101.000000
Mean = 1.340909
std = 28.681039
RMS = 28.384935
______
***Row Num = 87
Min = -128.000000
Max = 127.000000
Mean = -2.568182
std = 51.074227
RMS = 50.555775
***Row Num = 88
Min = -73.000000
Max = 60.000000
Mean = -0.931818
std = 26.470166
RMS = 26.184225
_____
***Row Num = 89
Min = -27.000000
Max = 39.000000
Mean = 2.659091
std = 13.211945
RMS = 13.328882
______
***Row Num = 90
Min = -89.000000
Max = 52.000000
Mean = -3.636364
std = 25.623473
RMS = 25.590304
______
***Row Num = 91
Min = -50.750000
Max = 59.750000
Mean = -1.387818
std = 20.996962
RMS = 20.803332
-----
***Row Num = 92
Min = -50.750000
Max = 59.750000
Mean = -1.387818
std = 20.996962
RMS = 20.803332
***Row Num = 93
Min = -50.750000
Max = 59.750000
```

```
Mean = -1.387818
std = 20.996962
RMS = 20.803332
______
***Row Num = 94
Min = -177.630000
Max = 104.630000
Mean = -4.048330
std = 47.593537
RMS = 47.223439
***Row Num = 95
Min = -177.630000
Max = 104.630000
Mean = -4.048330
std = 47.593537
RMS = 47.223439
______
***Row Num = 96
Min = -177.630000
Max = 104.630000
Mean = -4.048330
std = 47.593537
RMS = 47.223439
_____
***Row Num = 97
Min = 2.495600
Max = 2.887100
Mean = 2.728395
std = 0.118006
RMS = 2.730888
_____
***Row Num = 98
Min = 3.029400
Max = 3.100900
Mean = 3.066384
std = 0.021797
RMS = 3.066460
______
***Row Num = 99
Min = 0.814030
Max = 1.136400
Mean = 0.998747
std = 0.094370
RMS = 1.003094
***Row Num = 100
Min = 6.227500
Max = 8.132100
Mean = 6.923157
```

```
std = 0.514756
RMS = 6.941833
_____
***Row Num = 101
Min = 2.885900
Max = 5.860400
Mean = 4.544648
std = 1.168426
RMS = 4.689138
_____
***Row Num = 102
Min = 0.020397
Max = 9.975300
Mean = 2.184565
std = 2.908542
RMS = 3.611050
***Row Num = 103
Min = 0.856450
Max = 1.050300
Mean = 0.939532
std = 0.041354
RMS = 0.940421
______
***Row Num = 104
Min = -0.493160
Max = -0.180660
Mean = -0.337558
std = 0.057806
RMS = 0.342361
***Row Num = 105
Min = -0.126460
Max = 0.158690
Mean = 0.041793
std = 0.053997
RMS = 0.067794
_____
***Row Num = 106
Min = -1.766100
Max = 2.466800
Mean = 0.236759
std = 0.836029
RMS = 0.859718
______
***Row Num = 107
Min = -0.209470
Max = 1.014600
Mean = 0.576015
std = 0.295574
```

```
RMS = 0.645888
***Row Num = 108
Min = -1.574700
Max = 1.213900
Mean = 0.375534
std = 0.455580
RMS = 0.586397
______
***Row Num = 109
Min = -6.000000
Max = 13.000000
Mean = -0.045455
std = 3.728922
RMS = 3.686585
_____
***Row Num = 110
Min = -9.000000
Max = 13.000000
Mean = -0.500000
std = 4.134371
RMS = 4.117590
_____
***Row Num = 111
Min = -5.000000
Max = 11.000000
Mean = -0.568182
std = 2.983659
RMS = 3.003785
***Row Num = 112
Min = -5.000000
Max = 2.000000
Mean = -1.272727
std = 1.245711
RMS = 1.770978
______
***Row Num = 113
Min = -4.000000
Max = 3.000000
Mean = -1.386364
std = 1.401260
RMS = 1.959824
***Row Num = 114
Min = -7.000000
Max = 4.000000
Mean = -1.090909
std = 1.974467
RMS = 2.236068
```

```
_____
***Row Num = 115
Min = -6.000000
Max = 6.000000
Mean = -0.636364
std = 3.327761
RMS = 3.350712
_____
***Row Num = 116
Min = -7.000000
Max = 5.000000
Mean = -0.977273
std = 2.740638
RMS = 2.880183
***Row Num = 117
Min = -110.000000
Max = 79.000000
Mean = 1.159091
std = 39.670705
RMS = 39.234435
______
***Row Num = 118
Min = -95.000000
Max = 68.000000
Mean = 3.727273
std = 27.425471
RMS = 27.367034
_____
***Row Num = 119
Min = -31.000000
Max = 46.000000
Mean = 4.318182
std = 15.833102
RMS = 16.236883
***Row Num = 120
Min = -55.000000
Max = 88.000000
Mean = 1.954545
std = 28.398292
RMS = 28.141687
______
***Row Num = 121
Min = -120.000000
Max = 127.000000
Mean = 4.113636
std = 57.643740
RMS = 57.133218
```

```
***Row Num = 122
Min = -86.000000
Max = 91.000000
Mean = 1.863636
std = 35.729338
RMS = 35.370121
***Row Num = 123
Min = -42.000000
Max = 66.000000
Mean = -0.863636
std = 19.151284
RMS = 18.952093
______
***Row Num = 124
Min = -128.000000
Max = 118.000000
Mean = -0.522727
std = 38.308107
RMS = 37.873894
_____
***Row Num = 125
Min = -67.125000
Max = 56.000000
Mean = -0.068182
std = 21.681345
RMS = 21.433659
***Row Num = 126
Min = -67.125000
Max = 56.000000
Mean = -0.068182
std = 21.681345
RMS = 21.433659
______
***Row Num = 127
Min = -67.125000
Max = 56.000000
Mean = -0.068182
std = 21.681345
RMS = 21.433659
______
***Row Num = 128
Min = -133.380000
Max = 497.810000
Mean = 2.420068
std = 93.819755
RMS = 92.779062
***Row Num = 129
```

```
Min = -133.380000
Max = 497.810000
Mean = 2.420068
std = 93.819755
RMS = 92.779062
_____
***Row Num = 130
Min = -133.380000
Max = 497.810000
Mean = 2.420068
std = 93.819755
RMS = 92.779062
***Row Num = 131
Min = 2.533800
Max = 2.813700
Mean = 2.707427
std = 0.070417
RMS = 2.708322
_____
***Row Num = 132
Min = 3.027600
Max = 3.096900
Mean = 3.060750
std = 0.014608
RMS = 3.060784
______
***Row Num = 133
Min = 0.826740
Max = 1.117900
Mean = 0.964614
std = 0.077299
RMS = 0.967636
_____
***Row Num = 134
Min = 6.233800
Max = 7.680800
Mean = 6.872152
std = 0.357897
RMS = 6.881254
______
***Row Num = 135
Min = 2.858600
Max = 5.807800
Mean = 4.460855
std = 1.133459
RMS = 4.599430
***Row Num = 136
Min = 0.027495
```

```
Max = 2.757300
Mean = 1.183688
std = 0.858806
RMS = 1.456676
______
***Row Num = 137
Min = 0.838870
Max = 1.028800
Mean = 0.935136
std = 0.034917
RMS = 0.935773
***Row Num = 138
Min = -0.470210
Max = -0.200200
Mean = -0.342973
std = 0.047142
RMS = 0.346124
_____
***Row Num = 139
Min = -0.123050
Max = 0.143550
Mean = 0.039084
std = 0.052334
RMS = 0.064840
______
***Row Num = 140
Min = -1.364300
Max = 2.252000
Mean = 0.165049
std = 0.778259
RMS = 0.786869
______
***Row Num = 141
Min = 0.053223
Max = 1.002900
Mean = 0.571444
std = 0.275094
RMS = 0.632855
-----
***Row Num = 142
Min = -1.528800
Max = 1.299300
Mean = 0.402310
std = 0.436444
RMS = 0.589922
_____
***Row Num = 143
Min = -7.000000
Max = 9.000000
```

```
Mean = -1.204545
std = 3.151814
RMS = 3.340523
______
***Row Num = 144
Min = -19.000000
Max = 23.000000
Mean = -0.545455
std = 5.496107
RMS = 5.460603
***Row Num = 145
Min = -9.000000
Max = 10.000000
Mean = -0.136364
std = 3.379768
RMS = 3.343923
______
***Row Num = 146
Min = -3.000000
Max = 2.000000
Mean = -1.000000
std = 1.257535
RMS = 1.595448
***Row Num = 147
Min = -4.000000
Max = 1.000000
Mean = -1.204545
std = 1.286415
RMS = 1.751623
_____
***Row Num = 148
Min = -5.000000
Max = 3.000000
Mean = -0.818182
std = 1.603379
RMS = 1.783765
______
***Row Num = 149
Min = -7.000000
Max = 8.000000
Mean = -0.886364
std = 3.995439
RMS = 4.048007
***Row Num = 150
Min = -7.000000
Max = 4.000000
Mean = -1.068182
```

```
std = 2.500211
RMS = 2.692582
_____
***Row Num = 151
Min = -73.000000
Max = 88.000000
Mean = -2.863636
std = 34.793471
RMS = 34.514819
_____
***Row Num = 152
Min = -58.000000
Max = 54.000000
Mean = 3.931818
std = 19.070735
RMS = 19.258410
***Row Num = 153
Min = -46.000000
Max = 65.000000
Mean = 3.863636
std = 19.309705
RMS = 19.476093
______
***Row Num = 154
Min = -111.000000
Max = 93.000000
Mean = 1.272727
std = 37.944490
RMS = 37.532410
***Row Num = 155
Min = -128.000000
Max = 114.000000
Mean = -7.909091
std = 61.324459
RMS = 61.137327
_____
***Row Num = 156
Min = -93.000000
Max = 104.000000
Mean = 4.136364
std = 37.648676
RMS = 37.447539
_____
***Row Num = 157
Min = -31.000000
Max = 50.000000
Mean = 3.727273
std = 15.959780
```

```
RMS = 16.211668
***Row Num = 158
Min = -49.000000
Max = 86.000000
Mean = 1.931818
std = 22.480377
RMS = 22.307255
______
***Row Num = 159
Min = -53.625000
Max = 65.438000
Mean = -0.708830
std = 22.741235
RMS = 22.492498
_____
***Row Num = 160
Min = -53.625000
Max = 65.438000
Mean = -0.708830
std = 22.741235
RMS = 22.492498
_____
***Row Num = 161
Min = -53.625000
Max = 65.438000
Mean = -0.708830
std = 22.741235
RMS = 22.492498
***Row Num = 162
Min = -103.440000
Max = 155.060000
Mean = 1.080818
std = 43.895573
RMS = 43.407350
______
***Row Num = 163
Min = -103.440000
Max = 155.060000
Mean = 1.080818
std = 43.895573
RMS = 43.407350
***Row Num = 164
Min = -103.440000
Max = 155.060000
Mean = 1.080818
std = 43.895573
RMS = 43.407350
```

```
_____
***Row Num = 165
Min = 2.533800
Max = 2.785200
Mean = 2.682400
std = 0.065672
RMS = 2.683186
_____
***Row Num = 166
Min = 3.032500
Max = 3.097500
Mean = 3.060680
std = 0.016323
RMS = 3.060722
***Row Num = 167
Min = 0.930080
Max = 1.164200
Mean = 1.057562
std = 0.054135
RMS = 1.058915
______
***Row Num = 168
Min = 6.173500
Max = 8.104300
Mean = 6.848807
std = 0.416416
RMS = 6.861167
_____
***Row Num = 169
Min = 2.926900
Max = 5.781200
Mean = 4.579800
std = 1.128212
RMS = 4.713651
***Row Num = 170
Min = 0.202290
Max = 9.711600
Mean = 1.444391
std = 1.534985
RMS = 2.094969
______
***Row Num = 171
Min = 0.882810
Max = 0.988770
Mean = 0.937290
std = 0.019193
RMS = 0.937482
```

```
***Row Num = 172
Min = -0.409180
Max = -0.279300
Mean = -0.336448
std = 0.026714
RMS = 0.337483
***Row Num = 173
Min = -0.035156
Max = 0.135740
Mean = 0.051258
std = 0.037644
RMS = 0.063343
______
***Row Num = 174
Min = -0.961910
Max = 1.645500
Mean = 0.127563
std = 0.704482
RMS = 0.708017
_____
***Row Num = 175
Min = 0.176760
Max = 0.961910
Mean = 0.611617
std = 0.235706
RMS = 0.654500
***Row Num = 176
Min = -0.451170
Max = 1.007800
Mean = 0.413641
std = 0.309938
RMS = 0.514759
______
***Row Num = 177
Min = -6.000000
Max = 14.000000
Mean = -0.636364
std = 3.271376
RMS = 3.296003
_____
***Row Num = 178
Min = -5.000000
Max = 9.000000
Mean = -1.068182
std = 2.346672
RMS = 2.553963
***Row Num = 179
```

```
Min = -4.000000
Max = 3.000000
Mean = -1.136364
std = 1.706225
RMS = 2.033805
***Row Num = 180
Min = -4.000000
Max = 1.000000
Mean = -1.136364
std = 1.090997
RMS = 1.566699
***Row Num = 181
Min = -4.000000
Max = 2.000000
Mean = -0.886364
std = 1.104239
RMS = 1.406155
_____
***Row Num = 182
Min = -8.000000
Max = 4.000000
Mean = -0.931818
std = 2.139308
RMS = 2.311041
______
***Row Num = 183
Min = -24.000000
Max = 10.000000
Mean = -1.181818
std = 5.690763
RMS = 5.748518
***Row Num = 184
Min = -5.000000
Max = 3.000000
Mean = -0.818182
std = 2.233703
RMS = 2.354879
______
***Row Num = 185
Min = -85.000000
Max = 100.000000
Mean = -1.886364
std = 28.370650
RMS = 28.109769
***Row Num = 186
Min = -57.000000
```

```
Max = 36.000000
Mean = 0.909091
std = 16.874114
RMS = 16.706014
______
***Row Num = 187
Min = -21.000000
Max = 94.000000
Mean = -0.863636
std = 18.008513
RMS = 17.823631
_____
***Row Num = 188
Min = -36.000000
Max = 96.000000
Mean = 1.613636
std = 23.858318
RMS = 23.640778
_____
***Row Num = 189
Min = -103.000000
Max = 123.000000
Mean = -13.840909
std = 50.075266
RMS = 51.401494
______
***Row Num = 190
Min = -54.000000
Max = 53.000000
Mean = -1.022727
std = 20.211082
RMS = 20.006249
______
***Row Num = 191
Min = -35.000000
Max = 16.000000
Mean = -3.909091
std = 12.443020
RMS = 12.907010
-----
***Row Num = 192
Min = -60.000000
Max = 61.000000
Mean = -2.181818
std = 24.504649
RMS = 24.322642
***Row Num = 193
Min = -32.625000
Max = 48.375000
```

```
Mean = 0.029864
std = 16.197240
RMS = 16.012151
______
***Row Num = 194
Min = -32.625000
Max = 48.375000
Mean = 0.029864
std = 16.197240
RMS = 16.012151
***Row Num = 195
Min = -32.625000
Max = 48.375000
Mean = 0.029864
std = 16.197240
RMS = 16.012151
______
***Row Num = 196
Min = -85.313000
Max = 79.188000
Mean = -3.845159
std = 37.479985
RMS = 37.250616
***Row Num = 197
Min = -85.313000
Max = 79.188000
Mean = -3.845159
std = 37.479985
RMS = 37.250616
***Row Num = 198
Min = -85.313000
Max = 79.188000
Mean = -3.845159
std = 37.479985
RMS = 37.250616
______
***Row Num = 199
Min = 2.608200
Max = 2.910500
Mean = 2.760889
std = 0.085567
RMS = 2.762184
***Row Num = 200
Min = 3.022500
Max = 3.096600
Mean = 3.055761
```

```
std = 0.020279
RMS = 3.055827
_____
***Row Num = 201
Min = 0.902610
Max = 1.096000
Mean = 1.013313
std = 0.049733
RMS = 1.014505
_____
***Row Num = 202
Min = 6.285300
Max = 7.688100
Mean = 6.858730
std = 0.434283
RMS = 6.872153
***Row Num = 203
Min = 2.904200
Max = 5.779500
Mean = 4.647386
std = 1.121964
RMS = 4.777907
______
***Row Num = 204
Min = 0.007728
Max = 9.990000
Mean = 3.015863
std = 3.367924
RMS = 4.492277
***Row Num = 205
Min = 0.845700
Max = 1.004900
Mean = 0.940775
std = 0.025110
RMS = 0.941102
***Row Num = 206
Min = -0.430180
Max = -0.251460
Mean = -0.331100
std = 0.040809
RMS = 0.333549
______
***Row Num = 207
Min = -0.101070
Max = 0.113770
Mean = 0.036577
std = 0.045046
```

```
RMS = 0.057627
______
***Row Num = 208
Min = -1.119600
Max = 1.833500
Mean = 0.188465
std = 0.752019
RMS = 0.766941
______
***Row Num = 209
Min = 0.045410
Max = 1.023400
Mean = 0.586370
std = 0.280601
RMS = 0.648673
_____
***Row Num = 210
Min = -1.040500
Max = 1.006300
Mean = 0.337701
std = 0.379365
RMS = 0.504667
______
***Row Num = 211
Min = -8.000000
Max = 6.000000
Mean = -1.909091
std = 3.422349
RMS = 3.884702
***Row Num = 212
Min = -7.000000
Max = 5.000000
Mean = -1.386364
std = 2.598890
RMS = 2.919371
______
***Row Num = 213
Min = -6.000000
Max = 5.000000
Mean = -1.295455
std = 2.416797
RMS = 2.717787
***Row Num = 214
Min = -3.000000
Max = 3.000000
Mean = -0.818182
std = 1.559259
RMS = 1.745123
```

```
_____
***Row Num = 215
Min = -4.000000
Max = 2.000000
Mean = -0.818182
std = 1.280856
RMS = 1.507557
_____
***Row Num = 216
Min = -4.000000
Max = 6.000000
Mean = -1.045455
std = 1.904151
RMS = 2.153222
***Row Num = 217
Min = -11.000000
Max = 24.000000
Mean = -0.545455
std = 5.384969
RMS = 5.351296
______
***Row Num = 218
Min = -7.000000
Max = 4.000000
Mean = -0.522727
std = 2.256656
RMS = 2.291288
_____
***Row Num = 219
Min = -78.000000
Max = 119.000000
Mean = 2.454545
std = 32.973883
RMS = 32.689309
***Row Num = 220
Min = -68.000000
Max = 55.000000
Mean = -2.068182
std = 22.761042
RMS = 22.595756
______
***Row Num = 221
Min = -30.000000
Max = 29.000000
Mean = -0.681818
std = 8.896753
RMS = 8.821461
```

```
***Row Num = 222
Min = -57.000000
Max = 59.000000
Mean = 2.295455
std = 18.225435
RMS = 18.162774
***Row Num = 223
Min = -117.000000
Max = 89.000000
Mean = -5.000000
std = 43.964573
RMS = 43.748766
______
***Row Num = 224
Min = -59.000000
Max = 75.000000
Mean = 2.340909
std = 27.675817
RMS = 27.459474
_____
***Row Num = 225
Min = -37.000000
Max = 23.000000
Mean = 0.909091
std = 13.100361
RMS = 12.982506
***Row Num = 226
Min = -79.000000
Max = 58.000000
Mean = -3.909091
std = 27.939984
RMS = 27.895910
______
***Row Num = 227
Min = -33.438000
Max = 36.938000
Mean = 0.413341
std = 15.553435
RMS = 15.381231
_____
***Row Num = 228
Min = -33.438000
Max = 36.938000
Mean = 0.413341
std = 15.553435
RMS = 15.381231
***Row Num = 229
```

```
Min = -33.438000
Max = 36.938000
Mean = 0.413341
std = 15.553435
RMS = 15.381231
_____
***Row Num = 230
Min = -74.625000
Max = 64.375000
Mean = 2.929000
std = 26.429187
RMS = 26.290796
***Row Num = 231
Min = -74.625000
Max = 64.375000
Mean = 2.929000
std = 26.429187
RMS = 26.290796
_____
***Row Num = 232
Min = -74.625000
Max = 64.375000
Mean = 2.929000
std = 26.429187
RMS = 26.290796
______
***Row Num = 233
Min = 2.570600
Max = 2.784700
Mean = 2.671857
std = 0.059960
RMS = 2.672514
_____
***Row Num = 234
Min = 3.020400
Max = 3.072100
Mean = 3.043759
std = 0.016454
RMS = 3.043803
______
***Row Num = 235
Min = 0.945670
Max = 1.123700
Mean = 1.064614
std = 0.042420
RMS = 1.065439
***Row Num = 236
Min = 6.490200
```

```
Max = 7.638800
Mean = 6.993536
std = 0.429635
RMS = 7.006421
______
***Row Num = 237
Min = 2.913500
Max = 5.790200
Mean = 4.506950
std = 1.230805
RMS = 4.668303
***Row Num = 238
Min = 0.002022
Max = 9.941300
Mean = 1.724205
std = 2.409572
RMS = 2.940572
______
***Row Num = 239
Min = 0.859860
Max = 1.006300
Mean = 0.938774
std = 0.025854
RMS = 0.939122
______
***Row Num = 240
Min = -0.440920
Max = -0.229000
Mean = -0.336802
std = 0.045303
RMS = 0.339767
______
***Row Num = 241
Min = -0.074707
Max = 0.111330
Mean = 0.020364
std = 0.034844
RMS = 0.040015
-----
***Row Num = 242
Min = -1.248500
Max = 1.593800
Mean = 0.163076
std = 0.687649
RMS = 0.699077
_____
***Row Num = 243
Min = 0.268550
Max = 1.085900
```

```
Mean = 0.637328
std = 0.255037
RMS = 0.685386
______
***Row Num = 244
Min = -0.885740
Max = 0.910640
Mean = 0.303023
std = 0.336658
RMS = 0.450096
***Row Num = 245
Min = -11.000000
Max = 12.000000
Mean = -2.204545
std = 3.714081
RMS = 4.282629
______
***Row Num = 246
Min = -18.000000
Max = 13.000000
Mean = -0.954545
std = 4.879738
RMS = 4.917501
***Row Num = 247
Min = -12.000000
Max = 8.000000
Mean = -1.113636
std = 3.804623
RMS = 3.922546
***Row Num = 248
Min = -3.000000
Max = 2.000000
Mean = -0.840909
std = 1.445815
RMS = 1.658312
______
***Row Num = 249
Min = -3.000000
Max = 2.000000
Mean = -0.954545
std = 1.363213
RMS = 1.651446
***Row Num = 250
Min = -9.000000
Max = 4.000000
Mean = -1.227273
```

```
std = 2.657710
RMS = 2.899843
_____
***Row Num = 251
Min = -26.000000
Max = 12.000000
Mean = -1.568182
std = 6.139456
RMS = 6.268609
_____
***Row Num = 252
Min = -11.000000
Max = 21.000000
Mean = -0.477273
std = 5.114906
RMS = 5.078923
______
***Row Num = 253
Min = -117.000000
Max = 72.000000
Mean = -6.795455
std = 40.465075
RMS = 40.575687
______
***Row Num = 254
Min = -50.000000
Max = 25.000000
Mean = -5.386364
std = 17.536959
RMS = 18.154013
***Row Num = 255
Min = -25.000000
Max = 40.000000
Mean = -1.590909
std = 11.568438
RMS = 11.546349
***Row Num = 256
Min = -47.000000
Max = 92.000000
Mean = -0.204545
std = 21.529406
RMS = 21.284331
_____
***Row Num = 257
Min = -128.000000
Max = 127.000000
Mean = -3.227273
std = 71.299194
```

```
RMS = 70.558164
______
***Row Num = 258
Min = -93.000000
Max = 82.000000
Mean = -0.227273
std = 33.993066
RMS = 33.605330
_____
***Row Num = 259
Min = -39.000000
Max = 32.000000
Mean = -5.000000
std = 16.988368
RMS = 17.522713
_____
***Row Num = 260
Min = -72.000000
Max = 69.000000
Mean = -1.818182
std = 28.656159
RMS = 28.386937
_____
***Row Num = 261
Min = -39.750000
Max = 49.563000
Mean = -1.504273
std = 17.047227
RMS = 16.919399
***Row Num = 262
Min = -39.750000
Max = 49.563000
Mean = -1.504273
std = 17.047227
RMS = 16.919399
______
***Row Num = 263
Min = -39.750000
Max = 49.563000
Mean = -1.504273
std = 17.047227
RMS = 16.919399
***Row Num = 264
Min = -108.060000
Max = 74.000000
Mean = 1.686114
std = 34.367897
RMS = 34.016921
```

```
_____
***Row Num = 265
Min = -108.060000
Max = 74.000000
Mean = 1.686114
std = 34.367897
RMS = 34.016921
_____
***Row Num = 266
Min = -108.060000
Max = 74.000000
Mean = 1.686114
std = 34.367897
RMS = 34.016921
***Row Num = 267
Min = 2.513900
Max = 2.672700
Mean = 2.598380
std = 0.048098
RMS = 2.598815
______
***Row Num = 268
Min = 3.031700
Max = 3.069000
Mean = 3.048657
std = 0.011501
RMS = 3.048678
_____
***Row Num = 269
Min = 0.857330
Max = 1.085000
Mean = 0.968121
std = 0.060377
RMS = 0.969959
***Row Num = 270
Min = 6.385800
Max = 7.696200
Mean = 7.096377
std = 0.398624
RMS = 7.107310
_____
***Row Num = 271
Min = 2.988400
Max = 5.804700
Mean = 4.595568
std = 1.148081
RMS = 4.733643
```

```
***Row Num = 272
Min = 0.001511
Max = 9.994900
Mean = 3.117266
std = 3.598703
RMS = 4.730082
***Row Num = 273
Min = 0.877930
Max = 1.046900
Mean = 0.935048
std = 0.031208
RMS = 0.935556
______
***Row Num = 274
Min = -0.454100
Max = -0.169430
Mean = -0.345981
std = 0.050562
RMS = 0.349573
_____
***Row Num = 275
Min = -0.085449
Max = 0.141600
Mean = 0.041437
std = 0.045459
RMS = 0.061128
***Row Num = 276
Min = -1.513700
Max = 2.049800
Mean = -0.001209
std = 0.687188
RMS = 0.679335
______
***Row Num = 277
Min = 0.020996
Max = 1.082500
Mean = 0.716928
std = 0.254461
RMS = 0.759780
_____
***Row Num = 278
Min = -0.512210
Max = 1.142600
Mean = 0.404098
std = 0.284401
RMS = 0.492282
***Row Num = 279
```

```
Min = -6.000000
Max = 7.000000
Mean = -0.727273
std = 2.975588
RMS = 3.030152
***Row Num = 280
Min = -11.000000
Max = 12.000000
Mean = -0.704545
std = 4.934829
RMS = 4.929042
***Row Num = 281
Min = -16.000000
Max = 17.000000
Mean = -0.863636
std = 5.115371
RMS = 5.130125
_____
***Row Num = 282
Min = -2.000000
Max = 2.000000
Mean = -0.636364
std = 1.013649
RMS = 1.187051
______
***Row Num = 283
Min = -4.000000
Max = 6.000000
Mean = -0.772727
std = 1.915222
RMS = 2.044949
_____
***Row Num = 284
Min = -6.000000
Max = 5.000000
Mean = -0.818182
std = 2.202248
RMS = 2.325745
______
***Row Num = 285
Min = -22.000000
Max = 20.000000
Mean = -0.818182
std = 6.922403
RMS = 6.892024
***Row Num = 286
Min = -13.000000
```

```
Max = 17.000000
Mean = -0.863636
std = 4.648535
RMS = 4.675857
______
***Row Num = 287
Min = -126.000000
Max = 61.000000
Mean = 0.568182
std = 37.921828
RMS = 37.492727
_____
***Row Num = 288
Min = -50.000000
Max = 65.000000
Mean = 0.477273
std = 27.156299
RMS = 26.850174
_____
***Row Num = 289
Min = -21.000000
Max = 29.000000
Mean = -0.636364
std = 12.990320
RMS = 12.857612
______
***Row Num = 290
Min = -84.000000
Max = 57.000000
Mean = 0.159091
std = 23.777988
RMS = 23.506769
______
***Row Num = 291
Min = -107.000000
Max = 127.000000
Mean = 10.090909
std = 54.180928
RMS = 54.503961
-----
***Row Num = 292
Min = -61.000000
Max = 68.000000
Mean = 9.704545
std = 26.623630
RMS = 28.051495
_____
***Row Num = 293
Min = -59.000000
Max = 63.000000
```

```
Mean = 1.840909
std = 20.305737
RMS = 20.157899
______
***Row Num = 294
Min = -61.000000
Max = 82.000000
Mean = -0.750000
std = 29.095772
RMS = 28.773015
***Row Num = 295
Min = -47.313000
Max = 56.563000
Mean = -1.217295
std = 20.196149
RMS = 20.002404
______
***Row Num = 296
Min = -47.313000
Max = 56.563000
Mean = -1.217295
std = 20.196149
RMS = 20.002404
***Row Num = 297
Min = -47.313000
Max = 56.563000
Mean = -1.217295
std = 20.196149
RMS = 20.002404
***Row Num = 298
Min = -176.380000
Max = 136.190000
Mean = -4.736091
std = 56.539411
RMS = 56.093522
______
***Row Num = 299
Min = -176.380000
Max = 136.190000
Mean = -4.736091
std = 56.539411
RMS = 56.093522
***Row Num = 300
Min = -176.380000
Max = 136.190000
Mean = -4.736091
```

```
std = 56.539411
RMS = 56.093522
_____
***Row Num = 301
Min = 2.546800
Max = 2.761800
Mean = 2.678400
std = 0.065069
RMS = 2.679172
_____
***Row Num = 302
Min = 3.039300
Max = 3.097200
Mean = 3.064325
std = 0.017550
RMS = 3.064374
***Row Num = 303
Min = 0.787290
Max = 1.035200
Mean = 0.889599
std = 0.064351
RMS = 0.891871
______
***Row Num = 304
Min = 6.416900
Max = 7.275100
Mean = 6.903489
std = 0.259475
RMS = 6.908252
***Row Num = 305
Min = 2.958300
Max = 5.832700
Mean = 4.919673
std = 0.923739
RMS = 5.003707
***Row Num = 306
Min = 0.188290
Max = 2.455300
Mean = 1.184464
std = 0.827028
RMS = 1.439231
_____
***Row Num = 307
Min = 0.816890
Max = 1.004400
Mean = 0.931584
std = 0.029118
```

```
RMS = 0.932029
***Row Num = 308
Min = -0.472170
Max = -0.263670
Mean = -0.355380
std = 0.038342
RMS = 0.357395
______
***Row Num = 309
Min = -0.116210
Max = 0.155760
Mean = 0.044944
std = 0.047617
RMS = 0.065083
_____
***Row Num = 310
Min = -1.052700
Max = 2.172400
Mean = 0.009623
std = 0.688109
RMS = 0.680313
_____
***Row Num = 311
Min = 0.204100
Max = 1.064000
Mean = 0.712280
std = 0.211120
RMS = 0.742227
***Row Num = 312
Min = -1.498000
Max = 1.168900
Mean = 0.403598
std = 0.421395
RMS = 0.580026
______
***Row Num = 313
Min = -7.000000
Max = 5.000000
Mean = -0.977273
std = 2.680582
RMS = 2.824407
***Row Num = 314
Min = -8.000000
Max = 11.000000
Mean = 0.090909
std = 3.765314
RMS = 3.723390
```

```
_____
***Row Num = 315
Min = -9.000000
Max = 15.000000
Mean = -0.272727
std = 4.652399
RMS = 4.607306
_____
***Row Num = 316
Min = -4.000000
Max = 1.000000
Mean = -1.204545
std = 1.192604
RMS = 1.685500
***Row Num = 317
Min = -5.000000
Max = 1.000000
Mean = -1.431818
std = 1.420739
RMS = 2.005674
______
***Row Num = 318
Min = -8.000000
Max = 2.000000
Mean = -1.159091
std = 2.291980
RMS = 2.545049
_____
***Row Num = 319
Min = -18.000000
Max = 11.000000
Mean = -1.409091
std = 5.239910
RMS = 5.368257
***Row Num = 320
Min = -14.000000
Max = 10.000000
Mean = -0.886364
std = 4.183111
RMS = 4.229227
______
***Row Num = 321
Min = -102.000000
Max = 79.000000
Mean = 2.045455
std = 35.695713
RMS = 35.346981
```

```
***Row Num = 322
Min = -92.000000
Max = 94.000000
Mean = 1.818182
std = 35.883709
RMS = 35.520161
***Row Num = 323
Min = -27.000000
Max = 88.000000
Mean = 2.090909
std = 23.676913
RMS = 23.499516
______
***Row Num = 324
Min = -49.000000
Max = 35.000000
Mean = -3.363636
std = 16.695760
RMS = 16.844206
_____
***Row Num = 325
Min = -128.000000
Max = 63.000000
Mean = -21.977273
std = 46.738007
RMS = 51.164396
***Row Num = 326
Min = -88.000000
Max = 68.000000
Mean = -1.590909
std = 31.615656
RMS = 31.294786
______
***Row Num = 327
Min = -36.000000
Max = 61.000000
Mean = -1.159091
std = 17.806379
RMS = 17.640990
_____
***Row Num = 328
Min = -98.000000
Max = 90.000000
Mean = -5.681818
std = 32.991735
RMS = 33.105891
***Row Num = 329
```

```
Min = -39.563000
Max = 30.813000
Mean = -0.684625
std = 14.127260
RMS = 13.982571
_____
***Row Num = 330
Min = -39.563000
Max = 30.813000
Mean = -0.684625
std = 14.127260
RMS = 13.982571
***Row Num = 331
Min = -39.563000
Max = 30.813000
Mean = -0.684625
std = 14.127260
RMS = 13.982571
_____
***Row Num = 332
Min = -87.313000
Max = 125.880000
Mean = 7.504636
std = 46.716142
RMS = 46.788007
______
***Row Num = 333
Min = -87.313000
Max = 125.880000
Mean = 7.504636
std = 46.716142
RMS = 46.788007
_____
***Row Num = 334
Min = -87.313000
Max = 125.880000
Mean = 7.504636
std = 46.716142
RMS = 46.788007
______
***Row Num = 335
Min = 2.605600
Max = 2.774200
Mean = 2.703523
std = 0.046931
RMS = 2.703921
***Row Num = 336
Min = 3.061700
```

```
Max = 3.108100
Mean = 3.085114
std = 0.012424
RMS = 3.085138
______
***Row Num = 337
Min = 0.786840
Max = 0.986220
Mean = 0.889899
std = 0.051293
RMS = 0.891343
***Row Num = 338
Min = 6.190200
Max = 7.424200
Mean = 6.880789
std = 0.363618
RMS = 6.890172
______
***Row Num = 339
Min = 3.019100
Max = 5.815300
Mean = 4.956784
std = 0.948277
RMS = 5.044651
______
***Row Num = 340
Min = 0.094847
Max = 2.291000
Mean = 1.031908
std = 0.799024
RMS = 1.299525
______
***Row Num = 341
Min = 0.866210
Max = 1.018600
Mean = 0.929389
std = 0.032897
RMS = 0.929958
-----
***Row Num = 342
Min = -0.490230
Max = -0.193360
Mean = -0.368895
std = 0.052430
RMS = 0.372519
_____
***Row Num = 343
Min = -0.065430
Max = 0.168460
```

```
Mean = 0.064198
std = 0.050768
RMS = 0.081488
______
***Row Num = 344
Min = -1.459500
Max = 1.570800
Mean = -0.012398
std = 0.656004
RMS = 0.648625
***Row Num = 345
Min = -0.089355
Max = 1.096200
Mean = 0.751377
std = 0.257272
RMS = 0.793254
______
***Row Num = 346
Min = -3.159700
Max = 1.138700
Mean = 0.338944
std = 0.586649
RMS = 0.671728
_____
***Row Num = 347
Min = -18.000000
Max = 11.000000
Mean = -0.409091
std = 4.867157
RMS = 4.828890
***Row Num = 348
Min = -14.000000
Max = 13.000000
Mean = -0.613636
std = 5.301232
RMS = 5.276449
______
***Row Num = 349
Min = -7.000000
Max = 11.000000
Mean = -1.068182
std = 3.737912
RMS = 3.846486
***Row Num = 350
Min = -6.000000
Max = 2.000000
Mean = -1.022727
```

```
std = 1.405779
RMS = 1.725478
_____
***Row Num = 351
Min = -6.000000
Max = 4.000000
Mean = -1.068182
std = 1.783617
RMS = 2.061553
_____
***Row Num = 352
Min = -4.000000
Max = 4.000000
Mean = -0.909091
std = 1.840351
RMS = 2.033805
***Row Num = 353
Min = -8.000000
Max = 15.000000
Mean = 0.000000
std = 3.760257
RMS = 3.717282
______
***Row Num = 354
Min = -4.000000
Max = 7.000000
Mean = 0.090909
std = 2.826932
RMS = 2.796101
***Row Num = 355
Min = -90.000000
Max = 69.000000
Mean = -1.295455
std = 34.568826
RMS = 34.198285
***Row Num = 356
Min = -98.000000
Max = 68.000000
Mean = 5.386364
std = 28.990950
RMS = 29.161385
_____
***Row Num = 357
Min = -21.000000
Max = 48.000000
Mean = 4.113636
std = 13.930418
```

```
RMS = 14.372480
______
***Row Num = 358
Min = -67.000000
Max = 46.000000
Mean = 0.409091
std = 19.880244
RMS = 19.657291
_____
***Row Num = 359
Min = -128.000000
Max = 117.000000
Mean = 4.977273
std = 52.047603
RMS = 51.692931
_____
***Row Num = 360
Min = -52.000000
Max = 60.000000
Mean = 2.409091
std = 25.387525
RMS = 25.212731
_____
***Row Num = 361
Min = -42.000000
Max = 28.000000
Mean = -1.409091
std = 15.376391
RMS = 15.265826
***Row Num = 362
Min = -69.000000
Max = 127.000000
Mean = -2.204545
std = 35.262853
RMS = 34.929474
______
***Row Num = 363
Min = -37.188000
Max = 27.938000
Mean = -0.453114
std = 13.603141
RMS = 13.455303
***Row Num = 364
Min = -37.188000
Max = 27.938000
Mean = -0.453114
std = 13.603141
RMS = 13.455303
```

```
_____
***Row Num = 365
Min = -37.188000
Max = 27.938000
Mean = -0.453114
std = 13.603141
RMS = 13.455303
_____
***Row Num = 366
Min = -137.630000
Max = 247.380000
Mean = 7.127898
std = 57.703960
RMS = 57.488067
***Row Num = 367
Min = -137.630000
Max = 247.380000
Mean = 7.127898
std = 57.703960
RMS = 57.488067
______
***Row Num = 368
Min = -137.630000
Max = 247.380000
Mean = 7.127898
std = 57.703960
RMS = 57.488067
_____
***Row Num = 369
Min = 2.654000
Max = 2.824700
Mean = 2.759380
std = 0.037601
RMS = 2.759630
***Row Num = 370
Min = 3.087100
Max = 3.129700
Mean = 3.104891
std = 0.010168
RMS = 3.104907
_____
***Row Num = 371
Min = 0.721350
Max = 0.989350
Mean = 0.828969
std = 0.056320
RMS = 0.830836
```

```
***Row Num = 372
Min = 6.399700
Max = 7.603900
Mean = 6.963455
std = 0.275217
RMS = 6.968768
***Row Num = 373
Min = 2.986700
Max = 5.765900
Mean = 4.988277
std = 0.840937
RMS = 5.057076
______
***Row Num = 374
Min = 0.005392
Max = 2.427200
Mean = 1.046961
std = 0.711051
RMS = 1.261043
_____
***Row Num = 375
Min = 0.845700
Max = 1.082500
Mean = 0.917770
std = 0.042286
RMS = 0.918721
***Row Num = 376
Min = -0.494140
Max = -0.310060
Mean = -0.372570
std = 0.037789
RMS = 0.374438
______
***Row Num = 377
Min = -0.163570
Max = 0.260740
Mean = 0.103194
std = 0.080510
RMS = 0.130321
_____
***Row Num = 378
Min = -1.136700
Max = 2.035600
Mean = 0.062312
std = 0.700824
RMS = 0.695611
***Row Num = 379
```

```
Min = -0.049316
Max = 1.219200
Mean = 0.686866
std = 0.276898
RMS = 0.739402
***Row Num = 380
Min = -0.835940
Max = 1.453600
Mean = 0.423040
std = 0.396785
RMS = 0.576908
***Row Num = 381
Min = -7.000000
Max = 10.000000
Mean = -0.181818
std = 3.336010
RMS = 3.302891
_____
***Row Num = 382
Min = -6.000000
Max = 16.000000
Mean = -0.136364
std = 3.997621
RMS = 3.954284
______
***Row Num = 383
Min = -11.000000
Max = 7.000000
Mean = -0.977273
std = 3.209641
RMS = 3.320049
***Row Num = 384
Min = -8.000000
Max = 2.000000
Mean = -1.613636
std = 1.673541
RMS = 2.311041
______
***Row Num = 385
Min = -5.000000
Max = 4.000000
Mean = -1.250000
std = 1.644229
RMS = 2.050499
***Row Num = 386
Min = -11.000000
```

```
Max = 11.000000
Mean = -0.818182
std = 3.149549
RMS = 3.219260
______
***Row Num = 387
Min = -33.000000
Max = 43.000000
Mean = 0.363636
std = 9.363688
RMS = 9.263810
***Row Num = 388
Min = -10.000000
Max = 8.000000
Mean = -0.272727
std = 3.315668
RMS = 3.289100
_____
***Row Num = 389
Min = -128.000000
Max = 100.000000
Mean = -1.113636
std = 41.171347
RMS = 40.716034
______
***Row Num = 390
Min = -48.000000
Max = 40.000000
Mean = -1.840909
std = 18.115833
RMS = 18.003156
______
***Row Num = 391
Min = -28.000000
Max = 16.000000
Mean = -2.386364
std = 9.344109
RMS = 9.540583
-----
***Row Num = 392
Min = -29.000000
Max = 82.000000
Mean = 2.068182
std = 18.092010
RMS = 18.004419
***Row Num = 393
Min = -128.000000
Max = 127.000000
```

```
Mean = -10.363636
std = 55.453350
RMS = 55.790599
______
***Row Num = 394
Min = -98.000000
Max = 101.000000
Mean = -4.840909
std = 32.873926
RMS = 32.856783
***Row Num = 395
Min = -29.000000
Max = 47.000000
Mean = 1.181818
std = 14.533478
RMS = 14.415900
______
***Row Num = 396
Min = -71.000000
Max = 61.000000
Mean = -5.340909
std = 24.226588
RMS = 24.538004
***Row Num = 397
Min = -84.313000
Max = 34.188000
Mean = -4.934727
std = 22.149486
RMS = 22.445518
***Row Num = 398
Min = -84.313000
Max = 34.188000
Mean = -4.934727
std = 22.149486
RMS = 22.445518
______
***Row Num = 399
Min = -84.313000
Max = 34.188000
Mean = -4.934727
std = 22.149486
RMS = 22.445518
***Row Num = 400
Min = -112.560000
Max = 95.563000
Mean = 0.921875
```

```
std = 42.039710
RMS = 41.569464
______
***Row Num = 401
Min = -112.560000
Max = 95.563000
Mean = 0.921875
std = 42.039710
RMS = 41.569464
_____
***Row Num = 402
Min = -112.560000
Max = 95.563000
Mean = 0.921875
std = 42.039710
RMS = 41.569464
______
***Row Num = 403
Min = 2.525600
Max = 3.048900
Mean = 2.900168
std = 0.168312
RMS = 2.904937
______
***Row Num = 404
Min = 3.054900
Max = 3.182100
Mean = 3.133159
std = 0.037458
RMS = 3.133378
***Row Num = 405
Min = 0.394700
Max = 0.730610
Mean = 0.554434
std = 0.082430
RMS = 0.560390
***Row Num = 406
Min = 6.465200
Max = 7.604500
Mean = 6.950905
std = 0.328077
RMS = 6.958467
______
***Row Num = 407
Min = 3.041900
Max = 5.812800
Mean = 4.801255
std = 1.048353
```

```
RMS = 4.911834
***Row Num = 408
Min = 0.096076
Max = 9.988400
Mean = 4.957840
std = 4.397978
RMS = 6.594148
______
***Row Num = 409
Min = 0.813960
Max = 1.012200
Mean = 0.924506
std = 0.030201
RMS = 0.924988
_____
***Row Num = 410
Min = -0.462890
Max = -0.310550
Mean = -0.369629
std = 0.031337
RMS = 0.370925
_____
***Row Num = 411
Min = 0.012695
Max = 0.188480
Mean = 0.098200
std = 0.039276
RMS = 0.105597
***Row Num = 412
Min = -1.483900
Max = 1.699200
Mean = -0.077760
std = 0.597742
RMS = 0.596005
______
***Row Num = 413
Min = 0.212890
Max = 0.962890
Mean = 0.698840
std = 0.203105
RMS = 0.727112
***Row Num = 414
Min = -1.051800
Max = 0.990720
Mean = 0.444801
std = 0.318923
RMS = 0.545205
```

```
_____
***Row Num = 415
Min = -11.000000
Max = 4.000000
Mean = -1.704545
std = 3.173873
RMS = 3.570714
_____
***Row Num = 416
Min = -8.000000
Max = 13.000000
Mean = -0.090909
std = 4.062410
RMS = 4.017009
***Row Num = 417
Min = -21.000000
Max = 4.000000
Mean = -1.318182
std = 3.856572
RMS = 4.033947
______
***Row Num = 418
Min = -3.000000
Max = 3.000000
Mean = -0.818182
std = 1.368631
RMS = 1.581139
_____
***Row Num = 419
Min = -3.000000
Max = 4.000000
Mean = -0.431818
std = 1.605191
RMS = 1.644550
***Row Num = 420
Min = -7.000000
Max = 13.000000
Mean = -0.659091
std = 3.041903
RMS = 3.078518
______
***Row Num = 421
Min = -57.000000
Max = 43.000000
Mean = -0.977273
std = 12.748896
RMS = 12.641023
```

```
***Row Num = 422
Min = -6.000000
Max = 16.000000
Mean = -0.545455
std = 3.656498
RMS = 3.655631
***Row Num = 423
Min = -88.000000
Max = 58.000000
Mean = 2.045455
std = 31.437612
RMS = 31.145553
______
***Row Num = 424
Min = -60.000000
Max = 44.000000
Mean = 2.954545
std = 19.870458
RMS = 19.864312
_____
***Row Num = 425
Min = -29.000000
Max = 21.000000
Mean = -0.431818
std = 10.597055
RMS = 10.484838
***Row Num = 426
Min = -43.000000
Max = 61.000000
Mean = -3.500000
std = 16.374257
RMS = 16.561181
______
***Row Num = 427
Min = -123.000000
Max = 127.000000
Mean = -5.477273
std = 54.408228
RMS = 54.064566
_____
***Row Num = 428
Min = -42.000000
Max = 79.000000
Mean = 8.681818
std = 22.609704
RMS = 23.978210
***Row Num = 429
```

```
Min = -60.000000
Max = 29.000000
Mean = -1.568182
std = 17.501359
RMS = 17.372261
_____
***Row Num = 430
Min = -62.000000
Max = 59.000000
Mean = -5.818182
std = 26.974814
RMS = 27.293855
***Row Num = 431
Min = -62.375000
Max = 31.750000
Mean = -1.198898
std = 15.818581
RMS = 15.683681
_____
***Row Num = 432
Min = -62.375000
Max = 31.750000
Mean = -1.198898
std = 15.818581
RMS = 15.683681
***Row Num = 433
Min = -62.375000
Max = 31.750000
Mean = -1.198898
std = 15.818581
RMS = 15.683681
***Row Num = 434
Min = -108.500000
Max = 80.750000
Mean = 4.120795
std = 36.098050
RMS = 35.922625
______
***Row Num = 435
Min = -108.500000
Max = 80.750000
Mean = 4.120795
std = 36.098050
RMS = 35.922625
***Row Num = 436
Min = -108.500000
```

```
Max = 80.750000
Mean = 4.120795
std = 36.098050
RMS = 35.922625
______
***Row Num = 437
Min = 2.685900
Max = 2.997800
Mean = 2.906173
std = 0.065593
RMS = 2.906896
***Row Num = 438
Min = 3.083600
Max = 3.149400
Mean = 3.125700
std = 0.015769
RMS = 3.125739
_____
***Row Num = 439
Min = 0.357280
Max = 0.593570
Mean = 0.442607
std = 0.048433
RMS = 0.445189
______
***Row Num = 440
Min = 6.351100
Max = 7.634000
Mean = 6.798261
std = 0.318317
RMS = 6.805540
______
***Row Num = 441
Min = 2.896000
Max = 5.797400
Mean = 5.021764
std = 0.900685
RMS = 5.100089
-----
***Row Num = 442
Min = 0.039035
Max = 9.680200
Mean = 1.920057
std = 2.873890
RMS = 3.429017
_____
***Row Num = 443
Min = 0.848630
Max = 0.996090
```

```
Mean = 0.925148
std = 0.027533
RMS = 0.925548
______
***Row Num = 444
Min = -0.497560
Max = -0.271480
Mean = -0.365356
std = 0.038633
RMS = 0.367347
***Row Num = 445
Min = -0.107420
Max = 0.195800
Mean = 0.075240
std = 0.064368
RMS = 0.098540
______
***Row Num = 446
Min = -1.490200
Max = 1.658200
Mean = -0.072352
std = 0.629705
RMS = 0.626698
***Row Num = 447
Min = 0.104980
Max = 1.027800
Mean = 0.727772
std = 0.233514
RMS = 0.763506
***Row Num = 448
Min = -1.492200
Max = 1.277800
Mean = 0.448929
std = 0.424615
RMS = 0.614604
______
***Row Num = 449
Min = -24.000000
Max = 7.000000
Mean = -1.454545
std = 4.805300
RMS = 4.968080
***Row Num = 450
Min = -14.000000
Max = 11.000000
Mean = -2.318182
```

```
std = 5.721330
RMS = 6.112580
_____
***Row Num = 451
Min = -11.000000
Max = 14.000000
Mean = -2.022727
std = 4.167921
RMS = 4.590009
_____
***Row Num = 452
Min = -6.000000
Max = 4.000000
Mean = -1.363636
std = 1.868850
RMS = 2.296242
***Row Num = 453
Min = -6.000000
Max = 4.000000
Mean = -1.409091
std = 1.944798
RMS = 2.383656
______
***Row Num = 454
Min = -14.000000
Max = 4.000000
Mean = -1.795455
std = 2.824968
RMS = 3.320049
***Row Num = 455
Min = -25.000000
Max = 8.000000
Mean = -3.522727
std = 6.568029
RMS = 7.387028
***Row Num = 456
Min = -8.000000
Max = 3.000000
Mean = -1.863636
std = 2.575293
RMS = 3.155082
_____
***Row Num = 457
Min = -100.000000
Max = 64.000000
Mean = -5.795455
std = 40.523080
```

```
RMS = 40.476986
______
***Row Num = 458
Min = -81.000000
Max = 68.000000
Mean = -7.795455
std = 28.959940
RMS = 29.671305
_____
***Row Num = 459
Min = -23.000000
Max = 27.000000
Mean = -0.886364
std = 11.592331
RMS = 11.494070
_____
***Row Num = 460
Min = -61.000000
Max = 41.000000
Mean = -4.590909
std = 20.617579
RMS = 20.892582
_____
***Row Num = 461
Min = -128.000000
Max = 127.000000
Mean = -15.431818
std = 62.973009
RMS = 64.137459
***Row Num = 462
Min = -87.000000
Max = 96.000000
Mean = 1.704545
std = 38.760793
RMS = 38.355692
______
***Row Num = 463
Min = -43.000000
Max = 38.000000
Mean = -1.409091
std = 19.038905
RMS = 18.873984
***Row Num = 464
Min = -69.000000
Max = 125.000000
Mean = -4.977273
std = 31.578244
RMS = 31.611635
```

```
_____
***Row Num = 465
Min = -79.313000
Max = 36.000000
Mean = -1.863659
std = 18.529109
RMS = 18.411903
-----
***Row Num = 466
Min = -79.313000
Max = 36.000000
Mean = -1.863659
std = 18.529109
RMS = 18.411903
***Row Num = 467
Min = -79.313000
Max = 36.000000
Mean = -1.863659
std = 18.529109
RMS = 18.411903
______
***Row Num = 468
Min = -105.690000
Max = 237.630000
Mean = 8.964602
std = 52.800971
RMS = 52.961725
_____
***Row Num = 469
Min = -105.690000
Max = 237.630000
Mean = 8.964602
std = 52.800971
RMS = 52.961725
***Row Num = 470
Min = -105.690000
Max = 237.630000
Mean = 8.964602
std = 52.800971
RMS = 52.961725
______
***Row Num = 471
Min = 2.512500
Max = 2.949300
Mean = 2.831882
std = 0.095975
RMS = 2.833471
```

```
***Row Num = 472
Min = 3.045300
Max = 3.148100
Mean = 3.110973
std = 0.027880
RMS = 3.111095
***Row Num = 473
Min = 0.455240
Max = 0.836990
Mean = 0.591720
std = 0.082864
RMS = 0.597364
______
***Row Num = 474
Min = 6.349600
Max = 7.651000
Mean = 6.839505
std = 0.341431
RMS = 6.847828
_____
***Row Num = 475
Min = 2.964700
Max = 5.844200
Mean = 5.025495
std = 0.868612
RMS = 5.098328
***Row Num = 476
Min = 0.016322
Max = 9.583300
Mean = 1.955776
std = 2.862438
RMS = 3.439825
______
***Row Num = 477
Min = 0.878910
Max = 1.029300
Mean = 0.929343
std = 0.024186
RMS = 0.929651
_____
***Row Num = 478
Min = -0.432130
Max = -0.293460
Mean = -0.355502
std = 0.030079
RMS = 0.356744
***Row Num = 479
```

```
Min = -0.050293
Max = 0.168460
Mean = 0.076316
std = 0.040426
RMS = 0.086147
_____
***Row Num = 480
Min = -1.252400
Max = 2.433100
Mean = -0.027167
std = 0.707081
RMS = 0.699527
***Row Num = 481
Min = -0.463380
Max = 0.940430
Mean = 0.659579
std = 0.274224
RMS = 0.713116
_____
***Row Num = 482
Min = -0.079102
Max = 1.296400
Mean = 0.512662
std = 0.290290
RMS = 0.587516
______
***Row Num = 483
Min = -10.000000
Max = 10.000000
Mean = -0.704545
std = 3.239147
RMS = 3.278719
***Row Num = 484
Min = -14.000000
Max = 15.000000
Mean = -0.090909
std = 5.842181
RMS = 5.776126
______
***Row Num = 485
Min = -20.000000
Max = 12.000000
Mean = -0.522727
std = 5.440967
RMS = 5.404123
***Row Num = 486
Min = -5.000000
```

```
Max = 2.000000
Mean = -1.363636
std = 1.331041
RMS = 1.894969
______
***Row Num = 487
Min = -7.000000
Max = 6.000000
Mean = -1.113636
std = 2.002509
RMS = 2.271363
***Row Num = 488
Min = -8.000000
Max = 3.000000
Mean = -0.977273
std = 1.934853
RMS = 2.147938
_____
***Row Num = 489
Min = -7.000000
Max = 16.000000
Mean = 0.477273
std = 3.637586
RMS = 3.627546
_____
***Row Num = 490
Min = -8.000000
Max = 3.000000
Mean = -0.931818
std = 2.537145
RMS = 2.675648
______
***Row Num = 491
Min = -82.000000
Max = 127.000000
Mean = 0.454545
std = 37.159277
RMS = 36.737397
-----
***Row Num = 492
Min = -53.000000
Max = 67.000000
Mean = 1.431818
std = 22.894498
RMS = 22.678083
***Row Num = 493
Min = -45.000000
Max = 17.000000
```

```
Mean = -4.863636
std = 13.850684
RMS = 14.530532
______
***Row Num = 494
Min = -45.000000
Max = 62.000000
Mean = -1.181818
std = 21.342471
RMS = 21.131622
***Row Num = 495
Min = -128.000000
Max = 127.000000
Mean = -16.318182
std = 69.572707
RMS = 70.686890
______
***Row Num = 496
Min = -64.000000
Max = 87.000000
Mean = -0.272727
std = 28.842285
RMS = 28.513952
_____
***Row Num = 497
Min = -40.000000
Max = 47.000000
Mean = -0.090909
std = 16.524567
RMS = 16.335961
***Row Num = 498
Min = -68.000000
Max = 91.000000
Mean = 5.295455
std = 33.179273
RMS = 33.224785
______
***Row Num = 499
Min = -29.813000
Max = 28.625000
Mean = -1.221614
std = 12.001371
RMS = 11.926935
***Row Num = 500
Min = -29.813000
Max = 28.625000
Mean = -1.221614
```

```
std = 12.001371
RMS = 11.926935
______
***Row Num = 501
Min = -29.813000
Max = 28.625000
Mean = -1.221614
std = 12.001371
RMS = 11.926935
_____
***Row Num = 502
Min = -137.130000
Max = 178.500000
Mean = -0.798432
std = 54.220102
RMS = 53.606369
______
***Row Num = 503
Min = -137.130000
Max = 178.500000
Mean = -0.798432
std = 54.220102
RMS = 53.606369
______
***Row Num = 504
Min = -137.130000
Max = 178.500000
Mean = -0.798432
std = 54.220102
RMS = 53.606369
***Row Num = 505
Min = 2.779500
Max = 2.908900
Mean = 2.827270
std = 0.031494
RMS = 2.827442
***Row Num = 506
Min = 3.067400
Max = 3.114400
Mean = 3.088080
std = 0.014157
RMS = 3.088111
_____
***Row Num = 507
Min = 0.439480
Max = 0.636010
Mean = 0.547133
std = 0.035987
```

```
RMS = 0.548288
***Row Num = 508
Min = 6.262100
Max = 7.310900
Mean = 6.723568
std = 0.273073
RMS = 6.728985
______
***Row Num = 509
Min = 3.045600
Max = 5.769900
Mean = 4.990459
std = 0.833709
RMS = 5.058059
_____
***Row Num = 510
Min = 0.000918
Max = 9.986300
Mean = 2.759189
std = 3.726204
RMS = 4.602409
_____
***Row Num = 511
Min = 0.840820
Max = 0.996090
Mean = 0.927901
std = 0.030543
RMS = 0.928392
***Row Num = 512
Min = -0.447750
Max = -0.259280
Mean = -0.362193
std = 0.044519
RMS = 0.364857
______
***Row Num = 513
Min = -0.125000
Max = 0.143070
Mean = 0.044722
std = 0.054583
RMS = 0.070083
***Row Num = 514
Min = -1.536600
Max = 1.629900
Mean = 0.042702
std = 0.667263
RMS = 0.661018
```

```
_____
***Row Num = 515
Min = 0.112790
Max = 1.022500
Mean = 0.648005
std = 0.258722
RMS = 0.696654
_____
***Row Num = 516
Min = -0.592770
Max = 1.286100
Mean = 0.409367
std = 0.377971
RMS = 0.554253
***Row Num = 517
Min = -10.000000
Max = 13.000000
Mean = -0.454545
std = 5.262657
RMS = 5.222330
______
***Row Num = 518
Min = -18.000000
Max = 51.000000
Mean = 2.250000
std = 11.668134
RMS = 11.752176
_____
***Row Num = 519
Min = -21.000000
Max = 51.000000
Mean = 1.204545
std = 11.780116
RMS = 11.707612
***Row Num = 520
Min = -8.000000
Max = 3.000000
Mean = -1.295455
std = 2.119451
RMS = 2.463368
______
***Row Num = 521
Min = -8.000000
Max = 10.000000
Mean = -1.022727
std = 3.030762
RMS = 3.165869
```

```
***Row Num = 522
Min = -19.000000
Max = 9.000000
Mean = -0.568182
std = 4.353014
RMS = 4.340612
***Row Num = 523
Min = -49.000000
Max = 32.000000
Mean = 0.045455
std = 13.454410
RMS = 13.300718
______
***Row Num = 524
Min = -19.000000
Max = 27.000000
Mean = -2.068182
std = 8.015676
RMS = 8.189517
_____
***Row Num = 525
Min = -87.000000
Max = 94.000000
Mean = -2.159091
std = 42.488271
RMS = 42.058131
***Row Num = 526
Min = -55.000000
Max = 54.000000
Mean = -4.954545
std = 26.091034
RMS = 26.264390
______
***Row Num = 527
Min = -21.000000
Max = 17.000000
Mean = -1.909091
std = 9.382860
RMS = 9.470048
_____
***Row Num = 528
Min = -46.000000
Max = 29.000000
Mean = -1.318182
std = 14.718716
RMS = 14.610084
***Row Num = 529
```

```
Min = -122.000000
Max = 127.000000
Mean = 1.204545
std = 53.727815
RMS = 53.127420
_____
***Row Num = 530
Min = -97.000000
Max = 62.000000
Mean = 2.568182
std = 30.768753
RMS = 30.525325
***Row Num = 531
Min = -68.000000
Max = 44.000000
Mean = -4.090909
std = 21.378992
RMS = 21.526939
_____
***Row Num = 532
Min = -78.000000
Max = 114.000000
Mean = -4.022727
std = 34.680260
RMS = 34.519099
***Row Num = 533
Min = -27.688000
Max = 35.500000
Mean = -1.299750
std = 13.941700
RMS = 13.843512
______
***Row Num = 534
Min = -27.688000
Max = 35.500000
Mean = -1.299750
std = 13.941700
RMS = 13.843512
______
***Row Num = 535
Min = -27.688000
Max = 35.500000
Mean = -1.299750
std = 13.941700
RMS = 13.843512
***Row Num = 536
Min = -78.375000
```

```
Max = 159.440000
Mean = 8.375170
std = 42.708176
RMS = 43.042740
______
***Row Num = 537
Min = -78.375000
Max = 159.440000
Mean = 8.375170
std = 42.708176
RMS = 43.042740
***Row Num = 538
Min = -78.375000
Max = 159.440000
Mean = 8.375170
std = 42.708176
RMS = 43.042740
_____
***Row Num = 539
Min = 2.547200
Max = 2.817500
Mean = 2.695907
std = 0.079370
RMS = 2.697048
______
***Row Num = 540
Min = 3.044300
Max = 3.124900
Mean = 3.090402
std = 0.022250
RMS = 3.090481
______
***Row Num = 541
Min = 0.301050
Max = 0.632800
Mean = 0.441791
std = 0.072301
RMS = 0.447536
-----
***Row Num = 542
Min = 6.237100
Max = 7.844600
Mean = 6.966782
std = 0.438941
RMS = 6.980282
_____
***Row Num = 543
Min = 2.914800
Max = 5.709700
```

```
Mean = 4.791523
std = 1.054124
RMS = 4.903531
______
***Row Num = 544
Min = 0.016316
Max = 9.986700
Mean = 4.067145
std = 4.299179
RMS = 5.882562
***Row Num = 545
Min = 0.833010
Max = 1.011700
Mean = 0.931130
std = 0.035422
RMS = 0.931788
______
***Row Num = 546
Min = -0.471190
Max = -0.247070
Mean = -0.353028
std = 0.049424
RMS = 0.356393
_____
***Row Num = 547
Min = -0.120610
Max = 0.168460
Mean = 0.058582
std = 0.051742
RMS = 0.077771
_____
***Row Num = 548
Min = -1.263700
Max = 1.982400
Mean = 0.152043
std = 0.719122
RMS = 0.726980
______
***Row Num = 549
Min = -0.180660
Max = 0.942870
Mean = 0.611749
std = 0.274055
RMS = 0.669056
***Row Num = 550
Min = -0.242680
Max = 1.239700
Mean = 0.424393
```

```
std = 0.323229
RMS = 0.531237
_____
***Row Num = 551
Min = -17.000000
Max = 18.000000
Mean = -0.159091
std = 7.077456
RMS = 6.998376
_____
***Row Num = 552
Min = -19.000000
Max = 14.000000
Mean = -0.340909
std = 5.681235
RMS = 5.626641
***Row Num = 553
Min = -7.000000
Max = 14.000000
Mean = -1.136364
std = 3.137107
RMS = 3.302891
______
***Row Num = 554
Min = -7.000000
Max = 2.000000
Mean = -1.477273
std = 1.731898
RMS = 2.261335
***Row Num = 555
Min = -8.000000
Max = 5.000000
Mean = -1.250000
std = 2.393062
RMS = 2.675648
***Row Num = 556
Min = -14.000000
Max = 4.000000
Mean = -1.522727
std = 2.921362
RMS = 3.264826
_____
***Row Num = 557
Min = -47.000000
Max = 29.000000
Mean = -2.500000
std = 10.471445
```

```
RMS = 10.649370
______
***Row Num = 558
Min = -47.000000
Max = 13.000000
Mean = -2.090909
std = 7.897065
RMS = 8.081966
______
***Row Num = 559
Min = -58.000000
Max = 65.000000
Mean = -1.295455
std = 30.696246
RMS = 30.373059
_____
***Row Num = 560
Min = -79.000000
Max = 91.000000
Mean = -6.477273
std = 29.230033
RMS = 29.613035
_____
***Row Num = 561
Min = -25.000000
Max = 45.000000
Mean = -0.545455
std = 14.337225
RMS = 14.183858
***Row Num = 562
Min = -57.000000
Max = 48.000000
Mean = -3.909091
std = 20.158463
RMS = 20.307858
______
***Row Num = 563
Min = -128.000000
Max = 127.000000
Mean = -13.386364
std = 55.892844
RMS = 56.852481
***Row Num = 564
Min = -82.000000
Max = 95.000000
Mean = 0.863636
std = 35.348492
RMS = 34.955166
```

```
_____
***Row Num = 565
Min = -45.000000
Max = 27.000000
Mean = -0.795455
std = 15.075900
RMS = 14.924812
_____
***Row Num = 566
Min = -51.000000
Max = 58.000000
Mean = -3.090909
std = 26.541602
RMS = 26.419690
***Row Num = 567
Min = -83.938000
Max = 56.500000
Mean = -0.036943
std = 20.243752
RMS = 20.012421
______
***Row Num = 568
Min = -83.938000
Max = 56.500000
Mean = -0.036943
std = 20.243752
RMS = 20.012421
_____
***Row Num = 569
Min = -83.938000
Max = 56.500000
Mean = -0.036943
std = 20.243752
RMS = 20.012421
______
***Row Num = 570
Min = -104.440000
Max = 100.440000
Mean = 1.494352
std = 40.332985
RMS = 39.900015
_____
***Row Num = 571
Min = -104.440000
Max = 100.440000
Mean = 1.494352
std = 40.332985
RMS = 39.900015
```

```
***Row Num = 572
Min = -104.440000
Max = 100.440000
Mean = 1.494352
std = 40.332985
RMS = 39.900015
***Row Num = 573
Min = 2.666900
Max = 2.855500
Mean = 2.747218
std = 0.044921
RMS = 2.747577
______
***Row Num = 574
Min = 3.041600
Max = 3.107800
Mean = 3.076534
std = 0.014941
RMS = 3.076570
_____
***Row Num = 575
Min = 0.343500
Max = 0.518510
Mean = 0.442451
std = 0.044903
RMS = 0.444672
***Row Num = 576
Min = 6.319000
Max = 7.509100
Mean = 6.836639
std = 0.329338
RMS = 6.844386
______
***Row Num = 577
Min = 2.896700
Max = 5.840400
Mean = 4.638505
std = 1.140133
RMS = 4.773477
_____
***Row Num = 578
Min = 0.100140
Max = 9.805600
Mean = 2.991307
std = 3.957071
RMS = 4.924475
***Row Num = 579
```

```
Min = 0.857910
Max = 1.070300
Mean = 0.930620
std = 0.034548
RMS = 0.931246
_____
***Row Num = 580
Min = -0.485840
Max = -0.248050
Mean = -0.358798
std = 0.051221
RMS = 0.362353
***Row Num = 581
Min = -0.101070
Max = 0.177730
Mean = 0.060758
std = 0.050250
RMS = 0.078480
_____
***Row Num = 582
Min = -1.162600
Max = 2.114700
Mean = 0.200139
std = 0.736477
RMS = 0.755068
***Row Num = 583
Min = 0.083984
Max = 1.072800
Mean = 0.626088
std = 0.256949
RMS = 0.675654
***Row Num = 584
Min = -1.334000
Max = 1.179200
Mean = 0.410045
std = 0.402635
RMS = 0.571460
______
***Row Num = 585
Min = -15.000000
Max = 8.000000
Mean = -1.954545
std = 4.366652
RMS = 4.738623
***Row Num = 586
Min = -22.000000
```

```
Max = 20.000000
Mean = -2.250000
std = 7.939085
RMS = 8.164502
______
***Row Num = 587
Min = -30.000000
Max = 9.000000
Mean = -1.727273
std = 5.362938
RMS = 5.575922
***Row Num = 588
Min = -5.000000
Max = 3.000000
Mean = -0.909091
std = 1.639883
RMS = 1.858641
_____
***Row Num = 589
Min = -4.000000
Max = 2.000000
Mean = -0.863636
std = 1.472080
RMS = 1.692228
_____
***Row Num = 590
Min = -8.000000
Max = 12.000000
Mean = -0.545455
std = 3.223854
RMS = 3.233349
______
***Row Num = 591
Min = -30.000000
Max = 24.000000
Mean = -0.863636
std = 8.165699
RMS = 8.118441
-----
***Row Num = 592
Min = -10.000000
Max = 8.000000
Mean = -0.250000
std = 3.531420
RMS = 3.500000
_____
***Row Num = 593
Min = -85.000000
Max = 71.000000
```

```
Mean = 0.931818
std = 36.300040
RMS = 35.897265
______
***Row Num = 594
Min = -67.000000
Max = 46.000000
Mean = -4.022727
std = 22.452522
RMS = 22.557502
***Row Num = 595
Min = -54.000000
Max = 68.000000
Mean = -0.977273
std = 20.549983
RMS = 20.338611
______
***Row Num = 596
Min = -44.000000
Max = 54.000000
Mean = -3.840909
std = 15.999917
RMS = 16.276726
***Row Num = 597
Min = -128.000000
Max = 126.000000
Mean = -16.159091
std = 53.849464
RMS = 55.632520
***Row Num = 598
Min = -128.000000
Max = 104.000000
Mean = -8.477273
std = 39.588281
RMS = 40.043442
______
***Row Num = 599
Min = -22.000000
Max = 42.000000
Mean = 0.204545
std = 12.868891
RMS = 12.723457
***Row Num = 600
Min = -45.000000
Max = 105.000000
Mean = 7.068182
```

```
std = 30.431316
RMS = 30.902707
______
***Row Num = 601
Min = -29.375000
Max = 47.563000
Mean = -0.235807
std = 14.754285
RMS = 14.587565
_____
***Row Num = 602
Min = -29.375000
Max = 47.563000
Mean = -0.235807
std = 14.754285
RMS = 14.587565
***Row Num = 603
Min = -29.375000
Max = 47.563000
Mean = -0.235807
std = 14.754285
RMS = 14.587565
______
***Row Num = 604
Min = -161.630000
Max = 119.250000
Mean = -1.069716
std = 50.618057
RMS = 50.050978
***Row Num = 605
Min = -161.630000
Max = 119.250000
Mean = -1.069716
std = 50.618057
RMS = 50.050978
_____
***Row Num = 606
Min = -161.630000
Max = 119.250000
Mean = -1.069716
std = 50.618057
RMS = 50.050978
_____
***Row Num = 607
Min = 2.600700
Max = 2.853800
Mean = 2.766900
std = 0.059640
```

```
RMS = 2.767528
______
***Row Num = 608
Min = 3.042900
Max = 3.136700
Mean = 3.089970
std = 0.023462
RMS = 3.090058
______
***Row Num = 609
Min = 0.233680
Max = 0.541920
Mean = 0.348590
std = 0.071878
RMS = 0.355759
_____
***Row Num = 610
Min = 6.320500
Max = 7.742900
Mean = 6.803725
std = 0.327305
RMS = 6.811415
_____
***Row Num = 611
Min = 2.895100
Max = 5.734100
Mean = 4.640675
std = 1.092941
RMS = 4.764791
***Row Num = 612
Min = 0.051100
Max = 9.933700
Mean = 2.752375
std = 3.865115
RMS = 4.709051
______
***Row Num = 613
Min = 0.848630
Max = 1.002400
Mean = 0.933293
std = 0.026249
RMS = 0.933654
***Row Num = 614
Min = -0.487300
Max = -0.223140
Mean = -0.349864
std = 0.049961
RMS = 0.353333
```

```
_____
***Row Num = 615
Min = -0.057129
Max = 0.166500
Mean = 0.056263
std = 0.049731
RMS = 0.074716
_____
***Row Num = 616
Min = -1.043500
Max = 1.593300
Mean = 0.183074
std = 0.667964
RMS = 0.685239
***Row Num = 617
Min = 0.174800
Max = 0.992680
Mean = 0.606899
std = 0.250510
RMS = 0.655481
______
***Row Num = 618
Min = -0.403810
Max = 1.141100
Mean = 0.437733
std = 0.319481
RMS = 0.539776
_____
***Row Num = 619
Min = -11.000000
Max = 16.000000
Mean = -0.727273
std = 5.177607
RMS = 5.169843
***Row Num = 620
Min = -20.000000
Max = 17.000000
Mean = -0.136364
std = 7.251595
RMS = 7.170013
______
***Row Num = 621
Min = -13.000000
Max = 22.000000
Mean = 0.000000
std = 5.569852
RMS = 5.506195
```

```
***Row Num = 622
Min = -5.000000
Max = 7.000000
Mean = -0.750000
std = 2.013039
RMS = 2.126670
***Row Num = 623
Min = -5.000000
Max = 4.000000
Mean = -1.250000
std = 1.713490
RMS = 2.105188
______
***Row Num = 624
Min = -6.000000
Max = 3.000000
Mean = -1.295455
std = 2.041198
RMS = 2.397916
_____
***Row Num = 625
Min = -21.000000
Max = 13.000000
Mean = -0.363636
std = 5.452078
RMS = 5.402020
***Row Num = 626
Min = -20.000000
Max = 7.000000
Mean = -1.522727
std = 4.267174
RMS = 4.484823
______
***Row Num = 627
Min = -86.000000
Max = 59.000000
Mean = -4.000000
std = 30.258576
RMS = 30.179011
_____
***Row Num = 628
Min = -76.000000
Max = 123.000000
Mean = 2.727273
std = 28.873714
RMS = 28.673713
***Row Num = 629
```

```
Min = -43.000000
Max = 56.000000
Mean = 0.750000
std = 15.736382
RMS = 15.574601
_____
***Row Num = 630
Min = -41.000000
Max = 44.000000
Mean = 1.113636
std = 13.289646
RMS = 13.184874
***Row Num = 631
Min = -126.000000
Max = 127.000000
Mean = 2.272727
std = 51.520311
RMS = 50.982172
_____
***Row Num = 632
Min = -113.000000
Max = 73.000000
Mean = -6.840909
std = 37.626650
RMS = 37.820449
______
***Row Num = 633
Min = -103.000000
Max = 42.000000
Mean = -2.204545
std = 24.022838
RMS = 23.850386
***Row Num = 634
Min = -99.000000
Max = 74.000000
Mean = 1.545455
std = 32.085246
RMS = 31.756173
______
***Row Num = 635
Min = -39.813000
Max = 39.625000
Mean = 0.035500
std = 15.506308
RMS = 15.329128
***Row Num = 636
Min = -39.813000
```

```
Max = 39.625000
Mean = 0.035500
std = 15.506308
RMS = 15.329128
______
***Row Num = 637
Min = -39.813000
Max = 39.625000
Mean = 0.035500
std = 15.506308
RMS = 15.329128
***Row Num = 638
Min = -74.188000
Max = 94.625000
Mean = 1.088057
std = 35.432463
RMS = 35.044402
_____
***Row Num = 639
Min = -74.188000
Max = 94.625000
Mean = 1.088057
std = 35.432463
RMS = 35.044402
______
***Row Num = 640
Min = -74.188000
Max = 94.625000
Mean = 1.088057
std = 35.432463
RMS = 35.044402
______
***Row Num = 641
Min = 2.694800
Max = 2.820000
Mean = 2.743102
std = 0.031757
RMS = 2.743282
-----
***Row Num = 642
Min = 3.054200
Max = 3.111500
Mean = 3.075750
std = 0.015871
RMS = 3.075790
_____
***Row Num = 643
Min = 0.198130
Max = 0.454770
```

```
Mean = 0.347018
std = 0.058277
RMS = 0.351767
______
***Row Num = 644
Min = 6.290100
Max = 7.660600
Mean = 6.827025
std = 0.370649
RMS = 6.836851
***Row Num = 645
Min = 2.871500
Max = 5.709100
Mean = 4.619584
std = 1.096485
RMS = 4.745051
______
***Row Num = 646
Min = 0.035222
Max = 9.728600
Mean = 2.580592
std = 3.634800
RMS = 4.423907
***Row Num = 647
Min = 0.815920
Max = 1.136200
Mean = 0.935713
std = 0.049338
RMS = 0.936983
***Row Num = 648
Min = -0.528810
Max = -0.220700
Mean = -0.343417
std = 0.059198
RMS = 0.348368
______
***Row Num = 649
Min = -0.135250
Max = 0.178220
Mean = 0.037154
std = 0.058290
RMS = 0.068563
***Row Num = 650
Min = -1.425300
Max = 2.524400
Mean = 0.268778
```

```
std = 0.769900
RMS = 0.807166
_____
***Row Num = 651
Min = -0.750490
Max = 1.227500
Mean = 0.552612
std = 0.375085
RMS = 0.665485
_____
***Row Num = 652
Min = -0.484380
Max = 1.402800
Mean = 0.342560
std = 0.393041
RMS = 0.517994
***Row Num = 653
Min = -17.000000
Max = 15.000000
Mean = -0.522727
std = 6.067407
RMS = 6.020797
______
***Row Num = 654
Min = -23.000000
Max = 24.000000
Mean = 0.613636
std = 8.608314
RMS = 8.532025
***Row Num = 655
Min = -12.000000
Max = 19.000000
Mean = -0.363636
std = 4.827686
RMS = 4.786344
***Row Num = 656
Min = -5.000000
Max = 2.000000
Mean = -1.250000
std = 1.766945
RMS = 2.147938
______
***Row Num = 657
Min = -8.000000
Max = 3.000000
Mean = -1.113636
std = 2.507810
```

```
RMS = 2.717787
______
***Row Num = 658
Min = -28.000000
Max = 15.000000
Mean = -1.250000
std = 5.953795
RMS = 6.017021
______
***Row Num = 659
Min = -61.000000
Max = 31.000000
Mean = -4.840909
std = 16.614568
RMS = 17.123217
_____
***Row Num = 660
Min = -15.000000
Max = 16.000000
Mean = -1.204545
std = 5.441356
RMS = 5.512383
_____
***Row Num = 661
Min = -56.000000
Max = 57.000000
Mean = 0.136364
std = 23.329382
RMS = 23.063154
***Row Num = 662
Min = -48.000000
Max = 49.000000
Mean = -0.386364
std = 17.593889
RMS = 17.397100
______
***Row Num = 663
Min = -76.000000
Max = 29.000000
Mean = -2.613636
std = 20.171608
RMS = 20.111620
***Row Num = 664
Min = -34.000000
Max = 53.000000
Mean = -1.068182
std = 17.283407
RMS = 17.119234
```

```
_____
***Row Num = 665
Min = -98.000000
Max = 63.000000
Mean = -6.704545
std = 36.616542
RMS = 36.813720
-----
***Row Num = 666
Min = -95.000000
Max = 46.000000
Mean = -3.840909
std = 31.382815
RMS = 31.260998
***Row Num = 667
Min = -47.000000
Max = 42.000000
Mean = -1.909091
std = 16.078034
RMS = 16.008520
______
***Row Num = 668
Min = -42.000000
Max = 80.000000
Mean = 1.750000
std = 23.128684
RMS = 22.931221
_____
***Row Num = 669
Min = -35.375000
Max = 38.813000
Mean = 0.176125
std = 15.820648
RMS = 15.640826
***Row Num = 670
Min = -35.375000
Max = 38.813000
Mean = 0.176125
std = 15.820648
RMS = 15.640826
______
***Row Num = 671
Min = -35.375000
Max = 38.813000
Mean = 0.176125
std = 15.820648
RMS = 15.640826
```

```
***Row Num = 672
Min = -84.875000
Max = 150.130000
Mean = 1.997250
std = 39.554168
RMS = 39.153080
***Row Num = 673
Min = -84.875000
Max = 150.130000
Mean = 1.997250
std = 39.554168
RMS = 39.153080
______
***Row Num = 674
Min = -84.875000
Max = 150.130000
Mean = 1.997250
std = 39.554168
RMS = 39.153080
_____
***Row Num = 675
Min = 2.524700
Max = 2.782300
Mean = 2.673984
std = 0.080771
RMS = 2.675176
***Row Num = 676
Min = 2.996600
Max = 3.118500
Mean = 3.058327
std = 0.042979
RMS = 3.058622
______
***Row Num = 677
Min = 0.266280
Max = 0.603090
Mean = 0.412882
std = 0.093360
RMS = 0.423071
_____
***Row Num = 678
Min = 6.471300
Max = 7.672600
Mean = 7.022727
std = 0.344204
RMS = 7.030966
***Row Num = 679
```

```
Min = 2.892800
Max = 5.728300
```

Mean = 4.359532

std = 1.220734

RMS = 4.523477

-----

\*\*\*Row Num = 680

Min = 0.080943

Max = 9.824600

Mean = 4.294582

std = 4.324322

RMS = 6.059554

>>