```
>> Untitled4
Action FATHER.csv
_____
***Row Num = 1
Min = 0.873050
Max = 0.937500
Mean = 0.905973
std = 0.013779
RMS = 0.906076
_____
***Row Num = 2
Min = -0.423340
Max = -0.353520
Mean = -0.394133
std = 0.018188
RMS = 0.394543
______
***Row Num = 3
Min = 0.108400
Max = 0.170410
Mean = 0.148238
std = 0.013902
RMS = 0.148874
______
***Row Num = 4
Min = -0.976070
Max = 1.081100
Mean = -0.058094
std = 0.811890
RMS = 0.804710
***Row Num = 5
Min = 0.286130
Max = 0.972660
Mean = 0.478116
std = 0.189379
RMS = 0.513463
_____
***Row Num = 6
Min = -0.334960
Max = 0.669430
Mean = 0.123768
std = 0.252307
RMS = 0.278443
_____
***Row Num = 7
Min = -3.000000
Max = 1.000000
Mean = -1.090909
std = 0.884444
```

```
RMS = 1.398051
***Row Num = 8
Min = -3.000000
Max = 2.000000
Mean = -1.022727
std = 1.171138
RMS = 1.544786
______
***Row Num = 9
Min = -4.000000
Max = 1.000000
Mean = -1.159091
std = 1.010254
RMS = 1.530003
_____
***Row Num = 10
Min = -3.000000
Max = 1.000000
Mean = -1.227273
std = 1.008421
RMS = 1.581139
***Row Num = 11
Min = -3.000000
Max = 2.000000
Mean = -1.068182
std = 0.974028
RMS = 1.438117
***Row Num = 12
Min = -5.000000
Max = 4.000000
Mean = -1.136364
std = 1.322276
RMS = 1.732051
_____
***Row Num = 13
Min = -6.000000
Max = 11.000000
Mean = -0.681818
std = 2.259581
RMS = 2.335497
***Row Num = 14
Min = -7.000000
Max = 1.000000
Mean = -0.931818
std = 1.353681
RMS = 1.630672
```

```
_____
***Row Num = 15
Min = -71.000000
Max = 57.000000
Mean = -5.431818
std = 25.679055
RMS = 25.960197
_____
***Row Num = 16
Min = -27.000000
Max = 21.000000
Mean = -2.545455
std = 9.349679
RMS = 9.586923
***Row Num = 17
Min = -15.000000
Max = 10.000000
Mean = -1.931818
std = 3.973153
RMS = 4.377110
______
***Row Num = 18
Min = -6.000000
Max = 6.000000
Mean = -1.318182
std = 2.370092
RMS = 2.688359
_____
***Row Num = 19
Min = -16.000000
Max = 4.000000
Mean = -1.681818
std = 3.455853
RMS = 3.807887
***Row Num = 20
Min = -16.000000
Max = 7.000000
Mean = -1.136364
std = 4.251352
RMS = 4.353682
______
***Row Num = 21
Min = -19.000000
Max = 14.000000
Mean = 0.045455
std = 6.216836
RMS = 6.145952
```

```
***Row Num = 22
Min = -38.000000
Max = 33.000000
Mean = -0.181818
std = 11.136098
RMS = 11.010326
***Row Num = 23
Min = -15.000000
Max = 11.250000
Mean = -1.264216
std = 5.436725
RMS = 5.521272
______
***Row Num = 24
Min = -15.000000
Max = 11.250000
Mean = -1.264216
std = 5.436725
RMS = 5.521272
_____
***Row Num = 25
Min = -15.000000
Max = 11.250000
Mean = -1.264216
std = 5.436725
RMS = 5.521272
***Row Num = 26
Min = -69.625000
Max = 70.813000
Mean = 2.453148
std = 28.026622
RMS = 27.814698
______
***Row Num = 27
Min = -69.625000
Max = 70.813000
Mean = 2.453148
std = 28.026622
RMS = 27.814698
_____
***Row Num = 28
Min = -69.625000
Max = 70.813000
Mean = 2.453148
std = 28.026622
RMS = 27.814698
______
***Row Num = 29
```

```
Min = 3.034800
Max = 3.117300
Mean = 3.060873
std = 0.022645
RMS = 3.060955
_____
***Row Num = 30
Min = 3.139100
Max = 3.230600
Mean = 3.191152
std = 0.031934
RMS = 3.191308
______
***Row Num = 31
Min = 7.126500
Max = 7.203500
Mean = 7.154150
std = 0.017130
RMS = 7.154170
_____
***Row Num = 32
Min = 6.545000
Max = 8.237400
Mean = 7.311489
std = 0.570408
RMS = 7.333201
***Row Num = 33
Min = 3.084300
Max = 6.871900
Mean = 5.216059
std = 1.657231
RMS = 5.467291
_____
***Row Num = 34
Min = 7.559500
Max = 9.788900
Mean = 8.529814
std = 0.806731
RMS = 8.567015
______
***Row Num = 35
Min = 0.890140
Max = 0.933110
Mean = 0.906639
std = 0.009243
RMS = 0.906685
***Row Num = 36
Min = -0.416500
```

```
Max = -0.365230
Mean = -0.393787
std = 0.013324
RMS = 0.394007
______
***Row Num = 37
Min = 0.124020
Max = 0.174320
Mean = 0.142090
std = 0.010407
RMS = 0.142462
_____
***Row Num = 38
Min = -1.063500
Max = 1.011700
Mean = 0.034423
std = 0.803189
RMS = 0.794755
_____
***Row Num = 39
Min = 0.260740
Max = 0.963870
Mean = 0.491933
std = 0.195893
RMS = 0.528677
_____
***Row Num = 40
Min = -0.219240
Max = 0.693850
Mean = 0.203025
std = 0.241031
RMS = 0.313041
______
***Row Num = 41
Min = -5.000000
Max = 4.000000
Mean = -1.068182
std = 1.662133
RMS = 1.959824
-----
***Row Num = 42
Min = -3.000000
Max = 0.000000
Mean = -1.431818
std = 0.974028
RMS = 1.725478
_____
***Row Num = 43
Min = -3.000000
Max = 4.000000
```

```
Mean = -1.045455
std = 1.461992
RMS = 1.783765
______
***Row Num = 44
Min = -3.000000
Max = 1.000000
Mean = -0.863636
std = 1.112109
RMS = 1.398051
***Row Num = 45
Min = -3.000000
Max = 1.000000
Mean = -1.022727
std = 0.901901
RMS = 1.356801
______
***Row Num = 46
Min = -3.000000
Max = 1.000000
Mean = -1.113636
std = 0.920463
RMS = 1.438117
_____
***Row Num = 47
Min = -3.000000
Max = 2.000000
Mean = -1.022727
std = 1.109968
RMS = 1.500000
***Row Num = 48
Min = -3.000000
Max = 1.000000
Mean = -1.022727
std = 1.022733
RMS = 1.438117
______
***Row Num = 49
Min = -77.000000
Max = 40.000000
Mean = -4.795455
std = 22.930207
RMS = 23.169828
______
***Row Num = 50
Min = -27.000000
Max = 10.000000
Mean = -2.931818
```

```
std = 8.303537
RMS = 8.716494
______
***Row Num = 51
Min = -27.000000
Max = 40.000000
Mean = -0.477273
std = 11.040072
RMS = 10.924326
_____
***Row Num = 52
Min = -17.000000
Max = 24.000000
Mean = -1.227273
std = 6.313012
RMS = 6.360389
______
***Row Num = 53
Min = -21.000000
Max = 20.000000
Mean = -1.681818
std = 7.148826
RMS = 7.264484
______
***Row Num = 54
Min = -11.000000
Max = 14.000000
Mean = -1.681818
std = 4.787448
RMS = 5.022676
***Row Num = 55
Min = -21.000000
Max = 18.000000
Mean = -0.113636
std = 5.751505
RMS = 5.686907
_____
***Row Num = 56
Min = -34.000000
Max = 22.000000
Mean = -2.454545
std = 8.010036
RMS = 8.290191
_____
***Row Num = 57
Min = -19.813000
Max = 12.813000
Mean = -0.643477
std = 7.082985
```

```
RMS = 7.031539
______
***Row Num = 58
Min = -19.813000
Max = 12.813000
Mean = -0.643477
std = 7.082985
RMS = 7.031539
______
***Row Num = 59
Min = -19.813000
Max = 12.813000
Mean = -0.643477
std = 7.082985
RMS = 7.031539
_____
***Row Num = 60
Min = -68.188000
Max = 75.438000
Mean = 7.686125
std = 28.976848
RMS = 29.658913
_____
***Row Num = 61
Min = -68.188000
Max = 75.438000
Mean = 7.686125
std = 28.976848
RMS = 29.658913
***Row Num = 62
Min = -68.188000
Max = 75.438000
Mean = 7.686125
std = 28.976848
RMS = 29.658913
_____
***Row Num = 63
Min = 3.018700
Max = 3.090200
Mean = 3.058132
std = 0.019837
RMS = 3.058195
***Row Num = 64
Min = 3.158700
Max = 3.208600
Mean = 3.185593
std = 0.018293
RMS = 3.185645
```

```
_____
***Row Num = 65
Min = 7.066100
Max = 7.146000
Mean = 7.093511
std = 0.020602
RMS = 7.093541
_____
***Row Num = 66
Min = 6.511000
Max = 7.933900
Mean = 7.074436
std = 0.473596
RMS = 7.089912
***Row Num = 67
Min = 3.152400
Max = 6.926300
Mean = 5.071525
std = 1.639582
RMS = 5.324237
______
***Row Num = 68
Min = 7.743800
Max = 9.500000
Mean = 8.431268
std = 0.623683
RMS = 8.453782
_____
***Row Num = 69
Min = 0.892090
Max = 0.927250
Mean = 0.909058
std = 0.007461
RMS = 0.909088
______
***Row Num = 70
Min = -0.404300
Max = -0.357420
Mean = -0.386497
std = 0.009827
RMS = 0.386619
______
***Row Num = 71
Min = 0.104490
Max = 0.166990
Mean = 0.144365
std = 0.012203
RMS = 0.144869
```

```
***Row Num = 72
Min = -1.023900
Max = 1.313000
Mean = -0.010221
std = 0.837218
RMS = 0.827713
***Row Num = 73
Min = 0.217770
Max = 0.935060
Mean = 0.436501
std = 0.201360
RMS = 0.479748
______
***Row Num = 74
Min = -0.358890
Max = 0.650880
Mean = 0.136897
std = 0.260407
RMS = 0.291567
______
***Row Num = 75
Min = -5.000000
Max = 3.000000
Mean = -0.750000
std = 1.259845
RMS = 1.453835
***Row Num = 76
Min = -3.000000
Max = 1.000000
Mean = -0.909091
std = 1.074399
RMS = 1.398051
______
***Row Num = 77
Min = -4.000000
Max = 1.000000
Mean = -1.272727
std = 0.996824
RMS = 1.609630
______
***Row Num = 78
Min = -4.000000
Max = 1.000000
Mean = -0.977273
std = 1.088815
RMS = 1.453835
***Row Num = 79
```

```
Min = -3.000000
Max = 1.000000
Mean = -1.022727
std = 0.927328
RMS = 1.373450
_____
***Row Num = 80
Min = -2.000000
Max = 1.000000
Mean = -0.840909
std = 0.861129
RMS = 1.196586
***Row Num = 81
Min = -4.000000
Max = 1.000000
Mean = -1.113636
std = 1.104239
RMS = 1.559429
_____
***Row Num = 82
Min = -5.000000
Max = 2.000000
Mean = -0.750000
std = 1.331637
RMS = 1.515076
***Row Num = 83
Min = -78.000000
Max = 93.000000
Mean = -0.477273
std = 26.231960
RMS = 25.936548
***Row Num = 84
Min = -20.000000
Max = 13.000000
Mean = -1.318182
std = 6.238562
RMS = 6.306562
______
***Row Num = 85
Min = -10.000000
Max = 26.000000
Mean = -1.000000
std = 4.969675
RMS = 5.013618
***Row Num = 86
Min = -4.000000
```

```
Max = 8.000000
Mean = -0.477273
std = 1.970582
RMS = 2.005674
______
***Row Num = 87
Min = -4.000000
Max = 11.000000
Mean = -0.409091
std = 2.404629
RMS = 2.412091
***Row Num = 88
Min = -8.000000
Max = 28.000000
Mean = -0.340909
std = 5.321930
RMS = 5.272139
_____
***Row Num = 89
Min = -10.000000
Max = 6.000000
Mean = -0.431818
std = 3.273557
RMS = 3.264826
______
***Row Num = 90
Min = -25.000000
Max = 22.000000
Mean = 0.636364
std = 8.789769
RMS = 8.712582
_____
***Row Num = 91
Min = -10.250000
Max = 13.313000
Mean = 0.333818
std = 5.778849
RMS = 5.722548
-----
***Row Num = 92
Min = -10.250000
Max = 13.313000
Mean = 0.333818
std = 5.778849
RMS = 5.722548
_____
***Row Num = 93
Min = -10.250000
Max = 13.313000
```

```
Mean = 0.333818
std = 5.778849
RMS = 5.722548
______
***Row Num = 94
Min = -87.188000
Max = 56.063000
Mean = 0.028432
std = 30.066345
RMS = 29.722732
***Row Num = 95
Min = -87.188000
Max = 56.063000
Mean = 0.028432
std = 30.066345
RMS = 29.722732
______
***Row Num = 96
Min = -87.188000
Max = 56.063000
Mean = 0.028432
std = 30.066345
RMS = 29.722732
_____
***Row Num = 97
Min = 3.045800
Max = 3.113200
Mean = 3.080125
std = 0.016506
RMS = 3.080168
_____
***Row Num = 98
Min = 3.153700
Max = 3.192400
Mean = 3.175452
std = 0.012155
RMS = 3.175475
______
***Row Num = 99
Min = 7.063100
Max = 7.170500
Mean = 7.103480
std = 0.029625
RMS = 7.103540
***Row Num = 100
Min = 6.579600
Max = 8.460000
Mean = 7.293789
```

```
std = 0.664373
RMS = 7.323299
_____
***Row Num = 101
Min = 3.046600
Max = 6.965700
Mean = 5.145859
std = 1.708467
RMS = 5.415938
_____
***Row Num = 102
Min = 7.502100
Max = 9.991500
Mean = 8.491877
std = 0.921148
RMS = 8.540563
***Row Num = 103
Min = 0.890140
Max = 0.942380
Mean = 0.910001
std = 0.009850
RMS = 0.910053
______
***Row Num = 104
Min = -0.416990
Max = -0.352050
Mean = -0.387385
std = 0.012805
RMS = 0.387592
***Row Num = 105
Min = 0.119140
Max = 0.171880
Mean = 0.139427
std = 0.010063
RMS = 0.139781
***Row Num = 106
Min = -1.119600
Max = 1.156300
Mean = 0.119109
std = 0.806412
RMS = 0.806045
_____
***Row Num = 107
Min = 0.228520
Max = 1.003400
Mean = 0.497003
std = 0.222231
```

```
RMS = 0.543394
***Row Num = 108
Min = -0.237300
Max = 0.698240
Mean = 0.187578
std = 0.262426
RMS = 0.320137
______
***Row Num = 109
Min = -3.000000
Max = 5.000000
Mean = -0.545455
std = 1.784358
RMS = 1.846372
_____
***Row Num = 110
Min = -6.000000
Max = 9.000000
Mean = -0.681818
std = 2.437810
RMS = 2.504541
______
***Row Num = 111
Min = -4.000000
Max = 5.000000
Mean = -0.590909
std = 1.884060
RMS = 1.954017
***Row Num = 112
Min = -3.000000
Max = 1.000000
Mean = -0.909091
std = 0.960092
RMS = 1.314257
_____
***Row Num = 113
Min = -3.000000
Max = 2.000000
Mean = -0.840909
std = 1.010254
RMS = 1.305582
***Row Num = 114
Min = -4.000000
Max = 6.000000
Mean = -0.409091
std = 1.795578
RMS = 1.821588
```

_____ ***Row Num = 115Min = -18.000000Max = 28.000000Mean = 0.704545std = 6.568351RMS = 6.531393_____ ***Row Num = 116Min = -4.000000Max = 2.000000Mean = -0.909091std = 1.235487RMS = 1.522558***Row Num = 117Min = -58.000000Max = 69.000000Mean = 4.840909std = 30.416445RMS = 30.456004______ ***Row Num = 118Min = -20.000000Max = 24.000000Mean = 0.613636std = 9.053371RMS = 8.970913_____ ***Row Num = 119Min = -15.000000Max = 22.000000Mean = -1.250000std = 6.495526RMS = 6.541823______ ***Row Num = 120Min = -10.000000Max = 3.000000Mean = -1.454545std = 2.463261RMS = 2.836451______ ***Row Num = 121Min = -26.000000Max = 8.000000Mean = -1.840909std = 5.071320RMS = 5.340667

```
***Row Num = 122
Min = -9.000000
Max = 12.000000
Mean = 0.204545
std = 3.985903
RMS = 3.945654
***Row Num = 123
Min = -23.000000
Max = 41.000000
Mean = -1.295455
std = 9.254991
RMS = 9.240474
______
***Row Num = 124
Min = -28.000000
Max = 60.000000
Mean = 0.295455
std = 14.848975
RMS = 14.682240
_____
***Row Num = 125
Min = -28.563000
Max = 23.688000
Mean = -0.603693
std = 8.252744
RMS = 8.180729
***Row Num = 126
Min = -28.563000
Max = 23.688000
Mean = -0.603693
std = 8.252744
RMS = 8.180729
______
***Row Num = 127
Min = -28.563000
Max = 23.688000
Mean = -0.603693
std = 8.252744
RMS = 8.180729
_____
***Row Num = 128
Min = -52.688000
Max = 87.188000
Mean = 8.744364
std = 32.153543
RMS = 32.966917
***Row Num = 129
```

```
Min = -52.688000
Max = 87.188000
Mean = 8.744364
std = 32.153543
RMS = 32.966917
_____
***Row Num = 130
Min = -52.688000
Max = 87.188000
Mean = 8.744364
std = 32.153543
RMS = 32.966917
***Row Num = 131
Min = 2.992000
Max = 3.091100
Mean = 3.059502
std = 0.022018
RMS = 3.059580
_____
***Row Num = 132
Min = 3.133800
Max = 3.198200
Mean = 3.172807
std = 0.017207
RMS = 3.172852
______
***Row Num = 133
Min = 7.056900
Max = 7.225400
Mean = 7.156402
std = 0.040709
RMS = 7.156515
_____
***Row Num = 134
Min = 6.554600
Max = 8.343900
Mean = 7.181677
std = 0.612838
RMS = 7.207186
______
***Row Num = 135
Min = 3.056000
Max = 6.906700
Mean = 4.916516
std = 1.656604
RMS = 5.182094
***Row Num = 136
Min = 7.574100
```

```
Max = 9.935800
Mean = 8.419048
std = 0.839529
RMS = 8.459855
______
***Row Num = 137
Min = 0.896000
Max = 0.929690
Mean = 0.918935
std = 0.008217
RMS = 0.918970
***Row Num = 138
Min = -0.407710
Max = -0.351560
Mean = -0.375233
std = 0.014356
RMS = 0.375501
_____
***Row Num = 139
Min = 0.078125
Max = 0.155270
Mean = 0.110784
std = 0.014404
RMS = 0.111695
______
***Row Num = 140
Min = -0.955570
Max = 1.549300
Mean = 0.212126
std = 0.824895
RMS = 0.842606
_____
***Row Num = 141
Min = 0.250980
Max = 0.962890
Mean = 0.449940
std = 0.196281
RMS = 0.489997
-----
***Row Num = 142
Min = -0.447750
Max = 0.676270
Mean = 0.118642
std = 0.284408
RMS = 0.305165
_____
***Row Num = 143
Min = -11.000000
Max = 11.000000
```

```
Mean = -0.363636
std = 4.570334
RMS = 4.532709
______
***Row Num = 144
Min = -7.000000
Max = 5.000000
Mean = -1.568182
std = 2.214096
RMS = 2.692582
***Row Num = 145
Min = -8.000000
Max = 2.000000
Mean = -1.704545
std = 1.862476
RMS = 2.509074
______
***Row Num = 146
Min = -4.000000
Max = 1.000000
Mean = -1.181818
std = 1.206045
RMS = 1.678744
***Row Num = 147
Min = -5.000000
Max = 2.000000
Mean = -0.977273
std = 1.438485
RMS = 1.725478
_____
***Row Num = 148
Min = -7.000000
Max = 5.000000
Mean = -0.886364
std = 2.014089
RMS = 2.179449
______
***Row Num = 149
Min = -24.000000
Max = 15.000000
Mean = -0.318182
std = 5.909286
RMS = 5.850408
***Row Num = 150
Min = -4.000000
Max = 2.000000
Mean = -0.909091
```

```
std = 1.343688
RMS = 1.609630
_____
***Row Num = 151
Min = -79.000000
Max = 36.000000
Mean = -1.159091
std = 24.221788
RMS = 23.972996
_____
***Row Num = 152
Min = -39.000000
Max = 22.000000
Mean = -0.750000
std = 11.375463
RMS = 11.270436
***Row Num = 153
Min = -20.000000
Max = 11.000000
Mean = -1.795455
std = 6.866093
RMS = 7.021072
______
***Row Num = 154
Min = -15.000000
Max = 8.000000
Mean = -1.863636
std = 4.480401
RMS = 4.805300
***Row Num = 155
Min = -25.000000
Max = 69.000000
Mean = -0.886364
std = 12.091157
RMS = 11.985787
_____
***Row Num = 156
Min = -19.000000
Max = 22.000000
Mean = -0.363636
std = 6.258356
RMS = 6.197507
______
***Row Num = 157
Min = -19.000000
Max = 13.000000
Mean = -0.545455
std = 5.970682
```

```
RMS = 5.927593
______
***Row Num = 158
Min = -39.000000
Max = 63.000000
Mean = 1.590909
std = 15.100159
RMS = 15.012116
______
***Row Num = 159
Min = -19.375000
Max = 20.375000
Mean = 0.322455
std = 8.973827
RMS = 8.877124
_____
***Row Num = 160
Min = -19.375000
Max = 20.375000
Mean = 0.322455
std = 8.973827
RMS = 8.877124
_____
***Row Num = 161
Min = -19.375000
Max = 20.375000
Mean = 0.322455
std = 8.973827
RMS = 8.877124
***Row Num = 162
Min = -45.938000
Max = 68.375000
Mean = 5.835205
std = 26.735836
RMS = 27.066750
_____
***Row Num = 163
Min = -45.938000
Max = 68.375000
Mean = 5.835205
std = 26.735836
RMS = 27.066750
***Row Num = 164
Min = -45.938000
Max = 68.375000
Mean = 5.835205
std = 26.735836
RMS = 27.066750
```

```
_____
***Row Num = 165
Min = 2.912600
Max = 3.026500
Mean = 2.968184
std = 0.034625
RMS = 2.968381
_____
***Row Num = 166
Min = 3.112400
Max = 3.169200
Mean = 3.136634
std = 0.017631
RMS = 3.136683
***Row Num = 167
Min = 7.158900
Max = 7.232100
Mean = 7.202866
std = 0.023360
RMS = 7.202903
______
***Row Num = 168
Min = 6.595500
Max = 8.251200
Mean = 7.201211
std = 0.463985
RMS = 7.215804
_____
***Row Num = 169
Min = 3.052100
Max = 6.898600
Mean = 4.730091
std = 1.687116
RMS = 5.015519
***Row Num = 170
Min = 7.496700
Max = 9.894000
Mean = 8.337857
std = 0.775037
RMS = 8.372986
______
***Row Num = 171
Min = 0.898440
Max = 0.939940
Mean = 0.917903
std = 0.010465
RMS = 0.917961
```

```
***Row Num = 172
Min = -0.402830
Max = -0.334470
Mean = -0.376521
std = 0.014051
RMS = 0.376777
***Row Num = 173
Min = 0.088379
Max = 0.148930
Mean = 0.111161
std = 0.011985
RMS = 0.111791
______
***Row Num = 174
Min = -0.981930
Max = 1.692400
Mean = 0.262906
std = 0.841737
RMS = 0.872661
_____
***Row Num = 175
Min = 0.208980
Max = 1.148400
Mean = 0.406527
std = 0.195940
RMS = 0.450316
***Row Num = 176
Min = -0.399410
Max = 1.441400
Mean = 0.177679
std = 0.287591
RMS = 0.335260
______
***Row Num = 177
Min = -4.000000
Max = 11.000000
Mean = -0.818182
std = 2.295321
RMS = 2.412091
_____
***Row Num = 178
Min = -3.000000
Max = 4.000000
Mean = -1.000000
std = 1.397672
RMS = 1.705606
***Row Num = 179
```

```
Min = -4.000000
Max = 2.000000
Mean = -1.227273
std = 1.344474
RMS = 1.809068
_____
***Row Num = 180
Min = -3.000000
Max = 2.000000
Mean = -0.818182
std = 1.280856
RMS = 1.507557
***Row Num = 181
Min = -3.000000
Max = 2.000000
Mean = -0.772727
std = 1.031225
RMS = 1.279204
_____
***Row Num = 182
Min = -4.000000
Max = 1.000000
Mean = -0.863636
std = 1.192826
RMS = 1.461630
***Row Num = 183
Min = -16.000000
Max = 10.000000
Mean = -1.022727
std = 3.553502
RMS = 3.658738
***Row Num = 184
Min = -4.000000
Max = 2.000000
Mean = -0.750000
std = 1.203193
RMS = 1.406155
______
***Row Num = 185
Min = -86.000000
Max = 61.000000
Mean = 1.795455
std = 27.735947
RMS = 27.477677
***Row Num = 186
Min = -42.000000
```

```
Max = 18.000000
Mean = -1.113636
std = 10.901709
RMS = 10.834499
______
***Row Num = 187
Min = -17.000000
Max = 6.000000
Mean = -1.272727
std = 4.494770
RMS = 4.622081
_____
***Row Num = 188
Min = -10.000000
Max = 8.000000
Mean = -1.363636
std = 3.155585
RMS = 3.404542
_____
***Row Num = 189
Min = -25.000000
Max = 9.000000
Mean = -1.386364
std = 5.628895
RMS = 5.734663
_____
***Row Num = 190
Min = -36.000000
Max = 30.000000
Mean = -0.477273
std = 8.486620
RMS = 8.403192
______
***Row Num = 191
Min = -9.000000
Max = 23.000000
Mean = -0.045455
std = 5.697631
RMS = 5.632697
_____
***Row Num = 192
Min = -26.000000
Max = 17.000000
Mean = -1.636364
std = 8.905423
RMS = 8.954430
_____
***Row Num = 193
Min = -13.063000
Max = 13.125000
```

```
Mean = 1.389227
std = 6.070344
RMS = 6.159671
______
***Row Num = 194
Min = -13.063000
Max = 13.125000
Mean = 1.389227
std = 6.070344
RMS = 6.159671
***Row Num = 195
Min = -13.063000
Max = 13.125000
Mean = 1.389227
std = 6.070344
RMS = 6.159671
______
***Row Num = 196
Min = -98.375000
Max = 97.250000
Mean = 2.021307
std = 26.951127
RMS = 26.719668
_____
***Row Num = 197
Min = -98.375000
Max = 97.250000
Mean = 2.021307
std = 26.951127
RMS = 26.719668
***Row Num = 198
Min = -98.375000
Max = 97.250000
Mean = 2.021307
std = 26.951127
RMS = 26.719668
______
***Row Num = 199
Min = 2.912100
Max = 3.002900
Mean = 2.965375
std = 0.024291
RMS = 2.965472
***Row Num = 200
Min = 3.115500
Max = 3.166600
Mean = 3.138382
```

```
std = 0.015448
RMS = 3.138419
_____
***Row Num = 201
Min = 7.195700
Max = 7.268900
Mean = 7.239075
std = 0.022723
RMS = 7.239110
_____
***Row Num = 202
Min = 6.564600
Max = 8.170500
Mean = 7.070070
std = 0.465660
RMS = 7.085041
***Row Num = 203
Min = 3.027000
Max = 6.887000
Mean = 4.534630
std = 1.720559
RMS = 4.843130
______
***Row Num = 204
Min = 7.718600
Max = 9.751100
Mean = 8.318107
std = 0.694135
RMS = 8.346363
***Row Num = 205
Min = 0.892580
Max = 0.937990
Mean = 0.918568
std = 0.009195
RMS = 0.918613
***Row Num = 206
Min = -0.400390
Max = -0.347170
Mean = -0.376787
std = 0.012749
RMS = 0.376998
_____
***Row Num = 207
Min = 0.082031
Max = 0.139160
Mean = 0.103971
std = 0.011849
```

```
RMS = 0.104629
***Row Num = 208
Min = -1.073200
Max = 1.427200
Mean = 0.188319
std = 0.819882
RMS = 0.832101
______
***Row Num = 209
Min = 0.178710
Max = 0.945310
Mean = 0.464732
std = 0.222907
RMS = 0.514329
_____
***Row Num = 210
Min = -0.490230
Max = 0.962400
Mean = 0.145951
std = 0.347309
RMS = 0.373073
_____
***Row Num = 211
Min = -9.000000
Max = 9.000000
Mean = -1.545455
std = 2.976298
RMS = 3.323470
***Row Num = 212
Min = -5.000000
Max = 6.000000
Mean = -1.068182
std = 1.860204
RMS = 2.126670
_____
***Row Num = 213
Min = -5.000000
Max = 2.000000
Mean = -1.363636
std = 1.511059
RMS = 2.022600
***Row Num = 214
Min = -3.000000
Max = 1.000000
Mean = -1.181818
std = 0.896316
RMS = 1.477098
```

```
_____
***Row Num = 215
Min = -4.000000
Max = 1.000000
Mean = -1.386364
std = 1.061283
RMS = 1.738599
_____
***Row Num = 216
Min = -6.000000
Max = 2.000000
Mean = -0.977273
std = 1.438485
RMS = 1.725478
***Row Num = 217
Min = -7.000000
Max = 4.000000
Mean = -0.931818
std = 2.453263
RMS = 2.598076
______
***Row Num = 218
Min = -5.000000
Max = 2.000000
Mean = -1.022727
std = 1.649364
RMS = 1.924720
_____
***Row Num = 219
Min = -89.000000
Max = 65.000000
Mean = 2.409091
std = 31.996597
RMS = 31.722519
______
***Row Num = 220
Min = -38.000000
Max = 28.000000
Mean = -0.659091
std = 11.553602
RMS = 11.440558
______
***Row Num = 221
Min = -21.000000
Max = 34.000000
Mean = -0.500000
std = 7.515875
RMS = 7.446781
```

```
***Row Num = 222
Min = -7.000000
Max = 15.000000
Mean = 0.250000
std = 4.621109
RMS = 4.575130
***Row Num = 223
Min = -12.000000
Max = 33.000000
Mean = 0.159091
std = 7.915082
RMS = 7.826238
______
***Row Num = 224
Min = -31.000000
Max = 39.000000
Mean = -1.340909
std = 9.797824
RMS = 9.778223
_____
***Row Num = 225
Min = -21.000000
Max = 32.000000
Mean = 0.568182
std = 7.692938
RMS = 7.626211
***Row Num = 226
Min = -57.000000
Max = 70.000000
Mean = 0.613636
std = 17.489154
RMS = 17.300158
______
***Row Num = 227
Min = -15.813000
Max = 17.813000
Mean = -0.426125
std = 7.367502
RMS = 7.295754
_____
***Row Num = 228
Min = -15.813000
Max = 17.813000
Mean = -0.426125
std = 7.367502
RMS = 7.295754
***Row Num = 229
```

```
Min = -15.813000
Max = 17.813000
Mean = -0.426125
std = 7.367502
RMS = 7.295754
_____
***Row Num = 230
Min = -43.875000
Max = 84.063000
Mean = 5.573886
std = 25.455755
RMS = 25.774726
***Row Num = 231
Min = -43.875000
Max = 84.063000
Mean = 5.573886
std = 25.455755
RMS = 25.774726
_____
***Row Num = 232
Min = -43.875000
Max = 84.063000
Mean = 5.573886
std = 25.455755
RMS = 25.774726
______
***Row Num = 233
Min = 2.900900
Max = 3.001900
Mean = 2.943145
std = 0.027167
RMS = 2.943268
_____
***Row Num = 234
Min = 3.113000
Max = 3.167600
Mean = 3.140384
std = 0.016555
RMS = 3.140427
______
***Row Num = 235
Min = 7.219700
Max = 7.311200
Mean = 7.278543
std = 0.021398
RMS = 7.278574
***Row Num = 236
Min = 6.590300
```

```
Max = 8.585900
Mean = 7.234843
std = 0.569274
RMS = 7.256698
______
***Row Num = 237
Min = 3.027500
Max = 6.929700
Mean = 4.802082
std = 1.661885
RMS = 5.075341
***Row Num = 238
Min = 0.056630
Max = 9.863300
Mean = 7.707374
std = 2.200819
RMS = 8.008566
_____
***Row Num = 239
Min = 0.884770
Max = 0.959470
Mean = 0.917858
std = 0.013228
RMS = 0.917952
______
***Row Num = 240
Min = -0.420900
Max = -0.338380
Mean = -0.375255
std = 0.016680
RMS = 0.375618
______
***Row Num = 241
Min = 0.074219
Max = 0.143550
Mean = 0.104925
std = 0.013634
RMS = 0.105787
-----
***Row Num = 242
Min = -1.077100
Max = 1.228500
Mean = 0.277132
std = 0.785637
RMS = 0.824621
_____
***Row Num = 243
Min = 0.246090
Max = 0.973140
```

```
Mean = 0.480113
std = 0.215645
RMS = 0.525314
______
***Row Num = 244
Min = -0.452150
Max = 0.666500
Mean = 0.181607
std = 0.238936
RMS = 0.297950
***Row Num = 245
Min = -9.000000
Max = 11.000000
Mean = -1.227273
std = 3.863145
RMS = 4.011348
______
***Row Num = 246
Min = -6.000000
Max = 7.000000
Mean = -0.795455
std = 2.338550
RMS = 2.444846
***Row Num = 247
Min = -4.000000
Max = 4.000000
Mean = -0.818182
std = 1.968032
RMS = 2.110579
***Row Num = 248
Min = -4.000000
Max = 1.000000
Mean = -1.000000
std = 1.099683
RMS = 1.477098
______
***Row Num = 249
Min = -3.000000
Max = 1.000000
Mean = -1.045455
std = 0.805636
RMS = 1.314257
***Row Num = 250
Min = -4.000000
Max = 1.000000
Mean = -1.136364
```

```
std = 1.192826
RMS = 1.637626
_____
***Row Num = 251
Min = -7.000000
Max = 10.000000
Mean = -0.863636
std = 2.938050
RMS = 3.030152
_____
***Row Num = 252
Min = -4.000000
Max = 1.000000
Mean = -0.840909
std = 1.345849
RMS = 1.573935
______
***Row Num = 253
Min = -125.000000
Max = 66.000000
Mean = -1.159091
std = 36.086423
RMS = 35.692818
______
***Row Num = 254
Min = -36.000000
Max = 19.000000
Mean = -0.431818
std = 11.899575
RMS = 11.771499
***Row Num = 255
Min = -14.000000
Max = 30.000000
Mean = -0.159091
std = 7.859058
RMS = 7.770866
***Row Num = 256
Min = -13.000000
Max = 9.000000
Mean = -1.590909
std = 4.368589
RMS = 4.602371
_____
***Row Num = 257
Min = -61.000000
Max = 15.000000
Mean = -0.977273
std = 11.244613
```

```
RMS = 11.158975
***Row Num = 258
Min = -26.000000
Max = 20.000000
Mean = -2.159091
std = 8.217800
RMS = 8.405896
______
***Row Num = 259
Min = -17.000000
Max = 13.000000
Mean = -0.068182
std = 6.714780
RMS = 6.638387
_____
***Row Num = 260
Min = -24.000000
Max = 46.000000
Mean = 0.090909
std = 11.476605
RMS = 11.345804
_____
***Row Num = 261
Min = -24.063000
Max = 25.750000
Mean = -0.524148
std = 8.991610
RMS = 8.904285
***Row Num = 262
Min = -24.063000
Max = 25.750000
Mean = -0.524148
std = 8.991610
RMS = 8.904285
______
***Row Num = 263
Min = -24.063000
Max = 25.750000
Mean = -0.524148
std = 8.991610
RMS = 8.904285
***Row Num = 264
Min = -39.500000
Max = 65.188000
Mean = 4.646318
std = 23.392142
RMS = 23.586954
```

```
_____
***Row Num = 265
Min = -39.500000
Max = 65.188000
Mean = 4.646318
std = 23.392142
RMS = 23.586954
_____
***Row Num = 266
Min = -39.500000
Max = 65.188000
Mean = 4.646318
std = 23.392142
RMS = 23.586954
***Row Num = 267
Min = 2.893900
Max = 3.001200
Mean = 2.947161
std = 0.026441
RMS = 2.947277
______
***Row Num = 268
Min = 3.104400
Max = 3.174200
Mean = 3.134995
std = 0.022980
RMS = 3.135078
_____
***Row Num = 269
Min = 7.243800
Max = 7.361700
Mean = 7.281159
std = 0.025121
RMS = 7.281201
***Row Num = 270
Min = 6.594000
Max = 8.287000
Mean = 7.133245
std = 0.469466
RMS = 7.148327
______
***Row Num = 271
Min = 3.045500
Max = 6.940800
Mean = 4.630877
std = 1.642822
RMS = 4.907398
```

```
***Row Num = 272
Min = 7.505900
Max = 9.955500
Mean = 8.310368
std = 0.755323
RMS = 8.343846
***Row Num = 273
Min = 0.896970
Max = 0.941410
Mean = 0.919457
std = 0.008968
RMS = 0.919499
______
***Row Num = 274
Min = -0.402340
Max = -0.335940
Mean = -0.376587
std = 0.013618
RMS = 0.376827
_____
***Row Num = 275
Min = 0.082520
Max = 0.120610
Mean = 0.100875
std = 0.010448
RMS = 0.101402
***Row Num = 276
Min = -1.230000
Max = 1.138200
Mean = 0.212912
std = 0.798982
RMS = 0.818044
______
***Row Num = 277
Min = 0.222170
Max = 0.998050
Mean = 0.496937
std = 0.226558
RMS = 0.545077
_____
***Row Num = 278
Min = -0.361330
Max = 0.653320
Mean = 0.188188
std = 0.228298
RMS = 0.293854
***Row Num = 279
```

```
Min = -6.000000
Max = 10.000000
Mean = -0.863636
std = 3.317262
RMS = 3.391165
***Row Num = 280
Min = -7.000000
Max = 5.000000
Mean = -1.045455
std = 2.281926
RMS = 2.486326
***Row Num = 281
Min = -3.000000
Max = 4.000000
Mean = -0.727273
std = 1.921284
RMS = 2.033805
_____
***Row Num = 282
Min = -3.000000
Max = 1.000000
Mean = -0.909091
std = 0.960092
RMS = 1.314257
______
***Row Num = 283
Min = -3.000000
Max = 1.000000
Mean = -0.886364
std = 0.945391
RMS = 1.288057
***Row Num = 284
Min = -3.000000
Max = 2.000000
Mean = -0.931818
std = 1.108062
RMS = 1.438117
______
***Row Num = 285
Min = -4.000000
Max = 2.000000
Mean = -1.000000
std = 1.509659
RMS = 1.796461
***Row Num = 286
Min = -3.000000
```

```
Max = 2.000000
Mean = -0.772727
std = 1.236342
RMS = 1.445998
______
***Row Num = 287
Min = -72.000000
Max = 52.000000
Mean = -4.727273
std = 33.585963
RMS = 33.536954
***Row Num = 288
Min = -22.000000
Max = 34.000000
Mean = -1.159091
std = 10.351819
RMS = 10.298941
_____
***Row Num = 289
Min = -20.000000
Max = 26.000000
Mean = -0.931818
std = 6.311296
RMS = 6.308364
______
***Row Num = 290
Min = -15.000000
Max = 13.000000
Mean = -1.886364
std = 5.863628
RMS = 6.095826
______
***Row Num = 291
Min = -47.000000
Max = 77.000000
Mean = -4.204545
std = 16.713147
RMS = 17.048727
-----
***Row Num = 292
Min = -46.000000
Max = 15.000000
Mean = -3.454545
std = 9.648363
RMS = 10.144412
_____
***Row Num = 293
Min = -15.000000
Max = 13.000000
```

```
Mean = -0.431818
std = 6.270632
RMS = 6.213987
______
***Row Num = 294
Min = -54.000000
Max = 22.000000
Mean = -3.909091
std = 16.197643
RMS = 16.482773
***Row Num = 295
Min = -16.438000
Max = 12.500000
Mean = 0.211682
std = 6.608172
RMS = 6.536076
______
***Row Num = 296
Min = -16.438000
Max = 12.500000
Mean = 0.211682
std = 6.608172
RMS = 6.536076
_____
***Row Num = 297
Min = -16.438000
Max = 12.500000
Mean = 0.211682
std = 6.608172
RMS = 6.536076
***Row Num = 298
Min = -91.250000
Max = 100.130000
Mean = 1.122216
std = 30.447358
RMS = 30.120290
______
***Row Num = 299
Min = -91.250000
Max = 100.130000
Mean = 1.122216
std = 30.447358
RMS = 30.120290
***Row Num = 300
Min = -91.250000
Max = 100.130000
Mean = 1.122216
```

```
std = 30.447358
RMS = 30.120290
_____
***Row Num = 301
Min = 2.883800
Max = 2.968600
Mean = 2.929827
std = 0.025747
RMS = 2.929938
_____
***Row Num = 302
Min = 3.109800
Max = 3.157000
Mean = 3.135182
std = 0.017037
RMS = 3.135227
***Row Num = 303
Min = 7.277000
Max = 7.352800
Mean = 7.317566
std = 0.015675
RMS = 7.317582
______
***Row Num = 304
Min = 6.572700
Max = 8.379700
Mean = 7.149945
std = 0.550317
RMS = 7.170613
***Row Num = 305
Min = 3.087100
Max = 6.957000
Mean = 4.751761
std = 1.643673
RMS = 5.021902
***Row Num = 306
Min = 7.837700
Max = 9.969400
Mean = 8.436934
std = 0.728018
RMS = 8.467575
_____
***Row Num = 307
Min = 0.898930
Max = 0.937990
Mean = 0.919656
std = 0.009058
```

```
RMS = 0.919700
***Row Num = 308
Min = -0.418460
Max = -0.334470
Mean = -0.375788
std = 0.015949
RMS = 0.376119
______
***Row Num = 309
Min = 0.072754
Max = 0.137700
Mean = 0.097401
std = 0.013581
RMS = 0.098322
_____
***Row Num = 310
Min = -0.909670
Max = 1.210000
Mean = 0.378607
std = 0.739277
RMS = 0.823075
_____
***Row Num = 311
Min = 0.099609
Max = 0.958500
Mean = 0.490047
std = 0.221418
RMS = 0.536710
***Row Num = 312
Min = -0.418950
Max = 0.627930
Mean = 0.206999
std = 0.219909
RMS = 0.300182
______
***Row Num = 313
Min = -12.000000
Max = 10.000000
Mean = -0.931818
std = 3.591966
RMS = 3.671141
***Row Num = 314
Min = -8.000000
Max = 2.000000
Mean = -0.977273
std = 2.107447
RMS = 2.301185
```

```
_____
***Row Num = 315
Min = -8.000000
Max = 5.000000
Mean = -1.409091
std = 2.536416
RMS = 2.876235
_____
***Row Num = 316
Min = -4.000000
Max = 2.000000
Mean = -1.340909
std = 1.218905
RMS = 1.802776
***Row Num = 317
Min = -3.000000
Max = 1.000000
Mean = -1.113636
std = 0.993371
RMS = 1.484771
______
***Row Num = 318
Min = -3.000000
Max = 2.000000
Mean = -0.863636
std = 1.047498
RMS = 1.348400
_____
***Row Num = 319
Min = -7.000000
Max = 2.000000
Mean = -1.045455
std = 1.829405
RMS = 2.088932
***Row Num = 320
Min = -4.000000
Max = 2.000000
Mean = -0.931818
std = 1.227547
RMS = 1.530003
______
***Row Num = 321
Min = -53.000000
Max = 91.000000
Mean = 6.886364
std = 25.610877
RMS = 26.237984
```

```
***Row Num = 322
Min = -17.000000
Max = 17.000000
Mean = 0.886364
std = 6.772777
RMS = 6.753787
***Row Num = 323
Min = -48.000000
Max = 19.000000
Mean = -2.454545
std = 10.105155
RMS = 10.286796
______
***Row Num = 324
Min = -11.000000
Max = 11.000000
Mean = 0.409091
std = 4.282567
RMS = 4.253341
_____
***Row Num = 325
Min = -81.000000
Max = 54.000000
Mean = -1.090909
std = 17.212513
RMS = 17.050726
***Row Num = 326
Min = -11.000000
Max = 13.000000
Mean = -0.704545
std = 5.133472
RMS = 5.123475
______
***Row Num = 327
Min = -13.000000
Max = 51.000000
Mean = 1.113636
std = 10.548263
RMS = 10.487005
_____
***Row Num = 328
Min = -33.000000
Max = 25.000000
Mean = -0.681818
std = 11.500804
RMS = 11.389788
***Row Num = 329
```

```
Min = -24.938000
Max = 16.938000
Mean = 0.017057
std = 8.765630
RMS = 8.665465
_____
***Row Num = 330
Min = -24.938000
Max = 16.938000
Mean = 0.017057
std = 8.765630
RMS = 8.665465
***Row Num = 331
Min = -24.938000
Max = 16.938000
Mean = 0.017057
std = 8.765630
RMS = 8.665465
_____
***Row Num = 332
Min = -82.250000
Max = 77.000000
Mean = 2.487284
std = 27.033779
RMS = 26.840308
______
***Row Num = 333
Min = -82.250000
Max = 77.000000
Mean = 2.487284
std = 27.033779
RMS = 26.840308
_____
***Row Num = 334
Min = -82.250000
Max = 77.000000
Mean = 2.487284
std = 27.033779
RMS = 26.840308
______
***Row Num = 335
Min = 2.871600
Max = 2.948100
Mean = 2.917389
std = 0.016142
RMS = 2.917432
***Row Num = 336
Min = 3.113900
```

```
Max = 3.169400
Mean = 3.134330
std = 0.016367
RMS = 3.134371
______
***Row Num = 337
Min = 7.271300
Max = 7.401000
Mean = 7.347177
std = 0.030356
RMS = 7.347239
***Row Num = 338
Min = 6.643200
Max = 8.284300
Mean = 7.030723
std = 0.453800
RMS = 7.045021
_____
***Row Num = 339
Min = 3.085200
Max = 6.877900
Mean = 4.431511
std = 1.563799
RMS = 4.693419
______
***Row Num = 340
Min = 7.762600
Max = 9.885400
Mean = 8.294386
std = 0.629544
RMS = 8.317702
______
***Row Num = 341
Min = 0.900390
Max = 0.942870
Mean = 0.922230
std = 0.009852
RMS = 0.922282
-----
***Row Num = 342
Min = -0.402340
Max = -0.315920
Mean = -0.370106
std = 0.017352
RMS = 0.370503
_____
***Row Num = 343
Min = 0.069824
Max = 0.119630
```

```
Mean = 0.095204
std = 0.011489
RMS = 0.095879
______
***Row Num = 344
Min = -1.085900
Max = 1.161600
Mean = 0.267955
std = 0.786901
RMS = 0.822764
***Row Num = 345
Min = 0.182130
Max = 0.905270
Mean = 0.499823
std = 0.213352
RMS = 0.542501
______
***Row Num = 346
Min = -0.364750
Max = 0.670900
Mean = 0.185003
std = 0.216707
RMS = 0.283056
***Row Num = 347
Min = -7.000000
Max = 12.000000
Mean = 0.272727
std = 4.442729
RMS = 4.400413
______
***Row Num = 348
Min = -8.000000
Max = 7.000000
Mean = -1.818182
std = 2.911666
RMS = 3.404542
______
***Row Num = 349
Min = -7.000000
Max = 13.000000
Mean = -0.909091
std = 3.367548
RMS = 3.450955
***Row Num = 350
Min = -4.000000
Max = 2.000000
Mean = -0.795455
```

```
std = 1.268208
RMS = 1.484771
______
***Row Num = 351
Min = -3.000000
Max = 2.000000
Mean = -0.954545
std = 1.010516
RMS = 1.381699
_____
***Row Num = 352
Min = -3.000000
Max = 1.000000
Mean = -0.909091
std = 1.052531
RMS = 1.381699
***Row Num = 353
Min = -4.000000
Max = 1.000000
Mean = -1.204545
std = 1.268208
RMS = 1.738599
______
***Row Num = 354
Min = -4.000000
Max = 1.000000
Mean = -1.159091
std = 1.292972
RMS = 1.725478
***Row Num = 355
Min = -41.000000
Max = 66.000000
Mean = 9.681818
std = 27.590673
RMS = 28.942733
***Row Num = 356
Min = -15.000000
Max = 27.000000
Mean = 1.931818
std = 9.299657
RMS = 9.394147
______
***Row Num = 357
Min = -48.000000
Max = 18.000000
Mean = -1.818182
std = 9.580195
```

```
RMS = 9.643651
***Row Num = 358
Min = -8.000000
Max = 12.000000
Mean = -0.409091
std = 4.150193
RMS = 4.123106
______
***Row Num = 359
Min = -9.000000
Max = 47.000000
Mean = 2.340909
std = 10.864800
RMS = 10.992766
_____
***Row Num = 360
Min = -17.000000
Max = 12.000000
Mean = -0.750000
std = 5.751137
RMS = 5.734663
_____
***Row Num = 361
Min = -22.000000
Max = 23.000000
Mean = 1.090909
std = 8.786401
RMS = 8.754220
***Row Num = 362
Min = -56.000000
Max = 27.000000
Mean = -1.090909
std = 10.739664
RMS = 10.672820
______
***Row Num = 363
Min = -11.750000
Max = 12.313000
Mean = 0.484386
std = 6.855238
RMS = 6.794179
***Row Num = 364
Min = -11.750000
Max = 12.313000
Mean = 0.484386
std = 6.855238
RMS = 6.794179
```

```
_____
***Row Num = 365
Min = -11.750000
Max = 12.313000
Mean = 0.484386
std = 6.855238
RMS = 6.794179
_____
***Row Num = 366
Min = -57.750000
Max = 92.438000
Mean = 5.674773
std = 27.458527
RMS = 27.731536
______
***Row Num = 367
Min = -57.750000
Max = 92.438000
Mean = 5.674773
std = 27.458527
RMS = 27.731536
______
***Row Num = 368
Min = -57.750000
Max = 92.438000
Mean = 5.674773
std = 27.458527
RMS = 27.731536
_____
***Row Num = 369
Min = 2.846400
Max = 2.956500
Mean = 2.914930
std = 0.026917
RMS = 2.915051
***Row Num = 370
Min = 3.086800
Max = 3.156600
Mean = 3.122823
std = 0.021832
RMS = 3.122897
______
***Row Num = 371
Min = 7.331400
Max = 7.392300
Mean = 7.360839
std = 0.017228
RMS = 7.360858
```

```
***Row Num = 372
Min = 6.628300
Max = 8.282300
Mean = 7.089380
std = 0.506182
RMS = 7.107018
***Row Num = 373
Min = 3.095100
Max = 6.886600
Mean = 4.649714
std = 1.607452
RMS = 4.913758
______
***Row Num = 374
Min = 7.695500
Max = 9.934100
Mean = 8.383627
std = 0.702152
RMS = 8.412314
_____
***Row Num = 375
Min = 0.896000
Max = 0.942380
Mean = 0.918434
std = 0.010735
RMS = 0.918496
***Row Num = 376
Min = -0.419920
Max = -0.323240
Mean = -0.381060
std = 0.017288
RMS = 0.381443
______
***Row Num = 377
Min = 0.069824
Max = 0.126950
Mean = 0.097745
std = 0.014813
RMS = 0.098836
_____
***Row Num = 378
Min = -0.959470
Max = 1.272000
Mean = 0.354783
std = 0.755193
RMS = 0.826574
***Row Num = 379
```

```
Min = 0.218750
Max = 0.956050
Mean = 0.481789
std = 0.211274
RMS = 0.525112
_____
***Row Num = 380
Min = -0.470700
Max = 0.693360
Mean = 0.200507
std = 0.249982
RMS = 0.318235
***Row Num = 381
Min = -9.000000
Max = 10.000000
Mean = -1.750000
std = 3.804068
RMS = 4.147836
_____
***Row Num = 382
Min = -7.000000
Max = 3.000000
Mean = -1.477273
std = 2.129403
RMS = 2.571699
______
***Row Num = 383
Min = -7.000000
Max = 5.000000
Mean = -1.454545
std = 2.636546
RMS = 2.984810
_____
***Row Num = 384
Min = -3.000000
Max = 2.000000
Mean = -0.977273
std = 1.130726
RMS = 1.484771
______
***Row Num = 385
Min = -3.000000
Max = 1.000000
Mean = -0.954545
std = 0.987234
RMS = 1.365151
***Row Num = 386
Min = -3.000000
```

```
Max = 1.000000
Mean = -1.022727
std = 0.952076
RMS = 1.389899
______
***Row Num = 387
Min = -5.000000
Max = 3.000000
Mean = -0.431818
std = 1.662133
RMS = 1.698930
***Row Num = 388
Min = -4.000000
Max = 2.000000
Mean = -0.681818
std = 1.443070
RMS = 1.581139
_____
***Row Num = 389
Min = -75.000000
Max = 60.000000
Mean = -0.136364
std = 29.998132
RMS = 29.655599
_____
***Row Num = 390
Min = -27.000000
Max = 17.000000
Mean = -1.750000
std = 9.452759
RMS = 9.507174
______
***Row Num = 391
Min = -18.000000
Max = 9.000000
Mean = -1.772727
std = 5.590123
RMS = 5.803604
-----
***Row Num = 392
Min = -16.000000
Max = 12.000000
Mean = -0.340909
std = 4.615158
RMS = 4.575130
______
***Row Num = 393
Min = -45.000000
Max = 20.000000
```

```
Mean = -1.545455
std = 10.422370
RMS = 10.418515
______
***Row Num = 394
Min = -14.000000
Max = 23.000000
Mean = 0.977273
std = 6.421217
RMS = 6.422616
***Row Num = 395
Min = -15.000000
Max = 23.000000
Mean = -0.500000
std = 8.777614
RMS = 8.691689
______
***Row Num = 396
Min = -42.000000
Max = 64.000000
Mean = -2.022727
std = 14.264101
RMS = 14.245414
***Row Num = 397
Min = -25.125000
Max = 13.875000
Mean = 0.231545
std = 8.861227
RMS = 8.763012
***Row Num = 398
Min = -25.125000
Max = 13.875000
Mean = 0.231545
std = 8.861227
RMS = 8.763012
______
***Row Num = 399
Min = -25.125000
Max = 13.875000
Mean = 0.231545
std = 8.861227
RMS = 8.763012
***Row Num = 400
Min = -176.250000
Max = 100.190000
Mean = 4.957477
```

```
std = 41.298412
RMS = 41.126302
______
***Row Num = 401
Min = -176.250000
Max = 100.190000
Mean = 4.957477
std = 41.298412
RMS = 41.126302
_____
***Row Num = 402
Min = -176.250000
Max = 100.190000
Mean = 4.957477
std = 41.298412
RMS = 41.126302
***Row Num = 403
Min = 2.864500
Max = 2.954400
Mean = 2.918780
std = 0.025950
RMS = 2.918892
______
***Row Num = 404
Min = 3.111100
Max = 3.169300
Mean = 3.142289
std = 0.015939
RMS = 3.142328
***Row Num = 405
Min = 7.313800
Max = 7.452000
Mean = 7.379870
std = 0.035171
RMS = 7.379952
***Row Num = 406
Min = 6.581900
Max = 8.297600
Mean = 7.044582
std = 0.463139
RMS = 7.059444
_____
***Row Num = 407
Min = 3.089300
Max = 6.886600
Mean = 4.481198
std = 1.581015
```

```
RMS = 4.745939
***Row Num = 408
Min = 7.601200
Max = 9.946000
Mean = 8.311498
std = 0.657586
RMS = 8.336881
_____
***Row Num = 409
Min = 0.895020
Max = 0.937990
Mean = 0.919500
std = 0.008379
RMS = 0.919537
_____
***Row Num = 410
Min = -0.408200
Max = -0.342290
Mean = -0.378329
std = 0.017148
RMS = 0.378709
______
***Row Num = 411
Min = 0.072266
Max = 0.140630
Mean = 0.094305
std = 0.014412
RMS = 0.095375
***Row Num = 412
Min = -1.008300
Max = 1.046400
Mean = 0.348444
std = 0.749993
RMS = 0.819218
______
***Row Num = 413
Min = 0.206540
Max = 1.051800
Mean = 0.491921
std = 0.222842
RMS = 0.538996
***Row Num = 414
Min = -0.437990
Max = 0.602050
Mean = 0.187655
std = 0.216784
RMS = 0.284854
```

```
_____
***Row Num = 415
Min = -10.000000
Max = 5.000000
Mean = -1.818182
std = 2.943441
RMS = 3.431141
_____
***Row Num = 416
Min = -12.000000
Max = 5.000000
Mean = -1.795455
std = 2.849558
RMS = 3.340523
***Row Num = 417
Min = -7.000000
Max = 6.000000
Mean = -1.659091
std = 2.614300
RMS = 3.071127
______
***Row Num = 418
Min = -4.000000
Max = 1.000000
Mean = -1.136364
std = 1.212165
RMS = 1.651446
_____
***Row Num = 419
Min = -3.000000
Max = 0.000000
Mean = -1.295455
std = 0.823479
RMS = 1.530003
***Row Num = 420
Min = -4.000000
Max = 2.000000
Mean = -1.181818
std = 1.084194
RMS = 1.595448
______
***Row Num = 421
Min = -5.000000
Max = 1.000000
Mean = -1.090909
std = 1.427605
RMS = 1.783765
```

```
***Row Num = 422
Min = -4.000000
Max = 3.000000
Mean = -0.954545
std = 1.413466
RMS = 1.692228
***Row Num = 423
Min = -45.000000
Max = 46.000000
Mean = 5.477273
std = 21.417759
RMS = 21.869967
______
***Row Num = 424
Min = -16.000000
Max = 23.000000
Mean = 1.000000
std = 8.985777
RMS = 8.939188
_____
***Row Num = 425
Min = -19.000000
Max = 19.000000
Mean = -1.409091
std = 6.251765
RMS = 6.338913
***Row Num = 426
Min = -11.000000
Max = 21.000000
Mean = -0.750000
std = 5.292052
RMS = 5.285056
______
***Row Num = 427
Min = -44.000000
Max = 51.000000
Mean = -0.931818
std = 11.781731
RMS = 11.684294
_____
***Row Num = 428
Min = -18.000000
Max = 20.000000
Mean = 0.000000
std = 7.685686
RMS = 7.597847
***Row Num = 429
```

```
Min = -21.000000
Max = 21.000000
Mean = -0.204545
std = 10.040799
RMS = 9.928151
_____
***Row Num = 430
Min = -22.000000
Max = 29.000000
Mean = -1.318182
std = 8.514755
RMS = 8.520030
***Row Num = 431
Min = -15.375000
Max = 15.688000
Mean = 0.453125
std = 7.616165
RMS = 7.542743
_____
***Row Num = 432
Min = -15.375000
Max = 15.688000
Mean = 0.453125
std = 7.616165
RMS = 7.542743
______
***Row Num = 433
Min = -15.375000
Max = 15.688000
Mean = 0.453125
std = 7.616165
RMS = 7.542743
***Row Num = 434
Min = -73.125000
Max = 65.313000
Mean = 5.056886
std = 24.296167
RMS = 24.545058
______
***Row Num = 435
Min = -73.125000
Max = 65.313000
Mean = 5.056886
std = 24.296167
RMS = 24.545058
***Row Num = 436
Min = -73.125000
```

```
Max = 65.313000
Mean = 5.056886
std = 24.296167
RMS = 24.545058
______
***Row Num = 437
Min = 2.855100
Max = 2.957300
Mean = 2.905670
std = 0.029220
RMS = 2.905814
***Row Num = 438
Min = 3.103600
Max = 3.167400
Mean = 3.134820
std = 0.020154
RMS = 3.134884
______
***Row Num = 439
Min = 7.346400
Max = 7.460400
Mean = 7.390366
std = 0.032345
RMS = 7.390435
_____
***Row Num = 440
Min = 6.648800
Max = 8.432200
Mean = 7.076175
std = 0.502230
RMS = 7.093571
______
***Row Num = 441
Min = 3.075100
Max = 6.895000
Mean = 4.493695
std = 1.573091
RMS = 4.755173
-----
***Row Num = 442
Min = 0.020777
Max = 9.725100
Mean = 7.837484
std = 1.828210
RMS = 8.043168
_____
***Row Num = 443
Min = 0.896970
Max = 0.939450
```

```
Mean = 0.920466
std = 0.008807
RMS = 0.920507
______
***Row Num = 444
Min = -0.420900
Max = -0.348630
Mean = -0.376831
std = 0.014980
RMS = 0.377122
***Row Num = 445
Min = 0.061035
Max = 0.116700
Mean = 0.088956
std = 0.013733
RMS = 0.089986
______
***Row Num = 446
Min = -0.995120
Max = 1.111800
Mean = 0.241044
std = 0.785966
RMS = 0.813514
***Row Num = 447
Min = 0.229980
Max = 0.914060
Mean = 0.496005
std = 0.196315
RMS = 0.532621
_____
***Row Num = 448
Min = -0.337400
Max = 0.640630
Mean = 0.189875
std = 0.241125
RMS = 0.304750
______
***Row Num = 449
Min = -8.000000
Max = 14.000000
Mean = -0.590909
std = 4.013455
RMS = 4.011348
***Row Num = 450
Min = -10.000000
Max = 7.000000
Mean = -0.590909
```

```
std = 3.519502
RMS = 3.529100
_____
***Row Num = 451
Min = -6.000000
Max = 6.000000
Mean = -1.818182
std = 2.713213
RMS = 3.240370
_____
***Row Num = 452
Min = -4.000000
Max = 3.000000
Mean = -1.204545
std = 1.650645
RMS = 2.028210
***Row Num = 453
Min = -3.000000
Max = 1.000000
Mean = -0.863636
std = 1.153174
RMS = 1.430194
______
***Row Num = 454
Min = -3.000000
Max = 2.000000
Mean = -0.750000
std = 1.037102
RMS = 1.270290
***Row Num = 455
Min = -4.000000
Max = 3.000000
Mean = -0.750000
std = 1.686127
RMS = 1.827815
***Row Num = 456
Min = -4.000000
Max = 3.000000
Mean = -1.045455
std = 1.293176
RMS = 1.651446
_____
***Row Num = 457
Min = -83.000000
Max = 75.000000
Mean = 5.909091
std = 33.774091
```

```
RMS = 33.906958
______
***Row Num = 458
Min = -24.000000
Max = 20.000000
Mean = 0.295455
std = 9.092751
RMS = 8.993685
______
***Row Num = 459
Min = -15.000000
Max = 21.000000
Mean = -0.090909
std = 5.643758
RMS = 5.579997
_____
***Row Num = 460
Min = -10.000000
Max = 20.000000
Mean = 0.204545
std = 4.717999
RMS = 4.668560
______
***Row Num = 461
Min = -17.000000
Max = 27.000000
Mean = -0.613636
std = 7.555118
RMS = 7.493937
***Row Num = 462
Min = -14.000000
Max = 26.000000
Mean = 0.000000
std = 7.970877
RMS = 7.879778
______
***Row Num = 463
Min = -27.000000
Max = 20.000000
Mean = -2.250000
std = 8.608068
RMS = 8.802118
***Row Num = 464
Min = -67.000000
Max = 25.000000
Mean = -0.068182
std = 13.650790
RMS = 13.494949
```

```
_____
***Row Num = 465
Min = -22.875000
Max = 16.500000
Mean = -0.157705
std = 7.816068
RMS = 7.728348
_____
***Row Num = 466
Min = -22.875000
Max = 16.500000
Mean = -0.157705
std = 7.816068
RMS = 7.728348
***Row Num = 467
Min = -22.875000
Max = 16.500000
Mean = -0.157705
std = 7.816068
RMS = 7.728348
______
***Row Num = 468
Min = -46.750000
Max = 85.563000
Mean = 5.183318
std = 25.040756
RMS = 25.291409
_____
***Row Num = 469
Min = -46.750000
Max = 85.563000
Mean = 5.183318
std = 25.040756
RMS = 25.291409
***Row Num = 470
Min = -46.750000
Max = 85.563000
Mean = 5.183318
std = 25.040756
RMS = 25.291409
______
***Row Num = 471
Min = 2.825500
Max = 2.908200
Mean = 2.872982
std = 0.018990
RMS = 2.873043
```

```
***Row Num = 472
Min = 3.113200
Max = 3.166000
Mean = 3.136134
std = 0.014559
RMS = 3.136167
***Row Num = 473
Min = 7.341300
Max = 7.459900
Mean = 7.411782
std = 0.029502
RMS = 7.411839
______
***Row Num = 474
Min = 6.587300
Max = 8.270500
Mean = 7.086980
std = 0.532280
RMS = 7.106487
_____
***Row Num = 475
Min = 3.054300
Max = 6.890900
Mean = 4.698805
std = 1.611717
RMS = 4.961588
***Row Num = 476
Min = 7.632000
Max = 9.862100
Mean = 8.318034
std = 0.749812
RMS = 8.350996
______
***Row Num = 477
Min = 0.897950
Max = 0.950200
Mean = 0.919967
std = 0.010897
RMS = 0.920030
_____
***Row Num = 478
Min = -0.402830
Max = -0.325200
Mean = -0.376365
std = 0.016871
RMS = 0.376735
***Row Num = 479
```

```
Min = 0.054199
Max = 0.124020
Mean = 0.092895
std = 0.011978
RMS = 0.093647
_____
***Row Num = 480
Min = -0.947270
Max = 1.210000
Mean = 0.286399
std = 0.758811
RMS = 0.802953
***Row Num = 481
Min = 0.146480
Max = 1.069300
Mean = 0.465408
std = 0.229416
RMS = 0.517726
_____
***Row Num = 482
Min = -0.333010
Max = 0.656740
Mean = 0.183072
std = 0.225676
RMS = 0.288596
______
***Row Num = 483
Min = -8.000000
Max = 4.000000
Mean = -1.204545
std = 2.368196
RMS = 2.632835
***Row Num = 484
Min = -6.000000
Max = 2.000000
Mean = -1.613636
std = 1.701106
RMS = 2.330626
______
***Row Num = 485
Min = -6.000000
Max = 7.000000
Mean = -1.227273
std = 2.467120
RMS = 2.730301
***Row Num = 486
Min = -4.000000
```

```
Max = 1.000000
Mean = -1.136364
std = 1.112109
RMS = 1.581139
______
***Row Num = 487
Min = -4.000000
Max = 1.000000
Mean = -1.227273
std = 1.117798
RMS = 1.651446
***Row Num = 488
Min = -3.000000
Max = 1.000000
Mean = -0.886364
std = 0.969678
RMS = 1.305582
_____
***Row Num = 489
Min = -4.000000
Max = 3.000000
Mean = -0.795455
std = 1.518560
RMS = 1.698930
______
***Row Num = 490
Min = -5.000000
Max = 2.000000
Mean = -1.159091
std = 1.328457
RMS = 1.751623
______
***Row Num = 491
Min = -63.000000
Max = 50.000000
Mean = 3.704545
std = 20.454805
RMS = 20.557569
-----
***Row Num = 492
Min = -25.000000
Max = 12.000000
Mean = -0.500000
std = 7.144684
RMS = 7.080704
_____
***Row Num = 493
Min = -32.000000
Max = 4.000000
```

```
Mean = -2.250000
std = 6.891603
RMS = 7.174766
______
***Row Num = 494
Min = -13.000000
Max = 10.000000
Mean = -0.795455
std = 2.992856
RMS = 3.063717
***Row Num = 495
Min = -13.000000
Max = 12.000000
Mean = -1.136364
std = 3.788544
RMS = 3.913845
______
***Row Num = 496
Min = -17.000000
Max = 8.000000
Mean = -1.772727
std = 5.577628
RMS = 5.791844
_____
***Row Num = 497
Min = -30.000000
Max = 18.000000
Mean = -0.090909
std = 8.285089
RMS = 8.190904
***Row Num = 498
Min = -53.000000
Max = 24.000000
Mean = -0.022727
std = 11.604908
RMS = 11.472299
______
***Row Num = 499
Min = -19.438000
Max = 10.000000
Mean = -0.585261
std = 6.562784
RMS = 6.514123
***Row Num = 500
Min = -19.438000
Max = 10.000000
Mean = -0.585261
```

```
std = 6.562784
RMS = 6.514123
______
***Row Num = 501
Min = -19.438000
Max = 10.000000
Mean = -0.585261
std = 6.562784
RMS = 6.514123
_____
***Row Num = 502
Min = -111.810000
Max = 85.625000
Mean = 4.056920
std = 31.600383
RMS = 31.501551
______
***Row Num = 503
Min = -111.810000
Max = 85.625000
Mean = 4.056920
std = 31.600383
RMS = 31.501551
______
***Row Num = 504
Min = -111.810000
Max = 85.625000
Mean = 4.056920
std = 31.600383
RMS = 31.501551
***Row Num = 505
Min = 2.835000
Max = 2.933600
Mean = 2.884316
std = 0.028704
RMS = 2.884455
***Row Num = 506
Min = 3.106900
Max = 3.169400
Mean = 3.135945
std = 0.019574
RMS = 3.136005
_____
***Row Num = 507
Min = 7.349500
Max = 7.430300
Mean = 7.384743
std = 0.017959
```

```
RMS = 7.384765
______
***Row Num = 508
Min = 6.573400
Max = 8.406600
Mean = 7.074666
std = 0.533032
RMS = 7.094263
______
***Row Num = 509
Min = 3.096600
Max = 6.884000
Mean = 4.556841
std = 1.608357
RMS = 4.826264
_____
***Row Num = 510
Min = 7.634900
Max = 9.976100
Mean = 8.274382
std = 0.724182
RMS = 8.305294
_____
***Row Num = 511
Min = 0.897460
Max = 0.945310
Mean = 0.918291
std = 0.008245
RMS = 0.918327
***Row Num = 512
Min = -0.407710
Max = -0.328130
Mean = -0.382014
std = 0.016054
RMS = 0.382344
______
***Row Num = 513
Min = 0.068848
Max = 0.116210
Mean = 0.093928
std = 0.011304
RMS = 0.094590
***Row Num = 514
Min = -1.133800
Max = 1.119100
Mean = 0.239035
std = 0.786213
RMS = 0.813154
```

```
_____
***Row Num = 515
Min = 0.201660
Max = 0.911620
Mean = 0.478361
std = 0.216900
RMS = 0.524219
_____
***Row Num = 516
Min = -0.466800
Max = 0.588870
Mean = 0.181963
std = 0.241019
RMS = 0.299801
***Row Num = 517
Min = -8.000000
Max = 11.000000
Mean = -1.068182
std = 2.904669
RMS = 3.063717
______
***Row Num = 518
Min = -4.000000
Max = 6.000000
Mean = -0.659091
std = 2.410666
RMS = 2.472577
_____
***Row Num = 519
Min = -8.000000
Max = 6.000000
Mean = -1.022727
std = 2.937240
RMS = 3.078518
***Row Num = 520
Min = -4.000000
Max = 2.000000
Mean = -1.181818
std = 1.368631
RMS = 1.796461
______
***Row Num = 521
Min = -3.000000
Max = 1.000000
Mean = -0.909091
std = 0.935556
RMS = 1.296849
```

```
***Row Num = 522
Min = -4.000000
Max = 1.000000
Mean = -0.954545
std = 1.077347
RMS = 1.430194
***Row Num = 523
Min = -4.000000
Max = 2.000000
Mean = -0.772727
std = 1.378635
RMS = 1.566699
______
***Row Num = 524
Min = -3.000000
Max = 1.000000
Mean = -1.136364
std = 1.090997
RMS = 1.566699
_____
***Row Num = 525
Min = -95.000000
Max = 47.000000
Mean = -0.022727
std = 26.382243
RMS = 26.080731
***Row Num = 526
Min = -24.000000
Max = 17.000000
Mean = 0.227273
std = 7.799415
RMS = 7.713624
______
***Row Num = 527
Min = -14.000000
Max = 20.000000
Mean = -0.159091
std = 5.995902
RMS = 5.929510
_____
***Row Num = 528
Min = -12.000000
Max = 7.000000
Mean = -0.886364
std = 3.505583
RMS = 3.577073
***Row Num = 529
```

```
Min = -7.000000
Max = 28.000000
Mean = 0.409091
std = 5.091343
RMS = 5.049752
_____
***Row Num = 530
Min = -11.000000
Max = 13.000000
Mean = -0.227273
std = 5.075539
RMS = 5.022676
***Row Num = 531
Min = -38.000000
Max = 14.000000
Mean = -1.818182
std = 8.052943
RMS = 8.165894
_____
***Row Num = 532
Min = -67.000000
Max = 18.000000
Mean = -4.250000
std = 14.898299
RMS = 15.328968
***Row Num = 533
Min = -18.813000
Max = 10.938000
Mean = -0.474432
std = 6.378620
RMS = 6.323542
***Row Num = 534
Min = -18.813000
Max = 10.938000
Mean = -0.474432
std = 6.378620
RMS = 6.323542
______
***Row Num = 535
Min = -18.813000
Max = 10.938000
Mean = -0.474432
std = 6.378620
RMS = 6.323542
***Row Num = 536
Min = -181.190000
```

```
Max = 120.810000
Mean = 2.843648
std = 41.120594
RMS = 40.749968
______
***Row Num = 537
Min = -181.190000
Max = 120.810000
Mean = 2.843648
std = 41.120594
RMS = 40.749968
_____
***Row Num = 538
Min = -181.190000
Max = 120.810000
Mean = 2.843648
std = 41.120594
RMS = 40.749968
_____
***Row Num = 539
Min = 2.843800
Max = 2.923900
Mean = 2.888211
std = 0.020182
RMS = 2.888280
______
***Row Num = 540
Min = 3.114100
Max = 3.176400
Mean = 3.144868
std = 0.019202
RMS = 3.144925
_____
***Row Num = 541
Min = 7.346100
Max = 7.455400
Mean = 7.389209
std = 0.022370
RMS = 7.389242
-----
***Row Num = 542
Min = 6.594800
Max = 8.727700
Mean = 7.130227
std = 0.626407
RMS = 7.157067
_____
***Row Num = 543
Min = 3.114300
Max = 6.907600
```

```
Mean = 4.708161
std = 1.600073
RMS = 4.966773
______
***Row Num = 544
Min = 0.196280
Max = 9.988600
Mean = 8.107929
std = 1.419978
RMS = 8.228550
***Row Num = 545
Min = 0.896000
Max = 0.937990
Mean = 0.920821
std = 0.008120
RMS = 0.920856
______
***Row Num = 546
Min = -0.414550
Max = -0.335450
Mean = -0.376465
std = 0.014524
RMS = 0.376739
_____
***Row Num = 547
Min = 0.056641
Max = 0.120120
Mean = 0.087868
std = 0.013007
RMS = 0.088804
_____
***Row Num = 548
Min = -1.048300
Max = 1.160200
Mean = 0.226964
std = 0.794332
RMS = 0.817396
______
***Row Num = 549
Min = 0.258790
Max = 0.922850
Mean = 0.483198
std = 0.204873
RMS = 0.523927
***Row Num = 550
Min = -0.444340
Max = 0.631840
Mean = 0.194080
```

```
std = 0.251681
RMS = 0.315549
_____
***Row Num = 551
Min = -9.000000
Max = 11.000000
Mean = -0.636364
std = 3.498112
RMS = 3.516196
_____
***Row Num = 552
Min = -7.000000
Max = 4.000000
Mean = -0.636364
std = 2.343630
RMS = 2.402650
***Row Num = 553
Min = -6.000000
Max = 4.000000
Mean = -1.090909
std = 2.639751
RMS = 2.828427
______
***Row Num = 554
Min = -3.000000
Max = 1.000000
Mean = -1.136364
std = 1.112109
RMS = 1.581139
***Row Num = 555
Min = -3.000000
Max = 1.000000
Mean = -0.977273
std = 0.952076
RMS = 1.356801
***Row Num = 556
Min = -3.000000
Max = 1.000000
Mean = -1.022727
std = 0.999736
RMS = 1.422226
_____
***Row Num = 557
Min = -5.000000
Max = 2.000000
Mean = -1.136364
std = 1.286620
```

```
RMS = 1.705606
______
***Row Num = 558
Min = -4.000000
Max = 2.000000
Mean = -1.295455
std = 1.211947
RMS = 1.764550
_____
***Row Num = 559
Min = -48.000000
Max = 63.000000
Mean = -2.750000
std = 23.607375
RMS = 23.499033
_____
***Row Num = 560
Min = -19.000000
Max = 16.000000
Mean = 0.045455
std = 6.706313
RMS = 6.629822
_____
***Row Num = 561
Min = -12.000000
Max = 30.000000
Mean = 0.909091
std = 7.290702
RMS = 7.264484
***Row Num = 562
Min = -7.000000
Max = 6.000000
Mean = -0.954545
std = 2.956699
RMS = 3.074824
______
***Row Num = 563
Min = -19.000000
Max = 8.000000
Mean = -1.090909
std = 4.203090
RMS = 4.295875
***Row Num = 564
Min = -12.000000
Max = 19.000000
Mean = 1.000000
std = 5.348332
RMS = 5.380943
```

```
_____
***Row Num = 565
Min = -24.000000
Max = 26.000000
Mean = 0.750000
std = 8.158674
RMS = 8.100224
_____
***Row Num = 566
Min = -27.000000
Max = 55.000000
Mean = -0.181818
std = 13.305485
RMS = 13.154674
***Row Num = 567
Min = -20.625000
Max = 20.313000
Mean = 0.238648
std = 7.969396
RMS = 7.881928
______
***Row Num = 568
Min = -20.625000
Max = 20.313000
Mean = 0.238648
std = 7.969396
RMS = 7.881928
_____
***Row Num = 569
Min = -20.625000
Max = 20.313000
Mean = 0.238648
std = 7.969396
RMS = 7.881928
______
***Row Num = 570
Min = -106.060000
Max = 84.813000
Mean = 3.259989
std = 29.863455
RMS = 29.701594
______
***Row Num = 571
Min = -106.060000
Max = 84.813000
Mean = 3.259989
std = 29.863455
RMS = 29.701594
```

```
***Row Num = 572
Min = -106.060000
Max = 84.813000
Mean = 3.259989
std = 29.863455
RMS = 29.701594
***Row Num = 573
Min = 2.821800
Max = 2.892700
Mean = 2.862748
std = 0.021419
RMS = 2.862826
______
***Row Num = 574
Min = 3.107300
Max = 3.156300
Mean = 3.134014
std = 0.014180
RMS = 3.134045
_____
***Row Num = 575
Min = 7.317700
Max = 7.438600
Mean = 7.391893
std = 0.024122
RMS = 7.391932
***Row Num = 576
Min = 6.579500
Max = 8.451700
Mean = 7.108689
std = 0.532629
RMS = 7.128162
______
***Row Num = 577
Min = 3.082700
Max = 6.939000
Mean = 4.737216
std = 1.637055
RMS = 5.006022
_____
***Row Num = 578
Min = 0.050657
Max = 9.876500
Mean = 8.079240
std = 1.419306
RMS = 8.200169
***Row Num = 579
```

```
Min = 0.900390
Max = 0.938960
Mean = 0.916770
std = 0.007136
RMS = 0.916798
_____
***Row Num = 580
Min = -0.421390
Max = -0.354490
Mean = -0.386685
std = 0.011998
RMS = 0.386867
***Row Num = 581
Min = 0.056152
Max = 0.122560
Mean = 0.087247
std = 0.013013
RMS = 0.088190
_____
***Row Num = 582
Min = -1.055200
Max = 1.109900
Mean = -0.022416
std = 0.829119
RMS = 0.819949
***Row Num = 583
Min = 0.098633
Max = 0.912600
Mean = 0.502819
std = 0.212638
RMS = 0.544990
______
***Row Num = 584
Min = -0.543950
Max = 0.576170
Mean = 0.143977
std = 0.240744
RMS = 0.278154
______
***Row Num = 585
Min = -8.000000
Max = 5.000000
Mean = -1.272727
std = 2.213738
RMS = 2.531618
***Row Num = 586
Min = -7.000000
```

```
Max = 9.000000
Mean = -0.863636
std = 2.397585
RMS = 2.522625
______
***Row Num = 587
Min = -6.000000
Max = 6.000000
Mean = -1.000000
std = 2.382104
RMS = 2.558409
***Row Num = 588
Min = -4.000000
Max = 2.000000
Mean = -1.250000
std = 1.241248
RMS = 1.751623
_____
***Row Num = 589
Min = -3.000000
Max = 1.000000
Mean = -0.931818
std = 1.043200
RMS = 1.389899
_____
***Row Num = 590
Min = -3.000000
Max = 1.000000
Mean = -0.931818
std = 1.149271
RMS = 1.469385
______
***Row Num = 591
Min = -4.000000
Max = 2.000000
Mean = -0.818182
std = 1.434990
RMS = 1.637626
-----
***Row Num = 592
Min = -3.000000
Max = 1.000000
Mean = -0.909091
std = 1.157748
RMS = 1.461630
***Row Num = 593
Min = -80.000000
Max = 48.000000
```

```
Mean = 1.840909
std = 25.671397
RMS = 25.444682
______
***Row Num = 594
Min = -27.000000
Max = 24.000000
Mean = -0.545455
std = 9.643541
RMS = 9.548917
***Row Num = 595
Min = -14.000000
Max = 16.000000
Mean = -0.545455
std = 5.529854
RMS = 5.493798
______
***Row Num = 596
Min = -8.000000
Max = 8.000000
Mean = -0.340909
std = 3.490473
RMS = 3.467380
_____
***Row Num = 597
Min = -18.000000
Max = 53.000000
Mean = -0.750000
std = 9.045428
RMS = 8.973446
***Row Num = 598
Min = -10.000000
Max = 11.000000
Mean = -0.386364
std = 3.901198
RMS = 3.875916
______
***Row Num = 599
Min = -16.000000
Max = 31.000000
Mean = 1.090909
std = 8.051630
RMS = 8.034019
***Row Num = 600
Min = -47.000000
Max = 31.000000
Mean = -2.068182
```

```
std = 11.596707
RMS = 11.649229
_____
***Row Num = 601
Min = -21.063000
Max = 23.000000
Mean = 0.147705
std = 8.722481
RMS = 8.624058
_____
***Row Num = 602
Min = -21.063000
Max = 23.000000
Mean = 0.147705
std = 8.722481
RMS = 8.624058
______
***Row Num = 603
Min = -21.063000
Max = 23.000000
Mean = 0.147705
std = 8.722481
RMS = 8.624058
______
***Row Num = 604
Min = -74.188000
Max = 89.313000
Mean = 6.987261
std = 32.288799
RMS = 32.675582
***Row Num = 605
Min = -74.188000
Max = 89.313000
Mean = 6.987261
std = 32.288799
RMS = 32.675582
***Row Num = 606
Min = -74.188000
Max = 89.313000
Mean = 6.987261
std = 32.288799
RMS = 32.675582
_____
***Row Num = 607
Min = 2.826100
Max = 2.886900
Mean = 2.855441
std = 0.014685
```

```
RMS = 2.855478
***Row Num = 608
Min = 3.116900
Max = 3.177800
Mean = 3.147918
std = 0.015542
RMS = 3.147956
______
***Row Num = 609
Min = 7.325000
Max = 7.437800
Mean = 7.389518
std = 0.027570
RMS = 7.389568
_____
***Row Num = 610
Min = 6.616300
Max = 8.572900
Mean = 7.276389
std = 0.535728
RMS = 7.295637
______
***Row Num = 611
Min = 3.103000
Max = 6.952300
Mean = 5.270545
std = 1.624075
RMS = 5.509657
***Row Num = 612
Min = 0.177770
Max = 9.988900
Mean = 8.253070
std = 1.458355
RMS = 8.378044
______
***Row Num = 613
Min = 0.911620
Max = 0.934080
Mean = 0.923029
std = 0.004967
RMS = 0.923042
***Row Num = 614
Min = -0.403320
Max = -0.350590
Mean = -0.371194
std = 0.010791
RMS = 0.371347
```

```
_____
***Row Num = 615
Min = 0.062500
Max = 0.108400
Mean = 0.086859
std = 0.009874
RMS = 0.087405
_____
***Row Num = 616
Min = -1.024900
Max = 1.091300
Mean = 0.216863
std = 0.812157
RMS = 0.831647
***Row Num = 617
Min = 0.155270
Max = 0.967290
Mean = 0.413741
std = 0.171666
RMS = 0.447193
______
***Row Num = 618
Min = -0.463380
Max = 0.686040
Mean = 0.157404
std = 0.223538
RMS = 0.271311
_____
***Row Num = 619
Min = -7.000000
Max = 6.000000
Mean = -1.250000
std = 2.488345
RMS = 2.759282
***Row Num = 620
Min = -8.000000
Max = 8.000000
Mean = -1.181818
std = 2.599398
RMS = 2.828427
______
***Row Num = 621
Min = -10.000000
Max = 9.000000
Mean = -0.818182
std = 3.674378
RMS = 3.723390
```

```
***Row Num = 622
Min = -4.000000
Max = 2.000000
Mean = -1.227273
std = 1.198131
RMS = 1.705606
***Row Num = 623
Min = -3.000000
Max = 0.000000
Mean = -1.159091
std = 0.887725
RMS = 1.453835
______
***Row Num = 624
Min = -3.000000
Max = 1.000000
Mean = -0.840909
std = 1.077102
RMS = 1.356801
_____
***Row Num = 625
Min = -3.000000
Max = 2.000000
Mean = -0.704545
std = 1.211947
RMS = 1.389899
***Row Num = 626
Min = -3.000000
Max = 1.000000
Mean = -0.772727
std = 1.117798
RMS = 1.348400
______
***Row Num = 627
Min = -76.000000
Max = 58.000000
Mean = 5.818182
std = 25.318688
RMS = 25.696657
_____
***Row Num = 628
Min = -23.000000
Max = 23.000000
Mean = 0.613636
std = 7.761611
RMS = 7.697402
***Row Num = 629
```

```
Min = -36.000000
Max = 4.000000
Mean = -2.159091
std = 5.810749
RMS = 6.136700
_____
***Row Num = 630
Min = -6.000000
Max = 4.000000
Mean = -0.863636
std = 1.746637
RMS = 1.930615
***Row Num = 631
Min = -57.000000
Max = 43.000000
Mean = -0.977273
std = 11.339350
RMS = 11.252272
_____
***Row Num = 632
Min = -15.000000
Max = 20.000000
Mean = 0.045455
std = 6.220576
RMS = 6.149649
______
***Row Num = 633
Min = -29.000000
Max = 14.000000
Mean = 0.409091
std = 7.977638
RMS = 7.897065
***Row Num = 634
Min = -21.000000
Max = 59.000000
Mean = 2.500000
std = 13.377350
RMS = 13.458691
______
***Row Num = 635
Min = -14.438000
Max = 20.125000
Mean = 0.637784
std = 6.279219
RMS = 6.240132
***Row Num = 636
Min = -14.438000
```

```
Max = 20.125000
Mean = 0.637784
std = 6.279219
RMS = 6.240132
______
***Row Num = 637
Min = -14.438000
Max = 20.125000
Mean = 0.637784
std = 6.279219
RMS = 6.240132
_____
***Row Num = 638
Min = -33.188000
Max = 47.375000
Mean = 2.048273
std = 15.730503
RMS = 15.685034
_____
***Row Num = 639
Min = -33.188000
Max = 47.375000
Mean = 2.048273
std = 15.730503
RMS = 15.685034
______
***Row Num = 640
Min = -33.188000
Max = 47.375000
Mean = 2.048273
std = 15.730503
RMS = 15.685034
______
***Row Num = 641
Min = 2.827700
Max = 2.910900
Mean = 2.869752
std = 0.019406
RMS = 2.869816
-----
***Row Num = 642
Min = 3.104400
Max = 3.153300
Mean = 3.124107
std = 0.013226
RMS = 3.124134
_____
***Row Num = 643
Min = 7.318500
Max = 7.402800
```

```
Mean = 7.381050
std = 0.016187
RMS = 7.381067
______
***Row Num = 644
Min = 6.558600
Max = 8.500100
Mean = 7.118973
std = 0.543549
RMS = 7.139223
***Row Num = 645
Min = 3.112300
Max = 6.982800
Mean = 4.695373
std = 1.719849
RMS = 4.993714
______
***Row Num = 646
Min = 0.141310
Max = 9.892700
Mean = 8.074423
std = 1.447721
RMS = 8.200278
***Row Num = 647
Min = 0.901860
Max = 0.927730
Mean = 0.916037
std = 0.004543
RMS = 0.916048
______
***Row Num = 648
Min = -0.405270
Max = -0.366210
Mean = -0.385953
std = 0.007625
RMS = 0.386027
______
***Row Num = 649
Min = 0.069824
Max = 0.104980
Mean = 0.088978
std = 0.007466
RMS = 0.089284
***Row Num = 650
Min = -1.052200
Max = 0.250000
Mean = -0.851572
```

```
std = 0.237411
RMS = 0.883322
_____
***Row Num = 651
Min = 0.185060
Max = 0.799800
Mean = 0.387496
std = 0.097088
RMS = 0.399205
_____
***Row Num = 652
Min = -0.445800
Max = 0.536620
Mean = -0.021107
std = 0.147355
RMS = 0.147192
***Row Num = 653
Min = -7.000000
Max = 10.000000
Mean = -0.954545
std = 2.917107
RMS = 3.037643
______
***Row Num = 654
Min = -6.000000
Max = 7.000000
Mean = -0.818182
std = 2.489725
RMS = 2.593699
***Row Num = 655
Min = -9.000000
Max = 4.000000
Mean = -1.431818
std = 2.880550
RMS = 3.187333
***Row Num = 656
Min = -3.000000
Max = 1.000000
Mean = -1.159091
std = 1.237837
RMS = 1.685500
______
***Row Num = 657
Min = -3.000000
Max = 2.000000
Mean = -0.840909
std = 1.328457
```

```
RMS = 1.559429
***Row Num = 658
Min = -4.000000
Max = 1.000000
Mean = -1.250000
std = 1.143739
RMS = 1.685500
______
***Row Num = 659
Min = -4.000000
Max = 2.000000
Mean = -0.931818
std = 1.531039
RMS = 1.777383
_____
***Row Num = 660
Min = -3.000000
Max = 2.000000
Mean = -1.159091
std = 1.098481
RMS = 1.588310
***Row Num = 661
Min = -66.000000
Max = 45.000000
Mean = 4.227273
std = 24.816408
RMS = 24.894322
***Row Num = 662
Min = -30.000000
Max = 21.000000
Mean = -0.227273
std = 10.103795
RMS = 9.990905
______
***Row Num = 663
Min = -13.000000
Max = 19.000000
Mean = 0.840909
std = 5.216000
RMS = 5.224505
***Row Num = 664
Min = -5.000000
Max = 5.000000
Mean = -0.159091
std = 2.261335
RMS = 2.241144
```

```
_____
***Row Num = 665
Min = -4.000000
Max = 16.000000
Mean = 0.090909
std = 3.109013
RMS = 3.074824
_____
***Row Num = 666
Min = -19.000000
Max = 19.000000
Mean = 0.159091
std = 6.164200
RMS = 6.095826
***Row Num = 667
Min = -18.000000
Max = 22.000000
Mean = -0.909091
std = 8.542148
RMS = 8.493313
______
***Row Num = 668
Min = -71.000000
Max = 47.000000
Mean = -1.227273
std = 16.575218
RMS = 16.431677
_____
***Row Num = 669
Min = -15.438000
Max = 13.563000
Mean = -0.018466
std = 4.769492
RMS = 4.715018
______
***Row Num = 670
Min = -15.438000
Max = 13.563000
Mean = -0.018466
std = 4.769492
RMS = 4.715018
______
***Row Num = 671
Min = -15.438000
Max = 13.563000
Mean = -0.018466
std = 4.769492
RMS = 4.715018
```

```
***Row Num = 672
Min = -21.563000
Max = 45.625000
Mean = 4.032693
std = 12.796334
RMS = 13.277321
***Row Num = 673
Min = -21.563000
Max = 45.625000
Mean = 4.032693
std = 12.796334
RMS = 13.277321
______
***Row Num = 674
Min = -21.563000
Max = 45.625000
Mean = 4.032693
std = 12.796334
RMS = 13.277321
_____
***Row Num = 675
Min = 2.848700
Max = 2.885600
Mean = 2.865907
std = 0.008212
RMS = 2.865918
***Row Num = 676
Min = 3.145600
Max = 3.161300
Mean = 3.152264
std = 0.002859
RMS = 3.152265
______
***Row Num = 677
Min = 7.315000
Max = 7.343200
Mean = 7.336768
std = 0.007658
RMS = 7.336772
_____
***Row Num = 678
Min = 6.791700
Max = 8.443100
Mean = 7.719120
std = 0.286934
RMS = 7.724330
***Row Num = 679
```

```
Min = 5.157700

Max = 6.927300

Mean = 6.805623

std = 0.341622

RMS = 6.813997
```

```
***Row Num = 680
Min = 0.052102
Max = 9.810500
Mean = 9.043768
std = 1.418846
RMS = 9.151891
```

>>