```
>> Untitled4
Action HEARING.csv
______
***Row Num = 1
Min = 0.870120
Max = 0.956050
Mean = 0.912343
std = 0.017198
RMS = 0.912501
_____
***Row Num = 2
Min = -0.415040
Max = -0.331050
Mean = -0.375155
std = 0.017154
RMS = 0.375538
______
***Row Num = 3
Min = 0.111820
Max = 0.181150
Mean = 0.136762
std = 0.015266
RMS = 0.137592
______
***Row Num = 4
Min = -1.097700
Max = 0.087891
Mean = -0.560204
std = 0.258346
RMS = 0.615674
***Row Num = 5
Min = 0.445310
Max = 1.202100
Mean = 0.720769
std = 0.182059
RMS = 0.742900
-----
***Row Num = 6
Min = -0.021973
Max = 0.574710
Mean = 0.271695
std = 0.164281
RMS = 0.316532
_____
***Row Num = 7
Min = -6.000000
Max = 7.000000
Mean = -1.068182
std = 2.106443
```

```
RMS = 2.340357
***Row Num = 8
Min = -5.000000
Max = 1.000000
Mean = -1.068182
std = 1.264869
RMS = 1.644550
______
***Row Num = 9
Min = -3.000000
Max = 1.000000
Mean = -1.068182
std = 1.020664
RMS = 1.469385
_____
***Row Num = 10
Min = -4.000000
Max = 3.000000
Mean = -1.045455
std = 1.180354
RMS = 1.566699
***Row Num = 11
Min = -6.000000
Max = 1.000000
Mean = -1.363636
std = 1.399184
RMS = 1.942351
***Row Num = 12
Min = -3.000000
Max = 1.000000
Mean = -1.136364
std = 0.954571
RMS = 1.477098
_____
***Row Num = 13
Min = -3.000000
Max = 2.000000
Mean = -0.727273
std = 1.207797
RMS = 1.398051
***Row Num = 14
Min = -3.000000
Max = 2.000000
Mean = -0.863636
std = 1.192826
RMS = 1.461630
```

```
_____
***Row Num = 15
Min = -80.000000
Max = 39.000000
Mean = -0.590909
std = 16.676565
RMS = 16.496556
-----
***Row Num = 16
Min = -29.000000
Max = 27.000000
Mean = -2.090909
std = 11.621588
RMS = 11.677484
***Row Num = 17
Min = -16.000000
Max = 18.000000
Mean = -0.750000
std = 6.531231
RMS = 6.500000
______
***Row Num = 18
Min = -15.000000
Max = 19.000000
Mean = -0.136364
std = 6.067799
RMS = 6.000000
_____
***Row Num = 19
Min = -32.000000
Max = 34.000000
Mean = 0.022727
std = 14.743526
RMS = 14.575041
______
***Row Num = 20
Min = -72.000000
Max = 83.000000
Mean = -2.772727
std = 20.896048
RMS = 20.842483
______
***Row Num = 21
Min = -18.000000
Max = 10.000000
Mean = -1.568182
std = 6.184744
RMS = 6.311966
```

```
***Row Num = 22
Min = -56.000000
Max = 48.000000
Mean = -3.727273
std = 23.848713
RMS = 23.868960
***Row Num = 23
Min = -23.375000
Max = 17.500000
Mean = 0.848057
std = 9.873977
RMS = 9.797899
______
***Row Num = 24
Min = -23.375000
Max = 17.500000
Mean = 0.848057
std = 9.873977
RMS = 9.797899
_____
***Row Num = 25
Min = -23.375000
Max = 17.500000
Mean = 0.848057
std = 9.873977
RMS = 9.797899
***Row Num = 26
Min = -100.310000
Max = 88.188000
Mean = 2.581057
std = 41.841316
RMS = 41.443565
______
***Row Num = 27
Min = -100.310000
Max = 88.188000
Mean = 2.581057
std = 41.841316
RMS = 41.443565
_____
***Row Num = 28
Min = -100.310000
Max = 88.188000
Mean = 2.581057
std = 41.841316
RMS = 41.443565
***Row Num = 29
```

```
Min = 3.015100
Max = 3.107000
Mean = 3.058561
std = 0.027031
RMS = 3.058678
_____
***Row Num = 30
Min = 3.128100
Max = 3.183700
Mean = 3.151214
std = 0.013595
RMS = 3.151242
***Row Num = 31
Min = 2.129900
Max = 2.202100
Mean = 2.166155
std = 0.016407
RMS = 2.166215
_____
***Row Num = 32
Min = 6.381300
Max = 7.236600
Mean = 6.990659
std = 0.207912
RMS = 6.993680
***Row Num = 33
Min = 4.477200
Max = 6.443900
Mean = 5.999720
std = 0.394603
RMS = 6.012389
_____
***Row Num = 34
Min = 3.543200
Max = 4.378900
Mean = 4.071393
std = 0.212373
RMS = 4.076803
______
***Row Num = 35
Min = 0.886230
Max = 0.952640
Mean = 0.917326
std = 0.012148
RMS = 0.917404
***Row Num = 36
Min = -0.423830
```

```
Max = -0.315430
Mean = -0.370195
std = 0.022149
RMS = 0.370842
______
***Row Num = 37
Min = 0.104490
Max = 0.166990
Mean = 0.130648
std = 0.012332
RMS = 0.131216
_____
***Row Num = 38
Min = -1.003900
Max = -0.262700
Mean = -0.627285
std = 0.194688
RMS = 0.656147
_____
***Row Num = 39
Min = 0.492680
Max = 1.168000
Mean = 0.725030
std = 0.160011
RMS = 0.742085
______
***Row Num = 40
Min = 0.064941
Max = 0.548830
Mean = 0.264671
std = 0.134348
RMS = 0.296125
______
***Row Num = 41
Min = -9.000000
Max = 10.000000
Mean = -0.227273
std = 3.041294
RMS = 3.015113
-----
***Row Num = 42
Min = -6.000000
Max = 3.000000
Mean = -1.181818
std = 1.956180
RMS = 2.266355
-----
***Row Num = 43
Min = -3.000000
Max = 1.000000
```

```
Mean = -0.931818
std = 0.949853
RMS = 1.322876
______
***Row Num = 44
Min = -4.000000
Max = 2.000000
Mean = -0.840909
std = 1.256484
RMS = 1.500000
***Row Num = 45
Min = -4.000000
Max = 3.000000
Mean = -1.113636
std = 1.401260
RMS = 1.777383
______
***Row Num = 46
Min = -3.000000
Max = 1.000000
Mean = -0.931818
std = 0.846270
RMS = 1.252271
_____
***Row Num = 47
Min = -4.000000
Max = 2.000000
Mean = -1.068182
std = 1.043200
RMS = 1.484771
***Row Num = 48
Min = -4.000000
Max = 1.000000
Mean = -0.840909
std = 1.119451
RMS = 1.389899
______
***Row Num = 49
Min = -45.000000
Max = 36.000000
Mean = -0.045455
std = 19.120128
RMS = 18.901659
***Row Num = 50
Min = -46.000000
Max = 26.000000
Mean = -1.590909
```

```
std = 12.406522
RMS = 12.367479
_____
***Row Num = 51
Min = -18.000000
Max = 20.000000
Mean = -1.181818
std = 6.314519
RMS = 6.353238
_____
***Row Num = 52
Min = -12.000000
Max = 13.000000
Mean = -1.000000
std = 3.905869
RMS = 3.988620
______
***Row Num = 53
Min = -31.000000
Max = 36.000000
Mean = -1.568182
std = 11.781731
RMS = 11.752176
______
***Row Num = 54
Min = -89.000000
Max = 45.000000
Mean = -0.386364
std = 24.163413
RMS = 23.890375
***Row Num = 55
Min = -17.000000
Max = 23.000000
Mean = -0.113636
std = 8.181704
RMS = 8.088994
_____
***Row Num = 56
Min = -43.000000
Max = 43.000000
Mean = 1.477273
std = 15.881082
RMS = 15.768928
_____
***Row Num = 57
Min = -15.375000
Max = 16.438000
Mean = 1.142057
std = 6.615481
```

```
RMS = 6.638843
______
***Row Num = 58
Min = -15.375000
Max = 16.438000
Mean = 1.142057
std = 6.615481
RMS = 6.638843
______
***Row Num = 59
Min = -15.375000
Max = 16.438000
Mean = 1.142057
std = 6.615481
RMS = 6.638843
_____
***Row Num = 60
Min = -67.313000
Max = 90.188000
Mean = 3.815341
std = 32.929397
RMS = 32.775872
_____
***Row Num = 61
Min = -67.313000
Max = 90.188000
Mean = 3.815341
std = 32.929397
RMS = 32.775872
***Row Num = 62
Min = -67.313000
Max = 90.188000
Mean = 3.815341
std = 32.929397
RMS = 32.775872
_____
***Row Num = 63
Min = 3.016600
Max = 3.102300
Mean = 3.053720
std = 0.020107
RMS = 3.053785
***Row Num = 64
Min = 3.117200
Max = 3.164800
Mean = 3.144370
std = 0.009664
RMS = 3.144385
```

```
_____
***Row Num = 65
Min = 2.179200
Max = 2.250000
Mean = 2.218964
std = 0.018438
RMS = 2.219038
_____
***Row Num = 66
Min = 6.744500
Max = 7.165500
Mean = 6.973216
std = 0.104679
RMS = 6.973984
***Row Num = 67
Min = 5.674900
Max = 6.430000
Mean = 6.110580
std = 0.206045
RMS = 6.113974
______
***Row Num = 68
Min = 3.831100
Max = 4.325000
Mean = 4.055820
std = 0.152404
RMS = 4.058618
_____
***Row Num = 69
Min = 0.850590
Max = 0.990720
Mean = 0.920555
std = 0.024213
RMS = 0.920866
______
***Row Num = 70
Min = -0.461430
Max = -0.298830
Mean = -0.364557
std = 0.039168
RMS = 0.366608
_____
***Row Num = 71
Min = 0.076660
Max = 0.167970
Mean = 0.119651
std = 0.021408
RMS = 0.121508
```

```
***Row Num = 72
Min = -1.139600
Max = 1.062500
Mean = -0.500133
std = 0.440918
RMS = 0.663417
***Row Num = 73
Min = 0.420410
Max = 1.314500
Mean = 0.734875
std = 0.214844
RMS = 0.764951
______
***Row Num = 74
Min = 0.049316
Max = 0.693850
Mean = 0.313255
std = 0.195208
RMS = 0.367925
______
***Row Num = 75
Min = -5.000000
Max = 6.000000
Mean = -0.840909
std = 2.675845
RMS = 2.775706
***Row Num = 76
Min = -9.000000
Max = 3.000000
Mean = -0.977273
std = 2.225525
RMS = 2.407375
______
***Row Num = 77
Min = -7.000000
Max = 1.000000
Mean = -1.613636
std = 1.528275
RMS = 2.210512
______
***Row Num = 78
Min = -4.000000
Max = 2.000000
Mean = -1.068182
std = 1.301122
RMS = 1.671961
***Row Num = 79
```

```
Min = -6.000000
Max = 1.000000
Mean = -1.227273
std = 1.273407
RMS = 1.758098
_____
***Row Num = 80
Min = -4.000000
Max = 0.000000
Mean = -1.136364
std = 0.878448
RMS = 1.430194
***Row Num = 81
Min = -4.000000
Max = 2.000000
Mean = -0.681818
std = 1.115905
RMS = 1.296849
_____
***Row Num = 82
Min = -4.000000
Max = 1.000000
Mean = -0.931818
std = 1.149271
RMS = 1.469385
***Row Num = 83
Min = -47.000000
Max = 35.000000
Mean = 0.181818
std = 18.199505
RMS = 17.992423
***Row Num = 84
Min = -20.000000
Max = 53.000000
Mean = -0.386364
std = 13.556455
RMS = 13.407088
______
***Row Num = 85
Min = -103.000000
Max = 16.000000
Mean = -3.295455
std = 17.115992
RMS = 17.238303
***Row Num = 86
Min = -11.000000
```

```
Max = 8.000000
Mean = -1.340909
std = 4.518403
RMS = 4.663690
______
***Row Num = 87
Min = -26.000000
Max = 52.000000
Mean = -1.113636
std = 13.265125
RMS = 13.160720
***Row Num = 88
Min = -72.000000
Max = 47.000000
Mean = -5.295455
std = 20.765109
RMS = 21.199807
_____
***Row Num = 89
Min = -34.000000
Max = 20.000000
Mean = -1.204545
std = 11.261334
RMS = 11.197605
______
***Row Num = 90
Min = -69.000000
Max = 76.000000
Mean = -2.386364
std = 26.752280
RMS = 26.553976
______
***Row Num = 91
Min = -23.125000
Max = 26.938000
Mean = -0.038341
std = 10.006226
RMS = 9.891940
-----
***Row Num = 92
Min = -23.125000
Max = 26.938000
Mean = -0.038341
std = 10.006226
RMS = 9.891940
***Row Num = 93
Min = -23.125000
Max = 26.938000
```

```
Mean = -0.038341
std = 10.006226
RMS = 9.891940
______
***Row Num = 94
Min = -93.688000
Max = 115.560000
Mean = 10.887784
std = 43.796270
RMS = 44.643741
***Row Num = 95
Min = -93.688000
Max = 115.560000
Mean = 10.887784
std = 43.796270
RMS = 44.643741
______
***Row Num = 96
Min = -93.688000
Max = 115.560000
Mean = 10.887784
std = 43.796270
RMS = 44.643741
_____
***Row Num = 97
Min = 2.972100
Max = 3.078200
Mean = 3.017525
std = 0.035381
RMS = 3.017728
_____
***Row Num = 98
Min = 3.097800
Max = 3.160100
Mean = 3.125502
std = 0.014410
RMS = 3.125535
______
***Row Num = 99
Min = 2.210300
Max = 2.356300
Mean = 2.279866
std = 0.029503
RMS = 2.280052
***Row Num = 100
Min = 6.347400
Max = 7.228000
Mean = 6.913530
```

```
std = 0.220045
RMS = 6.916951
______
***Row Num = 101
Min = 3.389400
Max = 6.511900
Mean = 5.912098
std = 0.670983
RMS = 5.949192
_____
***Row Num = 102
Min = 3.272200
Max = 4.323500
Mean = 3.904130
std = 0.256978
RMS = 3.912386
***Row Num = 103
Min = 0.856450
Max = 0.949710
Mean = 0.918979
std = 0.019044
RMS = 0.919172
______
***Row Num = 104
Min = -0.461910
Max = -0.312990
Mean = -0.371261
std = 0.035100
RMS = 0.372879
***Row Num = 105
Min = 0.093262
Max = 0.166020
Mean = 0.120006
std = 0.016693
RMS = 0.121135
_____
***Row Num = 106
Min = -0.967770
Max = 0.256350
Mean = -0.562245
std = 0.261269
RMS = 0.618732
_____
***Row Num = 107
Min = 0.450200
Max = 1.163600
Mean = 0.720361
std = 0.170190
```

```
RMS = 0.739747
______
***Row Num = 108
Min = 0.051270
Max = 0.632320
Mean = 0.303268
std = 0.148999
RMS = 0.337147
______
***Row Num = 109
Min = -7.000000
Max = 6.000000
Mean = -1.795455
std = 3.129600
RMS = 3.577073
_____
***Row Num = 110
Min = -7.000000
Max = 3.000000
Mean = -1.840909
std = 1.867011
RMS = 2.606809
______
***Row Num = 111
Min = -5.000000
Max = 5.000000
Mean = -1.363636
std = 2.024167
RMS = 2.421495
***Row Num = 112
Min = -4.000000
Max = 3.000000
Mean = -1.000000
std = 1.397672
RMS = 1.705606
_____
***Row Num = 113
Min = -6.000000
Max = 1.000000
Mean = -1.227273
std = 1.444535
RMS = 1.882938
***Row Num = 114
Min = -3.000000
Max = 1.000000
Mean = -0.954545
std = 0.963389
RMS = 1.348400
```

_____ ***Row Num = 115Min = -3.000000Max = 1.000000Mean = -0.840909std = 1.160256RMS = 1.422226_____ ***Row Num = 116Min = -4.000000Max = 1.000000Mean = -1.090909std = 1.177664RMS = 1.595448***Row Num = 117Min = -91.000000Max = 38.000000Mean = 1.727273std = 19.721743RMS = 19.572708______ ***Row Num = 118Min = -24.000000Max = 43.000000Mean = 0.590909std = 11.483696RMS = 11.367817_____ ***Row Num = 119Min = -10.000000Max = 34.000000Mean = 1.522727std = 7.023180RMS = 7.107934***Row Num = 120Min = -8.000000Max = 11.000000Mean = 0.136364std = 3.788544RMS = 3.747727______ ***Row Num = 121Min = -33.000000Max = 26.000000Mean = -0.090909std = 11.118428RMS = 10.991732

```
***Row Num = 122
Min = -53.000000
Max = 47.000000
Mean = -4.000000
std = 20.354989
RMS = 20.516069
***Row Num = 123
Min = -16.000000
Max = 20.000000
Mean = -0.590909
std = 7.863126
RMS = 7.795686
______
***Row Num = 124
Min = -53.000000
Max = 31.000000
Mean = -1.500000
std = 14.149534
RMS = 14.068017
_____
***Row Num = 125
Min = -17.313000
Max = 19.500000
Mean = 0.009943
std = 7.789684
RMS = 7.700662
***Row Num = 126
Min = -17.313000
Max = 19.500000
Mean = 0.009943
std = 7.789684
RMS = 7.700662
______
***Row Num = 127
Min = -17.313000
Max = 19.500000
Mean = 0.009943
std = 7.789684
RMS = 7.700662
_____
***Row Num = 128
Min = -92.375000
Max = 76.688000
Mean = 7.048318
std = 37.134798
RMS = 37.380894
***Row Num = 129
```

```
Min = -92.375000
Max = 76.688000
Mean = 7.048318
std = 37.134798
RMS = 37.380894
***Row Num = 130
Min = -92.375000
Max = 76.688000
Mean = 7.048318
std = 37.134798
RMS = 37.380894
***Row Num = 131
Min = 2.984200
Max = 3.040600
Mean = 3.008966
std = 0.017267
RMS = 3.009014
_____
***Row Num = 132
Min = 3.116500
Max = 3.156000
Mean = 3.134143
std = 0.009839
RMS = 3.134158
______
***Row Num = 133
Min = 2.274300
Max = 2.352100
Mean = 2.306105
std = 0.017910
RMS = 2.306173
_____
***Row Num = 134
Min = 6.341800
Max = 7.190900
Mean = 6.912393
std = 0.185900
RMS = 6.914836
______
***Row Num = 135
Min = 4.463200
Max = 6.418400
Mean = 6.013275
std = 0.375570
RMS = 6.024726
***Row Num = 136
Min = 3.499400
```

```
Max = 4.290300
Mean = 3.926005
std = 0.193782
RMS = 3.930675
______
***Row Num = 137
Min = 0.861820
Max = 0.964360
Mean = 0.922319
std = 0.018575
RMS = 0.922502
_____
***Row Num = 138
Min = -0.446290
Max = -0.303220
Mean = -0.367964
std = 0.032136
RMS = 0.369333
_____
***Row Num = 139
Min = 0.078125
Max = 0.145020
Mean = 0.110651
std = 0.017526
RMS = 0.111999
______
***Row Num = 140
Min = -1.044400
Max = 0.747560
Mean = -0.530750
std = 0.323142
RMS = 0.619470
______
***Row Num = 141
Min = 0.536620
Max = 1.063000
Mean = 0.686135
std = 0.135889
RMS = 0.699162
-----
***Row Num = 142
Min = 0.138670
Max = 0.713870
Mean = 0.366167
std = 0.157472
RMS = 0.397885
_____
***Row Num = 143
Min = -6.000000
Max = 8.000000
```

```
Mean = -0.704545
std = 2.937960
RMS = 2.988615
______
***Row Num = 144
Min = -6.000000
Max = 8.000000
Mean = -0.477273
std = 2.628012
RMS = 2.641453
***Row Num = 145
Min = -5.000000
Max = 3.000000
Mean = -0.840909
std = 2.079168
RMS = 2.220770
______
***Row Num = 146
Min = -4.000000
Max = 1.000000
Mean = -1.068182
std = 1.108062
RMS = 1.530003
***Row Num = 147
Min = -4.000000
Max = 2.000000
Mean = -0.886364
std = 1.185492
RMS = 1.469385
_____
***Row Num = 148
Min = -3.000000
Max = 1.000000
Mean = -0.977273
std = 0.999736
RMS = 1.389899
______
***Row Num = 149
Min = -4.000000
Max = 1.000000
Mean = -0.818182
std = 1.298886
RMS = 1.522558
***Row Num = 150
Min = -3.000000
Max = 1.000000
Mean = -0.977273
```

```
std = 1.109968
RMS = 1.469385
_____
***Row Num = 151
Min = -39.000000
Max = 33.000000
Mean = 0.295455
std = 14.540368
RMS = 14.377223
_____
***Row Num = 152
Min = -17.000000
Max = 19.000000
Mean = 0.068182
std = 8.320325
RMS = 8.225515
***Row Num = 153
Min = -13.000000
Max = 21.000000
Mean = -0.227273
std = 6.904207
RMS = 6.829082
______
***Row Num = 154
Min = -10.000000
Max = 11.000000
Mean = -0.295455
std = 4.095258
RMS = 4.059221
***Row Num = 155
Min = -22.000000
Max = 25.000000
Mean = 1.386364
std = 10.459703
RMS = 10.432685
***Row Num = 156
Min = -31.000000
Max = 24.000000
Mean = 0.227273
std = 11.790543
RMS = 11.658005
_____
***Row Num = 157
Min = -17.000000
Max = 17.000000
Mean = 0.454545
std = 6.814671
```

```
RMS = 6.752104
______
***Row Num = 158
Min = -27.000000
Max = 26.000000
Mean = -0.886364
std = 11.558176
RMS = 11.460406
______
***Row Num = 159
Min = -13.688000
Max = 20.938000
Mean = 0.669057
std = 8.439735
RMS = 8.370061
_____
***Row Num = 160
Min = -13.688000
Max = 20.938000
Mean = 0.669057
std = 8.439735
RMS = 8.370061
_____
***Row Num = 161
Min = -13.688000
Max = 20.938000
Mean = 0.669057
std = 8.439735
RMS = 8.370061
***Row Num = 162
Min = -76.938000
Max = 76.063000
Mean = 4.554045
std = 36.341695
RMS = 36.213835
_____
***Row Num = 163
Min = -76.938000
Max = 76.063000
Mean = 4.554045
std = 36.341695
RMS = 36.213835
***Row Num = 164
Min = -76.938000
Max = 76.063000
Mean = 4.554045
std = 36.341695
RMS = 36.213835
```

```
_____
***Row Num = 165
Min = 2.943400
Max = 3.004100
Mean = 2.969625
std = 0.016046
RMS = 2.969667
_____
***Row Num = 166
Min = 3.108300
Max = 3.143700
Mean = 3.125423
std = 0.006989
RMS = 3.125430
***Row Num = 167
Min = 2.306000
Max = 2.389000
Mean = 2.339875
std = 0.022375
RMS = 2.339980
______
***Row Num = 168
Min = 6.348800
Max = 7.025300
Mean = 6.762166
std = 0.189677
RMS = 6.764765
_____
***Row Num = 169
Min = 3.878900
Max = 6.407600
Mean = 5.944743
std = 0.541752
RMS = 5.968819
***Row Num = 170
Min = 3.178900
Max = 4.081300
Mean = 3.701093
std = 0.226796
RMS = 3.707878
_____
***Row Num = 171
Min = 0.843750
Max = 1.014600
Mean = 0.924126
std = 0.025484
RMS = 0.924470
```

```
***Row Num = 172
Min = -0.473140
Max = -0.292480
Mean = -0.363847
std = 0.038930
RMS = 0.365877
***Row Num = 173
Min = 0.066406
Max = 0.158200
Mean = 0.108188
std = 0.022750
RMS = 0.110500
______
***Row Num = 174
Min = -1.044400
Max = 1.180200
Mean = -0.217074
std = 0.646929
RMS = 0.675371
_____
***Row Num = 175
Min = 0.286130
Max = 1.223100
Mean = 0.657347
std = 0.237541
RMS = 0.698032
***Row Num = 176
Min = 0.010254
Max = 0.823730
Mean = 0.400257
std = 0.220806
RMS = 0.455909
______
***Row Num = 177
Min = -4.000000
Max = 4.000000
Mean = -1.068182
std = 1.648082
RMS = 1.948193
_____
***Row Num = 178
Min = -6.000000
Max = 4.000000
Mean = -0.613636
std = 1.955504
RMS = 2.028210
***Row Num = 179
```

```
Min = -6.000000
Max = 5.000000
Mean = -1.090909
std = 2.485476
RMS = 2.688359
_____
***Row Num = 180
Min = -4.000000
Max = 1.000000
Mean = -1.000000
std = 1.078328
RMS = 1.461630
***Row Num = 181
Min = -4.000000
Max = 1.000000
Mean = -1.045455
std = 1.199894
RMS = 1.581139
_____
***Row Num = 182
Min = -3.000000
Max = 1.000000
Mean = -0.954545
std = 0.776233
RMS = 1.224745
***Row Num = 183
Min = -4.000000
Max = 2.000000
Mean = -0.909091
std = 1.157748
RMS = 1.461630
_____
***Row Num = 184
Min = -4.000000
Max = 1.000000
Mean = -1.090909
std = 1.116852
RMS = 1.552125
______
***Row Num = 185
Min = -62.000000
Max = 30.000000
Mean = -3.340909
std = 20.051032
RMS = 20.101447
***Row Num = 186
Min = -46.000000
```

```
Max = 20.000000
Mean = -2.727273
std = 12.505559
RMS = 12.659887
______
***Row Num = 187
Min = -31.000000
Max = 30.000000
Mean = -0.522727
std = 9.585572
RMS = 9.490426
***Row Num = 188
Min = -25.000000
Max = 10.000000
Mean = -0.886364
std = 6.031761
RMS = 6.028342
_____
***Row Num = 189
Min = -25.000000
Max = 20.000000
Mean = 1.909091
std = 8.424268
RMS = 8.544004
______
***Row Num = 190
Min = -70.000000
Max = 58.000000
Mean = -1.386364
std = 17.947230
RMS = 17.796195
______
***Row Num = 191
Min = -23.000000
Max = 23.000000
Mean = 0.704545
std = 8.828020
RMS = 8.755518
-----
***Row Num = 192
Min = -27.000000
Max = 47.000000
Mean = -0.681818
std = 16.141486
RMS = 15.971566
***Row Num = 193
Min = -16.438000
Max = 25.000000
```

```
Mean = -0.524136
std = 9.100109
RMS = 9.011360
______
***Row Num = 194
Min = -16.438000
Max = 25.000000
Mean = -0.524136
std = 9.100109
RMS = 9.011360
***Row Num = 195
Min = -16.438000
Max = 25.000000
Mean = -0.524136
std = 9.100109
RMS = 9.011360
______
***Row Num = 196
Min = -127.750000
Max = 100.690000
Mean = 5.159159
std = 41.502542
RMS = 41.351313
_____
***Row Num = 197
Min = -127.750000
Max = 100.690000
Mean = 5.159159
std = 41.502542
RMS = 41.351313
_____
***Row Num = 198
Min = -127.750000
Max = 100.690000
Mean = 5.159159
std = 41.502542
RMS = 41.351313
______
***Row Num = 199
Min = 2.915500
Max = 2.996500
Mean = 2.957539
std = 0.023250
RMS = 2.957628
***Row Num = 200
Min = 3.100800
Max = 3.151300
Mean = 3.118255
```

```
std = 0.012308
RMS = 3.118278
______
***Row Num = 201
Min = 2.283300
Max = 2.393100
Mean = 2.344741
std = 0.029212
RMS = 2.344919
_____
***Row Num = 202
Min = 6.242400
Max = 6.990000
Mean = 6.653905
std = 0.175388
RMS = 6.656163
***Row Num = 203
Min = 3.056200
Max = 6.425500
Mean = 5.365134
std = 1.137141
RMS = 5.481639
______
***Row Num = 204
Min = 2.765700
Max = 3.955300
Mean = 3.407732
std = 0.332592
RMS = 3.423557
***Row Num = 205
Min = 0.854000
Max = 0.946780
Mean = 0.900713
std = 0.016312
RMS = 0.900857
***Row Num = 206
Min = -0.467770
Max = -0.324220
Mean = -0.394919
std = 0.028461
RMS = 0.395920
______
***Row Num = 207
Min = 0.130370
Max = 0.219730
Mean = 0.172219
std = 0.019589
```

```
RMS = 0.173305
***Row Num = 208
Min = -1.017100
Max = -0.279790
Mean = -0.663786
std = 0.174548
RMS = 0.685847
______
***Row Num = 209
Min = 0.535160
Max = 1.082500
Mean = 0.710937
std = 0.135003
RMS = 0.723355
_____
***Row Num = 210
Min = 0.078613
Max = 0.689940
Mean = 0.319968
std = 0.139692
RMS = 0.348497
______
***Row Num = 211
Min = -6.000000
Max = 4.000000
Mean = -1.068182
std = 1.945749
RMS = 2.200207
***Row Num = 212
Min = -24.000000
Max = 13.000000
Mean = -1.727273
std = 5.796405
RMS = 5.984829
_____
***Row Num = 213
Min = -6.000000
Max = 4.000000
Mean = -1.068182
std = 2.546294
RMS = 2.734460
***Row Num = 214
Min = -3.000000
Max = 1.000000
Mean = -1.022727
std = 1.067242
RMS = 1.469385
```

_____ ***Row Num = 215Min = -3.000000Max = 1.000000Mean = -1.113636std = 0.894841RMS = 1.422226_____ ***Row Num = 216Min = -3.000000Max = 1.000000Mean = -0.795455std = 0.904242RMS = 1.196586***Row Num = 217Min = -4.000000Max = 2.000000Mean = -0.818182std = 1.529139RMS = 1.718879______ ***Row Num = 218Min = -4.000000Max = 1.000000Mean = -1.022727std = 1.171138RMS = 1.544786_____ ***Row Num = 219Min = -74.000000Max = 41.000000Mean = -3.772727std = 25.021724RMS = 25.021809***Row Num = 220Min = -22.000000Max = 32.000000Mean = -2.045455std = 10.113207RMS = 10.204723______ ***Row Num = 221Min = -10.000000Max = 16.000000Mean = -1.340909std = 5.619498RMS = 5.714813

```
***Row Num = 222
Min = -12.000000
Max = 11.000000
Mean = -1.227273
std = 4.376808
RMS = 4.497474
***Row Num = 223
Min = -23.000000
Max = 23.000000
Mean = -1.681818
std = 9.830595
RMS = 9.862694
______
***Row Num = 224
Min = -56.000000
Max = 35.000000
Mean = -2.250000
std = 21.152959
RMS = 21.031902
_____
***Row Num = 225
Min = -15.000000
Max = 25.000000
Mean = 1.250000
std = 8.892445
RMS = 8.879240
***Row Num = 226
Min = -23.000000
Max = 34.000000
Mean = -0.500000
std = 14.427848
RMS = 14.271714
______
***Row Num = 227
Min = -17.000000
Max = 17.188000
Mean = -0.767045
std = 7.521978
RMS = 7.475467
_____
***Row Num = 228
Min = -17.000000
Max = 17.188000
Mean = -0.767045
std = 7.521978
RMS = 7.475467
***Row Num = 229
```

```
Min = -17.000000
Max = 17.188000
Mean = -0.767045
std = 7.521978
RMS = 7.475467
_____
***Row Num = 230
Min = -67.375000
Max = 90.125000
Mean = 3.274170
std = 31.789365
RMS = 31.596148
***Row Num = 231
Min = -67.375000
Max = 90.125000
Mean = 3.274170
std = 31.789365
RMS = 31.596148
_____
***Row Num = 232
Min = -67.375000
Max = 90.125000
Mean = 3.274170
std = 31.789365
RMS = 31.596148
***Row Num = 233
Min = 3.136600
Max = 3.172500
Mean = 3.152402
std = 0.008369
RMS = 3.152413
_____
***Row Num = 234
Min = 3.191800
Max = 3.229000
Mean = 3.208170
std = 0.009481
RMS = 3.208184
______
***Row Num = 235
Min = 1.543300
Max = 1.631600
Mean = 1.590459
std = 0.020388
RMS = 1.590587
***Row Num = 236
Min = 6.699100
```

```
Max = 7.011200
Mean = 6.827389
std = 0.069714
RMS = 6.827736
______
***Row Num = 237
Min = 5.711300
Max = 6.414600
Mean = 6.123257
std = 0.194278
RMS = 6.126268
***Row Num = 238
Min = 3.171600
Max = 3.605400
Mean = 3.369959
std = 0.128428
RMS = 3.372350
______
***Row Num = 239
Min = 0.852540
Max = 0.966310
Mean = 0.914262
std = 0.023381
RMS = 0.914554
______
***Row Num = 240
Min = -0.482420
Max = -0.283200
Mean = -0.378796
std = 0.045449
RMS = 0.381451
______
***Row Num = 241
Min = 0.089355
Max = 0.174320
Mean = 0.138795
std = 0.022147
RMS = 0.140511
-----
***Row Num = 242
Min = -1.066900
Max = 1.282700
Mean = -0.232045
std = 0.660374
RMS = 0.692841
_____
***Row Num = 243
Min = 0.268550
Max = 1.099600
```

```
Mean = 0.669033
std = 0.248274
RMS = 0.712632
______
***Row Num = 244
Min = -0.116210
Max = 0.758300
Mean = 0.335471
std = 0.206669
RMS = 0.392788
***Row Num = 245
Min = -7.000000
Max = 8.000000
Mean = -0.250000
std = 3.341946
RMS = 3.313197
______
***Row Num = 246
Min = -7.000000
Max = 8.000000
Mean = -0.863636
std = 2.783597
RMS = 2.884126
***Row Num = 247
Min = -10.000000
Max = 7.000000
Mean = -1.477273
std = 3.084007
RMS = 3.387812
_____
***Row Num = 248
Min = -4.000000
Max = 1.000000
Mean = -1.159091
std = 1.429639
RMS = 1.827815
______
***Row Num = 249
Min = -3.000000
Max = 2.000000
Mean = -1.068182
std = 1.149271
RMS = 1.559429
***Row Num = 250
Min = -4.000000
Max = 1.000000
Mean = -0.909091
```

```
std = 1.177664
RMS = 1.477098
_____
***Row Num = 251
Min = -4.000000
Max = 3.000000
Mean = -0.795455
std = 1.607823
RMS = 1.777383
_____
***Row Num = 252
Min = -4.000000
Max = 1.000000
Mean = -0.954545
std = 1.346046
RMS = 1.637626
***Row Num = 253
Min = -95.000000
Max = 63.000000
Mean = -4.568182
std = 30.518311
RMS = 30.513410
______
***Row Num = 254
Min = -24.000000
Max = 54.000000
Mean = 3.863636
std = 15.596050
RMS = 15.894539
***Row Num = 255
Min = -14.000000
Max = 123.000000
Mean = 5.568182
std = 23.028191
RMS = 23.436083
***Row Num = 256
Min = -24.000000
Max = 24.000000
Mean = -1.659091
std = 7.976545
RMS = 8.058028
_____
***Row Num = 257
Min = -39.000000
Max = 34.000000
Mean = -0.340909
std = 12.077161
```

```
RMS = 11.943998
***Row Num = 258
Min = -61.000000
Max = 27.000000
Mean = -1.181818
std = 14.159018
RMS = 14.046999
______
***Row Num = 259
Min = -32.000000
Max = 29.000000
Mean = -0.250000
std = 12.757351
RMS = 12.614025
_____
***Row Num = 260
Min = -77.000000
Max = 51.000000
Mean = -4.340909
std = 21.283188
RMS = 21.483080
_____
***Row Num = 261
Min = -21.438000
Max = 22.063000
Mean = -0.525580
std = 10.149895
RMS = 10.047648
***Row Num = 262
Min = -21.438000
Max = 22.063000
Mean = -0.525580
std = 10.149895
RMS = 10.047648
______
***Row Num = 263
Min = -21.438000
Max = 22.063000
Mean = -0.525580
std = 10.149895
RMS = 10.047648
***Row Num = 264
Min = -86.625000
Max = 113.560000
Mean = 9.264170
std = 41.156077
RMS = 41.727109
```

```
_____
***Row Num = 265
Min = -86.625000
Max = 113.560000
Mean = 9.264170
std = 41.156077
RMS = 41.727109
_____
***Row Num = 266
Min = -86.625000
Max = 113.560000
Mean = 9.264170
std = 41.156077
RMS = 41.727109
***Row Num = 267
Min = 3.010700
Max = 3.081100
Mean = 3.053655
std = 0.021230
RMS = 3.053727
______
***Row Num = 268
Min = 3.144000
Max = 3.183600
Mean = 3.160791
std = 0.012271
RMS = 3.160814
_____
***Row Num = 269
Min = 1.511100
Max = 1.622300
Mean = 1.575209
std = 0.033950
RMS = 1.575567
***Row Num = 270
Min = 6.224800
Max = 7.055400
Mean = 6.793661
std = 0.169071
RMS = 6.795717
______
***Row Num = 271
Min = 2.997700
Max = 6.336200
Mean = 5.413527
std = 1.160059
RMS = 5.533663
```

```
***Row Num = 272
Min = 2.225600
Max = 3.533900
Mean = 3.113702
std = 0.408807
RMS = 3.139820
***Row Num = 273
Min = 0.851070
Max = 0.948730
Mean = 0.909845
std = 0.017950
RMS = 0.910018
______
***Row Num = 274
Min = -0.471190
Max = -0.334470
Mean = -0.391801
std = 0.030853
RMS = 0.392986
_____
***Row Num = 275
Min = 0.095215
Max = 0.163570
Mean = 0.128063
std = 0.015164
RMS = 0.128937
***Row Num = 276
Min = -1.039600
Max = 0.376950
Mean = -0.578139
std = 0.268202
RMS = 0.636036
______
***Row Num = 277
Min = 0.538090
Max = 1.009300
Mean = 0.685570
std = 0.126876
RMS = 0.696949
_____
***Row Num = 278
Min = 0.063965
Max = 0.678710
Mean = 0.353948
std = 0.144156
RMS = 0.381560
***Row Num = 279
```

```
Min = -21.000000
Max = 10.000000
Mean = -1.704545
std = 5.998370
RMS = 6.169942
_____
***Row Num = 280
Min = -17.000000
Max = 10.000000
Mean = -0.977273
std = 5.087553
RMS = 5.123475
***Row Num = 281
Min = -6.000000
Max = 5.000000
Mean = -1.613636
std = 2.264138
RMS = 2.759282
_____
***Row Num = 282
Min = -3.000000
Max = 2.000000
Mean = -0.909091
std = 1.116852
RMS = 1.430194
______
***Row Num = 283
Min = -4.000000
Max = 1.000000
Mean = -1.113636
std = 1.384565
RMS = 1.764550
_____
***Row Num = 284
Min = -6.000000
Max = 5.000000
Mean = -1.045455
std = 2.640952
RMS = 2.812311
______
***Row Num = 285
Min = -18.000000
Max = 12.000000
Mean = -0.704545
std = 6.040867
RMS = 6.013243
***Row Num = 286
Min = -9.000000
```

```
Max = 4.000000
Mean = -0.954545
std = 2.684621
RMS = 2.820380
______
***Row Num = 287
Min = -91.000000
Max = 72.000000
Mean = -0.886364
std = 35.218399
RMS = 34.827171
_____
***Row Num = 288
Min = -21.000000
Max = 28.000000
Mean = 0.863636
std = 10.377953
RMS = 10.295630
_____
***Row Num = 289
Min = -21.000000
Max = 15.000000
Mean = -0.568182
std = 6.742430
RMS = 6.689544
______
***Row Num = 290
Min = -7.000000
Max = 12.000000
Mean = 0.022727
std = 4.682916
RMS = 4.629451
______
***Row Num = 291
Min = -12.000000
Max = 47.000000
Mean = 1.977273
std = 10.927858
RMS = 10.982424
-----
***Row Num = 292
Min = -29.000000
Max = 33.000000
Mean = 1.545455
std = 11.872294
RMS = 11.837921
***Row Num = 293
Min = -32.000000
Max = 28.000000
```

```
Mean = -1.454545
std = 12.348533
RMS = 12.293753
______
***Row Num = 294
Min = -27.000000
Max = 50.000000
Mean = 0.977273
std = 15.183358
RMS = 15.041609
***Row Num = 295
Min = -18.938000
Max = 15.313000
Mean = -0.636341
std = 7.458670
RMS = 7.400834
______
***Row Num = 296
Min = -18.938000
Max = 15.313000
Mean = -0.636341
std = 7.458670
RMS = 7.400834
_____
***Row Num = 297
Min = -18.938000
Max = 15.313000
Mean = -0.636341
std = 7.458670
RMS = 7.400834
______
***Row Num = 298
Min = -70.063000
Max = 88.875000
Mean = 4.447466
std = 34.628312
RMS = 34.520243
______
***Row Num = 299
Min = -70.063000
Max = 88.875000
Mean = 4.447466
std = 34.628312
RMS = 34.520243
***Row Num = 300
Min = -70.063000
Max = 88.875000
Mean = 4.447466
```

```
std = 34.628312
RMS = 34.520243
______
***Row Num = 301
Min = 2.976100
Max = 3.020100
Mean = 2.997832
std = 0.011080
RMS = 2.997852
_____
***Row Num = 302
Min = 3.154100
Max = 3.206100
Mean = 3.176666
std = 0.013043
RMS = 3.176692
***Row Num = 303
Min = 1.452100
Max = 1.515100
Mean = 1.486914
std = 0.015131
RMS = 1.486989
______
***Row Num = 304
Min = 6.327400
Max = 7.004100
Mean = 6.779686
std = 0.142054
RMS = 6.781141
***Row Num = 305
Min = 4.365000
Max = 6.407000
Mean = 6.028830
std = 0.385836
RMS = 6.040883
***Row Num = 306
Min = 2.970100
Max = 3.700100
Mean = 3.381977
std = 0.180002
RMS = 3.386655
_____
***Row Num = 307
Min = 0.863770
Max = 0.955570
Mean = 0.915937
std = 0.017989
```

```
RMS = 0.916110
***Row Num = 308
Min = -0.452640
Max = -0.315430
Mean = -0.374146
std = 0.031230
RMS = 0.375418
______
***Row Num = 309
Min = 0.096680
Max = 0.163090
Mean = 0.127342
std = 0.014332
RMS = 0.128127
_____
***Row Num = 310
Min = -1.026900
Max = 0.727540
Mean = -0.555598
std = 0.313253
RMS = 0.636071
______
***Row Num = 311
Min = 0.516110
Max = 0.929200
Mean = 0.667447
std = 0.110583
RMS = 0.676340
***Row Num = 312
Min = 0.138180
Max = 0.671390
Mean = 0.386530
std = 0.141821
RMS = 0.411171
______
***Row Num = 313
Min = -8.000000
Max = 7.000000
Mean = -0.022727
std = 3.836718
RMS = 3.792936
***Row Num = 314
Min = -17.000000
Max = 7.000000
Mean = -1.045455
std = 4.492653
RMS = 4.562695
```

```
_____
***Row Num = 315
Min = -7.000000
Max = 3.000000
Mean = -1.727273
std = 2.356225
RMS = 2.899843
_____
***Row Num = 316
Min = -3.000000
Max = 2.000000
Mean = -1.000000
std = 1.120631
RMS = 1.492405
***Row Num = 317
Min = -3.000000
Max = 1.000000
Mean = -0.909091
std = 0.984016
RMS = 1.331438
______
***Row Num = 318
Min = -4.000000
Max = 2.000000
Mean = -0.977273
std = 1.302746
RMS = 1.616674
_____
***Row Num = 319
Min = -9.000000
Max = 6.000000
Mean = -1.431818
std = 2.968029
RMS = 3.264826
***Row Num = 320
Min = -6.000000
Max = 2.000000
Mean = -0.795455
std = 1.471900
RMS = 1.658312
______
***Row Num = 321
Min = -72.000000
Max = 35.000000
Mean = -0.590909
std = 19.523770
RMS = 19.309677
```

```
***Row Num = 322
Min = -23.000000
Max = 23.000000
Mean = -0.159091
std = 9.375731
RMS = 9.269942
***Row Num = 323
Min = -42.000000
Max = 17.000000
Mean = -1.181818
std = 9.244163
RMS = 9.214613
______
***Row Num = 324
Min = -10.000000
Max = 8.000000
Mean = -1.022727
std = 4.049052
RMS = 4.131366
_____
***Row Num = 325
Min = -16.000000
Max = 7.000000
Mean = -0.954545
std = 4.355988
RMS = 4.410731
***Row Num = 326
Min = -23.000000
Max = 14.000000
Mean = -0.340909
std = 7.351454
RMS = 7.275426
______
***Row Num = 327
Min = -26.000000
Max = 19.000000
Mean = -2.750000
std = 10.138861
RMS = 10.393398
_____
***Row Num = 328
Min = -19.000000
Max = 39.000000
Mean = 0.431818
std = 12.170108
RMS = 12.038763
***Row Num = 329
```

```
Min = -13.688000
Max = 20.875000
Mean = 0.463091
std = 7.576492
RMS = 7.504203
_____
***Row Num = 330
Min = -13.688000
Max = 20.875000
Mean = 0.463091
std = 7.576492
RMS = 7.504203
***Row Num = 331
Min = -13.688000
Max = 20.875000
Mean = 0.463091
std = 7.576492
RMS = 7.504203
_____
***Row Num = 332
Min = -63.563000
Max = 78.375000
Mean = 4.889273
std = 31.033541
RMS = 31.066017
______
***Row Num = 333
Min = -63.563000
Max = 78.375000
Mean = 4.889273
std = 31.033541
RMS = 31.066017
_____
***Row Num = 334
Min = -63.563000
Max = 78.375000
Mean = 4.889273
std = 31.033541
RMS = 31.066017
______
***Row Num = 335
Min = 2.981600
Max = 3.047100
Mean = 3.012618
std = 0.018796
RMS = 3.012675
***Row Num = 336
Min = 3.132400
```

```
Max = 3.165000
Mean = 3.148732
std = 0.006826
RMS = 3.148739
______
***Row Num = 337
Min = 1.433000
Max = 1.494500
Mean = 1.471745
std = 0.013534
RMS = 1.471806
***Row Num = 338
Min = 6.331900
Max = 6.936700
Mean = 6.709493
std = 0.144259
RMS = 6.711009
_____
***Row Num = 339
Min = 3.883400
Max = 6.406500
Mean = 5.978809
std = 0.498398
RMS = 5.999076
______
***Row Num = 340
Min = 2.895600
Max = 3.654200
Mean = 3.324211
std = 0.191179
RMS = 3.329580
______
***Row Num = 341
Min = 0.868160
Max = 0.956540
Mean = 0.918913
std = 0.018825
RMS = 0.919101
-----
***Row Num = 342
Min = -0.459960
Max = -0.287600
Mean = -0.369263
std = 0.034534
RMS = 0.370838
_____
***Row Num = 343
Min = 0.097168
Max = 0.174320
```

```
Mean = 0.127519
std = 0.017431
RMS = 0.128678
______
***Row Num = 344
Min = -1.067900
Max = -0.015137
Mean = -0.570035
std = 0.242200
RMS = 0.618278
***Row Num = 345
Min = 0.454100
Max = 1.030800
Mean = 0.674006
std = 0.148913
RMS = 0.689895
______
***Row Num = 346
Min = 0.159670
Max = 0.679690
Mean = 0.414496
std = 0.144672
RMS = 0.438476
_____
***Row Num = 347
Min = -10.000000
Max = 7.000000
Mean = -0.636364
std = 3.544343
RMS = 3.561154
***Row Num = 348
Min = -10.000000
Max = 11.000000
Mean = -0.500000
std = 4.123106
RMS = 4.106536
______
***Row Num = 349
Min = -6.000000
Max = 5.000000
Mean = -1.113636
std = 2.169727
RMS = 2.416797
***Row Num = 350
Min = -5.000000
Max = 0.000000
Mean = -1.500000
```

```
std = 1.000000
RMS = 1.796461
_____
***Row Num = 351
Min = -4.000000
Max = 1.000000
Mean = -1.227273
std = 1.117798
RMS = 1.651446
_____
***Row Num = 352
Min = -3.000000
Max = 1.000000
Mean = -1.113636
std = 1.279824
RMS = 1.685500
***Row Num = 353
Min = -8.000000
Max = 9.000000
Mean = -1.500000
std = 3.151227
RMS = 3.457535
______
***Row Num = 354
Min = -7.000000
Max = 2.000000
Mean = -0.863636
std = 1.850090
RMS = 2.022600
***Row Num = 355
Min = -60.000000
Max = 54.000000
Mean = 3.568182
std = 21.164250
RMS = 21.224450
***Row Num = 356
Min = -23.000000
Max = 33.000000
Mean = -0.886364
std = 11.231633
RMS = 11.138590
_____
***Row Num = 357
Min = -25.000000
Max = 12.000000
Mean = -2.750000
std = 6.748385
```

```
RMS = 7.215829
______
***Row Num = 358
Min = -12.000000
Max = 11.000000
Mean = -1.090909
std = 4.339211
RMS = 4.426162
______
***Row Num = 359
Min = -13.000000
Max = 11.000000
Mean = -1.386364
std = 4.975362
RMS = 5.110150
_____
***Row Num = 360
Min = -28.000000
Max = 39.000000
Mean = -1.318182
std = 12.136381
RMS = 12.069872
***Row Num = 361
Min = -24.000000
Max = 14.000000
Mean = -1.909091
std = 8.791693
RMS = 8.898417
***Row Num = 362
Min = -42.000000
Max = 65.000000
Mean = 4.522727
std = 17.903473
RMS = 18.267582
______
***Row Num = 363
Min = -14.938000
Max = 21.750000
Mean = 0.866489
std = 8.956879
RMS = 8.896806
***Row Num = 364
Min = -14.938000
Max = 21.750000
Mean = 0.866489
std = 8.956879
RMS = 8.896806
```

```
_____
***Row Num = 365
Min = -14.938000
Max = 21.750000
Mean = 0.866489
std = 8.956879
RMS = 8.896806
_____
***Row Num = 366
Min = -70.250000
Max = 100.810000
Mean = 4.747125
std = 36.469872
RMS = 36.364245
***Row Num = 367
Min = -70.250000
Max = 100.810000
Mean = 4.747125
std = 36.469872
RMS = 36.364245
______
***Row Num = 368
Min = -70.250000
Max = 100.810000
Mean = 4.747125
std = 36.469872
RMS = 36.364245
_____
***Row Num = 369
Min = 2.979400
Max = 3.060100
Mean = 3.022825
std = 0.022837
RMS = 3.022909
***Row Num = 370
Min = 3.125200
Max = 3.155700
Mean = 3.141550
std = 0.006523
RMS = 3.141557
______
***Row Num = 371
Min = 1.450700
Max = 1.532300
Mean = 1.495075
std = 0.017186
RMS = 1.495172
```

```
***Row Num = 372
Min = 6.316200
Max = 6.939100
Mean = 6.684652
std = 0.142611
RMS = 6.686139
***Row Num = 373
Min = 4.802600
Max = 6.421900
Mean = 6.004682
std = 0.363932
RMS = 6.015450
______
***Row Num = 374
Min = 2.863800
Max = 3.631000
Mean = 3.288923
std = 0.202845
RMS = 3.295030
_____
***Row Num = 375
Min = 0.863770
Max = 0.950200
Mean = 0.916582
std = 0.018230
RMS = 0.916759
***Row Num = 376
Min = -0.457520
Max = -0.322750
Mean = -0.376310
std = 0.032553
RMS = 0.377683
______
***Row Num = 377
Min = 0.092285
Max = 0.156740
Mean = 0.125489
std = 0.014311
RMS = 0.126283
_____
***Row Num = 378
Min = -1.053200
Max = 0.883790
Mean = -0.525036
std = 0.341012
RMS = 0.623947
***Row Num = 379
```

```
Min = 0.452640
Max = 1.123000
Mean = 0.704588
std = 0.170810
RMS = 0.724539
_____
***Row Num = 380
Min = 0.181640
Max = 0.760740
Mean = 0.414440
std = 0.146848
RMS = 0.439129
***Row Num = 381
Min = -14.000000
Max = 11.000000
Mean = -0.704545
std = 4.567731
RMS = 4.570160
_____
***Row Num = 382
Min = -15.000000
Max = 10.000000
Mean = -2.000000
std = 4.695371
RMS = 5.054251
______
***Row Num = 383
Min = -6.000000
Max = 4.000000
Mean = -1.477273
std = 2.129403
RMS = 2.571699
***Row Num = 384
Min = -4.000000
Max = 2.000000
Mean = -1.045455
std = 1.256695
RMS = 1.623688
______
***Row Num = 385
Min = -5.000000
Max = 3.000000
Mean = -1.090909
std = 1.377868
RMS = 1.745123
***Row Num = 386
Min = -5.000000
```

```
Max = 5.000000
Mean = -0.954545
std = 2.352184
RMS = 2.513599
______
***Row Num = 387
Min = -16.000000
Max = 20.000000
Mean = -1.022727
std = 6.489665
RMS = 6.496503
***Row Num = 388
Min = -5.000000
Max = 4.000000
Mean = -0.931818
std = 1.717187
RMS = 1.936492
_____
***Row Num = 389
Min = -51.000000
Max = 65.000000
Mean = -2.022727
std = 22.319549
RMS = 22.156981
_____
***Row Num = 390
Min = -21.000000
Max = 28.000000
Mean = -2.477273
std = 9.888891
RMS = 10.084867
______
***Row Num = 391
Min = -18.000000
Max = 22.000000
Mean = -1.363636
std = 5.775211
RMS = 5.869799
-----
***Row Num = 392
Min = -25.000000
Max = 12.000000
Mean = -2.113636
std = 5.723131
RMS = 6.039642
_____
***Row Num = 393
Min = -27.000000
Max = 21.000000
```

```
Mean = -2.068182
std = 9.450970
RMS = 9.569126
______
***Row Num = 394
Min = -42.000000
Max = 21.000000
Mean = -2.022727
std = 11.275593
RMS = 11.328765
***Row Num = 395
Min = -18.000000
Max = 24.000000
Mean = -1.159091
std = 8.730974
RMS = 8.708669
______
***Row Num = 396
Min = -43.000000
Max = 43.000000
Mean = 0.409091
std = 14.832896
RMS = 14.669077
_____
***Row Num = 397
Min = -17.250000
Max = 23.000000
Mean = 1.416216
std = 10.192956
RMS = 10.175497
_____
***Row Num = 398
Min = -17.250000
Max = 23.000000
Mean = 1.416216
std = 10.192956
RMS = 10.175497
______
***Row Num = 399
Min = -17.250000
Max = 23.000000
Mean = 1.416216
std = 10.192956
RMS = 10.175497
***Row Num = 400
Min = -70.750000
Max = 84.625000
Mean = 1.853750
```

```
std = 39.238092
RMS = 38.833912
_____
***Row Num = 401
Min = -70.750000
Max = 84.625000
Mean = 1.853750
std = 39.238092
RMS = 38.833912
_____
***Row Num = 402
Min = -70.750000
Max = 84.625000
Mean = 1.853750
std = 39.238092
RMS = 38.833912
***Row Num = 403
Min = 2.974600
Max = 3.039500
Mean = 3.007786
std = 0.017238
RMS = 3.007835
______
***Row Num = 404
Min = 3.127500
Max = 3.163500
Mean = 3.143477
std = 0.008677
RMS = 3.143489
***Row Num = 405
Min = 1.503900
Max = 1.613900
Mean = 1.546441
std = 0.026209
RMS = 1.546658
***Row Num = 406
Min = 6.441200
Max = 6.930400
Mean = 6.698468
std = 0.126166
RMS = 6.699629
_____
***Row Num = 407
Min = 3.560500
Max = 6.405400
Mean = 5.891352
std = 0.559342
```

```
RMS = 5.917245
______
***Row Num = 408
Min = 2.821800
Max = 3.721300
Mean = 3.327986
std = 0.217831
RMS = 3.334946
______
***Row Num = 409
Min = 0.876460
Max = 0.958010
Mean = 0.917337
std = 0.016100
RMS = 0.917475
_____
***Row Num = 410
Min = -0.451170
Max = -0.313480
Mean = -0.377375
std = 0.028797
RMS = 0.378447
_____
***Row Num = 411
Min = 0.087402
Max = 0.160640
Mean = 0.125288
std = 0.015814
RMS = 0.126260
***Row Num = 412
Min = -1.011700
Max = -0.110350
Mean = -0.585748
std = 0.196283
RMS = 0.617051
______
***Row Num = 413
Min = 0.484860
Max = 1.189000
Mean = 0.702905
std = 0.162516
RMS = 0.721031
***Row Num = 414
Min = 0.201170
Max = 0.752440
Mean = 0.393011
std = 0.136289
RMS = 0.415464
```

```
_____
***Row Num = 415
Min = -14.000000
Max = 16.000000
Mean = 0.750000
std = 5.855330
RMS = 5.836796
_____
***Row Num = 416
Min = -13.000000
Max = 12.000000
Mean = 0.909091
std = 4.940663
RMS = 4.968080
***Row Num = 417
Min = -3.000000
Max = 5.000000
Mean = -0.795455
std = 1.706070
RMS = 1.864745
______
***Row Num = 418
Min = -4.000000
Max = 2.000000
Mean = -0.863636
std = 1.173167
RMS = 1.445998
_____
***Row Num = 419
Min = -4.000000
Max = 1.000000
Mean = -1.250000
std = 1.163895
RMS = 1.698930
***Row Num = 420
Min = -5.000000
Max = 1.000000
Mean = -1.204545
std = 1.407282
RMS = 1.840207
______
***Row Num = 421
Min = -10.000000
Max = 8.000000
Mean = -1.204545
std = 3.806845
RMS = 3.951409
```

```
***Row Num = 422
Min = -5.000000
Max = 3.000000
Mean = -1.136364
std = 2.041328
RMS = 2.315953
***Row Num = 423
Min = -68.000000
Max = 36.000000
Mean = -4.363636
std = 23.542234
RMS = 23.678721
______
***Row Num = 424
Min = -20.000000
Max = 19.000000
Mean = -0.409091
std = 9.609390
RMS = 9.508370
_____
***Row Num = 425
Min = -12.000000
Max = 15.000000
Mean = -0.772727
std = 6.716393
RMS = 6.684446
***Row Num = 426
Min = -20.000000
Max = 8.000000
Mean = -1.022727
std = 5.445240
RMS = 5.479300
______
***Row Num = 427
Min = -19.000000
Max = 14.000000
Mean = -2.022727
std = 7.215902
RMS = 7.414666
_____
***Row Num = 428
Min = -19.000000
Max = 18.000000
Mean = 0.772727
std = 7.615357
RMS = 7.567875
***Row Num = 429
```

```
Min = -18.000000
Max = 32.000000
Mean = 0.136364
std = 10.808246
RMS = 10.685589
_____
***Row Num = 430
Min = -41.000000
Max = 52.000000
Mean = -0.704545
std = 19.146412
RMS = 18.940697
***Row Num = 431
Min = -16.063000
Max = 20.000000
Mean = -0.177568
std = 8.065232
RMS = 7.975032
_____
***Row Num = 432
Min = -16.063000
Max = 20.000000
Mean = -0.177568
std = 8.065232
RMS = 7.975032
______
***Row Num = 433
Min = -16.063000
Max = 20.000000
Mean = -0.177568
std = 8.065232
RMS = 7.975032
***Row Num = 434
Min = -64.000000
Max = 92.500000
Mean = 5.758523
std = 33.172384
RMS = 33.295021
______
***Row Num = 435
Min = -64.000000
Max = 92.500000
Mean = 5.758523
std = 33.172384
RMS = 33.295021
***Row Num = 436
Min = -64.000000
```

```
Max = 92.500000
Mean = 5.758523
std = 33.172384
RMS = 33.295021
______
***Row Num = 437
Min = 2.971700
Max = 3.027900
Mean = 3.001905
std = 0.016028
RMS = 3.001946
***Row Num = 438
Min = 3.140500
Max = 3.173000
Mean = 3.152161
std = 0.007345
RMS = 3.152170
______
***Row Num = 439
Min = 1.539600
Max = 1.614000
Mean = 1.569827
std = 0.017447
RMS = 1.569922
______
***Row Num = 440
Min = 6.456900
Max = 6.887300
Mean = 6.725598
std = 0.105071
RMS = 6.726400
______
***Row Num = 441
Min = 5.502500
Max = 6.412400
Mean = 6.029082
std = 0.281609
RMS = 6.035506
-----
***Row Num = 442
Min = 3.048600
Max = 3.734100
Mean = 3.357920
std = 0.205483
RMS = 3.364059
_____
***Row Num = 443
Min = 0.876460
Max = 0.961430
```

```
Mean = 0.917625
std = 0.016475
RMS = 0.917769
______
***Row Num = 444
Min = -0.444340
Max = -0.314450
Mean = -0.375033
std = 0.026323
RMS = 0.375935
***Row Num = 445
Min = 0.097656
Max = 0.160640
Mean = 0.120860
std = 0.012945
RMS = 0.121536
______
***Row Num = 446
Min = -0.950680
Max = 0.378420
Mean = -0.576538
std = 0.249024
RMS = 0.626897
_____
***Row Num = 447
Min = 0.500490
Max = 1.001000
Mean = 0.681042
std = 0.110796
RMS = 0.689794
***Row Num = 448
Min = 0.106450
Max = 0.647950
Mean = 0.358088
std = 0.141259
RMS = 0.384354
______
***Row Num = 449
Min = -15.000000
Max = 23.000000
Mean = -0.454545
std = 5.816794
RMS = 5.768252
***Row Num = 450
Min = -26.000000
Max = 9.000000
Mean = -1.250000
```

```
std = 5.949888
RMS = 6.013243
_____
***Row Num = 451
Min = -6.000000
Max = 3.000000
Mean = -1.659091
std = 1.854513
RMS = 2.472577
_____
***Row Num = 452
Min = -3.000000
Max = 2.000000
Mean = -1.090909
std = 1.197248
RMS = 1.609630
***Row Num = 453
Min = -4.000000
Max = 2.000000
Mean = -0.954545
std = 1.140268
RMS = 1.477098
______
***Row Num = 454
Min = -4.000000
Max = 2.000000
Mean = -1.136364
std = 1.472080
RMS = 1.846372
***Row Num = 455
Min = -7.000000
Max = 4.000000
Mean = -1.295455
std = 2.873937
RMS = 3.122499
***Row Num = 456
Min = -5.000000
Max = 2.000000
Mean = -1.159091
std = 1.724558
RMS = 2.061553
_____
***Row Num = 457
Min = -50.000000
Max = 59.000000
Mean = 2.386364
std = 20.366658
```

```
RMS = 20.274816
______
***Row Num = 458
Min = -23.000000
Max = 29.000000
Mean = -1.386364
std = 12.507144
RMS = 12.441682
_____
***Row Num = 459
Min = -18.000000
Max = 17.000000
Mean = -1.863636
std = 7.016893
RMS = 7.182681
_____
***Row Num = 460
Min = -15.000000
Max = 6.000000
Mean = -1.931818
std = 4.448139
RMS = 4.802935
_____
***Row Num = 461
Min = -27.000000
Max = 18.000000
Mean = -3.477273
std = 8.036222
RMS = 8.672055
***Row Num = 462
Min = -29.000000
Max = 30.000000
Mean = -0.090909
std = 10.704961
RMS = 10.583005
______
***Row Num = 463
Min = -18.000000
Max = 21.000000
Mean = -0.568182
std = 10.012545
RMS = 9.914406
***Row Num = 464
Min = -31.000000
Max = 40.000000
Mean = 4.750000
std = 16.536253
RMS = 17.023380
```

```
_____
***Row Num = 465
Min = -14.375000
Max = 19.875000
Mean = -0.578136
std = 7.562792
RMS = 7.498677
_____
***Row Num = 466
Min = -14.375000
Max = 19.875000
Mean = -0.578136
std = 7.562792
RMS = 7.498677
***Row Num = 467
Min = -14.375000
Max = 19.875000
Mean = -0.578136
std = 7.562792
RMS = 7.498677
______
***Row Num = 468
Min = -66.813000
Max = 82.938000
Mean = 7.093818
std = 31.869611
RMS = 32.294131
_____
***Row Num = 469
Min = -66.813000
Max = 82.938000
Mean = 7.093818
std = 31.869611
RMS = 32.294131
***Row Num = 470
Min = -66.813000
Max = 82.938000
Mean = 7.093818
std = 31.869611
RMS = 32.294131
______
***Row Num = 471
Min = 2.955200
Max = 3.034000
Mean = 2.994264
std = 0.019562
RMS = 2.994326
```

```
***Row Num = 472
Min = 3.133400
Max = 3.165100
Mean = 3.148568
std = 0.008239
RMS = 3.148579
***Row Num = 473
Min = 1.495100
Max = 1.551400
Mean = 1.524116
std = 0.014373
RMS = 1.524182
______
***Row Num = 474
Min = 6.309900
Max = 6.945800
Mean = 6.772332
std = 0.137475
RMS = 6.773695
_____
***Row Num = 475
Min = 4.309000
Max = 6.366800
Mean = 6.036057
std = 0.377482
RMS = 6.047581
***Row Num = 476
Min = 3.028300
Max = 3.659600
Mean = 3.446448
std = 0.148869
RMS = 3.449588
______
***Row Num = 477
Min = 0.877930
Max = 0.944340
Mean = 0.918746
std = 0.013400
RMS = 0.918842
_____
***Row Num = 478
Min = -0.431640
Max = -0.320310
Mean = -0.374245
std = 0.021713
RMS = 0.374860
***Row Num = 479
```

```
Min = 0.096680
Max = 0.160640
Mean = 0.119795
std = 0.013366
RMS = 0.120522
_____
***Row Num = 480
Min = -0.921390
Max = -0.266600
Mean = -0.614213
std = 0.168313
RMS = 0.636352
***Row Num = 481
Min = 0.522460
Max = 1.031700
Mean = 0.699729
std = 0.134320
RMS = 0.712217
_____
***Row Num = 482
Min = 0.223140
Max = 0.673830
Mean = 0.407215
std = 0.124667
RMS = 0.425456
***Row Num = 483
Min = -9.000000
Max = 12.000000
Mean = -0.045455
std = 4.763986
RMS = 4.709758
***Row Num = 484
Min = -8.000000
Max = 10.000000
Mean = 0.409091
std = 4.520332
RMS = 4.487356
______
***Row Num = 485
Min = -6.000000
Max = 5.000000
Mean = -0.795455
std = 2.426401
RMS = 2.527126
***Row Num = 486
Min = -3.000000
```

```
Max = 2.000000
Mean = -0.818182
std = 1.262569
RMS = 1.492405
______
***Row Num = 487
Min = -4.000000
Max = 2.000000
Mean = -1.068182
std = 1.169331
RMS = 1.573935
***Row Num = 488
Min = -4.000000
Max = 3.000000
Mean = -1.227273
std = 1.476382
RMS = 1.906925
_____
***Row Num = 489
Min = -8.000000
Max = 7.000000
Mean = -0.909091
std = 3.269437
RMS = 3.357488
_____
***Row Num = 490
Min = -6.000000
Max = 2.000000
Mean = -0.818182
std = 1.646317
RMS = 1.821588
______
***Row Num = 491
Min = -91.000000
Max = 61.000000
Mean = -1.068182
std = 28.180810
RMS = 27.879204
-----
***Row Num = 492
Min = -21.000000
Max = 26.000000
Mean = 3.636364
std = 10.616115
RMS = 11.106918
***Row Num = 493
Min = -19.000000
Max = 21.000000
```

```
Mean = 1.113636
std = 6.748698
RMS = 6.763875
______
***Row Num = 494
Min = -12.000000
Max = 20.000000
Mean = -0.909091
std = 5.259844
RMS = 5.278602
***Row Num = 495
Min = -19.000000
Max = 26.000000
Mean = -1.545455
std = 8.617059
RMS = 8.657629
______
***Row Num = 496
Min = -39.000000
Max = 15.000000
Mean = -6.568182
std = 12.295580
RMS = 13.816163
***Row Num = 497
Min = -34.000000
Max = 16.000000
Mean = -1.727273
std = 9.930839
RMS = 9.968131
_____
***Row Num = 498
Min = -25.000000
Max = 66.000000
Mean = 4.545455
std = 18.212511
RMS = 18.569281
______
***Row Num = 499
Min = -20.313000
Max = 17.438000
Mean = 0.177580
std = 7.936947
RMS = 7.848245
***Row Num = 500
Min = -20.313000
Max = 17.438000
Mean = 0.177580
```

```
std = 7.936947
RMS = 7.848245
______
***Row Num = 501
Min = -20.313000
Max = 17.438000
Mean = 0.177580
std = 7.936947
RMS = 7.848245
_____
***Row Num = 502
Min = -61.438000
Max = 94.438000
Mean = 3.806864
std = 33.944849
RMS = 33.772140
______
***Row Num = 503
Min = -61.438000
Max = 94.438000
Mean = 3.806864
std = 33.944849
RMS = 33.772140
______
***Row Num = 504
Min = -61.438000
Max = 94.438000
Mean = 3.806864
std = 33.944849
RMS = 33.772140
***Row Num = 505
Min = 2.941000
Max = 3.008300
Mean = 2.987907
std = 0.016955
RMS = 2.987954
***Row Num = 506
Min = 3.134300
Max = 3.159000
Mean = 3.145693
std = 0.005385
RMS = 3.145698
______
***Row Num = 507
Min = 1.468200
Max = 1.536700
Mean = 1.503568
std = 0.017285
```

```
RMS = 1.503665
***Row Num = 508
Min = 6.530900
Max = 6.832700
Mean = 6.679693
std = 0.082498
RMS = 6.680191
______
***Row Num = 509
Min = 5.656000
Max = 6.326800
Mean = 6.051952
std = 0.214717
RMS = 6.055674
_____
***Row Num = 510
Min = 3.235700
Max = 3.659100
Mean = 3.418816
std = 0.139664
RMS = 3.421603
_____
***Row Num = 511
Min = 0.855960
Max = 0.949220
Mean = 0.916582
std = 0.020095
RMS = 0.916797
***Row Num = 512
Min = -0.458980
Max = -0.329100
Mean = -0.377308
std = 0.029024
RMS = 0.378398
______
***Row Num = 513
Min = 0.090332
Max = 0.160640
Mean = 0.122458
std = 0.015903
RMS = 0.123463
***Row Num = 514
Min = -1.088400
Max = -0.171390
Mean = -0.632892
std = 0.210109
RMS = 0.666104
```

```
_____
***Row Num = 515
Min = 0.497070
Max = 1.039600
Mean = 0.682430
std = 0.150475
RMS = 0.698455
_____
***Row Num = 516
Min = 0.180180
Max = 0.663570
Mean = 0.393666
std = 0.142226
RMS = 0.418021
***Row Num = 517
Min = -25.000000
Max = 10.000000
Mean = -1.204545
std = 5.748931
RMS = 5.809475
______
***Row Num = 518
Min = -16.000000
Max = 15.000000
Mean = -0.409091
std = 6.333074
RMS = 6.274045
_____
***Row Num = 519
Min = -6.000000
Max = 6.000000
Mean = -1.000000
std = 2.411214
RMS = 2.584921
***Row Num = 520
Min = -4.000000
Max = 1.000000
Mean = -1.068182
std = 1.189053
RMS = 1.588310
______
***Row Num = 521
Min = -4.000000
Max = 2.000000
Mean = -1.068182
std = 1.246348
RMS = 1.630672
```

```
***Row Num = 522
Min = -4.000000
Max = 2.000000
Mean = -0.954545
std = 1.461992
RMS = 1.732051
***Row Num = 523
Min = -8.000000
Max = 5.000000
Mean = -0.409091
std = 2.951690
RMS = 2.946493
______
***Row Num = 524
Min = -5.000000
Max = 2.000000
Mean = -0.818182
std = 1.871111
RMS = 2.022600
_____
***Row Num = 525
Min = -81.000000
Max = 51.000000
Mean = -2.090909
std = 33.814692
RMS = 33.493554
***Row Num = 526
Min = -22.000000
Max = 23.000000
Mean = 0.863636
std = 10.292447
RMS = 10.211402
______
***Row Num = 527
Min = -13.000000
Max = 15.000000
Mean = -0.386364
std = 5.694616
RMS = 5.642775
_____
***Row Num = 528
Min = -11.000000
Max = 24.000000
Mean = -0.500000
std = 6.055941
RMS = 6.007571
***Row Num = 529
```

```
Min = -32.000000
Max = 45.000000
Mean = 0.454545
std = 14.401961
RMS = 14.244616
_____
***Row Num = 530
Min = -42.000000
Max = 21.000000
Mean = -3.113636
std = 13.226499
RMS = 13.440948
***Row Num = 531
Min = -35.000000
Max = 16.000000
Mean = -0.204545
std = 11.253071
RMS = 11.126341
_____
***Row Num = 532
Min = -37.000000
Max = 43.000000
Mean = 0.409091
std = 16.106215
RMS = 15.927392
***Row Num = 533
Min = -14.875000
Max = 20.125000
Mean = 0.453159
std = 8.523684
RMS = 8.438444
***Row Num = 534
Min = -14.875000
Max = 20.125000
Mean = 0.453159
std = 8.523684
RMS = 8.438444
______
***Row Num = 535
Min = -14.875000
Max = 20.125000
Mean = 0.453159
std = 8.523684
RMS = 8.438444
***Row Num = 536
Min = -81.125000
```

```
Max = 82.625000
Mean = 6.191818
std = 39.310665
RMS = 39.351568
_____
***Row Num = 537
Min = -81.125000
Max = 82.625000
Mean = 6.191818
std = 39.310665
RMS = 39.351568
***Row Num = 538
Min = -81.125000
Max = 82.625000
Mean = 6.191818
std = 39.310665
RMS = 39.351568
_____
***Row Num = 539
Min = 2.953100
Max = 3.033400
Mean = 2.996941
std = 0.023521
RMS = 2.997031
______
***Row Num = 540
Min = 3.135500
Max = 3.169400
Mean = 3.153248
std = 0.007860
RMS = 3.153257
______
***Row Num = 541
Min = 1.406300
Max = 1.512000
Mean = 1.459052
std = 0.024501
RMS = 1.459253
-----
***Row Num = 542
Min = 6.384200
Max = 6.988800
Mean = 6.715709
std = 0.119822
RMS = 6.716754
_____
***Row Num = 543
Min = 5.573700
Max = 6.406900
```

```
Mean = 6.101402
std = 0.232512
RMS = 6.105730
______
***Row Num = 544
Min = 3.286300
Max = 3.783600
Mean = 3.488936
std = 0.166911
RMS = 3.492836
***Row Num = 545
Min = 0.878420
Max = 0.936040
Mean = 0.913507
std = 0.011918
RMS = 0.913583
______
***Row Num = 546
Min = -0.420410
Max = -0.321780
Mean = -0.379573
std = 0.020353
RMS = 0.380106
_____
***Row Num = 547
Min = 0.116700
Max = 0.170900
Mean = 0.144387
std = 0.011879
RMS = 0.144863
***Row Num = 548
Min = -1.046900
Max = -0.235350
Mean = -0.647594
std = 0.186306
RMS = 0.673275
______
***Row Num = 549
Min = 0.478030
Max = 0.948240
Mean = 0.671298
std = 0.114085
RMS = 0.680706
***Row Num = 550
Min = 0.132810
Max = 0.716310
Mean = 0.399236
```

```
std = 0.132991
RMS = 0.420326
_____
***Row Num = 551
Min = -10.000000
Max = 9.000000
Mean = -1.227273
std = 3.814682
RMS = 3.965763
_____
***Row Num = 552
Min = -10.000000
Max = 7.000000
Mean = -1.045455
std = 4.334580
RMS = 4.410731
***Row Num = 553
Min = -7.000000
Max = 4.000000
Mean = -0.909091
std = 1.986210
RMS = 2.163751
______
***Row Num = 554
Min = -5.000000
Max = 1.000000
Mean = -0.840909
std = 1.199674
RMS = 1.453835
***Row Num = 555
Min = -3.000000
Max = 1.000000
Mean = -1.090909
std = 0.960092
RMS = 1.445998
***Row Num = 556
Min = -4.000000
Max = 2.000000
Mean = -0.886364
std = 1.224097
RMS = 1.500000
_____
***Row Num = 557
Min = -5.000000
Max = 7.000000
Mean = -0.636364
std = 2.252553
```

```
RMS = 2.315953
***Row Num = 558
Min = -4.000000
Max = 2.000000
Mean = -0.954545
std = 1.140268
RMS = 1.477098
______
***Row Num = 559
Min = -100.000000
Max = 47.000000
Mean = -7.431818
std = 32.390350
RMS = 32.871306
_____
***Row Num = 560
Min = -42.000000
Max = 21.000000
Mean = -2.204545
std = 12.600442
RMS = 12.650009
_____
***Row Num = 561
Min = -13.000000
Max = 12.000000
Mean = -1.022727
std = 6.218833
RMS = 6.232248
***Row Num = 562
Min = -8.000000
Max = 13.000000
Mean = -0.909091
std = 4.387181
RMS = 4.431294
______
***Row Num = 563
Min = -13.000000
Max = 14.000000
Mean = -0.931818
std = 5.703519
RMS = 5.714813
***Row Num = 564
Min = -27.000000
Max = 27.000000
Mean = 0.727273
std = 11.363679
RMS = 11.257321
```

```
_____
***Row Num = 565
Min = -32.000000
Max = 23.000000
Mean = -1.090909
std = 9.992598
RMS = 9.938447
_____
***Row Num = 566
Min = -39.000000
Max = 45.000000
Mean = -2.863636
std = 18.850194
RMS = 18.853502
***Row Num = 567
Min = -19.000000
Max = 17.375000
Mean = 0.346591
std = 8.091786
RMS = 8.006810
______
***Row Num = 568
Min = -19.000000
Max = 17.375000
Mean = 0.346591
std = 8.091786
RMS = 8.006810
_____
***Row Num = 569
Min = -19.000000
Max = 17.375000
Mean = 0.346591
std = 8.091786
RMS = 8.006810
______
***Row Num = 570
Min = -65.063000
Max = 61.125000
Mean = 4.271352
std = 32.681321
RMS = 32.588939
______
***Row Num = 571
Min = -65.063000
Max = 61.125000
Mean = 4.271352
std = 32.681321
RMS = 32.588939
```

```
***Row Num = 572
Min = -65.063000
Max = 61.125000
Mean = 4.271352
std = 32.681321
RMS = 32.588939
***Row Num = 573
Min = 3.048500
Max = 3.099400
Mean = 3.073468
std = 0.013061
RMS = 3.073495
______
***Row Num = 574
Min = 3.153700
Max = 3.186800
Mean = 3.171205
std = 0.006647
RMS = 3.171211
_____
***Row Num = 575
Min = 1.218200
Max = 1.289400
Mean = 1.248739
std = 0.017833
RMS = 1.248863
***Row Num = 576
Min = 6.474900
Max = 6.808800
Mean = 6.644766
std = 0.093673
RMS = 6.645411
______
***Row Num = 577
Min = 5.753200
Max = 6.404100
Mean = 6.117550
std = 0.199641
RMS = 6.120733
_____
***Row Num = 578
Min = 3.311200
Max = 3.818600
Mean = 3.522564
std = 0.139650
RMS = 3.525268
***Row Num = 579
```

```
Min = 0.878420
Max = 0.935060
Mean = 0.913552
std = 0.012364
RMS = 0.913634
_____
***Row Num = 580
Min = -0.421880
Max = -0.340820
Mean = -0.380815
std = 0.018147
RMS = 0.381238
***Row Num = 581
Min = 0.109380
Max = 0.156740
Mean = 0.135976
std = 0.012187
RMS = 0.136509
_____
***Row Num = 582
Min = -0.908690
Max = -0.240230
Mean = -0.614257
std = 0.163237
RMS = 0.635100
***Row Num = 583
Min = 0.518550
Max = 0.842770
Mean = 0.659435
std = 0.088059
RMS = 0.665156
***Row Num = 584
Min = 0.208980
Max = 0.638180
Mean = 0.419822
std = 0.117273
RMS = 0.435536
______
***Row Num = 585
Min = -23.000000
Max = 10.000000
Mean = -1.772727
std = 6.699058
RMS = 6.855655
***Row Num = 586
Min = -11.000000
```

```
Max = 7.000000
Mean = -1.295455
std = 3.707814
RMS = 3.887626
______
***Row Num = 587
Min = -4.000000
Max = 1.000000
Mean = -1.295455
std = 1.024798
RMS = 1.644550
***Row Num = 588
Min = -3.000000
Max = 1.000000
Mean = -0.977273
std = 1.130726
RMS = 1.484771
_____
***Row Num = 589
Min = -3.000000
Max = 1.000000
Mean = -1.068182
std = 0.899554
RMS = 1.389899
_____
***Row Num = 590
Min = -3.000000
Max = 3.000000
Mean = -0.954545
std = 1.396916
RMS = 1.678744
______
***Row Num = 591
Min = -4.000000
Max = 7.000000
Mean = -0.431818
std = 2.356562
RMS = 2.369311
-----
***Row Num = 592
Min = -5.000000
Max = 3.000000
Mean = -0.636364
std = 1.600740
RMS = 1.705606
***Row Num = 593
Min = -58.000000
Max = 51.000000
```

```
Mean = -0.340909
std = 23.068093
RMS = 22.806997
______
***Row Num = 594
Min = -22.000000
Max = 22.000000
Mean = -1.386364
std = 9.729399
RMS = 9.717604
***Row Num = 595
Min = -14.000000
Max = 12.000000
Mean = -0.772727
std = 5.535776
RMS = 5.526794
______
***Row Num = 596
Min = -8.000000
Max = 9.000000
Mean = -0.772727
std = 3.916950
RMS = 3.948533
_____
***Row Num = 597
Min = -8.000000
Max = 21.000000
Mean = 0.409091
std = 4.985179
RMS = 4.945154
______
***Row Num = 598
Min = -36.000000
Max = 21.000000
Mean = -0.954545
std = 9.187845
RMS = 9.132858
______
***Row Num = 599
Min = -32.000000
Max = 29.000000
Mean = 0.045455
std = 13.518213
RMS = 13.363791
***Row Num = 600
Min = -31.000000
Max = 21.000000
Mean = 0.500000
```

```
std = 13.190024
RMS = 13.048859
______
***Row Num = 601
Min = -13.813000
Max = 12.938000
Mean = -0.029830
std = 6.537111
RMS = 6.462468
_____
***Row Num = 602
Min = -13.813000
Max = 12.938000
Mean = -0.029830
std = 6.537111
RMS = 6.462468
______
***Row Num = 603
Min = -13.813000
Max = 12.938000
Mean = -0.029830
std = 6.537111
RMS = 6.462468
______
***Row Num = 604
Min = -59.750000
Max = 60.500000
Mean = 5.826727
std = 27.613299
RMS = 27.912642
***Row Num = 605
Min = -59.750000
Max = 60.500000
Mean = 5.826727
std = 27.613299
RMS = 27.912642
_____
***Row Num = 606
Min = -59.750000
Max = 60.500000
Mean = 5.826727
std = 27.613299
RMS = 27.912642
_____
***Row Num = 607
Min = 2.997400
Max = 3.068400
Mean = 3.043209
std = 0.017316
```

```
RMS = 3.043257
***Row Num = 608
Min = 3.153200
Max = 3.175600
Mean = 3.164516
std = 0.005272
RMS = 3.164520
______
***Row Num = 609
Min = 1.179800
Max = 1.233100
Mean = 1.204184
std = 0.013774
RMS = 1.204261
_____
***Row Num = 610
Min = 6.394000
Max = 6.802900
Mean = 6.637900
std = 0.091830
RMS = 6.638521
_____
***Row Num = 611
Min = 5.438100
Max = 6.372100
Mean = 6.083198
std = 0.199371
RMS = 6.086390
***Row Num = 612
Min = 3.241700
Max = 3.776500
Mean = 3.441927
std = 0.138729
RMS = 3.444658
______
***Row Num = 613
Min = 0.877440
Max = 0.938480
Mean = 0.919234
std = 0.012175
RMS = 0.919313
***Row Num = 614
Min = -0.412110
Max = -0.329100
Mean = -0.369485
std = 0.019487
RMS = 0.369986
```

_____ ***Row Num = 615Min = 0.101070Max = 0.153320Mean = 0.128207std = 0.012638RMS = 0.128814_____ ***Row Num = 616Min = -0.946780Max = -0.268550Mean = -0.641447std = 0.175363RMS = 0.664460***Row Num = 617Min = 0.527340Max = 0.914550Mean = 0.651833std = 0.107747RMS = 0.660479______ ***Row Num = 618Min = 0.191890Max = 0.694340Mean = 0.428689std = 0.122648RMS = 0.445505_____ ***Row Num = 619Min = -16.000000Max = 9.000000Mean = -1.613636std = 5.113666RMS = 5.306514***Row Num = 620Min = -21.000000Max = 12.000000Mean = -1.590909std = 6.158066RMS = 6.292131______ ***Row Num = 621Min = -5.000000Max = 1.000000Mean = -1.227273std = 1.217386RMS = 1.718879

```
***Row Num = 622
Min = -3.000000
Max = 2.000000
Mean = -1.250000
std = 1.163895
RMS = 1.698930
***Row Num = 623
Min = -3.000000
Max = 1.000000
Mean = -1.159091
std = 1.033017
RMS = 1.544786
______
***Row Num = 624
Min = -4.000000
Max = 2.000000
Mean = -1.113636
std = 1.279824
RMS = 1.685500
_____
***Row Num = 625
Min = -5.000000
Max = 8.000000
Mean = -0.886364
std = 2.544633
RMS = 2.667140
***Row Num = 626
Min = -4.000000
Max = 3.000000
Mean = -0.454545
std = 1.731440
RMS = 1.770978
______
***Row Num = 627
Min = -40.000000
Max = 32.000000
Mean = 1.454545
std = 15.628618
RMS = 15.518318
_____
***Row Num = 628
Min = -24.000000
Max = 28.000000
Mean = 1.363636
std = 8.779180
RMS = 8.785318
***Row Num = 629
```

```
Min = -12.000000
Max = 9.000000
Mean = 0.659091
std = 4.802825
RMS = 4.793461
_____
***Row Num = 630
Min = -14.000000
Max = 7.000000
Mean = -0.113636
std = 4.436717
RMS = 4.387482
***Row Num = 631
Min = -45.000000
Max = 27.000000
Mean = -1.431818
std = 11.473727
RMS = 11.432609
_____
***Row Num = 632
Min = -72.000000
Max = 39.000000
Mean = -2.272727
std = 21.080536
RMS = 20.963171
***Row Num = 633
Min = -22.000000
Max = 14.000000
Mean = -0.090909
std = 7.679081
RMS = 7.591862
***Row Num = 634
Min = -34.000000
Max = 35.000000
Mean = -2.840909
std = 13.746785
RMS = 13.883443
______
***Row Num = 635
Min = -17.625000
Max = 16.188000
Mean = 0.244284
std = 7.879679
RMS = 7.793453
***Row Num = 636
Min = -17.625000
```

```
Max = 16.188000
Mean = 0.244284
std = 7.879679
RMS = 7.793453
______
***Row Num = 637
Min = -17.625000
Max = 16.188000
Mean = 0.244284
std = 7.879679
RMS = 7.793453
***Row Num = 638
Min = -55.188000
Max = 57.125000
Mean = 2.019852
std = 29.696766
RMS = 29.426766
_____
***Row Num = 639
Min = -55.188000
Max = 57.125000
Mean = 2.019852
std = 29.696766
RMS = 29.426766
______
***Row Num = 640
Min = -55.188000
Max = 57.125000
Mean = 2.019852
std = 29.696766
RMS = 29.426766
_____
***Row Num = 641
Min = 2.989800
Max = 3.049900
Mean = 3.025275
std = 0.017652
RMS = 3.025325
-----
***Row Num = 642
Min = 3.134600
Max = 3.152300
Mean = 3.143305
std = 0.004023
RMS = 3.143307
_____
***Row Num = 643
Min = 1.092600
Max = 1.188300
```

```
Mean = 1.145807
std = 0.023294
RMS = 1.146038
______
***Row Num = 644
Min = 6.438800
Max = 6.751300
Mean = 6.594207
std = 0.087493
RMS = 6.594774
***Row Num = 645
Min = 5.697000
Max = 6.409600
Mean = 6.121836
std = 0.213073
RMS = 6.125459
______
***Row Num = 646
Min = 3.241100
Max = 3.844100
Mean = 3.503927
std = 0.177421
RMS = 3.508314
***Row Num = 647
Min = 0.892580
Max = 0.949220
Mean = 0.922186
std = 0.012695
RMS = 0.922272
***Row Num = 648
Min = -0.416990
Max = -0.328610
Mean = -0.365712
std = 0.021621
RMS = 0.366336
______
***Row Num = 649
Min = 0.085449
Max = 0.140630
Mean = 0.117654
std = 0.012665
RMS = 0.118318
***Row Num = 650
Min = -0.969730
Max = 1.080100
Mean = -0.543113
```

```
std = 0.419343
RMS = 0.683245
_____
***Row Num = 651
Min = 0.511230
Max = 0.864750
Mean = 0.641790
std = 0.096609
RMS = 0.648857
_____
***Row Num = 652
Min = 0.187500
Max = 0.708500
Mean = 0.407482
std = 0.138803
RMS = 0.429965
***Row Num = 653
Min = -7.000000
Max = 12.000000
Mean = -0.613636
std = 3.699251
RMS = 3.708099
______
***Row Num = 654
Min = -18.000000
Max = 15.000000
Mean = -0.250000
std = 5.207888
RMS = 5.154433
***Row Num = 655
Min = -4.000000
Max = 2.000000
Mean = -1.136364
std = 1.423898
RMS = 1.809068
***Row Num = 656
Min = -3.000000
Max = 1.000000
Mean = -0.840909
std = 0.963115
RMS = 1.270290
______
***Row Num = 657
Min = -2.000000
Max = 1.000000
Mean = -0.954545
std = 0.745671
```

```
RMS = 1.206045
***Row Num = 658
Min = -4.000000
Max = 2.000000
Mean = -1.000000
std = 1.397672
RMS = 1.705606
______
***Row Num = 659
Min = -6.000000
Max = 5.000000
Mean = -0.727273
std = 2.213738
RMS = 2.306118
_____
***Row Num = 660
Min = -5.000000
Max = 3.000000
Mean = -1.159091
std = 1.879426
RMS = 2.189853
_____
***Row Num = 661
Min = -64.000000
Max = 54.000000
Mean = -2.818182
std = 21.515027
RMS = 21.455027
***Row Num = 662
Min = -52.000000
Max = 17.000000
Mean = -1.272727
std = 11.380039
RMS = 11.321741
______
***Row Num = 663
Min = -40.000000
Max = 117.000000
Mean = -0.136364
std = 20.143198
RMS = 19.913449
***Row Num = 664
Min = -12.000000
Max = 19.000000
Mean = -1.568182
std = 5.772419
RMS = 5.918000
```

_____ ***Row Num = 665Min = -15.000000Max = 23.000000Mean = -0.977273std = 5.479300RMS = 5.504131_____ ***Row Num = 666Min = -20.000000Max = 24.000000Mean = 0.204545std = 8.584950RMS = 8.489298***Row Num = 667Min = -20.000000Max = 19.000000Mean = 0.454545std = 8.165311RMS = 8.084778______ ***Row Num = 668Min = -22.000000Max = 49.000000Mean = 2.454545std = 14.086864RMS = 14.140528_____ ***Row Num = 669Min = -14.813000Max = 14.938000Mean = -0.129227std = 7.277128RMS = 7.195119***Row Num = 670Min = -14.813000Max = 14.938000Mean = -0.129227std = 7.277128RMS = 7.195119______ ***Row Num = 671Min = -14.813000Max = 14.938000Mean = -0.129227std = 7.277128RMS = 7.195119

```
***Row Num = 672
Min = -65.188000
Max = 59.563000
Mean = 6.338080
std = 30.779722
RMS = 31.081037
***Row Num = 673
Min = -65.188000
Max = 59.563000
Mean = 6.338080
std = 30.779722
RMS = 31.081037
______
***Row Num = 674
Min = -65.188000
Max = 59.563000
Mean = 6.338080
std = 30.779722
RMS = 31.081037
_____
***Row Num = 675
Min = 2.961800
Max = 3.019500
Mean = 2.988580
std = 0.019239
RMS = 2.988640
***Row Num = 676
Min = 3.116000
Max = 3.142300
Mean = 3.128018
std = 0.007024
RMS = 3.128026
______
***Row Num = 677
Min = 1.072200
Max = 1.159100
Mean = 1.110614
std = 0.022088
RMS = 1.110828
_____
***Row Num = 678
Min = 6.296200
Max = 6.780900
Mean = 6.619098
std = 0.135370
RMS = 6.620450
***Row Num = 679
```

```
Min = 3.318300

Max = 6.386400

Mean = 5.948495

std = 0.671606

RMS = 5.985432
```

***Row Num = 680 Min = 2.895100 Max = 3.850000 Mean = 3.520432 std = 0.205056 RMS = 3.526263

>>