

INDIAN OIL CORPORATION LIMITED EASTERN REGION PIPELINES, UNIT: BARAUNI

Reference No: PHBMPL/OPN/SOP/13

Revision No.: 00

Date of Approval:

STANDARD OPERATING PROCEDURE

शीर्षक: - बरौनी नियंत्रण कक्ष में शिफ्ट हैंडओवर और टेकओवर के लिए एसओपी

क्र.सं.	गतिविधि	उत्तरदायित्व
1.	सूचना की सूची, लेकिन इन तक सीमित नहीं, को शिफ्ट हैंडओवर और टेकओवर रिपोर्ट में शामिल किया जाना आवश्यक है।	शिफ्ट प्रभारी
2.	पंपिंग/वितरण स्थिति, योजना और पूरा होने के अपेक्षित समय का उल्लेख करें।	-करना-
3.	अंतिम शिफ्ट घंटे के दौरान इसके कारण के साथ स्टेशन बंद होने की अवधि का उल्लेख करें। यदि स्टेशन बंद है, तो डाउनस्ट्रीम स्टेशन की स्थिति।	-करना-
4.	कारण और उनके संबंधित रखरखाव विभाग के साथ उपकरणों की अनुपलब्धता का उल्लेख करें।	-करना-
5.	फीडिंग/निकासी के तहत बुलेट का उल्लेख करें, अगली गोली को खिलाया / खाली किया जाना है और टैंक परिवर्तन का अपेक्षित समय है।	-करना-
6.	संचार प्रणाली, सीसीटीवी- चालू और उपलब्ध की सूची का उल्लेख करें	-करना-
7.	उल्लेख करें कि क्या कोई एसवी / आरसीपी डीजी चल रहा है और चलाने की अवधि है।	-करना-
8.	ऑपरेशन में एमएफएम सामान्य) का उल्लेख करें।	-करना-
9.	PIG स्थिति का उल्लेख करें (यदि लॉन्च/प्राप्त किया जाना है)।	-करना-
10.	इसके अलावा, किसी भी अन्य प्रासंगिक जानकारी का स्पष्ट रूप से उल्लेख किया जाना चाहिए।	-करना-
11.	शिफ्ट हैंडलिंग रिपोर्ट ई-ओएमएस पोर्टल में प्रस्तुत की जानी है।	-करना-
12.	सौंपने से पहले, सभी जानकारी भी मौखिक रूप से अगली शिफ्ट प्रभारी को दी जानी चाहिए।	-करना-
13.	शिफ्ट लेने से पहले, शिफ्ट-इन-चार्ज संचार रजिस्टर के माध्यम से जाने के लिए और यदि कोई नया संचार दर्ज किया गया है तो उसे स्वीकार करें।	-करना-
14.	उत्तरवर्ती शिफ्ट-इन-चार्ज को ई-ओएमएस पोर्टल में शिफ्ट का कार्यभार संभालना चाहिए।	-करना-

Prepared By: Committee Members		Reviewed By:	Approved By:
Kundan Kumar	M (HSE)	Amit Jain, DGM (O)	Randhir Kumar, Unit Head
Kundan,	OM	Meghanand Sah, COM	
Aman Anand	M (T&I)		
Kushank Mehendi Ratta	OM		



INDIAN OIL CORPORATION LIMITED EASTERN REGION PIPELINES, UNIT: BARAUNI

Reference No: PHBMPL/OPN/SOP/13

Revision No.: 00

Date of Approval:

STANDARD OPERATING PROCEDURE

TITLE: - SOP for Shift Handover and Takeover in Barauni Control Room

SL. NO.	ACTIVITY	RESPONSIBILITY
15.	The list of information but not limited to, are required to be included in Shift Handover and Takeover Report.	Shift In charge
16.	Mention the pumping/delivery status, plan & expected time of completion.	-Do-
17.	Mention station shut down duration with its cause during the last shift hour. In case station is under shutdown, downstream station status.	-Do-
18.	Mention non-availability of equipment with reason & their respective maintenance department.	-Do-
19.	Mention the bullet under feeding/evacuation, next bullet to be fed/evacuate & expected time of tank changeover.	-Do-
20.	Mention the list of communication system, CCTV- operational and available	-Do-
21.	Mention if any SV/RCP DG is running & duration to be run.	-Do-
22.	Mention the MFM Normal)/Master in operation.	-Do-
23.	Mention the PIG status (if to be launched/received).	-Do-
24.	In addition, any other relevant information should be mentioned clearly.	-Do-
25.	The shift handling report is to be submitted in E-OMS portal.	-Do-
26.	Before handing, all information also should also be passed verbally to next shift in charge.	-Do-
27.	Before taking over the shift, the Shift-In-Charge to go through communication register and acknowledge the same if any new communication has been entered.	-Do-
28.	The succeeding Shift-In-Charge must take over the shift in E-OMS portal.	-Do-

Prepared By: Committee Members		Reviewed By:	Approved By:
Kundan Kumar Kundan, Aman Anand Kushank Mehendi Ratta	M (HSE) OM M (T&I) OM	Amit Jain, DGM (O) Meghanand Sah, COM	Randhir Kumar, Unit Head



INDIAN OIL CORPORATION LIMITED EASTERN REGION PIPELINES, UNIT: BARAUNI

Reference No: PHBMPL/OPN/SOP/13

Revision No.: 00

Date of Approval:

STANDARD OPERATING PROCEDURE

RECORDS GENERATED :

- 1) SHIFT LOGBOOK SHEET
- 2) SHIFT HANDING OVER REGISTER

Prepared By: Committee Members		Reviewed By:	Approved By:
Kundan Kumar Kundan, Aman Anand	M (HSE) OM M (T&I)	Amit Jain, DGM (O) Meghanand Sah, COM	Randhir Kumar, Unit Head
Kushank Mehendi Ratta	OM		