

Rotational speed [rpm]
Power [W]
Tool wear [min]
Temp_diff [K]
Overstrain_ratio
Torque [Nm]
Process temperature [K]
Overstrain [minNm]
Air temperature [K]
Type_L
Type_M
Type_H
High
Feature value
Low
−5
0
5
SHAP value (impact on model output)