

FISCHER PUMPS LTD. - SERVICE BULLETIN

Document FP-SB-2026-21 | Issued 20-Aug-2026 | Supplementary to FP-SB-2025-04

Bulletin reference:	FP-SB-2026-21
Issue date:	20-Aug-2026
Applies to:	EQ-102
Equipment class:	Centrifugal Feed Pump
Component:	FSL-2240B
Classification:	Advisory - recommended practice
Supersedes:	None. Supplements FP-SB-2025-04, which remains in force.

1. PURPOSE

This bulletin issues supplementary maintenance guidance for EQ-102. It does not revise any part number, material or rating published in FP-SB-2025-04, which remains the controlling document.

2. RECOMMENDED BEARING REGREASING INTERVAL

For EQ-102, Fischer Pumps Ltd. recommends a bearing regreasing interval of 2,400 operating hours. Interval halves where ambient at the bearing housing exceeds 45 degrees C.

3. GREASE CHARGE PER BEARING

Grease charge per bearing for EQ-102 is specified as 18 grams. Values beyond 25 grams are outside the qualified range and are the most common installation defect reported to service centres.

4. ACTION REQUIRED

Site reliability engineering to align planned maintenance for EQ-102 with Section 2 at the next scheduling review. No immediate shutdown action is required.