

FISCHER PUMPS LTD. - SERVICE BULLETIN

Document FP-SB-2026-20 | Issued 20-Aug-2026 | Supplementary to FP-SB-2025-04

Bulletin reference:	FP-SB-2026-20
Issue date:	20-Aug-2026
Applies to:	EQ-101
Equipment class:	Centrifugal Feed Pump
Component:	FSL-2240B
Classification:	Advisory - recommended practice
Supersedes:	None. Supplements FP-SB-2025-04, which remains in force.

1. PURPOSE

This bulletin issues supplementary maintenance guidance for EQ-101. It does not revise any part number, material or rating published in FP-SB-2025-04, which remains the controlling document.

2. RECOMMENDED SEAL INSPECTION INTERVAL

For EQ-101, Fischer Pumps Ltd. recommends a seal inspection interval of 5,000 operating hours. Units not subject to thermal cycling may retain the standard 8,000 hour interval.

3. GLAND FOLLOWER TORQUE

Gland follower torque for EQ-101 is specified as 47 N-m. Values beyond 55 N-m are outside the qualified range and are the most common installation defect reported to service centres.

4. ACTION REQUIRED

Site reliability engineering to align planned maintenance for EQ-101 with Section 2 at the next scheduling review. No immediate shutdown action is required.