

Veridian Petrochemicals
Bharuch Complex

Document no: FAIL-E-1107B-2026 Revision: A
Title: Failure history card, E-1107B
Owner: Neha Kulkarni
Issued: 25 August 2026

Primary equipment: E-1107B, Overhead condenser B

21 July 2026: work order raised on E-1107B. Outlet temperature above the control band, firing reduced. Repaired by Imran Sheikh, equipment returned to service.

24 August 2026: work order raised on E-1107B. Outlet temperature above the control band, firing reduced. Repaired by Ravi Solanki, equipment returned to service.

This is failure 2 in 74 days on E-1107B, roughly every 37 days. The failure is recurring: the cause has not been removed by the repairs so far, and a reliability review of the duty is recommended.