

Veridian Petrochemicals
Bharuch Complex

Document no: FAIL-K-2101A-2026 Revision: A
Title: Failure history card, K-2101A
Owner: Neha Kulkarni
Issued: 12 September 2026

Primary equipment: K-2101A, Recycle gas compressor A

25 July 2026: work order raised on K-2101A. Vibration alarm on the drive end, reading above the alarm setpoint. Repaired by Ravi Solanki, equipment returned to service.

19 August 2026: work order raised on K-2101A. Vibration alarm on the drive end, reading above the alarm setpoint. Repaired by Imran Sheikh, equipment returned to service.

11 September 2026: work order raised on K-2101A. Vibration alarm on the drive end, reading above the alarm setpoint. Repaired by Ravi Solanki, equipment returned to service.

This is failure 3 in 70 days on K-2101A, roughly every 23 days. The failure is recurring: the cause has not been removed by the repairs so far, and a reliability review of the duty is recommended.