

Veridian Petrochemicals
Bharuch Complex

Document no: FAIL-P-1101A-2026 Revision: A
Title: Failure history card, P-1101A
Owner: Neha Kulkarni
Issued: 15 September 2026

Primary equipment: P-1101A, Crude feed pump A

11 July 2026: work order raised on P-1101A. Mechanical seal leaking at the gland, product visible on the baseplate. Repaired by Anita Chauhan, equipment returned to service.

01 August 2026: work order raised on P-1101A. Seal flush line weeping, barrier fluid level dropping. Repaired by Imran Sheikh, equipment returned to service.

23 August 2026: work order raised on P-1101A. Mechanical seal leaking at the gland, product visible on the baseplate. Repaired by Ravi Solanki, equipment returned to service.

14 September 2026: work order raised on P-1101A. Seal flush line weeping, barrier fluid level dropping. Repaired by Anita Chauhan, equipment returned to service.

This is failure 4 in 84 days on P-1101A, roughly every 21 days. The failure is recurring: the cause has not been removed by the repairs so far, and a reliability review of the duty is recommended.