

Veridian Petrochemicals
Bharuch Complex

Document no: FAIL-P-2101B-2026 Revision: A
Title: Failure history card, P-2101B
Owner: Neha Kulkarni
Issued: 30 August 2026

Primary equipment: P-2101B, Reactor charge pump B

29 July 2026: work order raised on P-2101B. Mechanical seal leaking at the gland, product visible on the baseplate. Repaired by Dinesh Patel, equipment returned to service.

29 August 2026: work order raised on P-2101B. Seal flush line weeping, barrier fluid level dropping. Repaired by Imran Sheikh, equipment returned to service.

This is failure 2 in 66 days on P-2101B, roughly every 33 days. The failure is recurring: the cause has not been removed by the repairs so far, and a reliability review of the duty is recommended.