

Veridian Petrochemicals
Bharuch Complex

Document no: FAIL-P-3101B-2026 Revision: A
Title: Failure history card, P-3101B
Owner: Neha Kulkarni
Issued: 08 September 2026

Primary equipment: P-3101B, Cooling water pump B

18 July 2026: work order raised on P-3101B. Drive end bearing running hot, temperature trending up over the shift. Repaired by Ravi Solanki, equipment returned to service.

12 August 2026: work order raised on P-3101B. Vibration alarm on the drive end, reading above the alarm setpoint. Repaired by Anita Chauhan, equipment returned to service.

07 September 2026: work order raised on P-3101B. Coupling guard noise, suspected misalignment after the last overhaul. Repaired by Anita Chauhan, equipment returned to service.

This is failure 3 in 77 days on P-3101B, roughly every 26 days. The failure is recurring: the cause has not been removed by the repairs so far, and a reliability review of the duty is recommended.