

Veridian Petrochemicals
Dahej Tank Farm

Document no: FAIL-P-6101C-2026 Revision: A
Title: Failure history card, P-6101C
Owner: Neha Kulkarni
Issued: 03 September 2026

Primary equipment: P-6101C, Tank transfer pump C

04 August 2026: work order raised on P-6101C. Drive end bearing running hot, temperature trending up over the shift. Repaired by Ravi Solanki, equipment returned to service.

02 September 2026: work order raised on P-6101C. Vibration alarm on the drive end, reading above the alarm setpoint. Repaired by Ravi Solanki, equipment returned to service.

This is failure 2 in 60 days on P-6101C, roughly every 30 days. The failure is recurring: the cause has not been removed by the repairs so far, and a reliability review of the duty is recommended.