

COMMAND NEXUS · CIT 140 · WEEK 1

Problem Brief

Meridian Forge Robotics · The Process Below

LEARNER

Kristen Ramirez

ARTIFACT

Problem Brief

STATUS

Working document

SECTION 01

Visible Failure

MR-17 is repeatedly running Test K-44 even though the test was retired and the current scheduler shows no active test assigned to MR-17. A stop request was received, but MR-17 continued running the test.

SECTION 02

Verified Facts

Incident log: MR-17 accepted TEST_K44_START at 02:13:07.

Current scheduler: MR-17 has no active test assignment.

Maintenance archive: Test K-44 was marked retired 186 days before the incident.

SECTION 03

Assumptions and Open Questions

Assumption: legacy_sync.exe may be connected to why the retired test started running, but this has not been verified.

Open question: Was Test K-44 removed from every copy, service, and schedule when it was retired?

SECTION 04**System Environment Map****SECTION 04A****People and Roles**

Nia Voss – Night QA
Supervisor
Elias Chen – Robotics
Systems Engineer
Mara Ilyan – Production
Operations Manager
QA operator – sent the stop
request

SECTION 04B**Processes and
Rules**

Test scheduling and
assignment
Test retirement and removal
from the active workflow
Stop request procedure
QA and production procedures

SECTION 04C**Information and
Data**

Incident log
Current scheduler and test
catalog
Maintenance record
Command telemetry
TEST_K44_START and
ACTIVE_INSTRUCTION_PEN
DING messages

SECTION 04D**Technology and
Tools**

MR-17 robot
Current scheduling console
Command system
legacy_sync.exe
QA test cell

SECTION 04E

Environment and Constraints

Production is paused in the affected QA cell.

MR-17 is continuing the retired test despite the stop request.

The cause has not been confirmed yet.

Any investigation needs to consider production and safety.

SECTION 05

Investigation Boundary

Inside the Investigation

The team should investigate why MR-17 received the TEST_K44_START command, where legacy_sync.exe came from, and whether Test K-44 still exists in another service, copy, or schedule.

Outside for Now

A complete redesign of the scheduling system is outside the investigation for now because there is not enough evidence showing that the current scheduler caused the incident.

SECTION 06

Organizational Impact

Production is paused in the affected QA cell because MR-17 is continuing to run the retired test. This affects QA and production operations until the issue can be understood.

SECTION 07

Problem Statement

MR-17 is running a retired test even though the current scheduler shows no active test assignment. The robot continued the test after receiving a stop request, causing production in the affected QA cell to be paused.

SECTION 08

Next Investigation Step

Review the records and logs connected to legacy_sync.exe to determine what service owns it and whether it sent TEST_K44_START to MR-17. This could help determine where the command came from and why a retired test was able to run.

SHARED ARTIFACT

Working Document Link

[Not entered](#)

WEEK 1 STOPPING RULE

Define before designing.

This Problem Brief records the problem that requires investigation. It does not recommend a solution.