



Rev: 1

Customer:		RALEC KAOHSIUNG		Date:	12-Apr-15	Time: ####
Participant From Maruwa		Participant From Organizer		Report To		
1. Sivakumar	QA	1. Ms Suru Chou	Purchaser	1. Mr.Anthony,Mr.Ogawa		
2. Eric	TW Maruwa	2. Mr Desmond Wu	QA Engineer	2. Mr.Seeni,Mr.Naga,Mr.Sinna		
3.		3.		3. Mr.Theva,Mr.Shahrudin		
4		4		4 Mr. Matsumoto		
5.		5.		5.		

Meeting started at 03:30pm and attended by purchasing and QA

Explained Maruwa method of controlling the inner dimension and requested RALEC QA to measure and confirm the m

Electronic Ceramics
MARUWA

OUTLINE MEASUREMENT DATA

QA-RD-2106-C-011
REV. 4

PRODUCT TYPE : **MA02-4CR**

LOT NO :

MOULD NO :

S/N :

DATE :

GREEN SHEET

☐

AFTER FIRING

☒

MEASURED BY

W1

POINT	DATA	1A	1B	2	2A	2B	3	3A	3B	TOTAL	VARIANCE (1B-3B)
S1 W1 WD1	6.983		35			35			35		
S1 W1 WD2	35.513		-35			-35			-35		
S1 W1 WD3	7.032					-7		7.032	7.004	28	49.527
S1 W2 WD1	7.020					0		0.000	0.000	0	0.000
S1 W2 WD2	35.489					-3			14		25
S1 W2 WD3	7.009					0			28		0
S2 W1 WD1	0.000					-7			0		0
S2 W1 WD2	0.000		OK			OK			OK		
S2 W1 WD3	0.000										
S2 W2 WD1	0.000										
S2 W2 WD2	0.000										
S2 W2 WD3	0.000										
S1 L1 LD1	4.070										
S1 L1 LD2	52.012										
S1 L1 LD3	4.063										
S1 L2 LD1	4.070										
S1 L2 LD2	52.002										
S1 L2 LD3	4.074										
S2 L1 LD1	0.000										
S2 L1 LD2	0.000										
S2 L1 LD3	0.000										
S2 L2 LD1	0.000										
S2 L2 LD2	0.000										
S2 L2 LD3	0.000										

W2

POINT	DATA	1A	1B	2	2A	2B	3	3A	3B	TOTAL	VARIANCE (1B-3B)
S1 W1 WD1	6.983		35			35			35		
S1 W1 WD2	35.513		-35			-35			-35		
S1 W2 WD1	7.032					-7		7.032	7.004	28	49.527
S1 W2 WD2	7.020					0		0.000	0.000	0	0.000
S1 W2 WD3	35.489					-3			14		25
S1 W2 WD4	7.009					0			28		0
S2 W1 WD1	0.000					-7			0		0
S2 W1 WD2	0.000		OK			OK			OK		
S2 W1 WD3	0.000										
S2 W2 WD1	0.000										
S2 W2 WD2	0.000										
S2 W2 WD3	0.000										
S1 L1 LD1	4.070										
S1 L1 LD2	52.012										
S1 L1 LD3	4.063										
S1 L2 LD1	4.070										
S1 L2 LD2	52.002										
S1 L2 LD3	4.074										
S2 L1 LD1	0.000										
S2 L1 LD2	0.000										
S2 L1 LD3	0.000										
S2 L2 LD1	0.000										


PIC: Mr Izumo
Mr Prasan

Meeting adjourned at 04:30am

Requested Maruwa to solve the printing shifted issue since problem happening for all the manual press product

MA02-4CR OUTLINE MEASUREMENT

Outline at LD frame:



LD1


LD1;

- 1) Measure the 'a' length from WD side of the product until the 1st thru hole center point
- 2) Measure the 'b' length from center point of 1st thru hole until center point of last thru hole
- 3) 'c' = 'a' measurement method

LD2 = LD1 method

LD2

Spec reference to the the drawing



WD1

WD2

WD1;

- 1) Measure the 'a' length from LD side of the product until the 1st thru hole center point
- 2) Measure the 'b' length from center point of 1st thru hole until center point of last thru hole
- 3) 'c' = 'a' measurement method

WD2 = WD1 method