



Customer Visit Report

MM-IN-RD-9100-P06-04

Rev: 1

Customer: RALEC KUNSHAN		Date: 18-Apr-17	Time: 10:00
Participant From Maruwa		Participant From Organizer	Report To
1. Sivakumar MMSB QA		1. Ms Amay Zhu Purchase Chief	1. Mr. Anthony, Mr. Ogawa
2. Ronny Fang Shanghai		2. Mr Spring R&D Chief	2. Mr. Seen, Mr. Naga, Mr. Sinna
3.		3. Mr Bing IQC Chief	3. Mr. Theva, Mr. Shahrudin, Mr. Fauzi
4.		4. Mr Bin Zhao Engineer	4. Mr. Matsumoto
5.		5.	5.

Agenda

Meeting started of with Quality group.

The details as below (Please refer to the attach sheet for details)

MARUWA		RALEC QUALITY MEETING						18/04/2017
No	Complaint / Request	Product	Details	MARUWA Comment	Status	PIC	DATE	
1	Thru Hole Shifted	MA02-2C MA02-4C	RALEC continue detecting thru hold shifted for 1% ~ 3%. Product have end of life and total 300kpcs stock available.	Requested RALEC to sort and use it. Maruwa will pay for the sorting cost. Sorting method => CCD camera	RALEC Ms Amay will provide the sorting cost by this week 21/04	Ms Amay Mr Ronny	22-Apr	
2	Thru Hole Shifted	WA04-2C	RALEC requested MARUWA to do a comparison report between manual press & auto press. RALEC would like to confirm the effectiveness of the action	Will carry out the request. 1st shipment : 200pcs 2nd shipment : 1000pcs	-	Mr Azfar Mr Prasan Mr Siva	26-Apr	
3	Breaking abnormal	7910M	Informed that they received the sample for angle 20. Requested Maruwa to provide a confirmation method to understand the angle change	explained that it's difficult to confirm on the product since it been set on the mould. Will provide some comparison	Requested Maruwa to provide a simple report for the differewnces	Mr Izzat	26-Apr	

GENERAL

1. YA1210 new sample for RALEC - sample shipout on 18/04 to MW Shanghai
2. There is a sudden demand in powerchip especially for YA2512.
3. RETURN product : 0

Meeting adjouened at 11:45am

Conclusion & Opinion

QUALITY - RALEC targetting to focus on the new model of chiparray (WA04-2C, RN104PA). MARUWA will set up a proper spec and control method in order RALEC don't face any abnormal during process. To ensure this, this models have to be changed from *manual press* to *auto press*

No	Complaint / Request	Product	Details	MARUWA Comment	Status	PIC	DATE
1	Thru Hole Shifted	MA02-2C MA02-4C	RALEC continue detecting thru hold shifted for 1% ~ 3%. Product have end of life and total 300kpcs stock available.	Requested RALEC to sort and use it. Maruwa will pay for the sorting cost. Sorting method => CCD camera	RALEC Ms Amay will provide the sorting cost by this week 21/04	Ms Amay Mr Ronny	22-Apr
2	Thru Hole Shifted	WA04-2C	RALEC requested MARUWA to do a comparison report between manual press & auto press. RALEC would like to confirm the effectiveness of the action	Will carry out the request. 1st shipment : 200pcs 2nd shipment : 1000pcs	-	Mr Azfar Mr Prasan Mr Siva	26-Apr
3	Breaking abnormal	7910M	Informed that they received the sample for angle 20. Requested Maruwa to provide a confirmation method to understand the angle change	explained that it's difficult to confirm on the product since it been set on the mould. Will provide some comparison	Requested Maruwa to provide a simple report for the differewnces	Mr Izzat	26-Apr