

Customer: SORTING - Kamaya Malaysia (KM)		Date: 04-May-18	Time: 8:30
Participant From Maruwa		Participant From Organizer	Report To
1. Mr Loges	MMSB QA	1. Ms.Emily	1. Mr.Anthony,Mr.Ogawa
2. Ms.Kavitha	MMSB QC	2. Ms.Umai	2. Mr.Seeni,Mr.Naga,Mr.Sinna
3. Ms.Fateha	MMSB QC	3.	3. Mr.Theva,Mr.Shahrudin,Mr.Fauzi
4 Ms.Pavitra	MMSB QC	4	4 Mr Loga, Mr Matsumoto
5.		5.	5.

Agenda

Sorting started at 08.15am at the Kamaya-Warehouse

Result of sorting for 4th May 2018

Product	CV102685	CV102677	CV102714	Grand Total	Rework Status				Rate %
	19/4/18	19/4/18	25/4/18		2/5/18	3/5/18	4/5/18	Reject	
3080M	135000	1500	15000	151500	39000		112500	68	0.04%
874M	486000	1500	16500	504000	7500	384000	112500	58	0.01%
1598M	58500			58500			58500	0	0.00%
YA2010	49500			49500	49500			123	0.25%
Total	729000	3000	31500	763500	96000	384000	283500	249	0.03%

Result of sorting for 4th May 2018

Total Lot inspected : 189 boxes

Total qty : 283500 pcs

Total sample : 99000 pcs

Total reject : 46pcs (0.07%)

a. YA2010 - First 6 boxes with 100% inspection, No white crack detected.

After discussion with QC, agreed to proceed with sampling plan 300pcs/box with rejection 0/1

White crack 14pcs(0.03%) and others 48pcs. Sorting completed for YA2010

Educate QC Kamaya on crack/deep slit difference. LD dummy have issues in deep slit

b. 874M - No white crack detected. Continue with sampling inspection 9/15bundle.

Analysis crack mode colouring check with KM IQA, crack detected for bundle 100% coloured and visual at sorting place and transfer to IQA for recolour (3/600 : 0.33%)

Crack mode shows due to handling process (trolley, colouring method, product handling)

Request to feedback status of sorted product in KM production. 2nd May input 30boxes.

1st process result OK and waiting for 2nd process result.

c. 3080M - White crack detected less 0.03%. Most of crack found in IQA sampling quantity.

Inspection 100% for sampling coloured product, Sampling inspection 9/15bundle per box

Request to crack check method re-evaluate with IQA, will follow up on this.

c. 1598M - No White crack detected.

Sorting end at 5:15pm

Conclusion & Opinion