

Customer: **KAMAYA -CRACK** **Date:** **12/Dec/18** **Time:** **11:00**

Participant From Maruwa	Participant From Organizer	Report To
1. Mr Amirul MMSB QA	1. Ms.Emily (Purchasing	1. Mr.Anthony,Mr.Ogawa
2. Ms Fateha MMSB QC	2. Ms.Umai (IQA)	2. Mr.Seeni,Mr.Naga,Mr.Sinna
3. Ms Bama MMSB QC	3. Mr.Azman (Prod Head	3. Mr.Theva,Mr.Shahrudin,Mr.Fauzi
4	4	4 Mr Loga, Mr Matsumoto
5.	5.	5.

Agenda

Sorting started at 11.00 am at KAMAYA Warehouse

Result sorting for 12 Dec 2018

KAMAYA CRACK REWORK

No	Product	Rank	Carton No	Lot No	Qty	NG Qty	NG%
1	874m	66	18-J04613	AK31	1500	0	0.00%
2	874m	55	18-J05734	LT94	1500	4	0.27%
3	874m	55	18-J06678	LT94	1500	6	0.40%
4	874m	55	18-J06560	LT94	1500	2	0.13%
5	874m	55	18-J06304	LT94	1500	5	0.33%
6	874m	55	18-J06618	LT94	1500	0	0.00%
7	874m	56	18-J06587	DN93	1500	0	0.00%
8	874m	56	18-J06590	DN93	1500	0	0.00%
9	874m	56	18-J06785	DN93	1500	1	0.07%
10	874m	66	18-J04607	AK31	1500	0	0.00%
11	874m	66	18-J04956	AK31	1500	1	0.07%
12	874m	66	18-J04963	AK31	1500	9	0.60%
13	874m	66	18-J04965	AK31	1500	6	0.40%
14	874m	56	18-J05836	DN93	1500	0	0.00%
15	874m	55	18-J05830	LT94	1500	0	0.00%
16	874m	56	18-J05812	DN93	1500	0	0.00%
17	874m	55	18-J0648	LT94	1500	0	0.00%
18	874m	55	18-J06736	LT94	1500	0	0.00%
19	874m	55	18-J06735	LT94	1500	3	0.20%
20	874m	55	18-J06617	LT94	1500	0	0.00%
21	874m	55	18-J04966	LT94	1500	2	0.13%
22	874m	66	18-J04571	AK31	1500	6	0.40%
23	874m	55	18-J05824	LT94	1500	0	0.00%
24	874m	55	18-J06569	LT94	1500	0	0.00%
25	874m	55	18-J05827	LT94	1500	0	0.00%
26	874m	66	18-J04299	AK31	1500	1	0.07%
27	874m	66	18-J04550	AK31	1500	0	0.00%
28	874m	66	18-J05766	AK31	1500	5	0.33%
29	874m	55	18-J06702	LT94	1500	1	0.07%
30	874m	55	18-J06697	LT94	1500	1	0.07%
31	874m	55	18-J05730	LT94	1500	1	0.07%
32	874m	55	18-J05835	LT94	1500	0	0.00%
33	874m	55	18-J05837	LT94	1500	0	0.00%
34	874m	55	18-J06561	LT94	1500	0	0.00%
35	874m	56	18-J06577	DN93	1500	0	0.00%

36	874m	56	18-J05825	LT94	1500	0	0.00%
37	874m	56	18-J06574	DN93	1500	0	0.00%
38	874m	66	18-J05762	AK31	1500	0	0.00%
39	874m	55	18-J05685	LT94	1500	0	0.00%
40	874m	55	18-J05684	LT94	1500	1	0.07%
41	874m	65	18-J10889	EF42	1500	0	0.00%
42	874m	55	18-J04940	LT94	1500	0	0.00%
43	874m	56	18-J05796	DN93	1500	0	0.00%
44	874m	56	18-J05795	DN93	1500	1	0.07%
45	874m	65	18-J10898	EF42	1500	0	0.00%
46	874m	65	18-J11295	EF42	1500	0	0.00%
47	874m	55	18-J06157	LT94	1500	0	0.00%
49	874m	65	18-J10898	EF42	1500	1	0.07%
50	874m	55	18-J06596	LT94	1500	2	0.13%
51	874m	55	18-J06571	LT94	1500	0	0.00%
52	874m	56	18-J05818	DN93	1500	0	0.00%
53	874m	55	18-J06594	LT94	1500	0	0.00%
54	874m	56	18-J06589	DN93	1500	0	0.00%
55	874m	55	18-J06570	LT94	1500	0	0.00%
56	874m	56	18-J06853	DN93	1500	0	0.00%
57	874m	56	18-J05821	DN93	1500	0	0.00%
58	874m	56	18-J05813	DN93	1500	0	0.00%
59	874m	56	18-J05832	DN93	1500	0	0.00%
60	874m	56	18-J05798	DN93	1500	0	0.00%
61	874m	56	18-J05792	DN93	1500	0	0.00%
62	874m	56	18-J06056	DN93	1500	1	0.07%
63	874m	56	18-J06677	LT94	1500	1	0.07%
64	874m	66	18-J04347	AK31	1500	1	0.07%

Total lot Inspected: 64 boxes

Total qty: 94500 pcs

Total reject: 62 pcs (0.07%)

a. 874M - No white crack detected after 7 boxes. Proceed checking with 100% inspection, and will will discuss for sampling check. IQA Kamaya will continuously checking for crack, and they request to do continuous improvement to reduce crack NG.

Sorting end at 5.25pm

Conclusion & Opinion