

期間 Date 2019/8/29

出張者 Name Mr Siva

添付資料 Attachment 有 Yes 無 No

同行者 Colleage Mr Ronny, Mr Matsumoto

MM-IN-RD-9100-P06-04 Rev.2

出張先 Customer	PANASONIC TIANJIN	相手先 面談者 Attendance	Mr Matsumoto – PID QA Ms Pei – Buyer Mr Zhan – Production Engineer
出張目的 Visit Purpose	☒ ALT10PKB – Double slit ☒ Crack improvement ☒	会議フロア アップ項目 Meeting Follow Up	☒ As attach in below table ☒ ☒

報告内容 Report

Meeting begin at 1:00PM
 Discussion : Quality topics

Summary of discussion

1. ALT10PKB – Double slit

Expained MM action towards occurrence & flow out

Mr Matsumoto requested

- Gurantee point for outgoing for ALT10PKB
- Updated process flow for additional check point for double slit
- Propose auto detect in press for abnormal cyclinder/mould movement


Detected new cases of double slit and MM need to confirm the effected lot from Apr'19 shipment up July'19 shipment

Lot details as below

FG12-D19 RANK 12
 PY27-J12 RANK 12

Due to this occurrence ==> PID will sort out the double slit area and continue using the balance product

=> Fear of flow out of double slit product




Detected double slit at this area

2. Crack Improvement

Explained MM action towards crack and new proposal informed

- New carton for ALT3GKB – carton received and will feedback the outcome of IQC
- New wrapping method – reference to Japan customer
- Auto inspection – explain currently MM under evaluation for AUTO visual inspection
- Video on product handling



Detail of the follow up activity shown in below table

MARUWA		PID TIANJIN EXTERNAL VISIT - ACTION PLAN		29/8/2019		UNIROYAL	
No	Product	Activity	Date	MM PIC	Date	PIC	
1	ALT10PKB Double slit	Explained the action item base from the occurrence & flow out cause Follow up item a. Guarantee point for outgoing for ALT10PKB b. Updated process flow for additional check point for double slit c. Propose auto detect in press for abnormal cylinder/mould movement	TBC	Mr Siva & Team			
2	ALT10PKB 2nd Occurrence -Double slit	PID detected re-occurrence of 2x slit for ALT10PKB Lot details FG12-D19 RANK 12 PY27-J12 RANK 12 Same lot product have been on hold Total qty : 9000pcs MM need to confirm the effected qty and inclusive of May'19 ~ July'19 shipment Current stock have been on-hold in PID	03th Sept	Mr Theva Mr Loga & Team			
3	ALT10PKB Double slit - New detection	MM need to confirm Mode of occurrence Type 1 : Fully double slit (Assumption: Can't confirm by customer) Type 2 : Partially double slit (Assumption: Can't confirm by customer) Type 3 : Double slit (Assumption: Can't confirm by customer) Type 4 : Double slit (Assumption: Can't confirm by customer) Type 5 : Double slit (Assumption: Can't confirm by customer) Type 6 : Double slit (Assumption: Can't confirm by customer) Type 7 : Double slit (Assumption: Can't confirm by customer) Type 8 : Double slit (Assumption: Can't confirm by customer) Type 9 : Double slit (Assumption: Can't confirm by customer) Type 10 : Double slit (Assumption: Can't confirm by customer) Type 11 : Double slit (Assumption: Can't confirm by customer) Type 12 : Double slit (Assumption: Can't confirm by customer) Type 13 : Double slit (Assumption: Can't confirm by customer) Type 14 : Double slit (Assumption: Can't confirm by customer) Type 15 : Double slit (Assumption: Can't confirm by customer) Type 16 : Double slit (Assumption: Can't confirm by customer) Type 17 : Double slit (Assumption: Can't confirm by customer) Type 18 : Double slit (Assumption: Can't confirm by customer) Type 19 : Double slit (Assumption: Can't confirm by customer) Type 20 : Double slit (Assumption: Can't confirm by customer) Type 21 : Double slit (Assumption: Can't confirm by customer) Type 22 : Double slit (Assumption: Can't confirm by customer) Type 23 : Double slit (Assumption: Can't confirm by customer) Type 24 : Double slit (Assumption: Can't confirm by customer) Type 25 : Double slit (Assumption: Can't confirm by customer) Type 26 : Double slit (Assumption: Can't confirm by customer) Type 27 : Double slit (Assumption: Can't confirm by customer) Type 28 : Double slit (Assumption: Can't confirm by customer) Type 29 : Double slit (Assumption: Can't confirm by customer) Type 30 : Double slit (Assumption: Can't confirm by customer) Type 31 : Double slit (Assumption: Can't confirm by customer) Type 32 : Double slit (Assumption: Can't confirm by customer) Type 33 : Double slit (Assumption: Can't confirm by customer) Type 34 : Double slit (Assumption: Can't confirm by customer) Type 35 : Double slit (Assumption: Can't confirm by customer) Type 36 : Double slit (Assumption: Can't confirm by customer) Type 37 : Double slit (Assumption: Can't confirm by customer) Type 38 : Double slit (Assumption: Can't confirm by customer) Type 39 : Double slit (Assumption: Can't confirm by customer) Type 40 : Double slit (Assumption: Can't confirm by customer) Type 41 : Double slit (Assumption: Can't confirm by customer) Type 42 : Double slit (Assumption: Can't confirm by customer) Type 43 : Double slit (Assumption: Can't confirm by customer) Type 44 : Double slit (Assumption: Can't confirm by customer) Type 45 : Double slit (Assumption: Can't confirm by customer) Type 46 : Double slit (Assumption: Can't confirm by customer) Type 47 : Double slit (Assumption: Can't confirm by customer) Type 48 : Double slit (Assumption: Can't confirm by customer) Type 49 : Double slit (Assumption: Can't confirm by customer) Type 50 : Double slit (Assumption: Can't confirm by customer) Type 51 : Double slit (Assumption: Can't confirm by customer) Type 52 : Double slit (Assumption: Can't confirm by customer) Type 53 : Double slit (Assumption: Can't confirm by customer) Type 54 : Double slit (Assumption: Can't confirm by customer) Type 55 : Double slit (Assumption: Can't confirm by customer) Type 56 : Double slit (Assumption: Can't confirm by customer) Type 57 : Double slit (Assumption: Can't confirm by customer) Type 58 : Double slit (Assumption: Can't confirm by customer) Type 59 : Double slit (Assumption: Can't confirm by customer) Type 60 : Double slit (Assumption: Can't confirm by customer) Type 61 : Double slit (Assumption: Can't confirm by customer) Type 62 : Double slit (Assumption: Can't confirm by customer) Type 63 : Double slit (Assumption: Can't confirm by customer) Type 64 : Double slit (Assumption: Can't confirm by customer) Type 65 : Double slit (Assumption: Can't confirm by customer) Type 66 : Double slit (Assumption: Can't confirm by customer) Type 67 : Double slit (Assumption: Can't confirm by customer) Type 68 : Double slit (Assumption: Can't confirm by customer) Type 69 : Double slit (Assumption: Can't confirm by customer) Type 70 : Double slit (Assumption: Can't confirm by customer) Type 71 : Double slit (Assumption: Can't confirm by customer) Type 72 : Double slit (Assumption: Can't confirm by customer) Type 73 : Double slit (Assumption: Can't confirm by customer) Type 74 : Double slit (Assumption: Can't confirm by customer) Type 75 : Double slit (Assumption: Can't confirm by customer) Type 76 : Double slit (Assumption: Can't confirm by customer) Type 77 : Double slit (Assumption: Can't confirm by customer) Type 78 : Double slit (Assumption: Can't confirm by customer) Type 79 : Double slit (Assumption: Can't confirm by customer) Type 80 : Double slit (Assumption: Can't confirm by customer) Type 81 : Double slit (Assumption: Can't confirm by customer) Type 82 : Double slit (Assumption: Can't confirm by customer) Type 83 : Double slit (Assumption: Can't confirm by customer) Type 84 : Double slit (Assumption: Can't confirm by customer) Type 85 : Double slit (Assumption: Can't confirm by customer) Type 86 : Double slit (Assumption: Can't confirm by customer) Type 87 : Double slit (Assumption: Can't confirm by customer) Type 88 : Double slit (Assumption: Can't confirm by customer) Type 89 : Double slit (Assumption: Can't confirm by customer) Type 90 : Double slit (Assumption: Can't confirm by customer) Type 91 : Double slit (Assumption: Can't confirm by customer) Type 92 : Double slit (Assumption: Can't confirm by customer) Type 93 : Double slit (Assumption: Can't confirm by customer) Type 94 : Double slit (Assumption: Can't confirm by customer) Type 95 : Double slit (Assumption: Can't confirm by customer) Type 96 : Double slit (Assumption: Can't confirm by customer) Type 97 : Double slit (Assumption: Can't confirm by customer) Type 98 : Double slit (Assumption: Can't confirm by customer) Type 99 : Double slit (Assumption: Can't confirm by customer) Type 100 : Double slit (Assumption: Can't confirm by customer)	Double slit occurrence happen only 1/2 and not fully occurred	Mr Theva Mr Loga & Team			
3	Crack Improvement	New wrapping method Evaluate 1 carton for each product  -CONSIDERATION	Sept'19	Ms Attira			
5	ECN issuance	MM need to issue ECN a. Wrapping Method change b. New ALT3GKB carton	04th Sept	Mr Siva			

Meeting adjourned at 04:00pm

意見・Opinion

PID TJ feedback on quality ==> MM need to focus on the design failure which is impacting MM performace. Crack occurrence have improved in IQC and base from explanation, continues action have taken to solve the issue.

No	Product	Activity	MM		UNIROYAL	
			Date	PIC	Date	PIC
1	ALT10PKB Double slit	Explained the action item base from the occurrence & flow out cause Follow up item a. Gurantee point for outgoing for ALT10PKB b. Updated process flow for additional check point for double slit c. Propose auto detetct in press for abnormal cyclinder/mould movement	TBC	Mr Siva & team		
2	ALT10PKB 2nd Occurrence -Double slit	PID detetcted re-occurrence of 2x slit for ALT10PKB Lot details FG12-D19 RANK 12 PY27-J12 RANK 12 Same lot product have been on hold Total qty : 9000pcs MM need to confirm the effected qty and inclusive of May'19 ~ July'19 shipment Current stock have been on-hold in PID	03th Sept	Mr Theva Mr Loga & Team		
3	ALT10PKB Double slit - New detection	MM need to confirm Mode of occurrence Type 1 : Fully double slit (Assumption: Can't confirm by customer) Type 2 : half double slit (Detected on 29/08)  Double slit occurence happen only 1/2 and not fully occured		Mr Theva Mr Loga & Team		
3	Crack Improvement	New wrapping method Evaluate 1 carton for each product  CONFIDENTIAL	Sept'19	Ms Attira		
5	ECN issuance	MM need to issue ECN a. Wrapping Method change b. New ALT3GKB carton	04th Sept	Mr Siva		