



日付 Date	時間 Time (JST)	内容 Topic	担当者 (日本) Japan PIC	Activity / Action item
7/14 (月) Monday	8:30 ~ 10:00	MMS System金型システム	Mr. Tachibana / Mr. Watanabe 立花さん・渡辺さん	a. Explain on the mould system b. Explained in detail => each screen c. PIC will be Tachibana san d. Instructed Mr Ravi to duplicate the similar system e. 1st Step => Start to register mould in mould master for ALN f. Explain on the mould shot qty as well for servicing & renew g. All screen shared with the actual implementation in Malaysia Mould Department a. Department not establish yet b. Feedback that manpower shortage => shall discuss with Mr Nakano & Mr Kurata for establishment c. MMS system will function well with the dedicated manpower d. MM Mould team not aonly assembly & installation of mould but also qualify supplier & sourcing for supplier => Meeting adjourned at 1130pm Slitter - resurface a. Specs slitter already send out to supplier for resurfing. Mr Watanabe will follow up the quotation b. Specs will be tested at MM casting
	10:00 ~ 13:45	SN・ALN RM Mixing and SIN RM Mixing ALN・SN 原料システム / 材料製造システム	Mr. Morishita / Mr. Oomori 森下さん・大森さん	ALN RM Mixing - Mr Morishita a. System towards completion, pending final mixing label. Mr Ravi will upload updated system by tonite b. Production should be able to view final mixing details c. Adding quality buyoff for slurry & blocked issuance to casting if Data is NG or no data d. Will follow up again by 16/Jul SIN RM Mixing - Mr Oomori a. System stop at Synthesis process - requested to remove old data which causing error - removal done by 330pm JST b. Mr Oomori will test again and carry out the review on 15/Jul 2pm c. Current system requirement - not inclusive of buyoff => Add inthe buyoff similar to MM system
	13:45 ~ 15:00	Casting System 板厚測定システム・スリッター管理	Mr ・ Ta ke da 竹 田 さ	Mr Takeda not available & postpone to 15/Jul Explained to DX team (Ms Shimizu & Mr Tachibana) the difference between JM Casting & MM Casting Share improvement point a. Casting thickness alert by zone - simplify for operator b. Working table - centralise with all the resources - printer, laptop , tape & micrometer c. All the yield report - by lot & by machine d. Data display - abnormal data need to have action taken. Requested DX team to check what is needed & check on operator understanding on the system
7/15 (火) Tuesday	8:30 ~ 10:00	Ball Mill Systemボールミル	Mr ・ D ai m on 大 門 さ ん	Checked the Ball Mill Auto timer system Malaysia implementation method a. Link the BM panel with PLC b. PLC link to operation switch c. preset at the HMI screen Future plan => link to Ball Mill lot to understand i. Ball Mill running hour - PM (Alumina ball drop & Lining change) ii. Link to RM QC - Ball mill vs particle size General - Running hour change with access rights 
	10:00 ~ 13:45	IOT Dashboard 稼働率見える化ダッシュボード	Mr ・ D ai m on 大 門 さ ん	Requested Mr daimon to review the content of each process Dashboard. Findings a. Standard layout used which certain unrelvant column with no data - suggested to add n/a b. Operation location different plant but dashboard in same screen  Too many data dispaly Review - table fills => Not relevant check point  2 Different data display in single screen => Relayout by plant
	13:45 ~ 15:00	ALN・SN PC system and Inspection Dashboard生産管理システム・検査ダッシュ ボード	Ms. Shimizu / Mr. Izumo 清水さん・出雲さ ん	PC System completed - confirmed with Shimizu san Current issue 4 system used to key in data for Press ==> Requested to Mr Nakano & team to review and list up the difference between the system. Will review again on 16/Jul Explain MM using only 2 system for Manufacturing 1. Odoo - CRM 2. PC System 3. Packing System (Future to merge with PC System) Visual IoT a. Visual IoT - target setting & layout need to review - Mr Ravi will upload standard format with MM by 24/Jul b. Mr Izumo will train visual operator to key in accordingly in PC system - currently transaction done with single operator which IoT showing only single operator  PC System transaction done correctly - data display for all opt
7/16 (水) Wednesday	8:30 ~ 10:00	Yudentai QA System誘電体 QA	Mr ・ Ta ke ch e	Review the existing implementation Mr Takechi highlighted that some errors in each pattern and CSV upload Identify each problem with Mr Ravi Final conclusion => Mr Takechi will provide the all pattern's CSV file for Mr Ravi to check - Done Screen updating - 24/JUL & 31/Jul
	12:15 ~ 15:00	Server Managementサーバー管理	Mr. Kim 金さん	1. PIC for server management Mr Ravi - Full admin Mr Kim - Sub admin (Limited access) Mr Okada - Sub admin (Limited access) 2. Server room - To be follow up Mr Kim => Current date given is in Oct/25 3. Static IP - Consult with service provider to assign static ip PIC: Mr Kim 4. RAM update status - completed & monitoring 5. Programmer PC - 4 units => to be relocated in server room once complete 6. Antivirus - expired ==> Mr Kim will do the necessary arrangement to renew the license 7. Standardization of IP address for IoT ==> to avoid multiple license purchase => Currently using hub to connect from east wing to west wing => Next to use the fibre optic core to connect between east to west wing PIC: Mr Kim