```
JB, NM018_2, DT03-12-2019, TM13:22:23
MO, AD1, UN1, SF1.00000000, EC0, E00.0, AU0
--Stonex SurvCE Version 6.01
--CRD: Alphanumeric
-- Haszn. Meghat: HUNGARY/EOV-VITEL2014
               Stonex, S900, SN:S900281800035, FW:0.22.181113(STONEX)
--Equipment:
--Antenna Type: [STXS900
NONE], RA0.0785m, SHMP0.0547m, L10.0702m, L20.0608m, --L1/L2 Antenna
--Illesztési Fájl: None
--Geoid Elválaszt. Fájlok: None
--Grid Adjustment File: None
--GPS Lépték: 1.00000000
--Scale Point not used
--Import ASCII
SP,PN20,N 73452.7300,E 546973.5100,EL0.0000,--
SP, PN21, N 73577.9700, E 546814.0600, EL0.0000, --
SP, PN22, N 73554.5600, E 546847.0500, EL0.0000, --
SP,PN55,N 73604.2000,E 546483.8800,EL0.0000,--
SP, PN59, N 73752.0200, E 546581.4200, EL0.0000, --
SP, PN61, N 73744.5800, E 546593.9200, EL0.0000, --
SP,PN62,N 73545.1100,E 546707.1200,EL0.0000,--
SP,PN63,N 73487.2800,E 546761.3800,EL0.0000,--
SP, PN75, N 73382.8100, E 546831.8000, EL0.0000, --
SP, PN82, N 73259.3400, E 547035.7600, EL0.0000, --
SP, PN85, N 73392.6600, E 547046.5900, EL0.0000, --
SP,PN86,N 73346.6300,E 547106.9700,EL0.0000,--
SP,PN87,N 73308.0000,E 547161.7600,EL0.0000,--
SP, PN96, N 73191.4700, E 547072.6300, EL0.0000, --
SP, PN183, N 73633.9200, E 546728.8800, EL0.0000, --
SP, PN184, N 73617.0100, E 546750.6700, EL0.0000, --
--RTK Method: RTCM V3.1, Device: Internal GSM, Network: NTRIP 1033_VRS-
RTCM3.1-GLO
BP, PN4095, LA45.592883447636, LN17.393314207052, EL155.6289, AG0.0000, PA0.000
0, ATAPC, SRROVER, --
--Entered Rover HR: 2.0000 m, Vertical
LS, HR2.0702
GPS, PN2000, LA46.000166743600, LN17.424503793800, EL154.927000, --13
--GS,PN2000,N 73752.3033,E 546581.6133,EL108.1839,--13
--GT, PN2000, SW2044, ST217524800, EW2044, ET217524800
--HSDV:0.014, VSDV:0.030, STATUS:FIXED, SATS:15, AGE:1.0, PDOP:1.424,
HDOP:0.700, VDOP:1.240, TDOP:1.181, GDOP:0.795, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM13:25:11
GPS, PN2001, LA46.000158108400, LN17.424530451800, EL155.067000, --13
--GS, PN2001, N 73749.5392, E 546587.3037, EL108.3240, --13
--GT, PN2001, SW2044, ST217545000, EW2044, ET217545000
--HSDV:0.014, VSDV:0.030, STATUS:FIXED, SATS:14, AGE:1.0, PDOP:1.476,
HDOP: 0.800, VDOP: 1.240, TDOP: 1.243, GDOP: 0.795, NSDV: 0.010, ESDV: 0.010
--DT03-12-2019
--TM13:25:29
GPS, PN20000, LA46.000166827000, LN17.424503897000, EL154.889000, --131
--GS,PN20000,N 73752.3287,E 546581.6359,EL108.1459,--131
--GT, PN20000, SW2044, ST217576000, EW2044, ET217576000
--HSDV:0.022, VSDV:0.040, STATUS:FIXED, SATS:14, AGE:1.0, PDOP:1.476,
HDOP: 0.800, VDOP: 1.240, TDOP: 1.243, GDOP: 0.795, NSDV: 0.020, ESDV: 0.010
--DT03-12-2019
--TM13:26:09
GPS, PN2002, LA45.595800027200, LN17.425221126200, EL154.580000, --13
```

```
--GS, PN2002, N 73636.4439, E 546734.0278, EL107.8380, --13
--GT, PN2002, SW2044, ST217874000, EW2044, ET217874000
--HSDV:0.028, VSDV:0.060, STATUS:FIXED, SATS:13, AGE:1.0, PDOP:1.532,
HDOP:0.900, VDOP:1.240, TDOP:1.310, GDOP:0.795, NSDV:0.020, ESDV:0.020
--DT03-12-2019
--TM13:30:58
GPS, PN2003, LA45.595507799600, LN17.425836694400, EL154.834000, --13
--GS,PN2003,N 73543.9598,E 546864.9431,EL108.0929,--13
--GT, PN2003, SW2044, ST218023000, EW2044, ET218023000
--HSDV:0.028, VSDV:0.050, STATUS:FIXED, SATS:13, AGE:1.0, PDOP:1.476,
HDOP:0.800, VDOP:1.240, TDOP:1.243, GDOP:0.795, NSDV:0.020, ESDV:0.020
--DT03-12-2019
--TM13:33:27
GPS, PN2004, LA45.595367863400, LN17.430113128200, EL154.643000, --13
--GS,PN2004,N 73499.7410,E 546923.6888,EL107.9023,--13
--GT, PN2004, SW2044, ST218122600, EW2044, ET218122600
--HSDV:0.022, VSDV:0.040, STATUS:FIXED, SATS:14, AGE:1.0, PDOP:1.476,
HDOP:0.800, VDOP:1.240, TDOP:1.243, GDOP:0.795, NSDV:0.020, ESDV:0.010
--DT03-12-2019
--TM13:35:06
GPS, PN2005, LA45.595088788400, LN17.430637107600, EL154.129000, --13
--GS, PN2005, N 73411.6572, E 547034.9708, EL107.3891, --13
--GT, PN2005, SW2044, ST218330800, EW2044, ET218330800
--HSDV:0.022, VSDV:0.040, STATUS:FIXED, SATS:12, AGE:1.0, PDOP:1.532,
HDOP: 0.900, VDOP: 1.240, TDOP: 1.310, GDOP: 0.795, NSDV: 0.020, ESDV: 0.010
--DT03-12-2019
--TM13:38:36
GPS, PN2006, LA45.594879176000, LN17.431036072200, EL154.159000, --13
--GS, PN2006, N 73345.4793, E 547119.7196, EL107.4197, --13
--GT, PN2006, SW2044, ST218423000, EW2044, ET218423000
--HSDV:0.022, VSDV:0.030, STATUS:FIXED, SATS:12, AGE:1.0, PDOP:1.532,
HDOP: 0.900, VDOP: 1.240, TDOP: 1.310, GDOP: 0.795, NSDV: 0.020, ESDV: 0.010
--DT03-12-2019
--TM13:40:08
GPS, PN2007, LA45.594774248000, LN17.431249409400, EL154.068000, --13
--GS, PN2007, N 73312.3025, E 547165.0755, EL107.3290, --13
--GT, PN2007, SW2044, ST218638400, EW2044, ET218638400
--HSDV:0.022, VSDV:0.040, STATUS:FIXED, SATS:13, AGE:1.0, PDOP:1.532,
HDOP:0.900, VDOP:1.240, TDOP:1.310, GDOP:0.795, NSDV:0.020, ESDV:0.010
--DT03-12-2019
--TM13:43:43
GPS, PN2008, LA45.594385177400, LN17.430834429000, EL153.606000, --13
--GS, PN2008, N 73193.6969, E 547073.7328, EL106.8669, --13
--GT, PN2008, SW2044, ST219025000, EW2044, ET219025000
--HSDV:0.014, VSDV:0.030, STATUS:FIXED, SATS:12, AGE:1.0, PDOP:1.964,
HDOP:0.900, VDOP:1.746, TDOP:1.424, GDOP:1.353, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM13:50:09
GPS, PN2009, LA45.594616936400, LN17.430628335600, EL154.132000, --13
--GS,PN2009,N 73266.0065,E 547030.6022,EL107.3925,--13
--GT, PN2009, SW2044, ST219142000, EW2044, ET219142000
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:12, AGE:1.0, PDOP:1.921,
HDOP: 0.800, VDOP: 1.746, TDOP: 1.363, GDOP: 1.353, NSDV: 0.010, ESDV: 0.010
--DT03-12-2019
--TM13:52:07
GPS, PN2010, LA45.594996969800, LN17.425704185000, EL154.622000, --13
--GS,PN2010,N 73386.7290,E 546833.7389,EL107.8812,--13
--GT, PN2010, SW2044, ST219434800, EW2044, ET219434800
```

```
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:12, AGE:1.0, PDOP:1.911,
HDOP:1.000, VDOP:1.629, TDOP:1.489, GDOP:1.199, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM13:56:59
GPS, PN2011, LA45.595358039600, LN17.425326360200, EL154.471000, --13
--GS,PN2011,N 73499.5952,E 546754.3411,EL107.7295,--13
--GT, PN2011, SW2044, ST219587600, EW2044, ET219587600
--HSDV:0.022, VSDV:0.040, STATUS:FIXED, SATS:12, AGE:2.0, PDOP:1.682,
HDOP: 0.900, VDOP: 1.421, TDOP: 1.368, GDOP: 0.979, NSDV: 0.020, ESDV: 0.010
--DT03-12-2019
--TM13:59:32
GPS, PN2012, LA45.595503682400, LN17.425088118200, EL154.920000, --13
--GS, PN2012, N 73545.4371, E 546703.8447, EL108.1781, --13
--GT, PN2012, SW2044, ST219646200, EW2044, ET219646200
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:13, AGE:1.0, PDOP:1.631,
HDOP: 0.800, VDOP: 1.421, TDOP: 1.304, GDOP: 0.979, NSDV: 0.010, ESDV: 0.010
--DT03-12-2019
--TM14:00:30
GPS, PN2013, LA45.595684063400, LN17.424063301400, EL155.149000, --13 CLO
--GS, PN2013, N 73604.8988, E 546484.2811, EL108.4059, --13 CLO
--GT, PN2013, SW2044, ST219869800, EW2044, ET219869800
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:15, AGE:2.0, PDOP:1.631,
HDOP: 0.800, VDOP: 1.421, TDOP: 1.304, GDOP: 0.979, NSDV: 0.010, ESDV: 0.010
--DT03-12-2019
--TM14:04:16
GPS, PN20013, LA45.595683999800, LN17.424063331400, EL155.154000, --131
--GS,PN20013,N 73604.8790,E 546484.2872,EL108.4109,--131
--GT, PN20013, SW2044, ST219901200, EW2044, ET219901200
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:15, AGE:1.0, PDOP:1.631,
HDOP:0.800, VDOP:1.421, TDOP:1.304, GDOP:0.979, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM14:04:54
GPS, PN20012, LA45.595503665600, LN17.425088123600, EL154.870000, --131
--GS, PN20012, N 73545.4319, E 546703.8458, EL108.1281, --131
--GT, PN20012, SW2044, ST220163800, EW2044, ET220163800
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:14, AGE:1.0, PDOP:1.631,
HDOP: 0.800, VDOP: 1.421, TDOP: 1.304, GDOP: 0.979, NSDV: 0.010, ESDV: 0.010
--DT03-12-2019
--TM14:09:09
GPS, PN20010, LA45.594997031600, LN17.425704041000, EL154.608000, --131
--GS,PN20010,N 73386.7486,E 546833.7083,EL107.8672,--131
--GT, PN20010, SW2044, ST220397000, EW2044, ET220397000
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:17, AGE:1.0, PDOP:1.257,
HDOP:0.600, VDOP:1.104, TDOP:1.042, GDOP:0.702, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM14:13:02
SP, PN20010, N 73386.7486, E 546833.7083, EL107.8672, --132
GPS, PN20008, LA45.594384237200, LN17.430840794400, EL154.024000, --133
--GS,PN20008,N 73193.3833,E 547075.0976,EL107.2849,--133
--GT, PN20008, SW2044, ST220768000, EW2044, ET220768000
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:15, AGE:1.0, PDOP:1.265,
HDOP:0.700, VDOP:1.054, TDOP:1.094, GDOP:0.636, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM14:19:29
GPS, PN20008, LA45.594385266800, LN17.430834417000, EL154.079000, --133
--GS,PN20008,N 73193.7246,E 547073.7307,EL107.3399,--133
--GT, PN20008, SW2044, ST220855000, EW2044, ET220855000
```

--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:15, AGE:1.0, PDOP:1.213, HDOP:0.600, VDOP:1.054, TDOP:1.033, GDOP:0.636, NSDV:0.010, ESDV:0.010

--DT03-12-2019

--TM14:20:40