```
JB, NM14_10, DT03-12-2019, TM14:57:41
MO, AD1, UN1, SF1.00000000, EC0, EO0.0, AU0
--Stonex SurvCE Version 6.01
-- CRD: Alphanumeric
-- Haszn. Meghat: HUNGARY/EOV-VITEL2014
              Stonex, S900, SN:S900281800035, FW:0.22.181113(STONEX)
--Equipment:
--Antenna Type: [STXS900
NONE], RAO.0785m, SHMP0.0547m, L10.0702m, L20.0608m, --L1/L2 Antenna
--Illesztési Fájl: None
--Geoid Elválaszt. Fájlok: None
--Grid Adjustment File: None
-- GPS Lépték: 1.00000000
--Scale Point not used
--RTK Method: RTCM V3.1, Device: Internal GSM, Network: NTRIP 1033_VRS-
RTCM3.1-GLO
BP, PN4095, LA45.592883447636, LN17.393314207052, EL155.6289, AG0.0000, PA0.000
0, ATAPC, SRROVER, --
--Import ASCII
SP, PN101, N 73999.1700, E 546143.6200, EL0.0000, --
SP, PN103, N 73964.1700, E 546161.8800, EL0.0000, --
SP, PN105, N 73946.7800, E 546178.7100, EL0.0000, --
SP, PN106, N 73939.2800, E 546187.0300, EL0.0000, --
SP, PN834, N 74120.7100, E 546089.6500, EL0.0000, --
SP, PN873, N 74224.0400, E 546353.1900, EL0.0000, --
SP, PN874, N 74269.7000, E 546331.6600, EL0.0000, --
SP, PN910, N 74010.9800, E 546226.9700, EL0.0000, --
SP,PN911,N 74111.3100,E 546284.6800,EL0.0000,--
--DT03-12-2019
--TM15:06:31
-- Haszn. Meghat: HUNGARY/EOV-VITEL2014
--Equipment: Stonex, S900, SN:S900281800035, FW:0.22.181113(STONEX)
--Antenna Type: [STXS900
NONE], RAO.0785m, SHMP0.0547m, L10.0702m, L20.0608m, --L1/L2 Antenna
--Illesztési Fájl: None
--Geoid Elválaszt. Fájlok: None
--Grid Adjustment File: None
--GPS Lépték: 1.00000000
--Scale Point not used
--RTK Method: RTCM V3.1, Device: Internal GSM, Network: NTRIP 1033_VRS-
RTCM3.1-GLO
--Entered Rover HR: 2.0000 m, Vertical
LS, HR2.0702
GPS, PN2000, LA46.001838535600, LN17.423324532800, EL157.939000, --13
--GS, PN2000, N 74272.8051, E 546336.7243, EL111.1933, --13
--GT, PN2000, SW2044, ST223606600, EW2044, ET223606600
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:17, AGE:1.0, PDOP:1.277,
HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM15:06:33
GPS, PN2001, LA46.001721809800, LN17.423401628600, EL157.729000, --13
--GS,PN2001,N 74236.4824,E 546352.6935,EL110.9835,--13
--GT, PN2001, SW2044, ST223649800, EW2044, ET223649800
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:17, AGE:1.0, PDOP:1.277,
HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM15:07:14
GPS, PN2002, LA46.001690978200, LN17.423410215200, EL157.932000, --13
--GS,PN2002,N 74226.9316,E 546354.3776,EL111.1865,--13
```

```
--GT, PN2002, SW2044, ST223666400, EW2044, ET223666400
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:17, AGE:1.0, PDOP:1.277,
HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM15:07:30
GPS, PN2003, LA46.000898246200, LN17.422750044800, EL155.086000, --13
--GS, PN2003, N 73984.6151, E 546208.1370, EL108.3404, --13
--GT, PN2003, SW2044, ST223873000, EW2044, ET223873000
--HSDV:0.014, VSDV:0.030, STATUS:FIXED, SATS:16, AGE:1.0, PDOP:1.277,
HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM15:10:57
GPS, PN2004, LA46.000796969800, LN17.422620753200, EL155.395000, --13
--GS, PN2004, N 73953.8238, E 546179.7814, EL108.6494, --13
--GT, PN2004, SW2044, ST223912800, EW2044, ET223912800
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:15, AGE:1.0, PDOP:1.277,
HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM15:11:37
GPS, PN2005, LA46.000867178200, LN17.422523309000, EL155.453000, --13
--GS, PN2005, N 73975.8603, E 546159.1874, EL108.7072, --13
--GT, PN2005, SW2044, ST223943600, EW2044, ET223943600
--HSDV:0.014, VSDV:0.030, STATUS:FIXED, SATS:12, AGE:1.0, PDOP:1.334,
HDOP: 0.800, VDOP: 1.068, TDOP: 1.127, GDOP: 0.715, NSDV: 0.010, ESDV: 0.010
--DT03-12-2019
--TM15:12:08
GPS, PN2006, LA46.001342000800, LN17.422210127000, EL155.366000, --13 CLO
--GS,PN2006,N 74123.6164,E 546094.3229,EL108.6195,--13 CLO
--GT, PN2006, SW2044, ST224233800, EW2044, ET224233800
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:13, AGE:1.0, PDOP:1.334,
HDOP: 0.800, VDOP: 1.068, TDOP: 1.127, GDOP: 0.715, NSDV: 0.010, ESDV: 0.010
--DT03-12-2019
--TM15:17:01
GPS, PN20006, LA46.001341959400, LN17.422210136000, EL155.349000, --13
--GS,PN20006,N 74123.6036,E 546094.3246,EL108.6025,--13
--GT, PN20006, SW2044, ST224242800, EW2044, ET224242800
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:15, AGE:1.0, PDOP:1.277,
HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM15:17:14
GPS, PN20000, LA46.001838522400, LN17.423324519600, EL157.951000, --13
--GS, PN20000, N 74272.8011, E 546336.7214, EL111.2053, --13
--GT, PN20000, SW2044, ST224505400, EW2044, ET224505400
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:16, AGE:1.0, PDOP:1.277,
HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM15:21:35
GPS, PN20001, LA46.001721812800, LN17.423401729400, EL157.667000, --13
--GS,PN20001,N 74236.4829,E 546352.7152,EL110.9215,--13
--GT, PN20001, SW2044, ST224597600, EW2044, ET224597600
--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:16, AGE:1.0, PDOP:1.277,
HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010
--DT03-12-2019
--TM15:23:02
GPS, PN20002, LA46.001690968000, LN17.423410248200, EL157.942000, --13
--GS,PN20002,N 74226.9283,E 546354.3847,EL111.1965,--13
--GT, PN20002, SW2044, ST224636800, EW2044, ET224636800
```

--HSDV:0.014, VSDV:0.020, STATUS:FIXED, SATS:16, AGE:1.0, PDOP:1.277, HDOP:0.700, VDOP:1.068, TDOP:1.058, GDOP:0.715, NSDV:0.010, ESDV:0.010

--DT03-12-2019 --TM15:23:42