


Rapoo Black (White Bottom)	
Switch Type: Linear	Unknown
Total Stem Travel	3.975 mm
Peak Force	83.3 gf
Bottom Out Force	83.3 gf
# of Upstroke Points	1001
# of Downstroke Points	1138

#### **Testing Notes**

- This is certainly an odd one. It always seems like its OEM switches like this that end up having weird artifacts in their force curves and unfortunately I don't have a good answer as to what is causing these.


#### Rapoo Black (White Bottom)






## **Alternative Force Curve Representations**

Rapoo Black (White Bottom) (Downstroke)



### Rapoo Black (White Bottom) (Upstroke)





# **Alternative Force Curve Representations**

## Rapoo Black (White Bottom)

