



Inspection Report

REJECTED

INSPECTION & COMPONENT DETAILS			
Customer	Auto.customer	Part No.	46152
Part Name	Kappa 1.2 L Inlet	Batch / Lot	46152_5
Inspection Date	2026-08-12 14:09:24	Inspector	System
Component / Material	Metal / Steel	Size / Finish	- / -

DEFECT DETAILS (22)					
SL.NO	DEFECT TYPE	LOCATION	CAMERA / REF	IMAGE	STATUS
1	Face_Damage	P2	Kappa1.2 L_Inlet(1).jpg		REJECTED
2	Stem_Damage	P2	Kappa1.2 L_Inlet (3).jpg		REJECTED
3	Stem_Damage	P2	Kappa1.2 L_Inlet (2).jpg		REJECTED
4	Face_Damage	P2	Kappa1.2 L_Inlet(1).jpg		REJECTED
5	Stem_Damage	P2	Kappa1.2 L_Inlet.jpg		REJECTED
6	Stem_Damage	P2	Kappa1.2 L_Inlet (2).jpg		REJECTED
7	Face_Damage	P2	Kappa1.2 L_Inlet(1).jpg		REJECTED
8	Stem_Damage	P2	Kappa1.2 L_Inlet.jpg		REJECTED
9	Face_Damage	P4	Kappa1.2 L_Inlet(1).jpg		REJECTED
10	Face_Damage	P4	Kappa1.2 L_Inlet(1).jpg		REJECTED
11	Stem_Damage	P2	Kappa1.2 L_Inlet (2).jpg		REJECTED
12	Stem_Damage	P4	Kappa1.2 L_Inlet.jpg		REJECTED
13	Stem_Damage	P4	Kappa1.2 L_Inlet.jpg		REJECTED
14	Stem_Damage	P4	Kappa1.2 L_Inlet (2).jpg		REJECTED
15	Seat_Damage	P4	Kappa1.2 L_Inlet (3).jpg		REJECTED
16	Stem_Damage	P4	Kappa1.2 L_Inlet.jpg		REJECTED
17	Stem_Damage	P4	Kappa1.2 L_Inlet (2).jpg		REJECTED
18	Stem_Damage	P4	Kappa1.2 L_Inlet (3).jpg		REJECTED
19	Stem_Damage	P4	Kappa1.2 L_Inlet (2).jpg		REJECTED

SL.NO	DEFECT TYPE	LOCATION	CAMERA / REF	IMAGE	STATUS
20	Seat_Damage	P4	Kappa1.2 L_Inlet (3).jpg		REJECTED
21	Stem_Damage	P4	Kappa1.2 L_Inlet (3).jpg		REJECTED
22	Stem_Damage	P4	Kappa1.2 L_Inlet (2).jpg		REJECTED
22 INSPECTED		22 REJECTED		0 ERRORS	0 ACCEPTED

FINAL STATUS			
Final Decision	Rejected	Rework Required	NO
Scrap	NO	Approved By	-

Generated from the current inspection record by Valve Final Inspection System.