



INSPECTION STANDARD (HT LAB)



Page 01 of 01

☐ Prototype	☒ Pre-Launch	☒ Production	Date (Original)	18/12/17
Part Name:- FD Pinion Shaft Z-13 DDB		Part No.:- 93655131	Inspection Standard Number	SIP/4206/110
Customer :- TMTL		Change Level.:-00	Part Stage	HT Lab.

Sr.No.	Parameter	Special Char. Class	Methods				Reaction Plan
			Product Specification	Inspection Method	Inspection Frequency	Control Method	
1.	Surface Hardness	*	58~62 HRC	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
2.	ECD at 544 HV (52 HRC)	*	1.1~1.4 mm	Vicker Hardness Tester	1Pc/Lot	FMT-HT-39	A
3.	ECD Below Undercuts	*	0.5 mm min.	Vicker Hardness Tester	1Pc/Lot	FMT-HT-39	A
4.	Core Hardness At PCD	*	42 HRC Max.	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
5.	Core Hardness At RCD	*	30 HRC Min.	Rockwell Hardness Tester	1Pc/Lot	FMT-HT-39	A
6.	Case Micro	*	Tempered Martensite+RA<15%	Microscope	1Pc/Lot	FMT-HT-39	A
7.	Core Micro	*	Bainitic+LCTM	Microscope	1Pc/Lot	FMT-HT-39	A

OPEN SKTCH

Material:-SAE 8620H



Reaction Plan: A-यदि Inspection करते समय कम्पोनेंट खराब मिले तो खराब कम्पोनेंट को Rejection का टैग लगाकर Rejection टेबल पर रखें और उसके बारे में Department के Incharge को बतायें ।

Legends: ☒ Special Characteristics as Per Drawing * Special Characteristics For Process ☒ Special Characteristics For Safety

Change Details

Date	Rev. No.	Change	Reason for Change	Date	Rev. No.	Change	Reason for Change