

M/s. Milestone Gears Pvt. Ltd.,
Unit - 4, Opp. Himachal Fibers Ltd.
Ind. Area., Barotwala, Distt. -
Solani (HP)

Standard Operating Procedure

OPN. NO. **250**
PREV. OPERATION
NEXT OPERATION

Shot Blasting
Straightening

MACHINE NO.
REVISION NO.

SB-01

PART NAME/

Main Shaft
459/M5151

CUST. NAME

JCB

OPERATION

○ :- Metallurgical Testing

CHD. BY:

APPD. BY:

REVISION DATE

DATE OF ENACTMENT

07/01/12

INSPECTION INSTRUMENTS DETAIL :

FIXTURE NUMBER :

TOOLS / CUTTERS DETAIL :


Rocker Well Tester, Vicker H. Tester, Microscope

S.NO.	MACHINE / EQUIPMENT PARAMETERS	VALUE	LOCATE ☐	CLAMP ☐	REST ☐	INSPECT ☒	MAJOR Mj	MINOR Mn	CRITICAL Cr
1.									
2.									
3.									
S.NO.	JIG / FIX. / CTG. TOOL PARAMETERS	VALUE							
1.									
2.									
3.									

CONTROLLING OF DIEMENSION

S. No	Dimension	Specifications	Instrument	Operator	Inspector
1A.	Previous Operation	Shot Blasting	Visually	100%	100%
1.	Surface Hardness	58~63HRC	Rockwell Tester	1 piece per heat	1 piece per heat
2.	ECD	0.5~0.75mm	Vicker H. Tester	--do--	--do--
3.	Core Hardness at Root	350~412Vdh	--do--	--do--	--do--

OPTN. SKETCH



DO & DON'T s.

- 1 सभी Instrument साफ सुथरे होने चाहिये।
- 2 सभी Instrument का Leveling सही होना चाहिये।
- 3 सभी Instrument Calibrate होने चाहिये।

CONTROLLED COPY
SR NO. 01
ISSUED TO Jod - 7
DATE 29/08/22

WORKING INSTRUCTIONS

- Mettallurgical Testing के लिये नीचे लिखे Instruction को Follow करें :-
- 1) Rockwell Hardness Tester में Component की Surface Hardness चैक करें।
 - 2) Component को काट कर एक सैम्पल चैक करें।
 - 3) Rockwell/Vickers Hardness Tester में Sample की Core Hardness चैक करें।
 - 4) Vickers Hardness Tester में Sample को ECD चैक करें।
 - 5) Nital से Sample को Etching करें।
 - 6) Etching किये हुये Sample का Case & Core में Microstructure Microscope द्वारा चैक करें।

Note:-

- 1) Recording will be done by QA Inspector only.
- 2) If Any Doubt please ask Supervisor/QA Inspector.

ENG. CHANGES.

A.

B.

C.

D.